

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0600/2018
DATE : 23-JAN-2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : CHEW WAI MING
ADDRESS : 214 DEPOT ROAD
#12-68
S(109701)
TELEPHONE NO : 86662223

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100242780-07
VEHICLE NO : SKA1268C
MODEL CODE : SH5BK2S
MODEL/YEAR : FORESTER 2.0X
ENGINE NO : EJ20E071739
CHASSIS NO : JF1SH5KS5AG043832
MILEAGE : 1 KM
DATE IN : 23/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 20/01/2018

Print Date : 23/01/2018
Print Time : 09:19:30

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKA1268C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION:BENDEMEER ROAD DATE:20/01/2018 TIME:1315HRS		
3	ZZ/002	REMOVE/REPLACE TAILGATE, REAR BUMPER, REAR PANEL	1680.00	
4	ZZ/003	RESPRAY TAILGATE, REAR BUMPER, REAR PANEL	1260.00	
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	
6	ZZ/005	TRANSFER (BOOTLID / TAILGATE) MECHANISM	150.00	
7	ZZ/006	WHEEL ALIGNMENT	200.00	
8	ZZ/007	REMOVE/REFIX CARPET,SEATS,REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	550.00	
9	ZZ/008	REMOVE & INSTALL (FRT / REAR)WINDSCREEN	300.00	
10	ZZ/009	TO REMOVE & REFIX FUEL TANK	200.00	
11	ZZ/011	TO CONDUCT (PER SIDE) ANTI-RUST COATING	580.00	
12	ZZ/012	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	300.00	
13	ZZ/013	TO SUPPLY & INSTALL (PER SIDE) TINTED FILM	145.00	
14	ZZ/014	SUNDRIES	100.00	
15	ZZ/10	TO CONDUCT (FRT / REAR) LIGTING TEST	50.00	
TOTAL LABOUR CHARGES			5615.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKA1268C

		DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
1	EXH PIPE ASSY R	44200SC031	1123.20				
2	MUFFLER LH	44300SC142	601.20				
3	MUFFLER RH W/O CUTTER (SC030/090/170)	44300SC150	601.20				
4	FLOOR PAN RR 4D	52122FG0719P	370.80				
5	SKIRT CPL REAR	52401SC0119P	288.00				
6	REAR BUMPER	57704SC010	432.00				
7	REAR BUMPER RH SIDE BRACKET	57707SC080	14.40				
8	REAR BUMPER LH SIDE BRACKET	57707SC090	14.40				
9	BEAM CPL R	57711FG0109P	208.80				
10	REAR TOWING HOOK COVER	57731SC050WU	14.40				
11	TAILGATE PANEL	60809SC0009P	1072.80				
12	GLASS R/G	63019SC000	799.20				
13	LATCH&ACT ASSY RG (USE FG111)	63032FG112	176.40				
14	REAR WINDSCREEN DAM RUBBER RH/LH	63232SC000	14.40				
15	REAR WINDSCREEN MOULDING	63232SC010	14.40				
16	GARNISH COLOR	91119SC000WU	468.00				
17	LABEL R/G	91572SC000	14.40				
18	REAR FORESTER LETTERMARK (SUPP)	93073SC000	44.20				
19	REAR SUBARU LETTERMARK (SUPP)	93073SC010	43.20				
SUB TOTAL			6315.40	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			1263.08	0.00	0.00	0.00	
GRAND TOTAL			5052.32	0.00	0.00	0.00	
OVERALL TOTAL			5052.32				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKA1268C

TOTAL LABOUR CHARGES 5615.00
TOTAL SPARE PARTS CHARGES 5052.32

GRAND TOTAL 10667.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.