

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 20/01/2018

TP Veh Reg No: SGD4560U

Estimate No: ES1890098/AMK

Date: 30 Jan 2018

Policy No: DMPCSN3013341702

Veh Reg No: SDU6000C

Make/Model: VOLVO S60 2.0A

Chassis No: YV1FS445BB2019973

Engine No: B4204T6213101

Reg. Date: 15/07/2011

Estimate Repair Cost to Vehicle No :SDU6000C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR BUMPER	1,572.00	1 PC	1,572.00	✓
2 REAR BUMPER RH TOW HOOK COVER	74.00	1 PC	74.00	✓
3 REAR BUMPER RH OUTER PARKING SENSOR	194.00	1 PC	194.00	?
4 REAR BUMPER LOWER SPOILER	648.00	1 PC	648.00	✓
5 REAR BUMPER REINFORCEMENT	1,406.00	1 PC	1,406.00	?
			3,894.00	3,894.00
Labour				
6 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, LOWER SPOILER; KNOCKING & REPAIR REAR PANEL & REALIGN THE SAME	500.00	1 LA	500.00	350
7 PUTTY & RESPRAY REAR BUMPER, LOWER SPOILER, REAR RH FENDER & ALL AFFECTED AREAS	500.00	1 LA	500.00	450
			1,000.00	1,000.00
			Total	S\$ 4,894.00
			Add GST @ 7%	342.58
			Total Amount Payable	S\$ 5,236.58

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: