



320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SKT243EMake & Model : HONDA VEZEL .5X CVTYear of Manufacture : 2015Chassis No. : RU11017998Ins Company : AIG ASIAEngine No. : L15B351811

Excess : _____

Policy No. : _____

Date of Accident : 19/01/2018Time of Accident : 0715

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$2,618.60

Contact No

Plus/Less -20% \$(523.72)

68438736 – THOMAS

Total of Cost / List \$2,094.88(b) Nett Price Items \$-

Less _____

Total of Nett Item _____

(c) Special Nett Items \$245.00Total Parts Cost (Appendix A) \$2,339.88Labour (Appendix B) \$1,900.00Total Repair Cost \$4,239.88*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SKT243E Case Owner : ANIKKA

Make & Model : HONDA VEZEL .5X CVT Year Manufacture : 2015

Chassis No : RU11017998 Engine No : L15B351811

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	TAIL GATE	1		\$954.00			
2	TAIL GATE EMBLEM	1		\$22.00			
3	WORDING "VEZEL"	1		\$56.20			
4	TAIL GATE LOCK	1		\$180.00			
5	TAIL GATE CATCH	1		\$24.70			
6	TAIL GATE HINGE LH	1		\$50.00			
7	TAIL GATE HINGE RH	1		\$50.00			
8	TAIL GATE WEATHERSTRIP	1		\$97.00			
9	REAR BUMPER	1		\$863.70			
10	REAR BUMPER CLIPS	10		\$39.00			
11	REAR BUMPER REFLECTOR LH	1		\$141.00			
12	REAR BUMPER REFLECTOR RH	1		\$141.00			
13	REVERSE SENSOR	1				\$200.00	
14	REAR NUMBER PLATE	1				\$45.00	
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No.	: <u>SKT243E</u>	Case Owner	: <u>ANIKKA</u>
Make & Model	: <u>HONDA VEZEL .5X CVT</u>	Year of Manufacture	: <u>2015</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.