



SERVICE REQUESTS MESSAGES CLAIMS

CK130510
~~080~~
 08m00765

« Assessment Details

General & Workshop Details

Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

General Details

Workshop Details

Involving 1 2015 FORD MONDEO 1.5 (SLC2719P)

Total Rebate Amount 0

Date of Loss January 13, 2018

Nett Loss Amount \$0.00

Time of Loss 22:50

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

REFER TO ATTACHMENT PROVIDE BY

OWNER

Loss Description

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudices" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Target Date of Completion *

02/05/2018



Days of work completion *

12

Tawfik 97495749
 Authorised 25/1/18 @ 1430
 Ex \$400
 Resurvey before paint 9 days
 gnr@lkkauto.com



SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

Add

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUNTY	PART PRICENET	ACTION (PARTS)	REMOVE
	1	1			FRONT BUMPER PLATE				45	<i>de ✓</i>	45	Reviewing	
	2	1			FRONT NUMBER PLATE GARNISH				80	<i>de ✓</i>	80	Reviewing	
	3	1			FRONT BUMPER LOGO				68	<i>de ✓</i>	68	Reviewing	
	4	1			FRONT BUMPER GRILLE				420	<i>de ✓</i>	420	Reviewing	
	5	8			FRONT BUMPER GRILLE CLIPS				5	<i>de ✓</i>	40	Reviewing	
	6	1			FRONT BUMPER TOP GRILLE CHROME				330	<i>de ✓</i>	330	Reviewing	
	7	10			FRONT BUMPER CLIPS				7	<i>de ✓</i>	70	Reviewing	

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUNTK	PART PRICENET (PARTS)	ACTION (PARTS)	REMOVE
	8	1			FRONT BUMPER LOWER GRILLE				350	<i>del</i>	350	Reviewing	
	9	1			FRONT BUMPER LOWER GRILLE CHROME				280	<i>ant</i>	280	Reviewing	
	10	1			FRONT BUMPER TOW COVER				40	<i>del</i>	40	Reviewing	
	11	1			FRONT BUMPER				1150	<i>del</i>	1150	Reviewing	
	12	1			FRONT BUMPER REINFORCEMENT				290	<i>?</i>	290	Reviewing	
	13	1			FRONT BUMPER SPONGE				195	<i>?</i>	195	Reviewing	
	14	1			FRONT FENDER RH				380	<i>bt</i>	380	Reviewing	
	15	1			FRONT FENDER COWLING RH				140	<i>del</i>	140	Reviewing	
	16	10			FRONT FENDER COWLING CLIPS RH				9	<i>del</i>	90	Reviewing	
	17	1			FRONT FENDER VERTICAL SPONGE RH				98	<i>del</i>	98	Reviewing	
	18	1			ROCKER GARNISH				720	<i>dis</i>	720	Reviewing	

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUNTK	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐	19	2			ROCKER GARNISH RUBBER RH				85	<i>mn</i>	170	Reviewing	
☐	20	12			ROCKER GARNISH CLIPS				8	<i>nel</i>	96	Reviewing	
☐	21	1			R/F DOOR				2280	<i>bt</i>	2280	Reviewing	
☐	22	1			R/F DOOR RUBBER				115	<i>hn</i>	115	Reviewing	
☐	23	2			R/F DOOR <i>hinge</i>				150	<i>R</i>	300	Reviewing	
☐	24	1			R/R DOOR				2100	<i>bt</i>	2100	Reviewing	
☐	25	1			R/R DOOR RUBBER				138	<i>dn</i>	138	Reviewing	
☐	26	1			R/ R DOOR EDGE RUBBER				100	<i>nel</i>	100	Reviewing	
☐	27	2			R/R DOOR HINGES				150	<i>R</i>	300	Reviewing	
☐	28	1			RH CENTRE PILLAR - PRICE TO CONFIRM				0	<i>R</i>	0	Reviewing	
☐	29	1			R/R FENDER - REPAIR				0	<i>R</i>	0	Reviewing	
☐	30	1			RH ROCKER PANEL - REPAIR				0	<i>R</i>	0	Reviewing	

Labour

Add

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TOWING CHARGE	0	100	0	Reviewing		
	2		TO CUT / WELD CENTER PILLAR RH, ROCKER PANEL RH, TO REPAIR REAR FENDER RH, BONNET FRONT INNER PANEL RH, REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS	0	1200	0	Reviewing		
	3		TO SPRAY AFFECTED AREAS	0	1300	1500	Reviewing		
	4		TO REMOVE AND REFIX DOOR MECHANISM CHECK & TEST POWER, WINDOW AND CENTER LOCKING SYSTEM	0	160	0	Reviewing		
	5		TO REMOVE AND REFIX CUSHION, SAFETY BELT CARPET AND OTHER ATTACHMENT PARTS	0	80	0	Reviewing		
	6		TO CHECK WHEEL ALIGNMENT	0	80	0	Reviewing		



- SERVICE REQUESTS
- MESSAGES
- CLAIMS

« Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$13,505.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$10,385.00	\$10,385.00
Labour	\$1,620.00	\$1,620.00
Paint	\$1,500.00	\$1,500.00