



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2014 BMW 428 I (SKC178A)

Date of Loss

11 January 2018

Time of Loss

10.00

Loss Description

SKC178A (INSD) C/W GBG8268G (TP)

Comment

Workshop Details

Total Rebate Amount

96234

Nett Loss Amount

\$68,766.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

04/04/2018



Days of work completion *

70



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

25/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/45R18

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

225/45R18

Front left side

GOODYEAR6mm

Rear left side

GOODYEAR6mm

Front right side

GOODYEAR6mm

Rear right side

GOODYEAR6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		1	1			HEADLAMP ASSY RH			Cut	1500				1500	Review
		2	1			HEADLAMP LOWER BRACKET RH			Serviceable	0	0	0	0	0	Deny
		3	1			HEADLAMP WASHER COVER RH			Cut	32				32	Review
		4	1			HEADLAMP WASHER JET RH			Serviceable	0	0	0	0	0	Deny
		5	1			HEADLAMP TOP BRACKET RH			Necessary	12				12	Review
		6	1			FRONT BUMPER			Deformed	900				900	Review
		7	1			FRONT BUMPER RETAINER RH			Necessary	18				18	Review
		8	1			FRONT BUMPER SPONGE			Serviceable	0	0	0	0	0	Deny
		9	1			FRONT BUMPER REINFORCEMENT			Serviceable	0	0	0	0	0	Deny
		10	1			FRONT BUMPER LOGO			Necessary	65				65	Review
		11	1			FOG LAMP ASSY RH			Serviceable	0	0	0	0	0	Deny
		12	1			FOG LAMP GARNISH RH			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
☐		13	1			FRONT FENDER RH			Repair	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
☐		1		TO KNOCK AND STRAIGHTEN HEADLAMP PANEL RH, FRONT FENDER RH, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	300	0	0	Reviewing		1
☐		2		SPRAY PAINT FRONT BUMPER, FRONT FENDER RH	300	0	0	Reviewing		1
☐		3		DIAGNOSE CHECK AND RESET FRONT BUMPER SENSOR	100	0	0	Reviewing		1
☐		4		CHECK WIRING AND FOCUS HEADLAMP	30	0	0	Reviewing		1

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 3 DAYS	Reviewing			
☐		2	(REPAIR COST NOT CONCLUDE)	Reviewing			

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$2,857.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$730.00	\$730.00
Spare Parts	\$2,527.00	\$2,527.00
Excess	-\$400.00	-\$400.00

Submit for Review