

CS/III18001471/ Urd302

Member: Marcus Gabriel Wee

ASSIGNMENT NO.: III

24/01/2018 @ 11:25am

①

UNIT NO. / RES. / CH. RES. / EX. / INT. / REV. / CS

Co. / Dept. / Vehicle No.

GX 7777 L

SHA 7414T

Co. / Trade / Reg. No.

Yi Heng Motor

6509 0052

1 Kaki Bukit Ave 6 #02-19 Autobay

Policy No.

Expiry

Start Insured

End

Make of Veh.

23/01/2018

Client's Record

CA / REV. / REP. / REV 24 HRS

'wp'

25/01/18

Time Taken

12:02pm @ 24/1/18

Person Insured

Wan Ping

Time

②

Time Taken

Amount Insured

✓

③

GX7777L-X

SHA 7414T-004/III16002904/UzaBq2

A-0-A-1-11-22/2016

(08/11/13) wef
ASS. REC. BY: *MORIS*

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *GX7777L*
at Workshop m/s *1/1 hy*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: *GX7777L* Yr Regn: *3, 04*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CM*
Make: *Nissan urvan* c.c. *2953*
Colour: *Grey* A/C: Insured / Std / NI / NA
Sp. Reading: *271330* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *JN1MG4E2520710994*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *195 R15*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *14k.*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *10* days Res: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS *COE 28/2/19*
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Front _____ Rear _____
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *23/1/18* D.O.I. *24/1/18*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Rf.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
12/2/18 cont'd 2/5 @ \$200 with Ad Boy

Ref: 915.164.74, 651.

RECEIVED 2018

Date/Time. File Pass to? : Preli. Report
1) *typist* : Final Report
Date/Time. File Return to?

Days Of Repair: *10*

Resurvey No. of Trip: *2*

Survey Fee:	<i>450</i>
Transportation:	
) S + RS	
) Photos	
) Others	
TOTAL	<i>450</i>

Report Format : *TP*
Lump Sum / H.B.I. (\$) *8200*

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III18001471/Urd3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 24-01-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7414T	Veh. Inspected	GX 7777L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Engine No.	HIDDEN	Accident Date	23/01/2018	Inspection Date	
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

***Nivitha (LKK Auto)**

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 24 January 2018 11:25 AM
To: ct-admin@visionlawllc.com; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Natalie Lee
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. GX7777L (Accident involving GX7777L and SHA7414T on 23.01.2018)
Attachments: 1161_001.pdf; 1088_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GX7777L and let us have your report urgently.

This claim will be handled by Ms Natalie.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Motor Claim - III

Sent: 23 January, 2018 4:22 PM

To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. GX7777L(Accident involving GX7777L and SHA7414Ton 23.01.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: 23 January, 2018 2:07 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Attached Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIM
TAN YINGXIAN SELWYN

Company Registration No. 200721148H

Head Office:

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch:

490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this matter

OUR REF: AKN-atv-INS-Y44-GX7777L-2017 - [please reply to: annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)
YOUR REF: **SHA7414T**

24 January 2018

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04/06-00 IOB Building
Singapore 049711

Attn: Motor Claims Department

BY FAX: 6224 4174 & EMAIL
motorclaim@iii.com.sg

Dear Sirs

NAME OF CLAIMANT: SOON WENG ENGINEERING

VEHICLE NUMBER: GX 7777 L

YOUR INSURED VEHICLE NUMBER: SHA 7414 T

ACCIDENT ALONG UBI ROAD 2 TOWARD UBI ROAD 1 ON 23 JAN 2018 AT ABOUT 1115HOURS

We refer to your email dated 23 JAN 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **Adrian Link from LKK Consultant Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

YI HENG MOTOR WORKSHOP
1 KAKI BUKIT AVENUE 6
#02-19 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
TEL: 6509 0052 (WAN PING)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

cc. **GX 7777 L** - By fax 6747-9402 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2018 17:47
Date Of Accident	23/01/2018 11:15
Exact Location Of Accident	UBI RD 2 TWDS UBI RD 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX7777L
Insured/Policyholder	
Name Of Registered Owner	SOON WENG ENGINEERING
Co Reg No	53154353J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91801319

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5045525009-07
Cover Note Number	

Driver

Name of Driver	THAM WENG SOON
NRIC No	S8061458F
Date Of Birth	09/10/1980
Occupation	INDOOR
Date Of Driving Pass	10/12/2003
Driving Experience	14 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91801369
Fax Number	
Contact Number	
Email Address	NOEMAIL


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour LORRY
Details Of Properties VEHICLE C
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name THAM WENG SOON
Approximate Age
Injuries Sustain
Injured person in which vehicle? GX7777L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23-01-2018 @ 11:15 AM I was travelling on UBI ROAD 2 TOWARD UBI ROAD 1 in extreme left lane front lorry stop so I follow to stop in stationary position suddenly taxi SHA 7444T behind me could not stop in time and collect onto my vehicle GX7777L Rear portion and the impact was so great that throw my vehicle hit onto front lorry. After accident we 3 person come down to inspect and the front lorry drive away in hurry so I forget to take down his detail.

SOON WENG ENGINEERING
 Blk 529 Hougang Ave 6
 #02-245 Singapore 530529
 Tel: 9180 1369

DECLARATION

The foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre/Personnel's Signature
 Name:
 NRIC/FIN No.:

23/1/18 5.25pm



**SINGAPORE
POLICE FORCE**



T/20180124/2036

1 of 4

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20180124/2036

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/01/2018 11:53	Vide Report No.:	Station Diary No.: 33
--	------------------	--------------------------

Informant's Particulars

Name of Informant: THAM WENG SOON		Address: APT BLK 529 HOUGANG AVENUE 6 #02-245 SINGAPORE 530529	
ID Type / ID No.: NRIC NO / S8061458F		Contact No.: Home/Office:	Mobile: 91801369
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 37	Date of Birth: 09/10/1980	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: AIRCON TECHNICIAN		Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 23/01/2018 11:15	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 UBI ROAD 2 UBI ROAD 1 Most left lane				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GX7777L	Van				Slightly Damaged	0
SHA7414T	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



urvan Price Range Depreciation > 10 year Vehicle Type Submit Advanced Search

Home > Used Cars > Direct Owners > Nissan Urvan (COE till 02/2019)

Tools & Tips


- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Tyres



HDFC HOME LOANS
credit your space

BECAUSE WE KNOW THAT YOUR TRUE HOME WILL ALWAYS BE IN INDIA



INDIA HOMES FAIR

OVER 30 DEVELOPERS
\$30 LAKH ONWARDS

27 & 28 JAN 2018
11AM TO 7.30PM

& WIN EXCITING PRIZES!
LUCKY DRAW AT THE VENUE
ON 27 & 28 JAN, 2018

Register Now
T&C Apply

Nissan Urvan (COE till 02/2019)

Overview Financial Accessories Similar Research Photos Map **DIRECT OWNER**

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$13,000	?
Depreciation	\$12,490 /yr	?
Reg Date	10-Feb-2004 (1yr 15days COE left)	?
Lifespan	09-Feb-2024	?
Manufactured	2003	?
Mileage	-	?
Transmission	Manual	?
Engine Cap	2,953 cc	?
Curb Weight	1,740 kg	?
Fuel type	Diesel	?
Features	4 Doors Nissan Urvan E25. COE Ends Nov 2018. Can Renew Another 5 Years.	?
Accessories	Full Bodykit. Full Luxury PVC Leather Seat And All Panels. (Door, Roof, Rear Side Panel And All Pillars) Rear Cabin Window.	?
COE	\$25,709	?
OMV	\$24,201	?
ARF	\$1,211	?
Dereg Value	\$5,353 as of today (change)	?
No. of Owners	2	?
Type of Veh	Van	?
Category	COE Car, Direct Owner Sale	?
Availability	Available	DIRECT OWNER



Add to Shortlist Add to Compare Add a Note

Posted on: 25-Jan-2018 | Last Updated on: 25-Jan-2018
Tags: Nissan Urvan, 2004 Nissan Urvan, Nissan, Urvan, Used Nissan

Upfront Payment x more Financial info

Transfer Fee	\$25	?
Down Payment	\$1,300 (change)	Maximum 90% Loan ?
1st Instalment	\$1,019	?
Total Upfront Payment	\$2,344 (excluding insurance)	?

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.



100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER

Preferred Viewing Area

Seller Information



Contact Person(s) Syed
Contact No. 90197364
Enquiry Contact Seller

USEFUL FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form

» M01
Instructions on how to complete a seller to end-consumer deal
Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.

Useful Services

-  Make sure of this car condition with STA Evaluation.
Vehicle Evaluation
-  Find out the market value for your car. Get a free Car Valuation.
Free Valuation

Recommended for you

highlight

1-6 of 18



Nissan Urvan Price Range Depreciation > 10 year Vehicle Type Submit

Advanced Search

Home » Used Cars » ABWIN (1994) Pte Ltd » Nissan Urvan (COE till 03/2019)

Tools & Tips

Nissan Urvan (COE till 03/2019)

Car Buying

Overview

Financial

Accessories

Similar

Research

Photos

Map

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price **\$14,800**
 Depreciation \$12,530 /yr
 Reg Date 25-May-2004
 (1yr 2mths 7days COE left)

Lifespan 24-May-2024

Manufactured 2004

Mileage -

Transmission Manual

Engine Cap 2,953 cc

Curb Weight 1,500 kg

Fuel type Diesel

Features -

Accessories -

Description Hot Deal! Very Good Condition Urvan! Very Reliable And Durable, Spacious And Easy To Maintain. Low Low Depreciation! High Loan, Trade In, Low Interest! Call Now To Inquire!

COE \$25,158

OMV \$22,108

ARF \$1,106

Dereg Value \$5,941 as of today (change)

No. of Owners 2

Type of Veh Van

Category COE Car


Availability Available

Add to Shortlist Add to Compare Add a Note

Posted on: 24-Jan-2018 | Last Updated on: 24-Jan-2018
 Tags: Nissan Urvan, 2004 Nissan Urvan, Nissan, Urvan, Used Nissan

Upfront Payment » more Financial info

Transfer Fee \$25



Location Map


Seller Information

Company **ABWIN (1994) Pte Ltd**
 » dealer's pricelist
 » 160 vehs sold | 182 vehs available

Address 210 Turf Club Road Lot A10/A11/A28/A29
 Search cars nearby this location

Location Car Mall @ The Grandstand


Contact Person(s) Rosson Ng 90683033



GOODBYE WORK, HELLO HOLIDAY!

Compare

ANNOUNCING
 as sgCarMart Premium Dealer for the 5th Consecutive Year



Nissan Urvan Price Range Depreciation > 10 year Vehicle Type Submit Advanced Search

Home > Used Cars > 555 Trading Pte Ltd > Nissan Urvan (COE till 03/2019)

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Nissan Urvan (COE till 03/2019)

- Overview Financial Accessories Similar Research Photos Map



Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$14,555	
Depreciation	\$12,330 /yr	?
Reg Date	16-Apr-2004 (1yr 2mths 7days COE left)	
Lifespan	15-Apr-2024	
Manufactured	2004	?
Mileage	67,555 km (4.9k /yr)	
Transmission	Manual	
Engine Cap	2,953 cc	
Curb Weight	1,500 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	Low Mileage With Good Condition. New Black 2k Paint \$1250 For New Owner	
COE	\$25,158	?
OMV	\$22,656	?
ARF	\$1,133	?
Dereg Value	\$5,941 as of today (change)	?
No. of Owners	2	?
Type of Veh	Van	
Category	COE Car, Low Mileage Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 20-Jan-2018 | Last Updated on: 24-Jan-2018
 Tags: Nissan Urvan, 2004 Nissan Urvan, Nissan, Urvan, Used Nissan

Upfront Payment » more Financial info

Transfer Fee	\$25	?
Down Payment	\$1,456 (change)	Maximum 90% Loan ?



Seller Information

Company **555 Trading Pte Ltd**
 » dealer's pricelist
 » 9 vehs sold | 11 vehs available

Address 802 Woodlands Street 81 #05-89
 Search cars nearby this location

Website www.555trading.com.sg

Contact Person(s) Eric Teo 85223999

Tyres



**GOODBYE
 WORK,
 HELLO
 HOLIDAY!**

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 4353J

Vehicle Details

Vehicle No.: GX7777L

Vehicle to be Exported: No

Intended De-registration
Date: 25 Jan 2018

Vehicle Make: NISSAN

Vehicle Model: URVAN

Primary Colour: Silver

Secondary Colour: Grey

Manufacturing Year: 2004

Engine No.: ZD30036499

Chassis No.: JN1MG4E25Z0710994

Maximum Power Output: -

Open Market Value: \$23,209.00

Original Registration Date: 10 Mar 2004

First Registration Date: 10 Mar 2004

Transfer Count: 1

Actual ARF Paid: \$1,161.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Feb 2019

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$25,709.00

COE Rebate Amount: \$5,616.00

Total Rebate Amount: \$5,616.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6

#02-19 SINGAPORE 4017883

TEL: 6 5090052 FAX: 6 7479402

- To be done on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

No of Author
here
2/5 # 8200/2
24/1/18
10 day
take up the after 10 days

24-01-18

OUR REF NO. GX 7777L

SOON WENG ENGINEERING
BLK 529, HOUGANG
AVE 6, #02-245
SINGAPORE 530529

**ESTIMATE BILL FOR VEHICLE NO. GX 7777L
MODEL : NISSAN URVAN**

LIST ITEM

1) FRONT ROSE PANEL		1,077.70	α
2) FRONT GRILLE		483.00	✓
3) FRONT GRILLE CLIP	6 PCS @ \$ 3.80	22.80	α
4) FRONT BUMPER		658.00	—
5) FRONT BUMPER CLIP	8 PCS @ \$ 3.00	24.00	—
6) FRONT BUMPER BEAM		148.00	?
7) FRONT BUMPER FOG LAMP COVER	2 PCS @ \$ 95.50	191.00	X
8) FRONT BUMPER FOG LAMP	2 PCS @ \$ 275.00	550.00	X
9) BOOT LID		1,863.62	—
10) BOOT LID WEATHERSTRIPE		247.60	2
11) BOOT LID OUTER GARNISH		483.70	α
12) BOOT LID OUTER HANDLE		89.00	α
13) BOOT LID LOCK COVER		38.00	—
14) BOOT LID ACTUATOR		247.00	—
15) BOOT LID SIDE GUARD	2 PCS @ \$ 101.30	202.60	X
16) BOOT LID DAMPER	2 PCS @ \$ 382.00	764.00	α
17) BOOT LID WIPER MOTOR	2 PCS @ \$ 273.00	546.00	X
18) REAR LICENCE PLATE LAMP	2 PCS @ \$ 309.30	618.60	X
19) REAR BUMPER		683.80	—
20) REAR BUMPER BEAM		163.00	—
21) REAR FLOOR PANEL		1,283.00	α

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
 #02-19 SINGAPORE 417883
 TEL: 6 5090052 FAX: 6 7479402

22) REAR FLOOR TOP ALUMINIUM		<i>Surf</i>	129.00	✓
23) REAR END PANEL (INNER)		<i>Ko Joo</i>	473.00	✓
24) REAR END PANEL (OUTER)		<i>3o Joo</i>	560.00	✓
25) SPARE WHEEL CARRIER	<i>312.10</i>	<i>Yun</i>	423.80	2 ✓
26) SPARE WHEEL GUARD GARNISH	<i>115.00</i>	<i>one</i>	183.00	2 ✓
27) REAR EXHAUST SILENCER	<i>681.10</i>	<i>bell/hor</i>	973.00	2 ✓
28) REAR MUDGUARD	2 PCS @ \$ 1384.00	<i>n</i>	2,768.00	α
29) REAR MUDGUARD HOUSING PANEL	2 PCS @ \$ 687.00	<i>n</i>	1,374.00	α
30) REAR MUDGUARD INNER BOARD	2 PCS @ \$ 83.00	<i>n</i>	166.00	α
31) REAR MUDGUARD INNER BOARD CLIP	22 PCS @ \$ 3.50	<i>n</i>	77.00	✓ <i>net</i>
			17911.22	
			5253.31	
			12251.25	
			15,097.72	
			4,529.32	
			10,568.40	
	LESS DISCOUNT - 30%			
				<i>8903.22</i>
				<i>1832.18</i>

NETT ITEM

1) FRONT GRILLE BADGE		<i>M.S</i>	65.00	✓
2) HEAD LAMP ASSY	2 PCS @ \$ 350.00	<i>ora</i>	700.00	✓
3) SIGNAL LAMP	2 PCS @ \$ 88.50	<i>n</i>	177.00	α
4) BOOT LID BADGE		<i>net</i>	52.80	✓
5) BOOT LID STICKER 'URVAN'		<i>net</i>	48.60	✓
6) BOOT LID STICKER '3.0DI'		<i>net</i>	29.80	✓
7) BOOT LID LOCK		<i>Yun</i>	266.10	✓
8) BOOT LID STRIKER		<i>n</i>	34.00	α
9) BOOT LID INNER BOARD		<i>Yun</i>	266.10	2 ✓
10) BOOT LID INNER BOARD CLIP	11 PCS @ \$ 3.50	<i>net</i>	38.50	✓
11) BOOT LID WIPER ARM		<i>n</i>	83.60	α
12) BOOT LID WIPER BLADE		<i>n</i>	32.10	α
13) REAR BUMPER CLIP	6 PCS @ \$ 3.50	<i>net</i>	21.00	✓
14) REAR BUMPER SIDE ATTACHMENT	2 PCS @ \$ 68.00	<i>Yun</i>	136.00	✓

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
 #02-19 SINGAPORE 417883
 TEL: 6 5090052 FAX: 6 7479402

15) REAR BUMPER BEAM CLIP	4 PCS @ \$ 3.50	nee	14.00	—
16) REAR EXHAUST MOUNTING	2 PCS @ \$ 24.00	11	48.00	α
			2,012.60	1637.9
	LESS DISCOUNT - 10%		201.26	1474.11
				1,811.34

SPECIAL NETT ITEM

1) BOOT LID STICKER ' 70KM/H '		nee	20.00	10
2) REAR LICENCE PLATE (EMBOSS)		11	55.00	α
3) REVERSE SENSOR WITH CONTROL UNIT		shhd	350.00	200
4) REAR WINDSCREEN INNERSEAL		nee	60.00	30
REAR WINDSCREEN GUM Sealant		nee	60.00	40
REAR FLOOR WOODEN BLANK		11	1,200.00	α
				1,745.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM			50.00	30
2) TO APPLY UNDERSEALING ON AFFECTED AREAS			120.00	80
3) TO REMOVE AND REFIX REAR WINDSCREEN			180.00	100
4) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT			240.00	60
5) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT			120.00	50
6) TO REMOVE AND REFIX SPARE TYRE CARRIER		11	120.00	α
7) TO REMOVE AND REFIX REAR EXHAUST SILENCER			180.00	60
8) TO REMOVE AND REFIX ROOF LINNING, FLOOR BOARD, TRIM, GARNISH, UPHOLSTERY AND ETC		11	150.00	α
9) TO REMOVE AND REFIX FRONT WOODEN PLANK AND WOODEN BOX COMPARTMENT		11	1,200.00	α
10) TO MOUNT VEHICLE ON CAR O - LINER		11	380.00	α
11) TO REPLACE NEW PART, CUT, WELD, KNOCK ETC			3,840.00	1800
12) TO RESPRAY ON AFFECTED AREAS			2,660.00	1600
			9,240.00	
			4060	23,364.74

10366.36 23,064.19
 8197

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jan 2018 Edit Reg		24 Jan 2018 00:00 Edit Adj Rpt	S\$8,200.00 Edit Estimates	S\$8,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	SOON WENG ENGINEERING , Co. Reg. No.: 53154353J	
Vehicle Reg. No.:	GX7777L	Date of Loss: 23/01/2018 11:00 - :59
Claim Type:	TP	Policy/Cover Note No.:
Vehicle Reg. No. (Insured):	SHA7414T	Policy No. (Claimant):
		Excess:
Repairer:	Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:	
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/02/2018]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		



































ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

















































*GX7777L
[SHA7414T]
TP
SOON WENG ENGINEERING
Jan 23 2018 11:00AM
[-]
Yi Heng Motor Workshop

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
2	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
3	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
4	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
5	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
6	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
7	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
8	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
9	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
10	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
11	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
12	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
13	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
15	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
16	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
21	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
22	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
23	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
24	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
25	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
26	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
27	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
28	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
29	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
30	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
31	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/02/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>

			1		☑
35	13/02/18 10:55	General View	1	Load JPG	☑
36	13/02/18 10:55	General View	1	Load JPG	☑
37	13/02/18 10:55	General View	1	Load JPG	☑
38	13/02/18 10:55	General View	1	Load JPG	☑
39	13/02/18 10:55	General View	1	Load JPG	☑
40	13/02/18 10:55	General View	1	Load JPG	☑
41	13/02/18 10:55	General View	1	Load JPG	☑
42	13/02/18 10:55	General View	1	Load JPG	☑
43	13/02/18 10:55	General View	1	Load JPG	☑
44	13/02/18 10:55	General View	1	Load JPG	☑
45	13/02/18 10:55	General View	1	Load JPG	☑
46	13/02/18 10:55	General View	1	Load JPG	☑
47	13/02/18 10:55	General View	1	Load JPG	☑
48	13/02/18 10:55	General View	1	Load JPG	☑
49	13/02/18 10:55	General View	1	Load JPG	☑
50	13/02/18 10:55	General View	1	Load JPG	☑
51	13/02/18 10:55	General View	1	Load JPG	☑
52	13/02/18 10:55	General View	1	Load JPG	☑
53	13/02/18 10:55	General View	1	Load JPG	☑
54	13/02/18 10:55	General View	1	Load JPG	☑
55	13/02/18 10:55	General View	1	Load JPG	☑
56	13/02/18 10:55	General View	1	Load JPG	☑
57	13/02/18 10:55	General View	1	Load JPG	☑
58	13/02/18 10:55	General View	1	Load JPG	☑
59	13/02/18 10:55	General View	1	Load JPG	☑
60	13/02/18 10:55	General View	1	Load JPG	☑
61	13/02/18 10:55	General View	1	Load JPG	☑
62	13/02/18 10:55	General View	1	Load JPG	☑
63	13/02/18 10:55	General View	1	Load JPG	☑
64	13/02/18 10:55	General View	1	Load JPG	☑
65	13/02/18 10:55	General View	1	Load JPG	☑
66	13/02/18 10:55	General View	1	Load JPG	☑
67	13/02/18 10:55	General View	1	Load JPG	☑
68	13/02/18 10:55	General View	1	Load JPG	☑
69	13/02/18 10:55	General View	1	Load JPG	☑
70	13/02/18 10:55	General View	1	Load JPG	☑
71	13/02/18 10:55	General View	1	Load JPG	☑
72	13/02/18 10:55	General View	1	Load JPG	☑
73	13/02/18 10:55	General View	1	Load JPG	☑
74	13/02/18 10:55	General View	1	Load JPG	☑
75	13/02/18 10:55	General View	1	Load JPG	☑
76	13/02/18 10:55	General View	1	Load JPG	☑
77	13/02/18 10:55	General View	1	Load JPG	☑
78	13/02/18 10:55	Reinspection Photo	1	Load JPG	☑
79	13/02/18 10:55	Reinspection Photo	1	Load JPG	☑
80	13/02/18 10:55	Reinspection Photo	1	Load JPG	☑
81	13/02/18 10:55	Reinspection Photo	1	Load JPG	☑

82	13/02/18 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
83	13/02/18 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	13/02/18 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	13/02/18 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
87	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
88	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
89	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
90	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
91	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
92	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
93	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
94	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
95	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
96	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
97	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
98	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
99	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
100	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
101	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
102	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
103	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
104	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
105	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
106	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
107	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
108	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
109	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
110	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
111	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
112	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
113	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
114	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
115	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
116	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
117	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
118	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
119	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
120	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
121	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
122	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
123	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
124	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
125	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
126	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
127	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
128	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
129	13/02/18 11:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▾	🖨
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/01/18 08:45	Singapore Accident Statement	📄	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

//

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III18001471/URD3E2
Date: 21/02/2018**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	GX7777L	Insured Vehicle No :	SHA7414T
Date of Loss:	23/01/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX7777L	Engine No:	ZD30036499
Make & Model:	NISSAN URVAN, 3.0 D (A)	Chassis No:	JN1MG4E25Z0710994
Reg. Date:	10/03/2004 (Man. Year: 2004)	Odometer:	271330 km
Colour:	Grey		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,814.19	6,586.36	9,227.83	58.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,240.00	3,780.00	5,460.00	59.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,054.19	10,366.36	14,687.83	58.62
Approved Total (Overridden) (S\$)		8,200.00		
Nett Amount (S\$)	25,054.19	8,200.00	16,854.19	67.27

INSPECTION

Date of Assignment:	24/01/2018		
Date Inspected:	24/01/2018	Inspected At:	Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19 Singapore 417883
Estimated Period of Repair:	10.0 days		

Adjuster: MARCUS CHUA**Manager:** Janice Lee Si Hua*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Feb 2018)
Parts: 213 NISSAN URVAN 3.0 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GX7777L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Repair	1,077.70 FL	*- FL
2	1		*FRONT GRILLE	Cracked	483.00 FL	*483.00 FL
3	6		*FRONT GRILLE CLIP	Not Necessary	22.80 FL	*- FL
4	1		*FRONT BUMPER	Dented / Torn	658.00 FL	*658.00 FL
5	8		*FRONT BUMPER CLIP	Necessary	24.00 FL	*24.00 FL
6	1		*FRONT BUMPER BEAM	Bent	148.00 FL	*148.00 FL
7	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	191.00 FL	*- FL
8	2		*FRONT BUMPER FOG LAMP	Not Necessary	550.00 FL	*- FL
9	1		*BOOT LID	Badly Dented	1,863.62 FL	*1,863.62 FL
10	1		*BOOT LID WEATHERSTRIPE	Twisted	247.60 FL	*247.60 FL
11	1		*BOOT LID OUTER GARNISH	Not Necessary	483.70 FL	*- FL
12	1		*BOOT LID OUTER HANDLE	Not Necessary	89.00 FL	*- FL
13	1		*BOOT LID LOCK COVER	Twisted	38.00 FL	*38.00 FL
14	1		*BOOT LID ACTUATOR	Jammed	247.00 FL	*247.00 FL
15	2		*BOOT LID SIDE GUARD	Not Necessary	202.60 FL	*- FL
16	2		*BOOT LID DAMPER	Not Necessary	764.00 FL	*- FL
17	2		*BOOT LID WIPER MOTOR	Not Necessary	546.00 FL	*- FL
18	2		*REAR LICENCE PLATE LAMP	Not Necessary	618.60 FL	*- FL
19	1		*REAR BUMPER	Distorted	683.80 FL	*683.80 FL
20	1		*REAR BUMPER BEAM	Bent	163.00 FL	*163.00 FL
21	1		*REAR FLOOR PANEL	Repair	1,283.00 FL	*- FL
22	1		*REAR FLOOR TOP ALUMINIUM	Bent	129.00 FL	*129.00 FL
23	1		*REAR END PANEL (INNER)	Badly Dented	473.00 FL	*473.00 FL
24	1		*REAR END PANEL (OUTER)	Badly Dented	560.00 FL	*560.00 FL
25	1		*SPARE WHEEL CARRIER	Jammed	423.80 FL	*312.10 FL
26	1		*SPARE WHEEL GUARD GARNISH	Cracked	183.00 FL	*115.00 FL
27	1		*REAR EXHAUST SILENCER	Bent / Twisted	973.00 FL	*681.10 FL
28	2		*REAR MUDGUARD	Repair	2,768.00 FL	*- FL
29	2		*REAR MUDGUARD HOUSING PANEL	Repair	1,374.00 FL	*- FL
30	2		*REAR MUDGUARD INNER BOARD	Not Necessary	166.00 FL	*- FL
31	1		*REAR MUDGUARD INNER BOARD CLIP (22 PCS)	Necessary	77.00 FL	*77.00 FL
32	1		*FRONT GRILLE BADGE	Missing	65.00 FN	*65.00 FN
33	2		*HEAD LAMP ASSY	Cracked	700.00 FN	*700.00 FN
34	2		*SIGNAL LAMP	Not Necessary	177.00 FN	*- FN
35	1		*BOOT LID BADGE	Necessary	52.80 FN	*52.80 FN
36	1		*BOOT LID STICKER URVAN	Necessary	48.60 FN	*48.60 FN
37	1		*BOOT LID STICKER 3.0DI	Necessary	29.80 FN	*29.80 FN
38	1		*BOOT LID LOCK	Twisted	266.10 FN	*266.10 FN
39	1		*BOOT LID STRIKER	Not Necessary	34.00 FN	*- FN
40	1		*BOOT LID INNER BOARD	Torn	266.10 FN	*266.10 FN
41	11		*BOOT LID INNER BOARD CLIP	Necessary	38.50 FN	*38.50 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*BOOT LID WIPER ARM	Not Necessary	83.60 FN	*- FN
43	1		*BOOT LID WIPER BLADE	Not Necessary	32.10 FN	*- FN
44	6		*REAR NUMBER CLIP	Necessary	21.00 FN	*21.00 FN
45	2		*REAR BUMPER SIDE ATTACHMENT	Twisted	136.00 FN	*136.00 FN
46	4		*REAR BUMPER BEAM CLIP	Necessary	14.00 FN	*14.00 FN
47	2		*REAR EXHAUST MOUNTING	Not Necessary	48.00 FN	*- FN
48	1		*BOOT LID STICKER 70KM/H	Necessary	20.00 FS	*10.00 FS
49	1		*REAR LICENCE PLATE (EMBOSS)	Not Necessary	55.00 FS	*- FS
50	1		*REVERSE SENSOR WITH CONTROL UNIT	Shorted	350.00 FS	*200.00 FS
51	1		*REAR WINDSCREEN INNERSEAL	Necessary	60.00 FS	*30.00 FS
52	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
53	1		*REAR FLOOR WOODEN BLANK	Not Necessary	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

	Sub Total (\$)	21,268.82	8,821.12
	- List Item Discount on L Items 30.00/30.00% (\$)	5,253.37	2,070.97
	- Nett Item Discount on N Items 10.00/10.00% (\$)	201.26	163.79
	Total Parts (\$)	15,814.19	6,586.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO APPLY UNDERSEALING ON AFFECTED AREAS	New	120.00	80.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	100.00
4	TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	New	240.00	60.00
5	TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	New	120.00	50.00
6	TO REMOVE AND REFIX SPARE TYRE CARRIER	New	120.00	0.00
7	TO REMOVE AND REFIX REAR EXHAUST SILENCER	New	180.00	60.00
8	TO REMOVE AND REFIX ROOF LINING, FLOOR BOARD, TRIM, GARNISH, UPHOLSTERY AND ETC	New	150.00	0.00
9	TO REMOVE AND REFIX FRONT WOODEN PLANK AND WOODEN BOX COMPARTMENT	New	1,200.00	0.00
10	TO MOUNT VEHICLE ON CAR O - LINER	New	380.00	0.00
11	TO REPLACE NEW PART, CUT, WELD, KNOCK ETC	New	3,840.00	1,800.00
12	TO RESPRAY ON AFFECTED AREAS	New	2,660.00	1,600.00
Gross Labour Cost (S\$)			9,240.00	3,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >