



Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6

Ark@KB Singapore 417892

Email: vfixauto@gmail.com

Tel: 64489268 Fax: 64452368

ATTN: LKK Auto Consultants Pte Ltd

Your Vehicle No. : SHD7184R

Our Vehicle No. : XD8594U

24 JAN 2018

M/S INDIA INT'L INS PTE LTD

64 CECIL STREET

05-01 IOB BUILDING

SINGAPORE 049711

ATTN: MOTOR CLAIMS DEPT

Dear Sir / Madam,

ACCIDENT INVOLVING XD8594R AND SHD7184R ON 19 DEC 2017

We refer to the above matter.

We hereby give 2 days' notice to conduct a pre-repair inspection of vehicle number

XD8594U at 60 Kaki Bukit Ave 6, ARK@KB, Singapore 417892.

Kindly arrange to survey at the address as follows :

NO 2 BUROH CRESCENT #04-08, #04-09

ACE @BUROH

SINGAPORE 627546

Thank you.

Yours faithfully,

Vfix Auto Service Pte Ltd