

M/S INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

ESTIMATE

DATE : 24/1 /2018
ACC DATE : 19/12/2017
REF NO. : VFIX-TP20170392
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO : XD8594U NISSAN CKB45A

DESCRIPTION	LIST ITEM :	AMOUNT S\$
1	1 FRONT BUMPER	bt 2,352.00
2	1 FRONT BUMPER END GARNISH RH	de 165.80
3	1 HEADLAMP RH	x 2,218.40
4	1 FRONT BUMPER SIGNAL LAMP RH	x 332.30
5	1 UPPER STEP BOARD GARNISH R	cut 475.20
6	1 UPPER STEP BOARD RH	x 455.20
7	1 LOWER STEP BOARD RH	bmr 452.10
8	1 LOWER STEP BOARD GARNISH RH	cr 425.10
9	1 LOWER STEP BOARD REFLECTOR RH	cut 185.60
		\$ 7,061.70
	wheel Cap cover \$80 b1	LESS 30%
		\$ 2,118.51
		\$ 4,943.19

LABOUR & MISCELLANEOUS:

	AMOUNT S\$
1 To remove damaged body parts with all necessary components/ attachments apply hot-works where necessary straighten repair, reshape, dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	500 800.00
2 To spray paint replaced/repared body parts inclusive of preparatory works and painting materials	500 800.00
3 To conduct headlamp alignment	✓ 30.00
	\$ 1,630.00


4) wheel alignment \$100 80.

GRAND TOTAL : \$ 6,573.19

6,729.19

SINGAPORE DOLLARS : SIX THOUSAND FIVE HUNDRED SEVENTY THREE & CENTS

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey the vehicle after painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

Amjiah 97443749
WP
3/1/18 @ 1200 Am
Lumpsum
Resurvey after repair
4 days