

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BG 3520**
Date Estimated : **23/01/2018**
Prepared By : **Wong Guo Xiang**

Page No. : **1 of 1**

- ESTIMATE REPAIR FOR -

Tay Teow Kwang
94 Loyang Rise

Singapore 507507

- ACCOUNT - **2000**

CASH - Sale service
.

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLF606D	WF0DXXGAKDFM48882	12/08/2016	Fie Titn 1.0	0

DESCRIPTION	VALUE
SUNDRIES	150.00
TO REPAIR REAR RHS DOOR,REAR RHS FENDER,REAR BUMPER	1,800.00
TO RESPRAY REAR RHS DOOR,REAR RHS FENDE,REAR BUMPER	2,400.00
WIRING CONNECTION & CHECK (NETT)	150.00
REMOVE & REFIX REVERSE SENSOR (NETT)	150.00
WHEEL ALIGNMENT (NETT)	600.00
TO REMOVE & REPLACE REAR SUSPENSION SYSTEM (NETT)	1,500.00
TUFF KOTE @ \$60 PER PANEL	180.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODE	600.00

Total Labour 1: **7,530.00**

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
8V515K952BL	REAR AXLE ASSY WITH CTRL HOLE(A)	1	1,034.00	10.00	930.60
Total Parts :					930.60

Customer Service Officer

Contact

Labour 1	:	7,530.00
Parts	:	930.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	592.24
Grand Total	:	9,052.84

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.