

22/03/2018

ASS. REC. BY:

REF: CS/ICS18001495/migbez Special Instruction:

Surveyor:

Ma

ASSIGNMENT (Office)

From (Person):

Carrie Tan

of

ICS

Date/Time:

24/01/2018 336pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 1022D

Insured:

at Workshop m/s

Falcon - Air

Tel:

6452 0880

of

B1C 176 Sin ming Drive #01-06

Policy No:

Claim No:

DMPC 1800027A

Sum Insured:

Excess:

JBA \$50

D.O.A.

24/01/2018

Make of Veh:

(Client's Record)

CA / ~~REV~~ / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

25/01/2018 10:04am

Person Contacted:

Florence

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 1022D - X

26/1/18 @ 1.41pm revert to Carrie Tan by email.

29/1/18 @ 4.45pm Lionel Chua informed C/A on P/P if repairs accepted 10% cost plus instead of 15% cost plus & ex: \$500 by email.

29/1/18 @ 4.50pm informed Joshua C/A on cost 10% instead of 15% & ex: \$500.

22/6/18 @ 2.28pm confirmed with Florence final fig \$7870.95.

LRed \$4632.85, 37%) no temp sum.

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Falcon
 of: _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$70K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 3D1022D Yr Regn: OCT 2011
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523i C.C. 2497Colour: Black A/C: Insured / Std / NI / NASo. Reading: 182183 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: WBAPD22070C868268Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim orTyre Size: F: 185/45/18 CONR: 185/45/18 RY.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 24/1/2018

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 25/1/2018

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11/1/2018

Signature
22/6/2018

Date/Time, File Pass to?

22/6/2018☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

21

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

8-PS \$

Photos

Others

Add Fee:

☐ : Site Insp \$☐ : Interview \$☐ : Tech. Insp \$☐ : Weekend \$Report Format: ODLump Sum / I.B.I. \$ 7870.95

TOTAL

350

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18001495/M1qb

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 25-01-2018



Code : ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKD 1022D
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	24/01/2018
CARRIE TAN		

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/01/2018	Inspection Date	25/01/2018
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Wednesday, 24 January, 2018 3:36 PM
To: Florence Loh; Phoebe Jay Xie (ECICS, Claims)
Cc: ECICS Claims; motorsurvey; Ashley Chong (LKK Auto)
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Florence,

Thank you for your email.

Dear LKK,

Please assist to do OD PRI survey.

Thank you.

Regards,
Carrie Tan
Claims Division

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Florence Loh [mailto:fa_autoservices@falconair.com.sg]
Sent: Wednesday, 24 January, 2018 2:26 PM
To: Phoebe Jay Xie (ECICS, Claims)
Cc: ECICS Claims; motorsurvey
Subject: Re: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Good afternoon Phoebe,

Insured is making an Own Damage claim.

Attach estimate and documents for your perusal.

Please arrange vehicle survey at our Sin Ming w/shop. Vehicle is in.

Thank you.
Florence Loh
Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive
#01-06/07 Sin Ming AutoCare
Singapore 575721

25012018 @10:04am
Florence very in

Tel: 6452 0880 Fax: 6454 7862

From: Phoebe Jay Xie (ECICS, Claims)
Sent: Wednesday, January 24, 2018 11:24 AM
To: Florence Loh
Cc: ECICS Claims ; motorsurvey
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Florence,

The loss of use is \$100 per day as per surveyor's recommendation.

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited
DID: +65 6303 0180
FAX: +65 6338 9267

Email: phoebejay_xie@ecics.com.sg

From: Florence Loh [mailto:fa_autoservices@falconair.com.sg]
Sent: Wednesday, 24 January, 2018 11:10 AM
To: Phoebe Jay Xie (ECICS, Claims)
Cc: Lionel Chua Kok Keong (ECICS, Claims)
Subject: Own Damage Claim_SKD1022D (doa: 24/01/2018)
Importance: High

Good morning Phoebe,

Insured is making an OD claim and we are assisting them with the reporting and claim.

The are also checking whether their policy cover the transport/loss of use.

Appreciate your help to check and let me know asap.

Thank you.

Florence Loh
Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive
#01-06/07 Sin Ming AutoCare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee

indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 29 January 2018 4:50 PM
To: joshua@falconair.com.sg
Cc: SUR
Subject: VEHICLE SKD 1022D (DOA: 24/01/2018)

Dear Joshua,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SKD 1022D at cost plus 10% instead of 15% on part by part basis. (excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 29 January 2018 4:45 PM
To: Shiau Chan (LKKAUTO)
Cc: ECICS Claims; motorsurvey; Phoebe Jay Xie (ECICS, Claims); assignments; SUR
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Our claim no. DMPC1800027H

Dear Shiau Chan,

We noted that the workshop was unable to source for any second hand/used/salvage parts for the above vehicles older than 3 years, which the repairs should be made on lump sum basis. But we wish to propose the parts costs at 10% instead of 15% and advise our w/shop to proceed the repaired for this Own Damage claim accordingly.
Excess (Section I): S\$500.00

Thank you.

Regards,
Lionel Chua
DID: +65 6303 0167
FAX: +65 6338 9267
ECICS LIMITED
Email: claims@ecics.com.sg

follow us on  follow us on  visit our website 
facebook  twitter  ecics.com.sg 

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, 29 January, 2018 4:12 PM
To: ECICS Claims
Cc: motorsurvey; Phoebe Jay Xie (ECICS, Claims); assignments; SUR
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Lionel,

Thank you for the email.

We have checked with the repairer, they insist to repair the vehicle SKD 1022D on part by parts basis due to no second hand parts available.

Kindly advise on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ECICS Claims [<mailto:claims@ecics.com.sg>]

Sent: Monday, 29 January 2018 4:04 PM

To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Cc: ECICS Claims <claims@ecics.com.sg>; motorsurvey <motorsurvey@ecics.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Our claim no. DMPC1800027H

Dear Shiau Chan,

Thank you for your email with the attachment.

We wish to highlight you for those vehicles older than 3 years; repairs should be made on lump sum basis and we opine that your recommendation on part by part is too high for this claim. We would appreciate it, if you could assist us to reduce the claim costs and get this vehicle proceed to repair as per your preliminary advice pertaining to the above. Excess applicable is \$500.00.

We look forward to receive your report soon.

Thank you.

Regards,

Lionel Chua

DID: +65 6303 0167

FAX: +65 6338 9267

ECICS LIMITED

Email: claims@ecics.com.sg

follow us on  facebook follow us on  twitter visit our website ecics.com.sg 

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]

Sent: Monday, 29 January, 2018 3:09 PM

To: motorsurvey; Phoebe Jay Xie (ECICS, Claims)

Cc: ECICS Claims; assignments; SUR

Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Phoebe,

Any status of authorisation?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)

Sent: Friday, 26 January 2018 1:41 PM

To: 'motorsurvey' <motorsurvey@ecics.com.sg>; 'Phoebe Jay Xie (ECICS, Claims)' <PhoebeJay_Xie@ecics.com.sg>

Cc: 'ECICS Claims' <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Importance: Low

Dear Phoebe,

Enclosed herewith preliminary advice of SKD 1022D.

Repair cost economical.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 25 January 2018 10:05 AM

To: 'motorsurvey' <motorsurvey@ecics.com.sg>; 'Phoebe Jay Xie (ECICS, Claims)' <PhoebeJay_Xie@ecics.com.sg>

Cc: 'ECICS Claims' <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Carrie,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motorsurvey [<mailto:motorsurvey@ecics.com.sg>]

Sent: Wednesday, 24 January, 2018 3:36 PM

To: Florence Loh <fa_autoservices@falconair.com.sg>; Phoebe Jay Xie (ECICS, Claims)

<PhoebeJay_Xie@ecics.com.sg>

Cc: ECICS Claims <claims@ecics.com.sg>; motorsurvey <motorsurvey@ecics.com.sg>; Ashley Chong (LKK Auto)

<admin-d@lkkauto.com>

Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Florence,

Thank you for your email.

Dear LKK,

Please assist to do OD PRI survey.

Thank you.

Regards,
Carrie Tan

Claims Division

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Florence Loh [mailto:fa_autoservices@falconair.com.sg]
Sent: Wednesday, 24 January, 2018 2:26 PM
To: Phoebe Jay Xie (ECICS, Claims)
Cc: ECICS Claims; motorsurvey
Subject: Re: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Good afternoon Phoebe,

Insured is making an Own Damage claim.

Attach estimate and documents for your perusal.

Please arrange vehicle survey at our Sin Ming w/shop. Vehicle is in.

Thank you.
Florence Loh
Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive
#01-06/07 Sin Ming AutoCare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862

From: Phoebe Jay Xie (ECICS, Claims)
Sent: Wednesday, January 24, 2018 11:24 AM
To: Florence Loh
Cc: ECICS Claims ; motorsurvey
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Florence,

The loss of use is \$100 per day as per surveyor's recommendation.

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180

FAX: +65 6338 9267

Email: phoebejay_xie@ecics.com.sg

From: Florence Loh [mailto:fa_autoservices@falconair.com.sg]
Sent: Wednesday, 24 January, 2018 11:10 AM
To: Phoebe Jay Xie (ECICS, Claims)
Cc: Lionel Chua Kok Keong (ECICS, Claims)
Subject: Own Damage Claim_SKD1022D (doa: 24/01/2018)
Importance: High

Good morning Phoebe,

Insured is making an OD claim and we are assisting them with the reporting and claim.

The are also checking whether their policy cover the transport/loss of use.

Appreciate your help to check and let me know asap.

Thank you.

Florence Loh
Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive
#01-06/07 Sin Ming AutoCare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 26 January 2018 1:41 PM
To: 'motorsurvey'; 'Phoebe Jay Xie (ECICS, Claims)'
Cc: 'ECICS Claims'; assignments; SUR
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)
Attachments: CSICS18001495M1qb.pdf

Importance: Low

Dear Phoebe,

Enclosed herewith preliminary advice of SKD 1022D.
Repair cost economical.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 25 January 2018 10:05 AM
To: 'motorsurvey' <motorsurvey@ecics.com.sg>; 'Phoebe Jay Xie (ECICS, Claims)' <PhoebeJay_Xie@ecics.com.sg>
Cc: 'ECICS Claims' <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Carrie,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motorsurvey [<mailto:motorsurvey@ecics.com.sg>]
Sent: Wednesday, 24 January, 2018 3:36 PM
To: Florence Loh <fa_autoservices@falconair.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>
Cc: ECICS Claims <claims@ecics.com.sg>; motorsurvey <motorsurvey@ecics.com.sg>; Ashley Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: RE: Own Damage Claim_SKD1022D (doa: 24/01/2018)

Dear Florence,

Thank you for your email.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SKD 1022D

Date: 26th January 2018

Our Ref: CS/ICS18001495/M1qb

The Motor Claims Department
ECICS Limited

Attn: Carrie

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKD 1022D .


We thank you for the instruction on 24/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/01/2018 at the premises of M/s FALCON-AIR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,494.45</u> .
Revised Estimate Amount	: S\$ <u>7,346.90</u> .
"Check" Items Amount	: S\$ <u>4,016.95</u> .
Market Value	: S\$ <u>70,000.00</u> .
Salvage Value	: S\$ <u>56,028.00</u> .
Nett Value	: S\$ <u>13,972.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

We have not authorize repair.

Yours faithfully

MA C.F.
Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7104H
Vehicle Details	
Vehicle No.:	SKD1022D
Vehicle to be Exported:	No
Intended De-registration Date:	24 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	09077878N52B25AF
Chassis No.:	WBAFP32070C868268
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$48,316.00
Original Registration Date:	28 Oct 2011
First Registration Date:	28 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$48,316.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2021
PARF Rebate Amount:	\$31,405.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$67,000.00
COE Rebate Amount:	\$24,623.00
Total Rebate Amount:	\$56,028.00

The information contained herein is correct as at 24 Jan 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2018 11:53
Date Of Accident	24/01/2018 09:30
Exact Location Of Accident	ALONG CTE (BEFORE BRADDELL EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD1022D
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	CHEN YING LIANG, WILLIAM
NRIC No	S1217104H
Email Address	XINXIANG918@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91399999
Alternative Phone No	OTHERS-94388888

Vehicle Particulars

Manufacturer	BMW
Model	523I-2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17B00060001
Cover Note Number	

Driver

Name of Driver	YUAN JIAPING
NRIC No	S8582198I
Date Of Birth	27/12/1985
Occupation	INDOOR
Date Of Driving Pass	16/02/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94388888
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 1995011400
GST Reg. No.: 1995011400

ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE 038987
ATTN: MOTOR CLAIMS
Attention: Motor Claim Department
Contact: 63030167 Fax No.: 63386951

Estimate : ES011541

Date : 24/01/2018
Vehicle Num. : SKD 1022D
Make/Model : BMW 523i-2011
Chassis/Eng# : WBAFP32070C868268
Accident Date : 24/01/2018
Claim No. :
Reference : O/D
Policy No. : MPC17B00060001

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 PC	BONNET	1,400.00	1,400.00
2.	1 PC	RH BONNET LOCK	160.00	160.00
3.	1 PC	RH BONNET LOCK STRIKER	58.00	58.00
4.	1 PC	RH HEADLAMP	1,450.00	1,450.00
5.	1 PC	RH HEADLAMP PANEL	125.00	125.00
6.	1 PC	RH HEADLAMP MODULE	600.00	600.00
7.	1 PC	RH HEADLAMP LED MODULE	300.00	300.00
8.	1 PC	RH HEADLAMP WASHER COVER	28.00	28.00
9.	1 PC	RH HEADLAMP WASHER COVER LEVER	10.00	10.00
10.	1 PC	RH HEADLAMP WASHER COVER LEVER SPRING	5.00	5.00
11.	1 PC	RH HEADLAMP WASHER NOZZLE	173.00	173.00
12.	1 PC	RH HEADLAMP WASHER HOSE	38.00	38.00
13.	1 PC	FRONT BUMPER	1,240.00	1,240.00
14.	1 PC	FRONT BUMPER LOGO	67.00	67.00
15.	1 PC	RH FRONT BUMPER SIDE RETAINER	10.00	10.00
16.	1 PC	FRONT BUMPER SPONGE	45.00	45.00
17.	1 PC	FRONT BUMPER REINFORCEMENT	500.00	500.00
18.	2 PCS	RH FRONT BUMPER SENSOR	330.00	660.00
19.	2 PCS	FRONT V PANEL	30.00	60.00
20.	2 PCS	RADIATOR GRILLE	170.00	340.00
21.	1 PC	AIR CON CONDENSER	890.00	890.00
22.	1 PC	RADIATOR	600.00	600.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE 038987
ATTN: MOTOR CLAIMS
Attention: Motor Claim Department
Contact: 63030167 Fax No.: 63386951

Estimate : ES011541

Date : 24/01/2018
Vehicle Num. : SKD 1022D
Make/Model : BMW 523i-2011
Chassis/Eng#: WBAFP32070C868268
Accident Date : 24/01/2018
Claim No. :
Reference : O/D
Policy No. : MPC17B00060001

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	RADIATOR TOP BRACKET		7 55.00 X NN
24.	1 PC	RADIATOR BOTTOM BRACKET		X 186.00 NN
25.	1 PC	AIR GUIDE		285.00
26.	1 PC	RH AIR GUIDE		38.00 X NN
27.	1 PC	RH BRAKE AIR DUCT		50.00 X
(10) Total Parts Purchased S\$:				8,843.00
15.00% Of The Above Parts S\$:				1,326.45
Based On Cost Plus S\$:				10,169.45
1.	10 PCS	SPECIAL NETT ITEMS :		
2.	1 PC	FRONT BUMPER CLIPS	4.00	40.00 hz
		FRONT NUMBER PLATE		45.00
Special Nett Total S\$:				85.00
LABOUR :				
TO FOCUS HEADLAMP AND CHECK WIRING				60 80.00
TO REMOVE/REFIX AIR CON CONDENSER, PIPE				
VACUUM AND TOP UP AIR CON GAS				220 120.00 X
TO DIAGNOSE, RESETTING, CODE HEADLAMP MODULE				380.00
TO STRAIGHTEN RH FRONT CHASSIS, RH FRONT FENDER, FRONT				
SUPPORT PANEL AND REPLACEMENT OF PARTS				550 780.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE 038987
ATTN: MOTOR CLAIMS
Attention: Motor Claim Department
Contact: 63030167 Fax No.: 63386951

Estimate : ES011541

Date : 24/01/2018
Vehicle Num. : SKD 1022D
Make/Model : BMW 523i-2011
Chassis/Eng# : WBAFP32070C868268
Accident Date : 24/01/2018
Claim No. :
Reference : O/D
Policy No. : MPC17B00060001

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT SUPPORT
PANEL, RH FRONT FENDER

500 * ~~880.00~~

Labour Total S\$:

2,240.00

*Prevent
P/P Depn
Before paint job
H&K Auto (M) Ltd
25/1/2018
4wday S
EXCESS TBH*

30/1/18

12904.23

E. & O.E.

Total S\$: 12,494.45

=====

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528640) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE 038987
ATTN: MOTOR CLAIMS
Attention: Motor Claim Department
Contact: 63030167 Fax No.: 63386951

Supplementary Estimate : ES011577

Date: 23/03/2018
Vehicle Num.: SKD 1022D
Make/Model: BMW 523i-2011
Chassis/Eng#: WBAFP32070C868268
Accident Date: 24/01/2018
Claim No.:
Reference: O/D(SM)
Policy No.: MPC17B00060001

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	PARTS PURCHASED: RH BONNET ADJUSTER		8.50
		Total Parts Purchased S\$:		8.50
		15.00% Of The Above Parts S\$:		1.28
		Based On Cost Plus S\$:		9.78

E. & O.E.

Total S\$: 9.78

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop [Blk 1/Blk K] S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE 038987
ATTN: MOTOR CLAIMS
Attention: Motor Claim Department
Contact: 63030167 Fax No.: 63386951

FALCON-AIR AUTO SERVICES PTE LTD
Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Estimate: ES011541

Date: 24/01/2018
Vehicle Num.: SKD 1022D
Make/Model: BMW 523i-2011
Chassis/Eng#: WBAFP32070C868268
Accident Date: 24/01/2018
Claim No.:
Reference: O/D
Policy No.: MPC17B00060001

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED:				
1.	1 PC	BONNET	1,400.00	
2.	1 PC	RH BONNET LOCK	160.00	X
3.	1 PC	RH BONNET LOCK STRIKER	58.00	
4.	1 PC	RH HEADLAMP	1,450.00	
5.	1 PC	RH HEADLAMP PANEL	125.00	X
6.	1 PC	RH HEADLAMP MODULE	600.00	X
7.	1 PC	RH HEADLAMP LED MODULE	300.00	X
8.	1 PC	RH HEADLAMP WASHER COVER	28.00	
9.	1 PC	RH HEADLAMP WASHER COVER LEVER	10.00	
10.	1 PC	RH HEADLAMP WASHER COVER LEVER SPRING	5.00	
11.	1 PC	RH HEADLAMP WASHER NOZZLE	173.00	
12.	1 PC	RH HEADLAMP WASHER HOSE	38.00	
13.	1 PC	FRONT BUMPER	1,240.00	
14.	1 PC	FRONT BUMPER LOGO	67.00	
15.	1 PC	RH FRONT BUMPER SIDE RETAINER	10.00	
16.	1 PC	FRONT BUMPER SPONGE	45.00	
17.	1 PC	FRONT BUMPER REINFORCEMENT	500.00	
18.	2 PCS	RH FRONT BUMPER SENSOR	165.00	
19.	2 PCS	FRONT V PANEL	15.00	
20.	2 PCS	RADIATOR GRILLE	85.00	
21.	1 PC	AIR CON CONDENSER	330.00	X
22.	1 PC	RADIATOR	890.00	X

1 PC - RH Bonnet adjuster - 850

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

ECICS LIMITED

7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE 038987
ATTN: MOTOR CLAIMS

Attention: Motor Claim Department

Contact: 63030167 Fax No.: 63386951

Estimate: ES011541

Date: 24/01/2018
Vehicle Num.: SKD 1022D
Make/Model: BMW 523i-2011
Chassis/Eng#: WBAFP32070C868268
Accident Date: 24/01/2018
Claim No.:
Reference: O/D
Policy No.: MPC17B00060001

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	RADIATOR TOP BRACKET		755.00 X
24.	1 PC	RADIATOR BOTTOM BRACKET		X 186.00
25.	1 PC	AIR GUIDE		285.00
26.	1 PC	RH AIR GUIDE		38.00 X
27.	1 PC	RH BRAKE AIR DUCT		50.00 X
Total Parts Purchased S\$:			5806.00	8,843.00
15.00% Of The Above Parts S\$:			580.60	1,326.45
Based On Cost Plus S\$:			6386.60	10,169.45
1.	10 PCS	SPECIAL NETT ITEMS:	4.00	40.00
2.	1 PC	FRONT BUMPER CLIPS		45.00
		FRONT NUMBER PLATE		85.00
Special Nett Total S\$:				
LABOUR:				60.00
TO FOCUS HEADLAMP AND CHECK WIRING				
TO REMOVE/REFIX AIR CON CONDENSER, PIPE				120.00
VACUUM AND TOP UP AIR CON GAS				380.00
TO DIAGNOSE, RESETTING, CODE HEADLAMP MODULE				
TO STRAIGHTEN RH FRONT CHASSIS, RH FRONT FENDER, FRONT				780.00
SUPPORT PANEL AND REPLACEMENT OF PARTS				

CONTINUE / ...

5019-5180

Parts - 6386.60
 Supply - 9.35.00
 S/N - 85.00
 Labor - 1390.00
 Total - \$7870.95
 P/P

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
 Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE 038987
ATTN: MOTOR CLAIMS
Attention: Motor Claim Department
Contact: 63030167 Fax No.: 63386951

Estimate : ES011541

Date : 24/01/2018
Vehicle Num. : SKD 1022D
Make/Model : BMW 523i-2011
Chassis/Eng# : WBAFP32070C868268
Accident Date : 24/01/2018
Claim No. :
Reference : O/D
Policy No. : MPC17B00060001

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, RH FRONT FENDER	500 *	880.00
		Labour Total S\$:		2,240.00

Subvent
P/P Depu
Subvent paint
HB Meito
25/1/2018
4wday S
excess TBA

E. & O.E.

Total S\$: 12,494.45

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/8B K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 9781 / 6745 9939

Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792

Dept Direct: 6417 9785

Dept Direct: 6417 9785

Dept Direct: 6417 9786

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721
TEL: 64520880 FAX: 64547862
ATTN: JOSHUA

TAX INVOICE : AR201801-15550
DATE : 25/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD1022D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	41617207194	BONNET	CC CC4-D-010	1	1400.00	1,400.00
2.	51137203650	FRT GRILLE RH	CC CC2-M-06C	1	85.00	85.00
3.	61677178742	H/LAMP CLEANING HOSE (FRT)	CC CC2-F-03J	1	38.00	38.00

SUB-TOTAL : 1,523.00
ADD GST 7.00 % 106.61

E. & O. E.

TOTAL AMOUNT SGD : 1,629.61

[P] 25/01/2018 2:54:40PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 25/01/2018 2:35:41PM

JAE Auto Pte. Ltd.

Sales Executive: RANDY

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WATERBURY DEALE
Dept Direct: 6417 9701 / 6745 9920



Dept Direct: 6305 9910

Dept Direct: 6305 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9795

Dept Direct: 6417 9795

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silipor (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721
TEL : 64520880 FAX : 64547862
ATTN : JOSHUA

TAX INVOICE : AR201801-15561
DATE : 25/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD1022D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 63117271910	H/LAMP HID RH	U2	1	1450.00	1,450.00
		BM-A56			
2. 51117246870	FRT BUMPER WASHER COVER RH	U2	1	28.00	28.00
		L1-A10-F2			
3. 51117202885	COVERING FRT BUMPER, SPRING	U2	1	5.00	5.00
		BM-A32-C4			
4. 51117207932	SPACER RH	U2	1	10.00	10.00
		BM-A79-G			
5. 66209270495	PARKING SENSOR	U2	2	165.00	330.00
		BM-A32-C1			
6. 51117285961	FRT BUMPER	U2	1	1240.00	1,240.00
		SUPPLIER			
7. 51747200787	FRONT SUPPORT AIR DUCT	U2	1	285.00	285.00
		SUPPLIER			

SUB-TOTAL : 3,348.00
ADD GST 7.00 % 234.36

E. & O.E TOTAL AMOUNT SGD : 3,582.36

[E] 25/01/2018 2:38:54PM

[P] 25/01/2018 2:53:39PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : RANDY



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature/ Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 8365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721
TEL: 64520880 FAX: 64547862
ATTN: JOSHUA

TAX INVOICE : AR201801-15628
DATE : 25/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD1022D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 51117200707	FRT BUMPER FOAM	U2	1	45.00	45.00
		BM-B32-SD			
2 51647187096	FRT SUPPORT V BAR RH	U2	1	15.00	15.00
		BM-A88			

SUB-TOTAL : 60.00
ADD GST 7.00 % 4.20

E. & O.E TOTAL AMOUNT SGD : 64.20

[E] 25/01/2018 3:30:25PM

[P] 25/01/2018 4:10:44PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : RANDY



* AR201801-15628 *

This is computer generated document.
No signature is required.

ORIGINAL.

Goods Received in Good Order

Signature / Co Stamp / Date

日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721
TEL : 64520880 FAX : 64547862
ATTN : JOSHUA

WIPER BLADES
Dept Direct: 6417 9791 / 9745 9939



Dept Direct: 6305 0610

Dept Direct: 6417 9791

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silipar (Made in Korea),
Ferch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201801-15670
DATE : 25/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD1022D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51647200794	H/LAMP LWR BRACKET RH	U2 SUPPLIER	1	125.00	125.00
2. 51117200792	BUMPER WASHER LEVER RH	U2 SUPPLIER	1	10.00	10.00
3. 61677377668	H/LAMP NOZZLE RH	U2 SUPPLIER	1	173.00	173.00
4. 51117200795	FRT BUMPER BEAM	U2 SUPPLIER	1	500.00	500.00
5. 51147057794	BMW LOGO	U2 SUPPLIER	1	67.00	67.00

SUB-TOTAL : 875.00
ADD GST 7.00 % 61.25

E. & O.E

TOTAL AMOUNT SGD : 936.25

[E] 25/01/2018 4:02:15PM

[P] 25/01/2018 4:10:54PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : RANDY



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WONGSANGHAT KEANG
Dept Direct: 6417 9791 / 6745 9809



Dept Direct: 6365 9610

Dept Direct: 6365 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721
TEL : 64520880 FAX : 64547862
ATTN : JOSHUA

TAX INVOICE : AR201801-16103
DATE : 26/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD1022D
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51767185752	BONNET ADJUSTER	U2	1	8.50	8.50
	SUPPLIER				

SUB-TOTAL : 8.50
ADD GST 7.00 % 0.60

E. & O.E TOTAL AMOUNT SGD : 9.10

[E] 26/01/2018 11:41:55AM

[P] 26/01/2018 11:42:17AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : RANDY



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18001495/M1qbe2

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 29-06-2018



Code : ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKD 1022D
Policy No.	MPC17B00060001	Coverage (\$)	0.00
Claim No.	DMPC1800027H	Excess (\$)	500.00
Assign From	CARRIE TAN	Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFP32070C868268	Colour	BLACK
Odometer	182183	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	CONTINENTAL	8 mm
L/H Front Tyre	245/45 R18	CONTINENTAL	8 mm
R/H Rear Tyre	245/45 R18	GOODYEAR	8 mm
L/H Rear Tyre	245/45 R18	GOODYEAR	8 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	24/01/2018	Inspection Date	25/01/2018
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		

5a. RemarksA) THE MARKET VALUE IS S\$70,000.00 (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 1022D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BENT	1,400.00	1,400.00
1	RH BONNET LOCK	NOT NECESSARY	160.00	-
1	RH BONNET LOCK STRIKER	SERVICEABLE	58.00	-
1	RH HEADLAMP	CRACKED	1,450.00	1,450.00
1	RH HEADLAMP PANEL	BENT	125.00	125.00
1	RH HEADLAMP MODULE	NOT NECESSARY	600.00	-
1	RH HEADLAMP LED MODULE	NOT NECESSARY	300.00	-
1	RH HEADLAMP WASHER COVER	MISSING	28.00	28.00
1	RH HEADLAMP WASHER COVER LEVER	CUT	10.00	10.00
1	RH HEADLAMP WASHER COVER LEVER SPRING	DISTORTED	5.00	5.00
1	RH HEADLAMP WASHER NOZZLE	DISTORTED	173.00	173.00
1	RH HEADLAMP WASHER HOSE	NECESSARY	38.00	38.00
1	FRONT BUMPER	DEFORMED	1,240.00	1,240.00
1	FRONT BUMPER LOGO	NECESSARY	67.00	67.00
1	RH FRONT BUMPER SIDE RETAINER	NECESSARY	10.00	10.00
1	FRONT BUMPER SPONGE	CRACKED	45.00	45.00
1	FRONT BUMPER REINFORCEMENT	DENTED	500.00	500.00
2	RH FRONT BUMPER SENSOR @\$165.00	SHORTED	330.00	330.00
2	FRONT V PANEL @\$15.00	O/S BENT / N/S NOT NECESSARY	30.00	15.00
2	RADIATOR GRILLE @\$85.00	O/S CRACKED / N/S NOT NECESSARY	170.00	85.00
1	AIR CON CONDENSER	NOT NECESSARY	890.00	-
1	RADIATOR	NOT NECESSARY	600.00	-
1	RADIATOR TOP BRACKET	NOT NECESSARY	55.00	-
1	RADIATOR BOTTOM BRACKET	NOT NECESSARY	186.00	-
1	AIR GUIDE	DISTORTED	285.00	285.00
1	RH AIR GUIDE	NOT NECESSARY	38.00	-
1	RH BRAKE AIR DUCT	NOT NECESSARY	50.00	-
1	RH BONNET ADJUSTER (ADDITIONAL)	CUT	8.50	8.50
	COST PLUS 10%		-	581.45

Report Ref No. CS/ICS18001495/M1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COST PLUS 15%		1,327.73	-
			10,179.23	6,395.95
	SPECIAL NETT ITEMS			
10	FRONT BUMPER CLIPS @\$4.00 (SN)	NECESSARY	40.00	40.00
1	FRONT NUMBER PLATE (SN)	BENT	45.00	45.00
			85.00	85.00
	LABOUR			
	TO FOCUS HEADLAMP AND CHECK WIRING.		80.00	60.00
	TO REMOVE / REFIX AIR CON CONDENSER, PIPE VACUUM AND TOP UP AIR CON GAS.	NOT NECESSARY	120.00	-
	TO DIAGNOSE, RESETTING, CODE HEADLAMP MODULE.		380.00	280.00
	TO STRAIGHTEN RH FRONT CHASSIS, RH FRONT FENDER, FRONT SUPPORT PANEL AND REPLACEMENT OF PARTS.		780.00	550.00
	TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, RH FRONT FENDER.		880.00	500.00
			2,240.00	1,390.00
	GRAND TOTAL		12,504.23	7,870.95
RECOMMENDED COST OF REPAIRS				7,870.95

Report Ref No. CS/ICS18001495/M1qbe2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.