

called to send vehicle
in on 24/01/2018 @ 1635

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax : <i>LICK MARUS</i> <i>1045 25.01</i>
---	---

Quotation No : QO18/01-1208	Quotation Date : 23/01/2018	Terms : 30 DAYS
Vehicle No : SLP7840U	Chassis No : MHFB29F3302011706	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SK893R, DATE OF ACCIDENT: 23.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER CENTRE GRILLE	1 <i>20/1m</i>	276.2000	276.20
2	LESS 25% ITEM 1	1	-69.0500	-69.05
3	FRONT LICENSE PLATE	1 <i>300</i>	50.0000	50.00
4	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. REPAIR FRONT BUMPER	1 <i>120</i>	300.0000	300.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1 <i>200</i>	350.0000	350.00

*NOT Authorised
Lick*

cost price ?

*Take photo After repair
25/1/18
24/1/18*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: **Sub Total** 907.15

GST(7.00%) 63.50

Total (SGD) 970.65

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216