

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED
7 TEMASEK BOULEVARD
#10-03 SUNTEC TOWER ONE
SINGAPORE 038987

TEL: 63374779 FAX: 63389267

ATTN: Motor Claim Department

Your Ref No: TP 0118-4928

Claim Type: Third Party

Accident Date: 22/01/2018

TP Veh Reg No: SJJ 6678 J

Claim No: EST1503217

Estimate No: EST1503217

Date: 28 Feb 2018

Policy No: 2100325923

Veh Reg No: SBV6699E

Make/Model: LEXUS RX270 AUTO

Chassis No: JTJZA11A902436865

Engine No: 1AR0775169

Reg. Date: 28/12/2012

Estimate Repair Cost to Vehicle No : SBV6699E

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
Spare Parts				
1 DOOR RIVET CLIP <i>Rec</i>	2.80	12 PCS	33.60	
			33.60	
	Add 10%		3.36	36.96

Total S\$ 36.96
GST Amount S\$ 2.59

Total Amount payable S\$ 39.55

Adrian Ling
28/02/18
sls

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

SUPP 36.96

PAPTS 1232.00

LAB. 970.00

2238.96

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED
7 TEMASEK BOULEVARD
#10-03 SUNTEC TOWER ONE
SINGAPORE 038987

TEL: 63374779 FAX: 63389267

ATTN: Motor Claim Department

Your Ref No: TP 0118-4928

Claim Type: Third Party

Accident Date: 22/01/2018

TP Veh Reg No: SJJ 6678 J

Claim No: EST1503217

Estimate No: EST1503217

Date: 22 Jan 2018

Policy No: 2100325923

Veh Reg No: SBV6699E

Make/Model: LEXUS RX270 AUTO

Chassis No: JTJZA11A902436865

Engine No: 1AR0775169

Reg. Date: 28/12/2012

Estimate Repair Cost to Vehicle No : SBV6699E

Description	U/Price	Quantity	Cost S\$	Amount S\$
Special Net				
1 REAR TYRE RH	220.00	1 PC	220.00	
				220.00

Spare Parts

2 REAR BUMPER	330.00	1 PC	330.00	
3 REAR BUMPER CLIPS	1.50	10 PC	15.00	
4 REAR BUMPER SIDE HOLDER RH	65.00	1 PC	65.00	
5 REAR BUMPER SIDE HOLDER LH	65.00	1 PC	65.00	
6 REAR TYRE RIM RH NO PRICE	0.00	1 PC	0.0000	
7 REAR TYRE RIM HUPCAP SMALL RH NO PRICE	0.00	1 PC	0.0000	
8 REAR DOOR RH	420.00	1 PC	420.00	
9 REAR DOOR RUBBER RH	120.00	1 PC	120.00	
10 REAR DOOR OUTER CHANNEL CHROME RH UPPER	85.00	1 PC	85.00	
11 REAR DOOR OUTER CHANNEL CHROME RH REAR	60.00	1 PC	60.00	
12 REAR DOOR OUTER CHROME LOWER RH	90.00	1 PC	90.00	
13 REAR DOOR STICKER RH NO PRICE	0.00	1 SET	0.0000	
14 REAR DOOR OUTER LOWER PROTECTOR BLACK RH	110.00	1 PC	110.00	
15 FRONT DOOR RH	440.00	1 PC	440.00	
16 FRONT DOOR RUBBER RH NO PRICE	0.00	1 PC	0.0000	
17 FRONT DOOR OUTER CHANNEL CHROME RH	90.00	1 PC	90.00	
18 FRONT DOOR OUTER CHROME LOWER RH	85.00	1 PC	85.00	
19 FRONT DOOR STICKER RH NO PRICE	0.00	1 SET	0.0000	
20 FRONT DOOR OUTER LOWER PROTECTOR BLACK RH	150.00	1 PC	150.00	
			2,125.00	
	Add 10%		212.50	2,337.50

Labour

21 TO KNOCK OUT DENTS. REMOVE. REPLACE ACCIDENT PARTS	500.00	1 JOB	500.00	
22 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.00	1 JOB	600.00	
23 TO CHECK WIRING	20.00	1 JOB	20.00	
24 TO TUFF-KOTE	60.00	1 JOB	60.00	

1,180.00