


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4646A
 Ref. No : TAX/01/18/2144
 Reg. Date : 24/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : ANG LIAN HONG(HONG LIANFENG)
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 23/01/2018 06:50:00 PM
 Accident Reported Date / Time : 24/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094264
 Special Instruction to ARC,if any :
 SJP2018J - AIG - LKK
 Prepared Date : 24/01/2018 11:47:40 AM



LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjil 97495749
 - WP'
 24/1/18 @ 230pm
 0/day
 Resurvey after repair
 Lumpur
 sw@lkkauto.com

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U705751251

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 0.00	0.00
Total Spray Painting Charges	: 180.00	0.00
Total Material Charges	: 128.88	128.88
Other Charges	: 120.00	0.00
TOTAL	: 428.88	0.00
Lum Sum Total	: 450.00	0.00
No. of Repair Days	: 2.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 24/01/2018 02:35:01 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 24/01/2018 02:35:01 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	180.00	0.00
Total Spray Painting & Panel Beating	180.00	0.00 <i>100</i>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	120.00	0.00
Total Other Costs	120.00	0.00 <i>100</i>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace	No <i>MIS</i> ✓
TOTAL MATERIALS								80.55	80.55	
TOTAL MATERIALS(Discounted)								128.88	128.88	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									