

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

 Accident Date : 05.01.2018

Policy No: Third Party

 Date: 23.01.2018

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mazda 3" Reg. No. SKW8449K Claiming Against Your Insured Reg. No. SBZ1111X		
1pc	Front Door LH	DA	1,256.00
1pc	Front Door Sticker	WZ	192.00
1pc	Front Door Weatherstrip	save	117.00
			1,565.00
	Less 20%		313.00
			1,252.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel	20	50.00
	Labour Charge - Panel Beating, Repairing Of Rocker Panel, Rear N/S Rear Door, Transfer Door Fitting and Parts Replacement	400	450.00
	To Respray Affected Areas	500	700.00
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas	X	350.00
		Total :	2,802.00

Not Authorized
 PIP Repair
 Before paint photo
 LKK Auto
 H/W days
 25/1/2018
 LKK Auto (M)

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: