

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG18001509/WQBS2**Date:** 08/02/2018REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/17-001781

Claimant Vehicle No : FQ1532P **Insured Vehicle No :** SKV1145M

Date of Loss: 08/12/2017 Nature of Claim: TP Claim No: MSC/V/18/000004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FQ1532P**

Make & Model: HONDA CB 400 F3WYB, 399cc (M) Engine No: NC23E1855217

Reg. Date: 08/05/1998 (Man. Year: 1998) Chassis No: NC311555208

Colour: Black Odometer: 29430 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60ZR17 Rear Tyre Size: 160/60ZR17

Front Left Side: DIABLO 2 mm Rear Left Side: Battlax 2 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,655.70	6,125.70	1,530.00	19.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	505.00	725.00	58.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,885.70	6,630.70	2,255.00	25.38
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	8,885.70	5,300.00	3,585.70	40.35

INSPECTION

Date of Assignment: 24/01/2018

Date Inspected: 25/01/2018 Inspected At: M/s First Motor (HQ)
Blk 3006 Ubi Road 1, #01-398
Singapore 408700

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/8/2018

Adjuster Report

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIRS.

MARKET VALUE : \$1,500.00(est)

LTA REIMBURSEMENT VALUE (RV) : \$135.00

NETT VALUE : \$1,365.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Feb 2018)	
Parts:	N/A	HONDA CB 400 F3WYB 399cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FQ1532P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	110.00 FL	*110.00 FL
2	2		*MIRROR (LH)&(RH)	Broken / Bent	130.00 FL	*130.00 FL
3	1		*CLUTCH LEVER	Scratched / Bent	18.00 FL	*18.00 FL
4	1		*BRAKE LEVER	Scratched / Bent	36.00 FL	*36.00 FL
5	1		*HANDLE GRIP	Necessary	28.00 FL	*28.00 FL
6	1		*BALANCE	Scratched	20.00 FL	*20.00 FL
7	1		*METER ASSY	Broken	850.00 FL	*850.00 FL
8	1		*HEADLAMP ASSY	Dented	275.00 FL	*275.00 FL
9	2		*FORK ASSY (LH)&(RH)	Bent	1,760.00 FL	*1,550.00 FL
10	1		*FRONT FENDER	Scratched	230.00 FL	*230.00 FL
11	1		*FRONT WHEEL	Warped	780.00 FL	*780.00 FL
12	2		*FRONT DISC (LH)&(RH)	Distorted	790.00 FL	*790.00 FL
13	1		*RADIATOR UNIT ASSY	Scratched	680.00 FL	*550.00 FL
14	1		*ENGINE GUARD	Dented	200.00 FL	*200.00 FL
15	1		*MUFFLE	Scratched	680.00 FL	*680.00 FL
16	1		*EXHAUST PIPE	Repair	780.00 FL	*- FL
17	2		*FRONT SIGNALLAMP (RH)&(LH)	Broken	116.00 FL	*116.00 FL
18	1		*REAR BOX GIVI	Scratched	180.00 FL	*180.00 FL
19	1		*BOX BRACKET	Bent	90.00 FL	*90.00 FL
20	1		*REAR SUSPENSION	Not Necessary	580.00 FL	*- FL
21	1		*ERP IU UNIT	Broken	156.00 FS	*156.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,489.00	6,789.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	833.30	663.30
Total Parts (\$\$)	7,655.70	6,125.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHASSIS REPAIR.	New	480.00	120.00
2	FUEL TANK PAINTING FEE.	New	350.00	0.00
3	TRANSPORT FEE.	New	50.00	35.00
4	LABOUR CHARGE.	New	350.00	350.00
Gross Labour Cost (\$\$)			1,230.00	505.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >