

ASS. REC. BY:

REF:

CS/MSC718001510 / Aqk

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSLH

Date/Time: 24-01-2018 4:30pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 4993B

Insured:

SGB 5106C

at Workshop t/s

MG Solution

Tel:

9188 6931

of

Kaki Bukit

Policy No:

A28656195 Amx

Claim No:

547174

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22.01.2018

CA / REV / REP. / REV 24 HRS 'wp'

25-01-2018

R.O.P. Endorsement:

Date/Time:

24/01/2018 4:34pm

Person Contacted:

Ms Hong

Vehicle ~~IN~~ / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLD 4993B x
	SGB 5106C CS/MSC716007648 / Ggbx2 DA: 220416
26/1/18 @ 11.20am	Informed Catherine Thia, we are pending estimate from repairer.
26/4/18 @ 11.44am	Revised to Catherine Thia via Meimian.
	LS A 4200, 6 days (Red & 9963.36, 70%)

26/4

TP # MS16

MV : 151C

$2V, 10.2E$

Next: A.81c

RECEIVED 27 APR 2018

Lump Sum / L.B. 43

The L/C / Chassis frame / Body Structure affected due to collision



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001510/Aqb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 25-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGB 5106C	Veh. Inspected	SLQ 4993B
Policy No.	A28656195QMX	Coverage (\$)	0.00
Claim No.	547174	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/01/2018	Inspection Date	25/01/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018		24 Jan 2018 17:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CAO LIYING, ID: S8284836C		
Main Claimant:	168 MOTOR, Co. Reg. No.: 53343850X		
Vehicle Reg. No.:	SLQ4993B	Date of Loss:	22/01/2018 08:00 - :59
Claim Type:	TP / 547174	Policy/Cover Note No.:	A28656195QMX (Comprehensive) Coverage: 21/12/2017 - 20/12/2018
Vehicle Reg. No. (Insured):	SGB5106C	Policy No. (Claimant):	
		Excess:	
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/01/2018]		
Driver/Custodian (Insured):	LI CHENG GONG (), NRIC: S8284835E, Tel: +6582982849		
Adj Asp. Remarks:	Third Party Pre-Repair Survey, Please request Adrian Ling to survey.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 26 Apr 2018

Preliminary Advice

Insured Vehicle No	: SGB5106C	Accident Date	: 22/01/2018
TP Vehicle No	: SLQ4993B	Assignment Date	: 25/01/2018
Make	: HONDA STREAM	Est. Duration of Repair	: 6
Date of Inspection	: 25/01/2018		
Inspection At	: MG Solution Pte Ltd		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,168.36
Revised Amount	:S\$	5,291.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,291.28
Lump Sum Repair	:S\$	4,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 26 January 2018 11:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLQ 4993B (YOUR REF: 547174)

This mail is associated with :

***SLQ4993B (547174)**

[SGB5106C]

TP

168 MOTOR

Jan 22 2018 8:00AM

[CAO LIYING]

MG Solution Pte Ltd

Dear Catherine,

Please be informed that we have inspected the vehicle SLQ 4993B on 25/01/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3850X
Vehicle Details	
Vehicle No.:	SLQ4993B
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Brown
Manufacturing Year:	2008
Engine No.:	R18A1770336
Chassis No.:	RN61063134
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,941.00
Original Registration Date:	06 Jun 2008
First Registration Date:	06 Jun 2008
Transfer Count:	2
Actual ARF Paid:	\$18,941.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jun 2018
PARF Rebate Amount:	\$9,470.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jun 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,501.00
COE Rebate Amount:	\$708.00
Total Rebate Amount:	\$10,178.00

The information contained herein is correct as at 25 Jan 2018



Honda Stream 1.8A (New 5-yr COE) **\$42,800** **\$8,560 /yr** **30-May-2008** **1,799 cc** **-** **MPV** **Available**

Newly 5 Yrs COE 1 Owner Just Arrived! Beautiful And Sporty Blue Reliable And Low Maintenance Cost. Own By Careful Owner. Most Popular Honda MPV For Your Family Usage! 100% Accident Free And No Modific...

Posted: 11-Dec-2017 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Honda Stream 1.8A X (OPC) (New 5-yr COE) **\$42,800** **\$8,560 /yr** **02-Jun-2008** **1,799 cc** **\$1,524 km** **MPV** **Available**

1 Owner. Low Mileage Done. Beautiful And Sporty White In Black Honda Stream 1.8A. Reliable And Low Maintenance Cost. Own By Careful Owner. Most Popular Honda MPV For Your Family Usage! 100% Accident F...

Posted: 19-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

PREMIUM LISTING



Honda Stream 1.8A **\$17,800** **N.A** **09-Jun-2008** **1,799 cc** **112,025 km** **MPV** **Available**

Low Interest At 1.99%. Very Low Mileage! Extended Warranty Available! Well Kept By Previous Owner In Spectacular Good Condition, Test It And It Will Show You! Buy It From Us With A Peace Of Mind, A Co...

Dickson Automobile

Posted: 23-Nov-2017 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Honda Stream 1.8A **\$14,998** **N.A** **11-Jun-2008** **1,799 cc** **-** **MPV** **Available**

Guaranteed Minimum Parf At \$10.2k Exclude Body Vaulc. Guaranteed Future COE Renewal Unit! Tip Top Conditions! All Our Quality Pre-Owned Cars Are Selling At The Most Reasonable Price And With A Peace O...

Posted: 11-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Honda Stream 1.8A Sunroof **\$18,888** **N.A** **18-Jun-2008** **1,799 cc** **197,000 km** **MPV** **Available**

Meticulous Owner Who Maintains His Car Very Well, All Wear And Tear Including Tyres Fully Replaced, Elegant Black With Lush Beautiful Black Interior, Upto 80% Financing Possible And We Do Welcome Trad...

Posted: 13-Dec-2017 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

PREMIUM LISTING



Honda Stream 1.8A X **\$15,800** **N.A** **24-Jun-2008** **1,799 cc** **108,000 km** **MPV** **Available**

Fast Deal. Fixed Price. Low Mileage Done. Good For COE Renewal. Minimum PARF At \$8,896.

Posted: 23-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

DIRECT OWNER



Honda Stream 1.8A **\$13,288** **N.A** **25-Jun-2008** **1,799 cc** **161,000 km** **MPV** **Available**

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only!

Boeki Auto & Marine

Posted: 22-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Honda Stream 1.8A RSZ **\$18,800** **N.A** **03-Jul-2008** **1,799 cc** **118,000 km** **MPV** **Available**

Negotiable! Lowest Mileage. Mints Condition. New 05 Years COE Offer \$44.8k. No Gimmick! Message / Whatsapp For Viewing Appointment.

Posted: 14-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

PREMIUM LISTING



Honda Stream 1.8A **-** **N.A** **15-Jul-2008** **1,799 cc** **-** **MPV** **Available**

Excellent Condition. Good For Short Term Drive. Buy With Confident.

Posted: 18-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

DIRECT OWNER



Honda Stream 1.8A **\$14,500** **N.A** **24-Jul-2008** **1,799 cc** **159,000 km** **MPV** **Available**

Monthly Depreciation Of \$980! Cheaper Than Renting A MPV! Guarantee Value Of \$9000 When Sell Back To Exporter! Drive For Another 6 Months And Suitable For Renewing For COE! Please Call Or SMS Me!

Posted: 07-Jan-2019 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

DIRECT OWNER



Honda Stream 1.8A X CNG **\$13,800** **\$13,370 /yr** **26-Jul-2008** **1,799 cc** **-** **MPV** **Available**

Good Condition. Very Good For Short Term Use. Can Renew COE.

Posted: 19-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

DIRECT OWNER



Honda Stream 1.8A X **\$14,800** **\$10,580 /yr** **28-Jul-2008** **1,799 cc** **127,000 km** **MPV** **Available**

\$0 Down Payment Available! sgCarMart Premium Dealer 2015 To 2017 Buy With Zero Worries! 100% No Hidden Costs! 100% Original Condition! Low Mileage! 100% Accident Free! In House Loan Or Bank Loan Avail...

88 Motor Trading

Posted: 23-Jan-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2018 15:45
Date Of Accident	22/01/2018 08:30
Exact Location Of Accident	SLIP ROAD FR TAMPINES AVE 12 TOWARDS TPE (CTE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ4993B
Insured/Policyholder	
Name Of Registered Owner	168 MOTOR
Co Reg No	53343850X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092557540
Cover Note Number	

Driver

Name of Driver	HAIRUL ASWAN BIN OSMAN
NRIC No	S7502736B
Date Of Birth	28/01/1975
Occupation	OUTDOOR
Date Of Driving Pass	26/08/1997
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84486628
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 17 TAMPINES CENTRAL 7 #10-13
Postcode	528772
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 22/01/2018 AT ABOUT 0830HRS AT SLIP ROAD FROM TAMPINES AVE 12 TOWARDS TPE (CTE). I WAS TRAVELLING ON THE ABOVE MENTIONED SLIP ROAD AND WHEN MY FRONT VEHICLE SLOW DOWN AND STOP DUE TO HEAVY TRAFFIC HENCE I FOLLOW SUIT. SUDDENLY I HEARD A LOUD BANG FROM BEHIND AND WHEN I ALIGHTED, I REALISED THAT IT WAS VEHICLE (B) WHO HIT ONTO MY REAR PORTION OF MY VEHICLE (A) CAUSING DAMAGES TO MY VEHICLE. IT WAS A CHAIN COLLISION OF TOTAL 4 VEHICLES INVOLVED. (A) SLQ4993B (B) SGB5106C (C) SGN2438Y (D) GBF3975L

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGB5106C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGN2438Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3


Vehicle Registration Number GBF3975L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

[illegible]

1. 姓名: 王小明
2. 性别: 男
3. 年龄: 25
4. 职业: 程序员
5. 籍贯: 浙江杭州
6. 学历: 本科
7. 毕业院校: 浙江大学
8. 联系电话: 13812345678
9. 电子邮箱: wangxm123@163.com
10. 身份证号: 330101199801010001

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/01/2018 at about 0830 hrs at Slip Road from Tampines Ave 12 towards TPE (CTE). I was travelling on the above mentioned slip road and when my front vehicle slow down and stop due to heavy traffic hence I follow suit. Suddenly I heard a loud bang from behind and when I alighted, I realised that it was vehicle (B) who hit onto my Rear Portion of my vehicle (A) causing damages to my vehicle. It was a chain collision of total 4

vehicles involved

(A) SLG 4993JB

(B) SGB 5106C

(C) SLN 2438Y

(D) GRF 347SL

DECLARATION

I declare that the foregoing is true and correct.

Police Officer's Signature
Date & Time:

Driver's Signature
If driver is not the police officer
Date & Time:

Reporting Officer's Signature
Date & Time:

L. Susan Tan

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: MSIG INSURANCE	DATE	: 23/01/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLQ4993B	Xiao Chan	
MODEL	: HONDA STREAM 1.8L A	2N61063134	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 22/01/2018
		TIME	: 08:30HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Bent</i>	1	\$ 988.70	\$ 988.70
2	TAILGATE LOGO <i>Not a</i>	1	\$ 65.00	\$ 65.00
3	TAILGATE EMBLEM 'STREAM' <i>new</i>	1	\$ 51.90	\$ 51.90
4	TAILGATE LOCK <i>Bent</i>	1	\$ 145.60	\$ 145.60
5	TAILGATE CATCH <i>new</i>	1	\$ 89.00	\$ 89.00
6	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 312.90	\$ 312.90
7	TAILGATE INNER HANDLE <i>new</i>	1	\$ 65.00	\$ 65.00
8	TAILGATE INNER TRIM BOARD <i>Bent</i>	1	\$ 335.60	\$ 335.60
9	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 133.00	\$ 133.00
10	REAR BUMPER BRACKET <i>Bent</i>	2	\$ 56.00	\$ 112.00
11	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 65.00	\$ 65.00
12	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 68.00	\$ 136.00
13	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 438.00	\$ 438.00
14	REAR FENDER INNER TRIM RH <i>new</i>	1	\$ 420.00	\$ 420.00
15	TAILLAMP <i>Bent</i>	2	\$ 477.80	\$ 955.60
16	TAILLAMP BOLT COVER <i>new</i>	2	\$ 55.00	\$ 110.00
17	REAR END PANEL <i>Bent</i>	1	\$ 553.50	\$ 553.50
18	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 186.50	\$ 186.50

19	REAR FLOOR PANEL <i>Revis</i>	1	\$ 1,468.50	\$ 1,468.50	+
20	REAR FLOOR PANEL COVER BOARD <i>new</i>	2	\$ 233.00	\$ 466.00	+
21	REAR TOOLS SPONGE <i>new</i>	1	\$ 196.40	\$ 196.40	+
22	REAR EXHAUST PIPE <i>new</i>	1	\$ 933.50	\$ 933.50	+
23	REAR EXHAUST MOUNTING <i>new</i>	2	\$ 52.00	\$ 104.00	+

2799.10

TOTAL PRICE \$ 8,351.70

LESS 20% \$ 1,670.34

2239.28

SUB TOTAL PRICE \$ 6,681.36

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	TAILGATE SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	TAILGATE INNER TRIM BOARD CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
4	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	30
5	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	30
6	REAR BUMPER LOWER LID WITH DIFFUSER <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	900
7	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 22.00	\$ 22.00	+
8	TAILLAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
9	REAR FENDER INNER TRIM CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
10	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	+
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
12	REAR FLOOR PANEL INSULATOR SEAL <i>new</i>	1	\$ 250.00	\$ 250.00	+
13	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	200

1282

TOTAL \$ 2,197.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,800.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$1,800.00	600	
3	TUFF COAT	\$250.00	40	
4	WIRING AND BULB CHECK	\$180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	\$250.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$180.00	40	
7	TRANSFER TAILGATE MECHANISM	\$180.00	80	

8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$180.00	120	
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$350.00	X	
10	CONDUCT WATER LEAKAGE TEST	\$120.00	X	

TOTAL

\$5,290.00

1770

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,878.36

TOTAL LABOUR COST : \$ 5,290.00

TOTAL REPAIR COST : \$ 14,168.36

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

total: 529128

H/S: A2K

06Days

Link Auto Consultants hence notify the Repairer of the following:

- Conducting vehicle paint spray painting
- Replacing damaged parts using resurvey
- Parts prices are based on quotation
- Third party supply is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental material must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018		25 Jan 2018 10:43 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	CAO LIYING , ID: S8284836C								
Main Claimant:	168 MOTOR , Co. Reg. No.: 53343850X								
Vehicle Reg. No.:	SLQ4993B	Date of Loss:	22/01/2018 08:00 - :59 [115 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 547174	Policy/Cover Note No.:	A28656195QMX (Comprehensive) Coverage: 21/12/2017 - 20/12/2018						
Vehicle Reg. No. (Insured):	SG85106C	Policy No. (Claimant):							
		Excess:							
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/02/2018]								
Driver/Custodian (Insured):	LI CHENG GONG (), NRIC: S8284835E, Tel: +6582982849								
Adj Asg. Remarks:	Third Party Pre-Repair Survey. Please request Adrian Ling to survey.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (25/01/2018): Cancellation of Assignment: SLQ4993B									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ4993B (547174)
[SGB5106C]
TP
168 MOTOR
Jan 22 2018 8:00AM
[CAO LIYING]
MG Solution Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print	
1	24/01/18 17:40	Accident Statement From: SC - Reg. No: SGB5106C, Claimant: CAO LIYING									Load HTML	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	26/04/18 11:44	Adjuster Immediate Advice									Load HTML	
									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	25/04/18 17:18	General View									Load JPG ☒	
2	25/04/18 17:18	General View									Load JPG ☒	
3	25/04/18 17:18	General View									Load JPG ☒	
4	25/04/18 17:18	General View									Load JPG ☒	
5	25/04/18 17:18	General View									Load JPG ☒	
6	25/04/18 17:18	General View									Load JPG ☒	
7	25/04/18 17:18	General View									Load JPG ☒	
8	25/04/18 17:18	General View									Load JPG ☒	
9	25/04/18 17:18	General View									Load JPG ☒	
10	25/04/18 17:18	General View									Load JPG ☒	
11	25/04/18 17:18	General View									Load JPG ☒	
12	25/04/18 17:18	General View									Load JPG ☒	
13	25/04/18 17:18	General View									Load JPG ☒	
14	25/04/18 17:18	General View									Load JPG ☒	
15	25/04/18 17:18	General View									Load JPG ☒	
16	25/04/18 17:18	General View									Load JPG ☒	
17	25/04/18 17:18	General View									Load JPG ☒	
18	25/04/18 17:18	General View									Load JPG ☒	
19	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
20	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
21	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
22	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
23	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
24	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
25	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
26	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
27	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
28	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
29	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
30	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
31	25/04/18 17:18	Reinspection Photo									Load JPG ☒	
32	25/04/18 17:18	Reinspection Photo									Load JPG ☒	

Assessment Reports			1 per page	☒
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
			1	☒
33	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
34	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
35	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
36	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
37	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
38	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
39	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
40	25/04/18 17:18	Reinspection Photo	1	Load JPG ☒
Documentation			1 per page	☒
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	24/01/18 16:59	TP PRI	1	Load PDF
2	24/01/18 17:40	E-FILE REPORT (SLQ49938) From: SC - Reg. No: SGBS106C, Claimant: CAO LIYING	1	Load PDF
3	24/01/18 17:40	E-FILE REPORT (SGN2430Y) From: SC - Reg. No: SGBS106C, Claimant: CAO LIYING	1	Load PDF
4	24/01/18 17:40	E-FILE REPORT (GBF3975L) From: SC - Reg. No: SGBS106C, Claimant: CAO LIYING	1	Load PDF
5	24/01/18 17:42	TP NOMINATED LKK TO BE SJE	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001510/AQBQ2

Date: 27/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28656195QMX
 Claimant Vehicle No: SLQ4993B Insured Vehicle No: SGB5106C
 Date of Loss: 22/01/2018 Nature of Claim: TP Claim No: 547174

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ4993B**
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1770336
 Reg. Date: 06/06/2008 (Man. Year: 2008) Chassis No: RN61063134
 Colour: Black Odometer: 145711 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,878.36	3,521.28	5,357.08	60.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	1,770.00	3,520.00	66.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,168.36	5,291.28	8,877.08	62.65
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	14,168.36	4,200.00	9,968.36	70.36
+ GST 7.00/7.00% (S\$)	991.79	294.00	697.79	70.36
Nett Amount (S\$)	15,160.15	4,494.00	10,666.15	70.36

INSPECTION

Date of Assignment: 25/01/2018
 Date Inspected: 25/01/2018 Inspected At: MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM
 Inspection Centre
 Singapore 415933
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2018)	
Parts: M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLQ4993B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	988.70 FL	*903.00 FL
2	1		*TAILGATE LOGO	Not Necessary	65.00 FL	*- FL
3	1		*TAILGATE EMBLEM STREAM	Necessary	51.90 FL	*51.90 FL
4	1		*TAILGATE LOCK	Damaged	145.60 FL	*145.60 FL
5	1		*TAILGATE CATCH	Not Necessary	89.00 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	312.90 FL	*- FL
7	1		*TAILGATE INNER HANDLE	Not Necessary	65.00 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD	Cracked	335.60 FL	*285.40 FL
9	1		*TAILGATE WINDSCREEN MOULDING	Necessary	133.00 FL	*133.00 FL
10	2		*REAR BUMPER BRACKET	Bent	112.00 FL	*112.00 FL
11	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	65.00 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	136.00 FL	*136.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	458.00 FL	*- FL
14	1		*REAR FENDER INNER TRIM RH	Not Necessary	420.00 FL	*- FL
15	2		*TAILLAMP	Cracked	955.60 FL	*726.20 FL
16	2		*TAILLAMP BOLT COVER	Not Necessary	110.00 FL	*- FL
17	1		*REAR END PANEL	Dented	553.50 FL	*306.00 FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	186.50 FL	*- FL
19	1		*REAR FLOOR PANEL	Repair	1,468.50 FL	*- FL
20	2		*REAR FLOOR PANEL COVER BOARD	Not Necessary	466.00 FL	*- FL
21	1		*REAR TOOLS SPONGE	Not Necessary	196.40 FL	*- FL
22	1		*REAR EXHAUST PIPE	Not Necessary	933.50 FL	*- FL
23	2		*REAR EXHAUST MOUNTING	Not Necessary	104.00 FL	*- FL
24	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*TAILGATE SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	20.00 FS	*20.00 FS
27	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
28	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
29	1		*REAR BUMPER LOWER LID WITH DIFFUSER	Deformed	1,200.00 FS	*900.00 FS
30	1		*SET REAR BUMPER CLIPS	Necessary	22.00 FS	*22.00 FS
31	1		*SET TAILLAMP CLIP	Necessary	20.00 FS	*20.00 FS
32	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
33	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	25.00 FS	*- FS
34	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
35	1		*REAR FLOOR PANEL INSULATOR SEAL	Not Necessary	250.00 FS	*- FS
36	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **10,548.70** **4,081.10**
- List Item Discount on L Items 20.00/20.00% (\$\$) **1,670.34** **559.82**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	8,878.36	3,521.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	600.00
3	TUFF COAT	New	250.00	40.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	180.00	40.00
7	TRANSFER TAILGATE MECHANISM	New	180.00	80.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	180.00	120.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	350.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
Gross Labour Cost (S\$)			5,290.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >