	ASSIGNMENT ()
1	
From: Date:	Veh No. 5K27027Kyr Regn. 1,16
Estimated Cost:	Type: M. Gar / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD THE WS TTP RES OD RES EVA INVINV	Truck / Trailer or CP
To Inspect Vehicle No: 5/2 27027	k Make negla 3 cc 1496
at Workshop m/s hockenon ?	Taym Colour 3/m 3/C: Insured/Std/NI/NA
of	Sp.Reading 20023 T/Radio: Insured / Std / NI / NA
Insured: <27386861	Eng/No:
Policy No.	CNO JMBBM 42Af603266
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inforder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII /S/Rim / STD A/Rim or
COLUMN TO THE TOTAL THE TOTAL TO THE TOTAL TOTAL TO THE T	
(Policy Condition)	Tyre Size: F:
Remark: The veh had commenced its	N/S 0/S RS/DIN/EYNOVA/GY/ES/1/74/M/S/0/75/1/76
repair at the time of inspection.	BS DOWN EXHOUS GT I FS / LIZA / MIC / OHTSU / PIR / SUMI /
The state of the s	TOYONYOKO or
3al. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or N	/ mm Noba. / mm
TA PR Seen: Consistent? : Yes or N	No L/Bail 7 mm L/Bail 7 mm
st Repairs: days Res.: Yes or	No D.O.A 28/12/17 D.O.I 26/1/18
um Sum: /.B/ % 3 Val. Yes or	No Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear & O/S / N/S / U/C / Rooftop or
Veh	icle: IN/OUT 0/5 fcf.
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
6/18 "Confirma for	ul 4 = 400 wrl Har.
(4.14, 1507)	
(Red \$400 507)	
te/Tame, File Pass to? " : Prelli, Report	Days Of Repair:
te/Time. File Pass to?	Machine State of the Control of the
: Final Report	Resurvey No. of Trip: Survey Fee:
: Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
: Final Report	Add Fee: Site Insp (\$)S+RSSi
: Final Report	Add Fee: Site Insp (\$)_S+RS_SI Interview (\$) Photos
	Add Fee: Site Insp (\$)S+RSSi



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

ACIFIC INS N WAY #0 UILDING E 079120 ed Veh. No. No. No. n From & Model e No. sis No. neter	Policy Particu SLF 3864E	Particulars & Condition c.c Year of Reg. Code/AIG1800* Date: 25-01-2018 Code: AIG Name of Code Coverage (\$) Excess (\$) Assign Date Particulars & Condition c.c Year of Reg. Colour Steering Modification			
ed Veh. No. No. n From & Model ee No. sis No.	Policy Particu SLF 3864E Vehicle F	Code: AIG Ilars:-THIRD PARTY CLA Veh. Inspected Coverage (\$) Excess (\$) Assign Date Particulars & Condition c.c Year of Reg. Colour Steering	SKZ 7027K 0.00 0.00 25/01/2018		
No. No. n From & Model e No. sis No.	Vehicle F	Veh. Inspected Coverage (\$) Excess (\$) Assign Date Particulars & Condition c.c Year of Reg. Colour Steering	SKZ 7027K 0.00 0.00 25/01/2018		
No. No. n From & Model e No. sis No.	Vehicle F	Veh. Inspected Coverage (\$) Excess (\$) Assign Date Particulars & Condition c.c Year of Reg. Colour Steering	SKZ 7027K 0.00 0.00 25/01/2018		
No. n From & Model e No. sis No. neter	HIDDEN	Excess (\$) Assign Date Particulars & Condition c.c Year of Reg. Colour Steering	0.00 25/01/2018		
& Model e No. sis No.	HIDDEN	Assign Date Particulars & Condition c.c Year of Reg. Colour Steering	25/01/2018		
& Model e No. sis No. neter	HIDDEN	Particulars & Condition c.c Year of Reg. Colour Steering			
e No. sis No. neter	HIDDEN	c.c Year of Reg. Colour Steering	0		
e No. sis No. neter	11311-11311-11311-1	Year of Reg. Colour Steering	0		
sis No. neter	11311-11311-11311-1	Colour Steering			
eter		Steering			
s	2	The second secon			
		Modification			
ral		Modification			
	Co	Conditions of Tyres			
	Size	Make	Balance		
ront Tyre			mm		
ront Tyre			mm		
ear Tyre			mm		
ear Tyre			mm		
	Desc	ription of Damages			
	Ge	neral Information			
ent Date	28/12/2017	Inspection Date			
y held at	HOCK WAH MOTOR WOR	RKSHOP PTE LTD			
ecessotivnit.	PREMIER @ KAKI BUKIT ((GATE 1)			
		Remarks			
	y held at	y held at HOCK WAH MOTOR WORD BLK 8 KAKI BUKIT AVENU PREMIER @ KAKI BUKIT #02-54/55 SINGAPORE 41	PREMIER @ KAKI BUKIT (GATE 1) #02-54/55 SINGAPORE 415875		

HOCK WAH MOTOR WORKSHOP PTE LTD

HLK 9006 TAMPINES ST 93 #01-204 SINGAPORE 528840 TEL 67853933 FAX:67883933 R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO: SKZ7027K TIEW KOK SOON BLK 384 TAMPINES ST 32 03-33

03-33

SINGAPORE 520384

TEL: FAX: PH:97929457 ATTN: ESTIMATE BILL

Number: EBK0000230

Date: 25/01/2018

Case No: ADK0000302

Vehicle No : SKZ7027K Chassis: Year of Mfr Policy No

Model: MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1 2 3 4	FRT BUMPER RH REPAIR FRT FENDER RH REPAIR LABOUR TO REMOVE AND REFIT NECESSARY PARTS SPRAY PAINT ON THE AFFECTED AREAS Labour 1 Sub Tot		300.00 500.00	0 0	300.00 500.00 800.00
	Teks philo Affer 19° 26/1/18 1 day.		a futo Contestinal recommend in contestinate of the contestinate o	existing between the source of the confirmation of the confirmatio	ing esurvey tion Prejudice" besis
	GAPORE DOLLARS : EIGHT HUNDRED FIFTY-SIX AND CEN RO ONLY	ITS	Less Excess SUBTOTAL GST 7.00% TOTAL		0.00 800.00 56.00 856.00

Date of accident: 27/12/2017 09:37 PM. Place: TUAS CUSTOM TOWARDS MALAYSIA

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE	AUTHORISED SIGNATURE	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	6050F	
Vehicle Details		
Vehicle No.:	SKZ7027K	
Vehicle to be Exported:	No	
Intended De-registration Date:	26 Jan 2018	
Vehicle Make:	MAZDA	
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT	
Primary Colour:	Blue	
Manufacturing Year:	2015	
Engine No.:	P520334992	
Chassis No.:	JM6BM42A8G0326667	
Maximum Power Output:	88.0 kW (118 bhp)	
Open Market Value:	\$17,812.00	
Original Registration Date:	29 Jan 2016	
First Registration Date:	29 Jan 2016	
Transfer Count:	0	
Actual ARF Paid:	\$12,812.00	
Intended PARF Rebate Deta	ails	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	28 Jan 2026	
PARF Rebate Amount:	\$9,609.00	
Intended COE Rebate Detail	ls	
COE Expiry Date:	28 Jan 2026	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$51,301.00	
COE Rebate Amount:	\$41,068.00	
Total Rebate Amount:	\$50,677.00	

The information contained herein is correct as at 26 Jan 2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Our Ref: CC6/AIG18001518/Umb3

14 MARCH 2018

LEONG CHIN ONG BLK 10 JALAN BATU #08-20 SINGAPORE 431010

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 3864E AND SKZ 7027K ON 28/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 24/03/2018, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim Case Handler DID: 6749 4274 FAX: 6741 4108

Email: bevanlim@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

'Jia Le (LKK Auto)

From:

Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>

Sent:

Tuesday, 28 May 2019 12:07 AM

To:

CS A Team

Cc:

Olivia Lau (LKKAuto); Hsiao Tong (LKKAuto); Admin A

Subject:

RE: Our Ref: 2777032136SG-003 || Accident Involving SLF3864E / SKZ7027K on

28/12/2017

Hi LKK Team

Referring to our email dated 29/04/2019.

Kindly render us your WP report and billing for closure urgently.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Tan, Bennie-WZ

Sent: Monday, April 29, 2019 4:36 PM

To: CS A Team

Cc: Olivia Lau (LKKAuto); Hsiao Tong (LKKAuto)

Subject: RE: Our Ref: 2777032136SG-003 || Accident Involving SLF3864E / SKZ7027K on 28/12/2017

Hi LKK Team

Reference to our 10days' notice email dated 30th March 2019.

We did not received any developments from TP till date. We will be closing this matter.

Kindly render us your WP report and billing for closure.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Tan, Bennie-WZ

Sent: Saturday, March 30, 2019 7:53 PM

To: 'sukyi@hockwah.com.sg'

Cc: 'Olivia Lau (LKKAuto)'; 'Hsiao Tong (LKKAuto)'

Subject: Our Ref: 2777032136SG-003 || Accident Involving SLF3864E / SKZ7027K on 28/12/2017

Dear Sir / Mdm

We are the insurer of SLF3864E at the material time of the Accident.

We note that you are acting for TIEW KOK SOON, the owner of SKZ7027K, in their claim for Property Damages against the Auto Insurance Policy of our Insured as a result of the above Accident.

The Claim has been outstanding for more than 12 months. If we do not hear from you in writing within the next 10 working day from the date of this email, we shall proceed to close our file.

Best Regards

Bennie Tan AIG Senior Complex Claims Examiner Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report) Revoked / No settlement

Case	Natified	Est Submitted	Ad) Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jan 2018 Edit Reg		26 Jan 2018 00:00 Edit Adj Rpt	S\$400.00 Edit Estimates	5\$400.00 View Rpt		Pending for Survey Report Cancel Case
	Main	R	eference	Claim De	tails	Documents	Show All
CLAIM SU	BFOLDER DI	ETAILS			[Create	d by adjuster]	
Insured:	Leong Ch	in Ong, ID: S16	55644)				
Main Claimant:	TIEW KO	K SOON, ID: S7	416050F				
Vehicle Rei No.:	SKZ702	7K		Date of	Loss: [22 Mont	17 09:00 - :59 hs and 29 Days Fro	ım LTA Reg Date (Man Yr)]
Claim Type	im Type: TP / 2777032136SG Policy/Cover Note No.: 2100479792 (Comprehensive)					e)	
Vehicle Rei No. (Insured):	SLF3864E (Claimant): 5087495695						
				Excess			
Repairer				006 TAMPINES ST 9			
Handling Insurer:	WZ.Tan@		e Pte. Ltd. (Expre	ss) - Tel: 65-6419-	1000 [Handled	by Tan, Bennie-W	/Z - 6419 1718] Bennie-
Claimant's Insurer:	NTUC Inc		Co-operative Ltd (
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	156-3561 [Handle	d by MARCUS C	HUA] [Final R	pt due 05/02/2018]
ASSOCIA	TED MAIL RE	CEIVED				Vie	w All Compose Case Ma
There are	no mail for this	case.					
ALL ASS	CIATED TAS	sks∃			View All	Search Tasks	reate New Task Comple
Due Dat		Type Task	Group Subject	ct Handler	Assigned By	Completed On	Created On Don

Claim Documents

*SKZ7027K (2777032136SG)

[SLF3864E]

TP

TIEW KOK SOON

Dec 28 2017 9:00AM

[Leong Chin Ong]

Hock Wah Motor Workshop Pte Ltd

Up	sload Documents U	load Photos Comp	oose New Letter	Upload Video	Upload Audio	View	View in Brow	ser 🗸
Ass	essment Reports					1 per	page 🔽	
No:	Finalized On	AIG Asia Pacific 1	Insurance Pte.	Ltd. (SG)			Thumbnail	Print
1	26/01/18 09:06	From:SC - Reg. No. SU		EONG CHIN ONG		0	Load HTM	
Pho	otos/Images					3 per	page V	
No	Relabel/Reorder	LKK Auto Consult	ants Pte Ltd (I	HQ)			Thumbnall	
1	26/01/18 15:36	Chassis Number				0	Load JPG	~
2	26/01/18 15:36	General View				0	Load JPG	V
3	26/01/18 15:36	Odometer Readin	ig			0	Load JPG	V
4	26/01/18 15:36	General View				0	Load JPG	1
5	26/01/18 15:36	General View				0	Load JPG	[Z]
6	26/01/18 15:36	General View				0	Load JPG	Z
7	26/01/18 15:36	General View				0	Load JPG	N.
8	26/01/18 15:36	General View				0	Load JPG	V
9	26/01/18 15:36	General View				0	Load JPG	V
10	26/01/18 15:36	General View				0	Load JPG	V
Doc	umentation					1 per p	page [V]	Z
No	Relabel/Reorder	LKK Auto Consult	ants Pte Ltd (F	4Q)		- Tenderoom	Thumbnail	1000
1	25/01/18 15:50	TP ESTIMATE				0	Load PDF	
2	25/01/18 15:50	TP GIA REPORT				0	Load PDF	
3	30/01/18 08:59	TP ESTIMATE- MA	RKED			0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG18001518/UDB3Q2

Date:

18/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100479792

Claimant Vehicle SKZ7027K

Insured Vehicle No:

SLF3864E

Date of Loss:

28/12/2017

Nature of Claim:

TP

Claim No: 2777032136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SKZ7027K

Make & Model:

MAZDA 3, 1.5 (A)

Engine No:

Pre-accident Condition:

P520334992

20023 km

Reg. Date:

29/01/2016 (Man. Year: 2015)

Chassis No: Odometer:

JM6BM42A8G0326667

Colour: Engine Capacity:

1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES

205/60 R16

Rear Tyre Size:

205/60 R16

Front Tyre Size: Front Left Side:

Toyo 7 mm

Rear Left Side:

Toyo 7 mm

Front Right Side:

Toyo 7 mm

Rear Right Side:

Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	400.00	400.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	800.00	400.00	400.00	50.00
+ GST 7.00/7.00% (S\$)	56.00	28.00	28.00	50.00
Nett Amount (S\$)	856.00	428.00	428.00	50.00
Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment:

26/01/2018

Date Inspected:

26/01/2018 Inspected At:

Hock Wah Motor Workshop Pte Ltd

BLK9006 TAMPINES ST 93 #01-204

Singapore 528840

Estimated Period of Repair.

1.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER RH (NPA)	Repair	0.00 F	*-F
2	1	*FRT FENDER RH (NPA)	Repair	0.00 F	*-F
F=Fn	inchise part.		Total Parts (S\$)	0.00	0.00
		Report was unsubmi	itted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO REMOVE AND REFIT NECESSARY PARTS }	New	300.00	400.00
2	SPRAY PAINT ON THE AFFECTED AREAS }	New	500.00	0.00
	Gross Labo	our Cost (S\$)	800.00	400.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >