

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL :67853933 FAX:67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : SKZ7027K
TIEW KOK SOON
BLK 384 TAMPINES ST 32
03-33
SINGAPORE 520384
TEL : FAX :
PH : 97929457
ATTN :

ESTIMATE BILL

Number : EBK0000230
Date : 25/01/2018
Case No : ADK0000302
Vehicle No : SKZ7027K
Chassis:
Year of Mfr
Policy No
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRT BUMPER RH REPAIR	1.0			
2	FRT FENDER RH REPAIR	1.0			
3	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	300.00	0	300.00
4	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
	Labour 1 Sub Total				800.00
SINGAPORE DOLLARS : EIGHT HUNDRED FIFTY-SIX AND CENTS ZERO ONLY			Less Excess		0.00
			SUBTOTAL		800.00
			GST 7.00%		56.00
			TOTAL		856.00

Date of accident : 27/12/2017 09:37 PM. Place : TUAS CUSTOM TOWARDS MALAYSIA

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE