

menmen Rasul

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CT1

Date/Time: 23/01/2018

Estimated Cost

BLN

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 9775X

Insured

SKD 9284L Kevin

at Workshop no:

Performance Motor

Tel:

63190174 / 91165600

at 303 Alexandra Road

Policy No:

DMPCSN3011271804

CHL No:

SNM18D00412C02

Sum Insured

Excess

Make of Veh:

DOA 21/01/2018

Client's Record

CA / REV / REP. / REV 24 HRS

lup

Unit / Ins. Premium

Date/Time: 10:33am @ 24/1/18

Person Contacted

Caroline

Vehicle ☒ OUT

Date/Time

Action/Inspection

✓

Findings

SKG 9775X - X

SKD 923111 - X

30/1/18

@1257pm Confirmed with Kevin, they are unable to repair the vehicle

30/1/18

@2pm Informed Boon Sen, vehicle recommend T/L

Singapore *Person*

REF:

8227E


COE PERM 2022

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / CP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SKH 9775X  
at Workshop m/s PERFORMANCE  
of \_\_\_\_\_  
Insured: CTI / IUP  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 90K  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR. Sess: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Veh No: SKH 9775X Yr Regn: 2012 / OCT  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: B.M.W 520I 20A c.c. 1997  
Colour: WHITE A/C: Insured / Std / NI / NA  
Sp. Reading: 132334 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WBAXG120X00X51613  
Gen. Cond: Good (X) / Poor / Burnt  
Steering: In order (X) / Jammed / Leaked / Burnt or  
Brake: In order (X) / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 225/55 R17  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (X) / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 21/01/18 D.O.I. 24/01/18  
Survey held at PERFORMANCE  
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Rear & O/S Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/01/18	Message to Kevin B.M.W Performance stating the vehicle nett amount is 21K. He noted and will check up and will get back asap. informed by Kevin vehicle needs unaccompanied for repair
30/1/18	Submit uneconomical TL

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 30/1- typist

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$ \_\_\_\_\_)

☐

Interview (\$ \_\_\_\_\_)

☐

Tech. Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)

ENTERED 3 1 JAN 2018

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

220

# Survey Department Check List (Case Handler)

Reference No.: CS/CTI/800/519/Rlvb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are ACCURATE.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 30/1/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/201



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18001519/R1vb

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-01-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 9284L	Veh. Inspected	SKG 9775X
Policy No.	DMPCSN3011271804	Coverage (\$)	0.00
Claim No.	SNM18D00412C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	23/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	21/01/2018	Inspection Date	25/01/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2018		23 Jan 2018 17:00 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	POON WAI MUN, ID: S1705819C		
Main Claimant:	PHUA SIEW LI, ID: S1758227E		
Vehicle Reg. No.:	SKG9775X	Date of Loss:	21/01/2018 09:00 - :59
Claim Type:	TP / SNM18D00412C02	Policy/Cover Note No.:	DMPCSN3011271804 (Comprehensive)
Vehicle Reg. No. (Insured):	SKD9284L	Policy No. (Claimant):	B27412557SMP
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/02/2018]		
Driver/Custodian (Insured):	SUTINI (49 / Female), NRIC: S6876302I, Tel: +6590301340		
Adj Asg. Remarks:	EST \$28,918.57 , CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8227E

### Vehicle Details

Vehicle No.: SKG9775X

Vehicle to be Exported: No

Intended De-registration Date: 24 Jan 2018

Vehicle Make: B.M.W.

Vehicle Model: 520i 2.0L AT D/AB 2WD 4DR GAS/D NAV

Primary Colour: White

Manufacturing Year: 2012

Engine No.: B4280296N20B20B

Chassis No.: WBAXG120X0DX51013

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$40,045.00

Original Registration Date: 29 Oct 2012

First Registration Date: 29 Oct 2012

Transfer Count: 0

Actual ARF Paid: \$40,045.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Oct 2022

PARF Rebate Amount: \$28,031.00

### Intended COE Rebate Details

COE Expiry Date:	28 Oct 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$85,801.00
COE Rebate Amount:	\$40,847.00
<b>Total Rebate Amount:</b>	<b>\$68,878.00</b>

The information contained herein is correct as at 24 Jan 2018

OK

90,000  
68,878  

---

21,122  
==

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/01/2018 11:44
Date Of Accident	21/01/2018 09:05
Exact Location Of Accident	JUNCTION OF SENGKANG EAST & PUNGGOL WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG9775X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PHUA SIEW LI
NRIC No	S1758227E
Email Address	HCWPSL@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81880165
Alternative Phone No	OFFICE-81880165

### Vehicle Particulars

Manufacturer	BMW
Model	520I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27412557SMP
Cover Note Number	

### Driver

Name of Driver	HO CHII WEN
NRIC No	S1662082C
Date Of Birth	15/09/1964
Occupation	INDOOR
Date Of Driving Pass	17/04/1984
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81009972
Fax Number	
Contact Number	
Email Address	HCWPSL@HOTMAIL.COM



Address	12 TAI HWAN PLACE
Postcode	555295
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PHUA SIEW LI
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD9284L/
Vehicle Make/Model/Colour	MERCEDES E250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SUTINI
NRIC/Passport Number	S6876302I
Contact Number	
Address	112 PUNGGOL WALK #17-26
Postcode	828766
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT

No.-Of Passenger (Including Driver)

2


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### SKETCH PLAN

As per Attachment

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On 21 Jan 2018, at or about 0903 hrs, I was driving north along Sengkang E Rd. At the junction of Punggol West Way Flyover & the East bound TPE ramp, I stopped as the way lights turned red.

Upon the green arrow to turn right onto the ramp appeared, the car on my left moved off first, & I followed. When the car to my left cleared the junction, I noticed the grey MB not slowing down heading south in lane 4 (leftmost lane).

Moments later, the MB crashed into my left rear, causing me to spin anti-clockwise, almost hitting a motorcycle. My rear right hit against the bushes of the road.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

1

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



for In

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

22 JAN 2018

Estimate No. : b1 45592  
Date Estimated : 22/01/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 3

**- ESTIMATE REPAIR FOR -**

Phua Siew Li  
229 Lorong 8 Toa Payoh  
#17-168

Singapore 310229

**- ACCOUNT - 135**

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG9775X	DX51013	29/10/2012	520iA	0

DESCRIPTIONVALUE

To replace on rear bumper, rear left side panel, rear left door and attachments including knock out dent area cause by accident.

5950 / 6,800.00

Painting on rear bumper, rear side panel, rear left door left rocker panel cover, boot, and rear right side panel

5001 / 5,557.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 / 873.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

X / 271.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 / 531.00

To replace tyre and wheel rim including balancing. (1x).

80 / 94.00

To remove and install rear windscreen glass including conduct water leak tests.

649.00

To supply and install rear windscreen solar film.

? / 531.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

X / 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 / 177.00

To carry out body cavity preservation. (Per panel).

X / 118.00

To carry out body cavity preservation. (For cut panel).

451 / 531.00

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180

Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : **b1 45592**  
Date Estimated : **22/01/2018**  
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKG9775X</b>	<b>DX51013</b>	<b>29/10/2012</b>	<b>520iA</b>	<b>0</b>

DESCRIPTION

Sundries.

VALUE

150.00

225/55/R17 Pirelli

70% ? 362.50

Total Labour 1: **17,175.50**DESCRIPTIONQTYPRICVALUE

PLASTIC NUT FOR COARSE THREADED PIN	10	0.80	8.00
ALLOY RIM 8JX17 V SPOKE 236	1	859.70	859.70
HUB CAP WITH CHROME EDGE (BMW)	1	23.75	23.75
RR LH DOOR	1	1,689.00	1,689.00
RR LH FENDER	1	1,710.55	1,710.55
REINFORCEMENT PLATE C PILLAR LH	1	49.20	49.20
REINFORCEMENT PLATE ROCKEL PANEL LH	1	49.20	49.20
LEFT UPPER REAR DOOR HINGE	1	55.75	55.75
LEFT LOWER REAR DOOR HINGE	1	54.90	54.90
SET MOUNTS PDC SENSOR REAR (PDC)	1	62.95	62.95
RR BUMPER CTR GUIDE	1	65.75	65.75
RR BUMPER LH MOUNT	1	141.65	141.65
RR BUMPER RH MOUNT	1	141.65	141.65
RR BUMPER CARRIER	1	696.80	696.80
RR BUMPER PANEL PRIMED (PDC)	1	1,431.40	1,431.40
RR BUMPER ADAPTER	1	46.80	46.80
EMBLEM GROMMET	1	0.80	0.80
MODEL LETTERING 520i	1	61.05	61.05
BMW EMBLEM	1	67.80	67.80
RR WINDOW GREEN	1	875.35	875.35
BUMP STOP	10	3.25	32.50
COVER WINDOW GUIDE RAIL LH	1	24.20	24.20
WINDOW GUIDE WEB COVER LH	1	51.25	51.25
INNER LEFT WINDOW CHANNEL COVER	1	75.05	75.05
RR LH DOOR OUTER WEATHERSTRIP	1	110.35	110.35
COVER COLUMN B DOOR REAR LH	1	154.95	154.95
RR LH DOOR WINDOW CHROME FRAME TOP	1	192.75	192.75
SEAL DOOR GAP DOOR RR BOTTOM	1	39.50	39.50
REAR LH DOOR SEAL SEAM ROOF	1	110.40	110.40
SEAL REAR PANEL EDGE LH	1	19.90	19.90
REAR LH WHEEL HOUSING COVER	1	155.05	155.05
BLIND RIVET AVIBVLB	11	0.55	6.05
SCREW (SF PLUS M5X15)	1	0.55	0.55
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
PUNCH RIVET N5	13	0.55	7.15
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	118.35
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
PUNCH RIVET N4	13	0.55	7.15
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

X

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**Estimate No. : b1 45592  
Date Estimated : 22/01/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG9775X	DX51013	29/10/2012	520iA	0

DESCRIPTION  
(S/L) SEAM SEAL 300ML

QTY	PRIC	VALUE
1	33.80	33.80

Total Parts : 9,851.20

24/01/18 @ 1220  
248ul  
9001006813 days  
Resin 64 part**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

  
29/1/18

Labour 1	:	17,175.50
Parts	:	9,851.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,891.87
Grand Total	:	28,918.57

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



BMW Dealer

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 45592  
 Date Estimated : 22/01/2018  
 Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 3

**- ESTIMATE REPAIR FOR -**

Phua Siew Li  
 229 Lorong 8 Toa Payoh  
 #17-168

Singapore 310229

**- ACCOUNT - 135**

China Taiping Insurance (S) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG9775X	DX51013	29/10/2012	520iA	0

**DESCRIPTION**

To replace on rear bumper, rear left side panel, rear left door and attachments including knock out dent area cause by accident.

8950 6,800.00

Painting on rear bumper, rear side panel, rear left door left rocker panel cover, boot, and rear right side panel

906147 6,831.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 878.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

X 271.00

To check steering geometry and conduct wheel alignment according to BMW specification (2X)

902 1,052.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To remove and install rear windscreen glass including conduct water leak tests.

649.00

To supply and install rear windscreen solar film.

? 531.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

X 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation. (Per panel).

X 118.00

To carry out body cavity preservation. (For cut panel).

451 531.00

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438280  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 45592  
Date Estimated : 22/01/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG9775X	DX51013	29/10/2012	520ia	0

## DESCRIPTION

Sundries.

VALUE

150.00

225/55/R17 Pirelli

253.75 70% 362.50

To remove and install rear suspension, rear axle and  
control system for inspection and replace of damaged parts.

2286 2,655.00

Total Labour 1: 21,635.50

## DESCRIPTION

QTY PRIC

VALUE

PLASTIC NUT FOR COARSE THREADED PIN

10 0.80

8.00

RR DRIVE FLANGE HUB

1 184.15

184.15

LH OUTPUT SHAFT D=30MM

1 1,900.90

1,900.90

RR INTEGRAL LINK

1 121.65

121.65

TRACK STRUT WITH RUBBER MOUNT

1 256.10

256.10

RR LH WISHBONE

1 552.85

552.85

RR LH WHEEL CARRIER

1 1,248.20

1,248.20

RR LH SWING PART

1 924.60

924.60

ANGULAR-CONTACT BALL BEARING UNIT

1 189.85

189.85

NUT(M27X1.5)

1 16.50

16.50

REAR GUIDE SUPPORT

1 131.80

131.80

REAR SPRING STRUT

1 496.80

496.80

SPRING PAD UPPER

1 13.45

13.45

SPRING PAD LOWER

1 14.80

14.80

RR STABILIZER SWING SUPPORT

1 90.70

90.70

ALLOY RIM 8JX17 V SPOKE 236

1 859.70

859.70

HUB CAP WITH CHROME EDGE (BMW)

1 23.75

23.75

RR LH DOOR

1 1,689.00

1,689.00

RR LH FENDER

1 1,710.55

1,710.55

REINFORCEMENT PLATE C PILLAR LH

1 49.20

49.20

REINFORCEMENT PLATE ROCKEL PANEL LH

1 49.20

49.20

LEFT UPPER REAR DOOR HINGE

1 55.75

55.75

LEFT LOWER REAR DOOR HINGE

1 54.90

54.90

SET MOUNTS PDC SENSOR REAR (PDC)

1 62.95

62.95

RR BUMPER CTR GUIDE

1 65.75

65.75

RR BUMPER LH MOUNT

1 141.65

141.65

RR BUMPER RH MOUNT

1 141.65

141.65

RR BUMPER CARRIER

1 696.80

696.80

RR BUMPER PANEL PRIMED (PDC)

1 1,431.40

1,431.40

RR BUMPER ADAPTER

1 46.80

46.80

EMBLEM GROMMET

1 0.80

0.80

MODEL LETTERING 520I

1 61.05

61.05

BMW EMBLEM

1 67.80

67.80

RR WINDOW GREEN

1 875.35

875.35

BUMP STOP

10 3.25

32.50

COVER WINDOW GUIDE RAIL LH

1 24.20

24.20

WINDOW GUIDE WEB COVER LH

1 51.25

51.25

INNER LEFT WINDOW CHANNEL COVER

1 75.05

75.05

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 45592  
Date Estimated : 22/01/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG9775X	DX51013	29/10/2012	520ia	0

DESCRIPTION	QTY	PRIC	VALUE
RR LH DOOR OUTER WEATHERSTRIP	1	110.35	110.35
COVER COLUMN B DOOR REAR LH	1	154.95	154.95
RR LH DOOR WINDOW CHROME FRAME TOP	1	192.75	192.75
SEAL DOOR GAP DOOR RR BOTTOM	1	39.50	39.50
REAR LH DOOR SEAL SEAM ROOF	1	110.40	110.40
SEAL REAR PANEL EDGE LH	1	19.90	19.90
REAR LH WHEEL HOUSING COVER	1	155.05	155.05
BLIND RIVET AVIBVLB	11	0.55	6.05
SCREW (SF PLUS M5X15)	1	0.55	0.55
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
PUNCH RIVET N5	13	0.55	7.15
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	118.35
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
PUNCH RIVET N4	13	0.55	7.15
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	1	33.80	33.80
Total Parts :			15,993.55

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	21,635.50
Parts	:	15,993.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,634.03
Grand Total	:	40,263.08

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2018		23 Jan 2018 17:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	<b>POON WAI MUN</b> , ID: S1705819C		
Main Claimant:	<b>PHUA SIEW LI</b> , ID: S1758227E		
Vehicle Reg. No.:	<b>SKG9775X</b>	Date of Loss:	21/01/2018 09:00 - :59
Claim Type:	<b>TP / SNM18D00412C02</b>	Policy/Cover Note No.:	DMPCSN3011271804 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SKD9284L</b>	Policy No. (Claimant):	B27412557SMP
		Excess:	S\$0.00
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 01/02/2018]		
Driver/Custodian (Insured):	SUTINI (49 / Female), NRIC: S6876302I, Tel: +6590301340		
Adj Asg. Remarks:	EST \$28,918.57 , CASE W/O SJE.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKG9775X (SNM18D00412C02)

[SKD9284L]

TP

PHUA SIEW LI

Jan 21 2018 9:00AM

[POON WAI MUN]

Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	22/01/18 11:54	Accident Statement	Load HTM	

Photos/ Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	22/01/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	22/01/18 11:53	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	22/01/18 11:53	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	22/01/18 11:53	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>



















No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/01/18 09:14	General View	Load JPG	<input checked="" type="checkbox"/>

10	26/01/18 09:14	General View	1	Load JPG	✓
11	26/01/18 09:14	General View	1	Load JPG	✓
12	26/01/18 09:14	General View	1	Load JPG	✓
13	26/01/18 09:14	General View	1	Load JPG	✓
14	26/01/18 09:14	General View	1	Load JPG	✓
15	26/01/18 09:14	General View	1	Load JPG	✓
16	26/01/18 09:14	General View	1	Load JPG	✓
17	26/01/18 09:14	General View	1	Load JPG	✓
18	26/01/18 09:14	General View	1	Load JPG	✓
19	26/01/18 09:14	General View	1	Load JPG	✓
20	26/01/18 09:14	General View	1	Load JPG	✓
21	26/01/18 09:14	General View	1	Load JPG	✓
22	26/01/18 09:14	General View	1	Load JPG	✓
23	26/01/18 09:14	General View	1	Load JPG	✓
24	26/01/18 09:14	General View	1	Load JPG	✓
25	26/01/18 09:14	General View	1	Load JPG	✓
26	26/01/18 09:14	General View	1	Load JPG	✓
27	26/01/18 09:14	General View	1	Load JPG	✓
28	26/01/18 09:14	General View	1	Load JPG	✓
29	26/01/18 09:14	General View	1	Load JPG	✓
30	26/01/18 09:14	General View	1	Load JPG	✓
31	26/01/18 09:14	General View	1	Load JPG	✓
32	26/01/18 09:14	General View	1	Load JPG	✓
33	26/01/18 09:14	General View	1	Load JPG	✓
34	26/01/18 09:14	General View	1	Load JPG	✓
35	26/01/18 09:14	General View	1	Load JPG	✓
36	26/01/18 09:14	General View	1	Load JPG	✓
37	26/01/18 09:14	General View	1	Load JPG	✓
38	26/01/18 09:14	General View	1	Load JPG	✓
39	26/01/18 09:14	General View	1	Load JPG	✓
40	26/01/18 09:14	General View	1	Load JPG	✓
41	26/01/18 09:14	General View	1	Load JPG	✓
42	26/01/18 09:14	General View	1	Load JPG	✓
43	26/01/18 09:14	General View	1	Load JPG	✓
44	26/01/18 09:14	General View	1	Load JPG	✓
45	26/01/18 09:14	General View	1	Load JPG	✓
46	26/01/18 09:14	General View	1	Load JPG	✓
47	26/01/18 09:14	General View	1	Load JPG	✓
48	26/01/18 09:14	General View	1	Load JPG	✓
49	26/01/18 09:14	General View	1	Load JPG	✓
50	26/01/18 09:14	General View	1	Load JPG	✓
51	26/01/18 09:14	General View	1	Load JPG	✓
52	26/01/18 09:14	General View	1	Load JPG	✓
53	26/01/18 09:14	General View	1	Load JPG	✓
54	26/01/18 09:14	General View	1	Load JPG	✓
55	26/01/18 09:14	General View	1	Load JPG	✓
56	26/01/18 09:14	General View	1	Load JPG	✓
57	26/01/18 09:14	General View	1	Load JPG	✓
58	26/01/18 09:14	General View	1	Load JPG	✓
59	26/01/18 09:14	General View	1	Load JPG	✓

60	26/01/18 09:14	General View	1	Load JPG	<input checked="" type="checkbox"/>
61	26/01/18 09:15	General View	1	Load JPG	<input checked="" type="checkbox"/>
62	26/01/18 09:15	General View	1	Load JPG	<input checked="" type="checkbox"/>
63	26/01/18 09:15	General View	1	Load JPG	<input checked="" type="checkbox"/>
64	26/01/18 09:15	General View	1	Load JPG	<input checked="" type="checkbox"/>
65	26/01/18 09:15	General View	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/01/18 16:59	OI GIA REPORT	1	Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	22/01/18 11:49	Sketch Plan <small>[Linked Accident Report Documents]</small>	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/01/18 12:56	AMEND ESTIMATE	1	Load PDF	
2	30/01/18 15:13	LTA	1	Load PDF	

## Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	22/01/18 11:54	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	22/01/18 11:50	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	22/01/18 11:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	22/01/18 11:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	22/01/18 11:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	22/01/18 11:49	Sketch Plan	 Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.



**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CT118001519/R1VBE2**Date:** 01/02/2018**REFERENCE****Handling Insurer:** China Taiping Insurance  
(Singapore) Pte. Ltd.**Policy No:** DMPCSN3011271804**Claimant Vehicle  
No :** SKG9775X**Insured Vehicle  
No :** SKD9284L**Date of Loss:** 21/01/2018**Nature of Claim:** TP**Claim  
No:** SNM18D00412C02**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SKG9775X**Make & Model:** BMW 520i, 2.0 (A)**Engine No:** B4280296N20B20B**Reg. Date:** 29/10/2012 (Man. Year: 2012)**Chassis No:** WBAXG120X0DX51013**Colour:** White**Odometer:** 132334 km**Engine Capacity:** 1997 cc**Market Value/New Car Price:** N/A**Sum Insured (S\$):** Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable): Yes Footbrake (Serviceable): Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 225/55 R17**Rear Tyre Size:** 225/55 R17**Front Left Side:** Pirelli 6 mm**Rear Left Side:** Pirelli 6 mm**Front Right Side:** Pirelli 6 mm**Rear Right Side:** Pirelli 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,143.55	7,264.05	8,879.50	55.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,485.50	17,580.75	3,904.75	18.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>37,629.05</b>	<b>24,844.80</b>	<b>12,784.25</b>	<b>33.97</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,634.03</b>	<b>1,739.14</b>	<b>894.89</b>	<b>33.97</b>
<b>Nett Amount (S\$)</b>	<b>40,263.08</b>	<b>26,583.94</b>	<b>13,679.14</b>	<b>33.97</b>

**INSPECTION****Date of Assignment:** 23/01/2018**Date Inspected:** 24/01/2018 Inspected At:Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941**Estimated Period of Repair:** 0.0 days

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :       \$90,000.00  
OMV :               \$40,045.00  
PARF Rebate (1) :     \$28,031.00  
Quota Premium Paid :   \$85,801.00  
COE Rebate (2) :     \$40,847.00  
Total Rebate (1) + (2) = : \$68,878.00

The total amount incurred will be Market Value \$90,000.00 minus Total Rebate \$68,878.00 = \$21,122.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(EXCLUDE CHECK ITEMS S\$9,299.85 NETT)

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 01 Feb 2018)  
**Parts:** 143      BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SKG9775X)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	10		*PLASTIC NUT FOR COARSE THREADED PIN	* Check	8.00 FS	*- FS
3	1		*RR DRIVE FLANGE HUB	* Check	184.15 FS	*- FS
4	1		*LH OUTPUT SHAFT D=30MM	* Check	1,900.90 FS	*- FS
5	1		*RR INTERGRAL LINK	* Check	121.65 FS	*- FS
6	1		*TRACK STRUT WITH RUBBER MOUNT	* Check	256.10 FS	*- FS
7	1		*RR LH WISHBONE	* Check	552.85 FS	*- FS
8	1		*RR LH WHEEL CARRIER	* Check	1,248.20 FS	*- FS
9	1		*RR LH SWING PART	* Check	924.60 FS	*- FS
10	1		*ANGULAR-CONTACT BALL BEARING UNIT	* Check	189.85 FS	*- FS
11	1		*NUT (M27X1.5)	* Check	16.50 FS	*- FS
12	1		*REAR GUIDE SUPPORT	* Check	131.80 FS	*- FS
13	1		*REAR SPRING STRUT	* Check	496.80 FS	*- FS
14	1		*SPRING PAD UPPER	* Check	13.45 FS	*- FS
15	1		*SPRING PAD LOWER	* Check	14.80 FS	*- FS
16	1		*RR STABILIZER SWING SUPPORT	* Check	90.70 FS	*- FS
17	1		*ALLOY RIM 8JX17 V SPOKE 236	Scratched	859.70 FS	*859.70 FS
18	1		*HUB CAP WITH CHROME EDGE (BMW)	Necessary	23.75 FS	*23.75 FS
19	1		*RR LH DOOR	Bent	1,689.00 FS	*1,689.00 FS
20	1		*RR LH FENDER	Buckled	1,710.55 FS	*1,710.55 FS
21	1		*REINFORCEMENT PLATE C PILLAR LH	* Check	49.20 FS	*- FS
22	1		*REINFORCEMENT PLATE ROCKER PANEL LH	* Check	49.20 FS	*- FS
23	1		*LEFT UPPER REAR DOOR HINGE	Not Necessary	55.75 FS	*- FS
24	1		*LEFT LOWER REAR DOOR HINGE	Not Necessary	54.90 FS	*- FS
25	1		*SET MOUNTS PDC SENSOR REAR (PDC)	* Check	62.95 FS	*- FS
26	1		*RR BUMPER CTR GUIDE	* Check	65.75 FS	*- FS
27	1		*RR BUMPER LH MOUNT	* Check	141.65 FS	*- FS
28	1		*RR BUMPER RH MOUNT	* Check	141.65 FS	*- FS
29	1		*RR BUMPER CARRIER	* Check	696.80 FS	*- FS
30	1		*RR BUMPER PANEL PRIMED (PDC)	Cut	1,431.40 FS	*1,431.40 FS
31	1		*RR BUMPER ADAPTER	* Check	46.80 FS	*- FS
32	1		*EMBLEM GROMMET	Necessary	0.80 FS	*0.80 FS
33	1		*MODEL LETTERING 520I	Necessary	61.05 FS	*61.05 FS
34	1		*BMW EMBLEM	Necessary	67.80 FS	*67.80 FS
35	1		*RR WINDOW GREEN	* Check	875.35 FS	*- FS
36	10		*BUMP STOP	* Check	32.50 FS	*- FS
37	1		*COVER WINDOW GUIDE RAIL LH	* Check	24.20 FS	*- FS
38	1		*WINDOW GUIDE WEB COVER LH	* Check	51.25 FS	*- FS
39	1		*INNER LEFT WINDOW CHANNEL COVER	* Check	75.05 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*RR LH DOOR OUTER WEATHERSTRIP	Necessary	110.35 FS	*110.35 FS
41	1		*COVER COLUMN B DOOR REAR LH	* Check	154.95 FS	*- FS
42	1		*RR LH DOOR WINDOW CHROME FRAME TOP	Necessary	192.75 FS	*192.75 FS
43	1		*SEAL DOOR GAP DOOR RR BOTTOM	Necessary	39.50 FS	*39.50 FS
44	1		*REAR LH DOOR SEAL SEAM ROOF	* Check	110.40 FS	*- FS
45	1		*SEAL REAR PANEL EDGE LH	* Check	19.90 FS	*- FS
46	1		*REAR LH WHEEL HOUSING COVER	Scratched	155.05 FS	*155.05 FS
47	11		*BLIND RIVET AVIBVLB	* Check	6.05 FS	*- FS
48	1		*SCREW (SF PLUS M5X15)	* Check	0.55 FS	*- FS
49	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
50	13		*PUNCH RIVET N5	* Check	7.15 FS	*- FS
51	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
52	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
53	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
54	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
55	13		*PUNCH RIVET N4	* Check	7.15 FS	*- FS
56	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
57	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
Total Parts (\$\$)					16,143.55	7,264.05

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE ON REAR BUMPER, REAR LEFT SIDE PANEL, REAR LEFT DOOR AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	6,800.00	5,950.00
2	PAINTING ON REAR BUMPER, REAR SIDE PANEL, REAR LEFT DOOR LEFT ROCKER PANEL COVER, BOOT, AND REAR RIGHT SIDE PANEL	New	6,831.00	6,147.00
3	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (2X)	New	1,062.00	902.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X)	New	94.00	80.00
7	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	649.00	649.00
8	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM (* CHECK)	New	531.00	0.00
9	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	0.00
10	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
11	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
12	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
13	255/55 R17 PIRELLI (70%)	New	362.50	253.75
14	TO REMOVE AND INSTALL REAR SUSPENSION, REAR AXLE AND CONTROL SYSTEM FOR INSPECTION AND REPLACE OF DAMAGED PARTS	New	2,655.00	2,256.00
Gross Labour Cost (S\$)			21,485.50	17,580.75

Report was unsubmitted during this print-out.

< END OF ESTIMATES >