

15/5/2010

CC 4/EQ11800 1520, RI p0352

LKK:

IDAC:

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

Rasul

DOI:

31/01/18

Date / Time :

25/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SJM 68665

Name of Insured :

YONG HAN HEN

Insured Tel No. :

HP: 94614506

Excess Sec II :\$

D.O.A : 24/01/18

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No. :

DM18HUUU V50/FN

Policy No. :

DMPPH Q 17-00716

Make / Model :

HOWDA

Place of Accident :

FPE / CRY NEAR KALLANG TUNNEL

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SJM 68665

UB 57905

SLA 31424



INSRS:

WSP:

Tel :

Liability :

RMKS:

01



INSRS:

WSP:

Tel :

Liability :

RMKS:

volkswagen

TP



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

26/1/18

31/1/18

28/3/18

14/4/18

20/4/18

stream called OI Mr Yong. Confirm 3 veh
cc. He was the last car inform TP
claim. Agreed to settle & aware NPD issue

Filepass to type mandate

PV sent

Filepass to Shm Per to close

RECEIVED 23 APR 2018

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed)

BOIA S/N No.:

Repair Cost:

SS

24370.01

Loss of Rental (LOR):

SS

1926.00

(

18

days)

x \$100

Loss of Use (LOU):

SS

=

(\$

x

days)

Loss of Income (LOI):

SS

=

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

=

Disbursement:

SS

=

(e.g. Tow/ Independent)

Legal Cost

SS

=

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Total:

SS

26298.01

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

26298.01

Name 1:

Volkswagen Centre Singapore.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: E01

95572

ASSIGNMENT

From: Date: 31-01-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLB 5790S

at Workshop m/s Volkswagen

of 247 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

2pm

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 100K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLB 5790S No Regn: 2016 APR

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf 1.4 cc 1395

Colour: ~~Black~~ Grey A/C: Insured / Std / NI / NA

Sp Reading: 10926 T.Radio: Insured / Std / NI / NA

Eng No:

C/No: WVV222AUZH W223060

Gen. Cond: Good (Fair) Poor / Burnt

Steering: (order) / Jammed / Leaked / Burnt or

Brake: (order) / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (R) / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 24/01/18

Survey held at: Volkswagen ALEXANDRA

Des. of Damages: (R) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

PIP # 22775.71 (Reel) \$ 14706.75 / 39%

Date/Time: File Pass to?

☐
☐

: Preli. Report

: Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

B - P - B

Photo

Other

TOTAL

Report Format :

Lump Sum / I.B.I: \$

Add Fee:

☐
☐
☐
☐

Site Insp: (\$)

Interview: (\$)

Tech. Insp: (\$)

Weekend: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ118001520/pb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 25-01-2018	
			Code : EQ1	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		SJM 6866S	Veh. Inspected SLB 5790S	
Policy No.			Coverage (\$)	
Claim No.			Excess (\$)	
Assign From			Assign Date	
2. Vehicle Particulars & Condition				
Make & Model			c.c	
Engine No.		HIDDEN	Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date		24/01/2018	Inspection Date	
Survey held at		VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

1,152.82	/
81.33	/
66.30	/
69.99	/
29.40	/
14.70	/
14.70	/
14.70	/
29.40	/
14.70	/
71.46	/
36.45	/
36.45	/
1,149.75	/
322.86	/
840.00	/
2,520.00	/
420.00	/
840.00	/
800.00	/
2,400.00	/
360.00	/
280.00	/
8,460.00	/
5,008.86	/
= 13,468.86	

40.45	/
1,167.63	/
40.21	/
19.54	/
19.54	/
531.87	/
40.17	/
606.52	/
509.37	/
134.01	/
2,023.13	/
2,023.13	/
36.45	/
36.45	/
420.00	/
420.00	/
60.00	/
900.00	/
7,433.47	/
= 8,333.47	

f supp
 \$ 850.00

= 21,802.33

ok



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQI18001520/R1pb3

Date: 01.02.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLB5790S


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31.01.2018 at the premises of M/s Volkswagen Centre Singapore and have the following to report:-

Workshop Estimate Amount	: S\$	30,882.33
Revised Estimate Amount	: S\$	13,468.86
"Check" Items Amount	: S\$	8,333.47
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 8-9 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
1T		CZC 524188	5G13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR FRONT	5	UNIT	840	4,200.00
P B&P ALEX LABOUR	LABOUR REAR	5	UNIT	2520	4,200.00
P B&P ALEX LABOUR	TRANSFER BOOT LID PARTS	1	UNIT	420	840.00
P B&P ALEX LABOUR	RE+REINSTALLED REAR LUAGG	1	UNIT	420	840.00
P B&P ALEX LABOUR	RE+REINSTALLED REAR WSCR	1	UNIT		840.00
P B&P ALEX PAINT	SPRAY PAINT FRONT	3	UNIT	800	2,400.00
P B&P ALEX PAINT	SPRAY PAINT REAR	5	UNIT	2400	4,000.00
P B&P AIRCON	VACUUM & REGAS AIRCON-NET	0.5	Time Un	420.00	210.00
	NETT PRICE				
P B&P AIRCON GAS	B&P AIRCON GAS.	1	Time Un		60.00
	SUPPLY OF B&P AIRCON GASS				
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		360.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				18,440.00
P 5G0805567	SUPPORT FOR LOCK CARRIER	1	Pieces		40.45
P 5G0805588AC	LOCK CARRIER	1	Pieces		1,167.63
	Predecessor 5G0805588Q				
P 5G0805705G	CENTER GUIDE FOR LOCK CAR	1	Pieces		40.21
P 5G0807049A	BUMPER BRACKET LHS	1	Pieces		19.54
P 5G0807050A	BUMPER BRACKET RHS	1	Pieces		19.54
P 5G0807109H	BUMPER REINFORCEMENT (Front)	1	Pieces		531.87
	Use Predecessor 5G0807109B				
P 5G0807217BPGRU	FRONT BUMPER	1	Pieces		1,152.82
	Sum carried forward				21,412.06

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 524188	5G13HZ

		Continued	21,412.06
P 5G0807248F	FOAM INSERT	1 Pieces	40.17
P 5G0807305B	Use Predecessor 5G0807248D BUMPER REINFORCEMENT (Recv)	1 Pieces	648.38
P 5G0853617A	Successor 5G0807305D VW SIGN	1 Pieces	81.33
P 5G0853651A ZLL	Use Predecessor 5G0853617		
P 5G0853675AT2ZZ	FRONT UPPER GRILLE	1 Pieces	509.37
P 5G0853677 9B9	NAME PLATE 230 TSI	1 Pieces	66.30
P 5G0853687 2ZZ	FRONT LOWER GRILLE	1 Pieces	134.01
P 5G0919491	NAME PLATE GOLF	1 Pieces	69.99
P 5G0919491A	SENSOR BRACKET	2 Pieces	29.40
P 5G0919491A	SENSOR BRACKET	1 Pieces	14.70
P 5G0919492A	SENSOR BRACKET	1 Pieces	14.70
P 5G0919493	SENSOR BRACKET	1 Pieces	14.70
P 5G0919493A	SENSOR BRACKET	2 Pieces	29.40
P 5G0919494	SENSOR BRACKET	1 Pieces	14.70
P 5G0998492 GRU	SENSOR BRACKET	1 Pieces	71.46
P 5G2941753	HEADLAMP LHS	1 Pieces	2,023.13
P 5G2941754	HEADLAMP RHS	1 Pieces	2,023.13
P 5G6807393	BUMPER BRACKET LHS	1 Pieces	36.45
P 5G6807393A	BUMPER RETAINER LHS	1 Pieces	36.45
P 5G6807394	BUMPER BRACKET RHS	1 Pieces	36.45
P 5G6807394A	BUMPER RETAINER RHS	1 Pieces	36.45
P 5G6807417APGRU	REAR BUMPER	1 Pieces	1,149.75
P 5G6807568D 9B9	Predecessor 5G6807417ARGRU REAR DIFFUSER - LOWER SPOIL Use Predecessor 5G6807568D	1 Pieces	322.86

Sum carried forward

28,773.48

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 524188	5G13HZ

Continued			28,773.48
P 5G6807863A	CENTER STRIP	1 Pieces	am? 67.06x
	Use Predecessor 5G6807863		
P 5G6827025Q	REAR LID	1 Pieces	H / 1,355.49✓
	Use Predecessor 5G6827025H		
P 5K0945087D	THIRD BRAKELIGHT	1 Pieces	goh? 114.18x
	Use Predecessor 5K0945087C		
P 5Q0919133 9B9	SENSOR O RING	12 Pieces	am? 23.76x
P D 004660M2	2K GLUE	1 Pieces	re / 183.87✓
P D 00920002	PRIMER	1 Pieces	re / 32.19✓
P D 00940104	CLEANER	1 Pieces	re / 113.83✓
	66H3 Service Campaign (GOLF)		
P D 00950025	APPLICATOR	1 Pieces	re / 11.19✓
P D 180KU2A1	2KADHESIVE	1 Pieces	re / 103.66✓
P D 181802M1	ACTIVATOR	1 Pieces	re / 29.46✓
P D 822150A1	BONDAGENT	1 Pieces	re / 74.16✓
	Sum Item		12,442.33

Sum Labor 18,440.00
Sum Item 12,442.33

Total SGD 30,882.33
7% GST 2,161.76
Total SGD Incl. GST 33,044.09

30424.09

37524.22

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 4

THIS IS NOT AN OFFICIAL TAX INVOICE

Make Volkswagen Passeng	Model Description GOLF A7 1.4 CL 92 (DSG) EQP	Mileage 9,943	Service Advisor Cheong Pearlyn
License No. SLB5790S	VIN WVWZZZAUZGW223060	Initial Registration 14/04/16	Sales Advisor Goh Terry
Engine Code	Labor Type 1T	Engine No. CZC 524188	Model Code 5G13HZ

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
8-9
4 days
31/01/18 @ 1350
Resurvey by paint

Supplementary or Omitted List



VEHICLE NUMBER: SLB5790S

MODEL	GOLF
-------	------

CLAIMS DETAILS

	LABOUR DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1	LABOUR TO REPLACED INNER / OUTER END PANEL (ADDITIONAL 2 DAY)	2	840	\$1,680.00
2	FRT & REAR NUMBER PLATE	2	80	\$160.00
3	R&R REAR SILENCER	1	420	\$420.00
Total				\$2,260.00

No.	Item No.	Description	Qty	Unit price	DISCOUNT	Amount
1	5G6807863A	REAR BUMPER CENTRE BRACKET	1	67.06		CAD / 67.06 ✓
✓ 2	5G0807305D	REAR REINFORCEMENT	1	648.28	Repeal end.	Pt 648.28 ✗
3	5G6813301B	REAR END PANEL INNER	1	681.39		Pt / 681.39 ✓
4	5G6813309	REAR END PANEL OUTER	1	1155.15		Bt / 1155.15 ✓
5	D 007600A1	INOXSPRAY	1	78.43		re / 78.43 ✓
6	D 180003M2	2KADHESIV	1	330.24		re / 330.24 ✓
7	476KD1M2	SEALANT	1	89.29		re / 89.29 ✓
8	863459K 82V	END PANEL TRIM COVER	1	86.13		CRA / 86.13 ✓
9	5G6827705E	WETHERSTRIP	1	274.35		ree / 274.35 ✓
10	5Q0825701E	REAR SILENCER HEAT PLATE	1	135.42		Pt / 135.42 ✓
				TOTAL:		\$3,545.74

Total Labour & Parts

\$5,805.74

Survey By

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800208
QuoteDate 06/02/18
Salesperson Goh Terry
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 524188	5G13HZ

SUPPLEMENTARY

No.	Description	Qty.	UoM	Unit Price	Amount
DIAMONDBRITE PKG A	DIAMONDBRITE PAINT PROTECT FOR DIAMONDBRITE PACKAGE	1		794.39	794.39
	Sum 3				794.39

	Sum Labor	794.39
Total	SGD	794.39
7% GST	794.39	55.61
Total SGD Incl. GST		850.00

Payment Terms No Credit

37482.46

Payments to: - BBN: - Acc.-No...:

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Thursday, 22 March 2018 12:39 PM
To: Cheong, Pearlyn (VWG Singapore; Rasul (LKKAUTO); Hsiao Tong (LKKAUTO)
Cc: Kong, Charmaine (VWG Singapore; Wong, Meiy (VWG Singapore; Goh, Edmund (VWG Singapore; Admin A; Zaini (LKK Auto)
Subject: RE: FINALISATION SLB5790S ***LKK REF:CC4/EQI18001520/R1pb3

Dear Pearlyn,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Rasul / Hsiao Tong,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]
Sent: Wednesday, 28 February 2018 5:31 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>
Subject: RE: FINALISATION SLB5790S

Dear Rasul,

Please ignore the previous email and confirmed

COR \$22775.71 before GST

Total 12 working days repairs.

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road

Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
Main line: +65 6305 7299
Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>



From: Ong, Germaine (VWG Singapore)
Sent: Monday, 26 February, 2018 12:09 PM
To: Rasul (LKK Auto) <Rasul@lkkauto.com> (Rasul@lkkauto.com)
Cc: Cheong, Pearlyn (VWG Singapore); Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Goh, Edmund (VWG Singapore)
Subject: FINALISATION SLB5790S

Dear Rasul

Please see attached finalisation

COR: As per attached

12 working days

Please note that vehicle is still in the mid of repairing

We are doing early finalisation

Best Regards

Germaine Ong
Insurance Service Advisor
AfterSales

Volkswagen Centre Singapore
17 Tuas Ave 9
Singapore 639197

HP: +65 92361588
Germaine.ong@vw.com.sg
<http://www.vw.com.sg>

New Arteon.

This is high performance art.



Hsiao Tong (LKKAUTO)

From: Ong, Germaine (VWG Singapore) <Germaine.ong@vw.com.sg>
Sent: Wednesday, 14 February 2018 8:51 AM
To: Rasul (LKKAUTO)
Cc: CS A Team; Admin A; Cheong, Pearlyn (VWG Singapore); Kong, Charmaine (VWG Singapore); Wong, MeiY (VWG Singapore); Goh, Edmund (VWG Singapore); Oh, Aik Seong (VWG Singapore)
Subject: SUPPLEMENTARY SLB5790S - URGENT
Attachments: SLB5790SSUPPLEMENTARY.xls; IMG_1723.JPG; IMG_1724.JPG; IMG_1725.JPG; IMG_1726.JPG; IMG_1727.JPG; IMG_1740.JPG; IMG_1741.JPG; IMG_1742.JPG; IMG_1743.JPG; IMG_1744.JPG; IMG_1745.JPG; IMG_1746.JPG; IMG_1747.JPG; IMG_1748.JPG; IMG_1749.JPG; IMG_1750.JPG; IMG_1751.JPG; IMG_1752.JPG; IMG_1753.JPG; IMG_1754.JPG; IMG_1755.JPG; IMG_1756.JPG; IMG_1757.JPG; IMG_1758.JPG; IMG_1759.JPG; IMG_1760.JPG; IMG_1761.JPG; IMG_1762.JPG; IMG_1763.JPG; IMG_1764.JPG; IMG_1765.JPG; IMG_1766.JPG; IMG_1767.JPG; IMG_1768.JPG; IMG_1769.JPG; IMG_1770.JPG; IMG_1771.JPG; IMG_1772.JPG; IMG_1773.JPG; IMG_1774.JPG; IMG_1775.JPG; IMG_1776.JPG; IMG_1777.JPG; IMG_1778.JPG; IMG_1779.JPG; IMG_1780.JPG; IMG_1781.JPG; IMG_1782.JPG; IMG_1783.JPG; IMG_1784.JPG; IMG_1785.JPG; IMG_1786.JPG; IMG_1787.JPG; IMG_1788.JPG; IMG_1789.JPG; IMG_1790.JPG; IMG_1791.JPG; IMG_1792.JPG; IMG_1793.JPG; IMG_1805.JPG; IMG_1806.JPG; IMG_1807.JPG; IMG_1808.JPG; IMG_1809.JPG; IMG_1810.JPG; IMG_1811.JPG; IMG_1812.JPG; IMG_1813.JPG; IMG_1814.JPG; IMG_1815.JPG; IMG_1816.JPG; IMG_1817.JPG; IMG_1818.JPG; IMG_1819.JPG; IMG_1820.JPG; IMG_1821.JPG; IMG_1822.JPG

Dear Rasul

Please see attached supplementary

Total working days: 12

Please revert

Best Regards

Germaine Ong
Insurance Service Advisor
AfterSales

Volkswagen Centre Singapore
17 Tuas Ave 9
Singapore 639197

HP: +65 92361588
Germaine.ong@vw.com.sg
<http://www.vw.com.sg>

New Arteon.

This is high performance art.



Service Order Confirmation

SERVICE ORDER NO.: 18P0329

CUSTOMER NO.: CV032648

CUSTOMER NAME: TAN NEE YEW

TELEPHONE NO.:

ADDRESS: 31 BISHAN STREET 11 #29-06
Singapore

VEH No.: SLB5790S

Order Date: 31/01/18

Reg Date: 14/04/16 KM: 11,134

VIN NO.: VVVZZZAUZGW223060 ENGINE NO:

SA: Cheong Pearlyn

MODEL: GOLF A7 1.4 CL 92 (DSG) EQP MODEL NO.: 5G13HZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	360		360 ✓
2	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280		280 ✓
3	B&P ALEX LABOUR LABOUR FRONT	1	UNIT	840		840 ✓
4	B&P ALEX PAINT SPRAY PAINT FRONT	1	UNIT	800		800 ✓
5	B&P ALEX LABOUR LABOUR REAR +2 day to replace end panel	5	UNIT	840	3520 + 160(A)	4,200 ✓
6	B&P ALEX PAINT SPRAY PAINT REAR	3	UNIT	800		2,400 ✓
7	B&P ALEX LABOUR TRANSFER BOOT LID PARTS	0.5	UNIT	840		420 ✓
8	B&P ALEX LABOUR RE+REINSTALLED REAR WSCREEN	1	UNIT	840		840 ✓
9	B&P NUMBER PLATE NUMBER PLATE FRT & REAR	2	ST	80		(A) 160 ✓
10	B&P ALEX LABOUR R&R REAR SILENCER	1	UNIT	420		(A) 420 ✓
Item						
11	5G0807217BPGRU FRONT BUMPER	1	PCS	1,152.82		1,152.82 ✓
12	5G0919493 SENSOR BRACKET	1	PCS	14.70		14.70 ✓
13	5G0919493A SENSOR BRACKET	2	PCS	14.70		29.40 ✓
14	5G0919494 SENSOR BRACKET	1	PCS	14.70		14.70 ✓
15	D 822150A1 BONDAGENT	1	PCS	74.16		74.16 ✓
16	D 180KU2A1 2KADHESIVE	1	PCS	103.66		103.66 ✓
17	5G6807417APGRU REAR BUMPER	1	PCS	1,149.75		1,149.75 ✓
18	5G0998492 GRU SENSOR BRACKET	1	PCS	71.46		71.46 ✓
19	5G0919491 SENSOR BRACKET	2	PCS	14.70		29.40 ✓
20	5G0919491A SENSOR BRACKET	1	PCS	14.70		14.70 ✓
21	5G0919492A SENSOR BRACKET	1	PCS	14.70		14.70 ✓
22	5G6807568D 9B9 REAR DIFFUSER - LOWER SPOILER	1	PCS	322.86		322.86 ✓
23	5G6807394A BUMPER RETAINER RHS	1	PCS	36.45		36.45 ✓
24	5G6827025Q REAR LID	1	PCS	1,355.49		1,355.49 ✓
25	5G0853617A VW SIGN	1	PCS	81.33		81.33 ✓
26	5G0853675AT2ZZ NAME PLATE 230 TSI	1	PCS	66.30		66.30 ✓
27	5G0853687 2ZZ NAME PLATE GOLF	1	PCS	69.99		69.99 ✓
28	D 004660M2 2K GLUE	1	PCS	183.87		183.87 ✓

Service Order Confirmation

SERVICE ORDER NO: 18IP0329

CUSTOMER NO.: GV032648

CUSTOMER NAME: TAN NEE YEW

TELEPHONE NO.:

ADDRESS: 31 BISHAN STREET 11 #29-06
Singapore

VEH No.: SLB5790S

Order Date: 31/01/18

Reg Date: 14/04/16 KM: 11,134

VIN NO.: WVVZZZAUZGW223060 ENGINE NO:

SA: Cheong Pearlyn

MODEL: GOLF A7 1.4 CL 92 (DSG) EQP MODEL NO.: 5G13HZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	D 00920002 PRIMER	1	PCS	32.19		32.19 ✓
30	D 00950025 APPLICATOR	1	PCS	11.19		11.19 ✓
31	D 181802M1 ACTIVATOR	1	PCS	29.46		29.46 ✓
32	D 00940104 CLEANER	1	PCS	113.83		113.83 ✓
33	5G6807394 BUMPER BRACKET RHS	1	PCS	36.45		36.45 ✓
34	5G0805705G FRT BUMPER CENTRE BRACKET	1	PCS	40.21		40.21 ✓
35	5G0853651A ZLL FRT UPPER GRILLE	1	PCS	509.37		509.37 ✓
36	5G0853677 9B9 FRT LOWER GRILLE	1	PCS	134.01		134.01 ✓
37	5G2941754 HEADLAMP RHS	1	PCS	2,023.13		2,023.13 ✓
38	5G6807663A REAR BUMPER CENTRE BRACKET	1	PCS	67.06		67.06
39	5G0807305D REAR REINFORCEMENT	1	PCS	648.28		648.28
40	5G6813301B REAR END PANEL INNER	1	PCS	681.39		681.39
41	5G6813309 REAR END PANEL OUTER	1	PCS	1,155.15		1,155.15
42	D 007600A1 INOXSPRAY	1	PCS	78.43		78.43
43	D 180003M2 2KADHESIV	1	PCS	330.24		330.24
44	D 476KD1M2 SEALANT	1	PCS	89.29		89.29
45	5G6863459K 82V END PANEL TRIM COVER	1	PCS	86.13		86.13
46	5G6827705E WETHERSTRIP	1	PCS	274.35		274.35
47	5Q0825701E REAR SILENCER HEAT PLATE	1	PCS	135.42		135.42

Remarks : DIRECT SETTLEMENT

DOA: 24/01/2018

TP VEHICLE NO: SJM6866S

SURVEY BY RASUL

+ Coating \$ ~~794~~ 794.39

Service Order Confirmation

SERVICE ORDER NO: 18IP0329

CUSTOMER NO.: CV032648

CUSTOMER NAME: TAN NEE YEW

TELEPHONE NO.:

ADDRESS: 31 BISHAN STREET 11 #29-06
Singapore

VEH No.: SLB5790S

Order Date: 31/01/18

Reg Date: 14/04/16

KM: 11,134

VIN NO.: WVVWZZAUZGW223060

ENGINE NO:

SA: Cheong Pearlyn

MODEL: GOLF A7 1.4 CL 92 (DSG) EQP MODEL NO.: 5G13HZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

22775.71

TOTAL	21,981.32
GST AMOUNT	1,538.89
TOTAL AMOUNT	23,520.01

24370.00

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9597Z
Vehicle Details	
Vehicle No.:	SLB5790S
Vehicle to be Exported:	No
Intended De-registration Date:	01 Feb 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ HID SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CZC524188
Chassis No.:	WVWZZZAUZGW223060
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$23,839.00
Original Registration Date:	14 Apr 2016
First Registration Date:	14 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$15,375.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Apr 2026
PARF Rebate Amount:	\$11,531.00
Intended COE Rebate Details	

COE Expiry Date:	13 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$37,313.00
Total Rebate Amount:	\$48,844.00

The information contained herein is correct as at 01 Feb 2018

OK

100 000
48 844

51,156
==