

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 524188	5G13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR FRONT	5	UNIT		840 4200.00
P B&P ALEX LABOUR	LABOUR REAR	5	UNIT		2520 4200.00
P B&P ALEX LABOUR	TRANSFER BOOT LID PARTS	1	UNIT		420 840.00
P B&P ALEX LABOUR	RE+REINSTALLED REAR LUAGG	1	UNIT		? 420 840.00
P B&P ALEX LABOUR	RE+REINSTALLED REAR WSCR	1	UNIT		840.00
P B&P ALEX PAINT	SPRAY PAINT FRONT	3	UNIT		800 2400.00
P B&P ALEX PAINT	SPRAY PAINT REAR	5	UNIT		2400 4000.00
P B&P AIRCON	VACUUM & REGAS AIRCON-NET	0.5	Time Un		? 420.00
	NETT PRICE				
P B&P AIRCON GAS	B&P AIRCON GAS	1	Time Un		? 60.00
	SUPPLY OF B&P AIRCON GASS				
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		360.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				18,440.00
P 5G0805567	SUPPORT FOR LOCK CARRIER	1	Pieces		? 40.45
P 5G0805588AC	LOCK CARRIER	1	Pieces		? 1,167.63
	Predecessor 5G0805588Q				
P 5G0805705G	CENTER GUIDE FOR LOCK CAR	1	Pieces		? 40.21
P 5G0807049A	BUMPER BRACKET LHS	1	Pieces		? 19.54
P 5G0807050A	BUMPER BRACKET RHS	1	Pieces		? 19.54
P 5G0807109H	BUMPER REINFORCEMENT	1	Pieces		? 531.87
	Use Predecessor 5G0807109B				
P 5G0807217BPGRU	FRONT BUMPER	1	Pieces		? 1,152.82
	Sum carried forward				21,412.06

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 524188	5G13HZ

Continued			21,412.06
P 5G0807248F	FOAM INSERT	1 Pieces	? 40.17
	Use Predecessor 5G0807248D		
P 5G0807305B	BUMPER REINFORCEMENT	1 Pieces	? 606.52
	Successor 5G0807305D		
P 5G0853617A	VW SIGN	1 Pieces	(RA) 81.33
	Use Predecessor 5G0853617		
P 5G0853651A ZLL	FRONT UPPER GRILLE	1 Pieces	? 509.37
P 5G0853675AT2ZZ	NAME PLATE 230 TSI	1 Pieces	neu 66.30
P 5G0853677 9B9	FRONT LOWER GRILLE	1 Pieces	? 134.01
P 5G0853687 2ZZ	NAME PLATE GOLF	1 Pieces	neu 69.99
P 5G0919491	SENSOR BRACKET	2 Pieces	neu 29.40
P 5G0919491A	SENSOR BRACKET	1 Pieces	neu 14.70
P 5G0919492A	SENSOR BRACKET	1 Pieces	neu 14.70
P 5G0919493	SENSOR BRACKET	1 Pieces	neu 14.70
P 5G0919493A	SENSOR BRACKET	2 Pieces	neu 29.40
P 5G0919494	SENSOR BRACKET	1 Pieces	neu 14.70
P 5G0998492 GRU	SENSOR BRACKET	1 Pieces	neu 71.46
P 5G2941753	HEADLAMP LHS	1 Pieces	? 2,023.13
P 5G2941754	HEADLAMP RHS	1 Pieces	? 2,023.13
P 5G6807393	BUMPER BRACKET LHS	1 Pieces	? 36.45
P 5G6807393A	BUMPER RETAINER LHS	1 Pieces	? 36.45
P 5G6807394	BUMPER BRACKET RHS	1 Pieces	neu 36.45
P 5G6807394A	BUMPER RETAINER RHS	1 Pieces	neu 36.45
P 5G6807417APGRU	REAR BUMPER	1 Pieces	DB 1,149.75
	Predecessor 5G6807417ARGRU		
P 5G6807568D 9B9	REAR DIFFUSER - LOWER SPOI	1 Pieces	cut 322.86
	Use Predecessor 5G6807568D		

Sum carried forward

28,773.48

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 524188	5G13HZ

Continued			28,773.48
P 5G6807863A	CENTER STRIP	1 Pieces	? 67.06
	Use Predecessor 5G6807863		
P 5G6827025Q	REAR LID	1 Pieces	H / 1,355.49
	Use Predecessor 5G6827025H		
P 5K0945087D	THIRD BRAKELIGHT	1 Pieces	? 114.18
	Use Predecessor 5K0945087C		
P 5Q0919133 9B9	SENSOR O RING	12 Pieces	? 23.76
P D 004660M2	2K GLUE	1 Pieces	nee / 183.87
P D 00920002	PRIMER	1 Pieces	nee / 32.19
P D 00940104	CLEANER	1 Pieces	nee / 113.83
	66H3 Service Campaign (GOLF)		
P D 00950025	APPLICATOR	1 Pieces	nee / 11.19
P D 180KU2A1	2KADHESIVE	1 Pieces	nee / 103.66
P D 181802M1	ACTIVATOR	1 Pieces	nee / 29.46
P D 822150A1	BONDAGENT	1 Pieces	nee / 74.16
	Sum Item		12,442.33

Sum Labor			18,440.00
Sum Item			12,442.33

Total	SGD	30,882.33
7% GST		2,161.76
Total SGD Incl. GST		33,044.09

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN NEE YEW
(CHEN ERYOU)
31 BISHAN STREET 11
#29-06
Singapore, 579819
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032648
Quote No. SER/QUO/1800139
QuoteDate 24/01/18
Salesperson Goh Terry
Page 4

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	9,943	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB5790S	WVWZZZAUZGW223060	14/04/16	Goh Terry
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 524188	5G13HZ

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
8-9
days

31/01/18 @ 1350

Resurvey by part

Payments to: - BBN: - Acc.-No.: