

22/07/2018

ASS. REC. BY:

REF:

CS/MSG18001530 / Sqb

Special Instruction:

SURVIVOR:

Sebastian

ASSIGNMENT (Office)

From (Person):

Catherine Thuy

of

MSL1

Date/Time:

25/12/18 924am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 5913H

Insured:

SJM 6475L

at Workshop m/s

World Auto

Tel:

of

No. 1 Krungji Loop.

Policy No:

28868481 BMX

Claim No:

547074

Sum Insured:

Excess:

Make of Veh:

D.O.A. 20012018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

25/12/18 1035am

Person Contacted:

Daniel

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 5913H - X
	SJM 6475L - CS/MSG17015740/Tlgbe2
29/1/18 @ 2:43pm	Revised to Catherine Thuy via Messenger.
	Finalised by Sebastian at Final Fy @ 6049.36, 6 days.
	Charged @ 2280.40, 27%.
	26/4

MSIG

26/01/18

SLK5913H

10/1/2017

0

SLK 5913H
World Auto
No.1 Kranji loop

10

Handy Shuttle

1496

Silver

110623

GP71045114

B

B

B

185/60R15

11

Giti
Giti



6

6

10/1/18

26/1/18

World Auto

0

Sebastian,

pls check parts prices

[Signature]

29/1

RECEIVED 7 JAN 2018

2014 April



File Record

6

MEX-TP
6049-36

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 29 Jan 2018

Preliminary Advice

Insured Vehicle No	: SJM6475L	Accident Date	: 20/01/2018
TP Vehicle No	: SLK5913H	Assignment Date	: 25/01/2018
Make	: HONDA SHUTTLE HYBRID	Est. Duration of Repair	: 6.00
Date of Inspection	: 26/01/2018		
Inspection At	: WORLD AUTO PTE LTD - KRANJI (HQ) NO 1 KRANJI LOOP SINGAPORE 739535		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,329.76
Revised Amount	:S\$	6,137.76
Check Items (Estimated)	:S\$	486.00
Total	:S\$	6,623.76
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2018 10:43
Date Of Accident	20/01/2018 13:50
Exact Location Of Accident	ALONG PIE BEFORE THOMSON RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK5913H
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201604597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	WONG JAN SIN
NRIC No	S8075753J
Date Of Birth	02/03/1980
Occupation	OUTDOOR
Date Of Driving Pass	30/07/2001
Driving Experience	16 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM6475L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA):
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 

Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A SLK 5913H
B CTH 6AT5L

End
(Tham) Cor Aid



PJE to Changi

Sketch Plan #2

Describe Circumstances of the Accident

On 20/1/18 at around 12:00pm, when I was travelling along PIE to word change before Thompson Rd Exit, the traffic quite moved, all the vehicles steady down then I also drive steady but suddenly the vehicle SJM 6435L hit my vehicle from behind.

Declaration

I/We declare the foregoing particulars are true in every respect.

 

Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (SINGAPORE) PTE LTD

4 SHENTON WAY #21-01 SGX CENTRE 2

068807

Attention : Motor Claim Department

Contact : 68277888

Estimate : ES201812

Date : 22/01/2018

Vehicle Num. : SLK 5913H (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 20/01/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	TAILGATE ✓ DT		1,450.00
2.	1	TAILGATE LOCK ASSY ✓ Jm		260.00
3.	1	TAILGATE HYBRID EMBLEM ✓ NEC		84.60
4.	1	TAILGATE SHUTTLE EMBLEM ✓ NEC		88.60
5.		REAR BUMPER ✓ Pua		1,200.00
6.		REAR BUMPER REFLECTOR LENS - LH ?		118.00
7.		REAR BUMPER REFLECTOR LENS GARNISH LH ✓ cut		128.00
8.		REAR BUMPER SIDE RETAINER LH ?		78.00
9.		REAR BOOT WEATHER STRIP ✓ Defam		310.50
10.		REAR END PANEL ✓ DT		950.00
11.		REAR END PANEL TOP GARNISH ✓ Defam		260.00
12.		TAIL LAMP PANEL LH ?		411.50
13.		REAR BOOT COMPARTMENT BOX X		420.00
14.		REAR BOOT COMPARTMENT BOX BACK COVER ✓ Defam		158.00
15.	1SET	REAR WINDSCREEN GLASS MOULDING ✓ NEC		195.00

List TotalS\$:

6,112.20

20.00% Discount S\$:

1,222.44

4,889.76

SPECIAL NETT ITEMS :				
1.	1SET	TAILGATE INNER TRIM CLIP ✓ NEC		30.00
2.	1SET	REAR BUMPER CLIP ✓ NEC		30.00
3.	1SET	REAR END PANEL TOP GARNISH CLIPS ✓ NEC		20.00
4.	1SET	REVERSE SENSOR ✓ DMG		280.00
5.	1	WINDSCREEN SEALANT ✓ NEC		80.00

Special Nett Total S\$:

440.00

LABOUR :

REMOVE & REFIT REAR WINDSCREEN GLASS

180.00 120

WIRINGS CHECK AND RECTIFY WHERE NECESSARY

120.00 30

REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE
REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN
CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS

1,500.00 800

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (SINGAPORE) PTE LTD

4 SHENTON WAY #21-01 SGX CENTRE 2

068807

Attention : Motor Claim Department

Contact : 68277888

Estimate : ES201812

Date : 22/01/2018

Vehicle Num. : SLK 5913H (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 20/01/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PUTTY AND SPRAY PAINT ALL AFFECTED AREAS

1,200.00

500

Labour Total S\$:

3,000.00

6 days

Sebastian

26/1/2018

- Part by part repair.
- Question Mark Item
- Photo
- Photo Before Paint

90036121

sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



29/1/18

E. & O.E.

Total S\$:

8,329.76

for WORLD AUTO PTE LTD

WORLD AUTO PTE LTD

Umpin #01-02/03

2, S'pore 577200

No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY #21-01 SGX CENTRE 2
068807

Attention : Motor Claim Department

Contact : 68277888

Estimate : ES201812

Date : 22/01/2018

Vehicle Num. : SLK 6913H (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 20/01/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	TAILGATE ✓ DT	1,480.00	1200
2.	1	TAILGATE LOCK ASSY ✓ J44	260.00	200
3.	1	TAILGATE HYBRID EMBLEM ✓ NEC	84.60	
4.	1	TAILGATE SHUTTLE EMBLEM ✓ NEC	88.60	
5.		REAR BUMPER ✓ PUN	1,200.00	
6.		REAR BUMPER REFLECTOR LENS - LH ? X44	448.00	
7.		REAR BUMPER REFLECTOR LENS GARNISH LH ✓ cut	128.00	
8.		REAR BUMPER SIDE RETAINER LH ? ✓ 400	78.00	
9.		REAR BOOT WEATHER STRIP ✓ h.g.m	310.50	
10.		REAR END PANEL ✓ DT	890.00	660
11.		REAR END PANEL TOP GARNISH ✓ Deform	260.00	
12.		TAIL LAMP PANEL LH ? ✓ DT	411.50	
13.		REAR BOOT COMPARTMENT BOX ✓ h.m	420.00	
14.		REAR BOOT COMPARTMENT BOX BACK COVER ✓ Deform	158.00	
15.	1SET	REAR WINDSCREEN GLASS MOULDING ✓ NEC	195.00	
List Total S\$:			6,112.20	
20.00% Discount S\$:			1,222.44	
			4,889.76	

4974.20
- 20%
1) 3979.56

SPECIAL NETT ITEMS :				
1.	1SET	TAILGATE INNER TRIM CLIP ✓ NEC	30.00	
2.	1SET	REAR BUMPER CLIP ✓ NEC	30.00	
3.	1SET	REAR END PANEL TOP GARNISH CLIPS ✓ NEC	20.00	
4.	1SET	REVERSE SENSOR ✓ DMG	280.00	200
5.	1	WINDSCREEN SEALANT ✓ NEC	80.00	40
Special Nett Total S\$:			440.00	

LABOUR :

REMOVE & REFIT REAR WINDSCREEN GLASS

WIRINGS CHECK AND RECTIFY WHERE NECESSARY

REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE
REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN
CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS

3) 1750

780.00 120

720.00 30

7,990.00 800

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01 SGX CENTRE 2
 068807

Attention : Motor Claim Department
 Contact : 68277888

Estimate : ES201812

Date : 22/01/2018
 Vehicle Num. : SLK 5913H (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 20/01/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS		1,200.00
		Labour Total S\$:		3,000.00

Sebastian
 26/1/2018
 - Part by part repair
 - Question Mark Item
 Photo
 - Photo Before Paint
 90056121

sebastianyeang@lkkauto.com

Parts :	\$	3979.36
S/Matt :	\$	320.00
Labour :	\$	1750.00

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

6049.36 @ 6 days

E. & O.E.

Total S\$:

8,329.76

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2018		25 Jan 2018 09:24 Edit Adj Rpt	S\$6,049.36 Edit Estimates	S\$6,049.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	MS HE JIAJING, ID: S8210782G, Tel: +6591849919, Email: NOEMAIL								
Main Claimant:	LCRF Pte Ltd, Co. Reg. No.: 201604597K								
Vehicle Reg. No.:	SLK5913H	Date of Loss:	20/01/2018 13:00 - :59 [12 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 547074	Policy/Cover Note No.:	28868481QMX (Comprehensive) Coverage: 13/01/2018 - 12/01/2019						
Vehicle Reg. No. (Insured):	SJM6475L	Policy No. (Claimant):							
		Excess:							
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 24/02/2018]								
Driver/Custodian (Insured):	MS HE JIAJING (35 / Male), NRIC: S8210782G, Tel: +6591849919								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK5913H (547074)
[SJM6475L]
TP
LCRF Pte Ltd
Jan 20 2018 1:00PM
[MS HE JIAJING]
World Auto Pte Ltd - Kranji

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/01/18 08:51	Accident Statement From: SC - Reg. No: SJM6475L, Claimant: MS HE JIAJING	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/18 14:42	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 14:37	General View	1 Load JPG	☒
2	23/04/18 14:37	General View	1 Load JPG	☒
3	23/04/18 14:37	General View	1 Load JPG	☒
4	23/04/18 14:37	General View	1 Load JPG	☒
5	23/04/18 14:37	General View	1 Load JPG	☒
6	23/04/18 14:37	General View	1 Load JPG	☒
7	23/04/18 14:37	General View	1 Load JPG	☒
8	23/04/18 14:37	General View	1 Load JPG	☒
9	23/04/18 14:37	General View	1 Load JPG	☒
10	23/04/18 14:37	General View	1 Load JPG	☒
11	23/04/18 14:37	General View	1 Load JPG	☒
12	23/04/18 14:37	General View	1 Load JPG	☒
13	23/04/18 14:37	General View	1 Load JPG	☒
14	23/04/18 14:37	General View	1 Load JPG	☒
15	23/04/18 14:37	General View	1 Load JPG	☒
16	23/04/18 14:37	General View	1 Load JPG	☒
17	23/04/18 14:37	General View	1 Load JPG	☒
18	23/04/18 14:37	General View	1 Load JPG	☒
19	23/04/18 14:37	General View	1 Load JPG	☒
20	23/04/18 14:37	General View	1 Load JPG	☒
21	23/04/18 14:37	General View	1 Load JPG	☒
22	23/04/18 14:37	General View	1 Load JPG	☒
23	23/04/18 14:37	General View	1 Load JPG	☒
24	23/04/18 14:37	General View	1 Load JPG	☒
25	23/04/18 14:37	General View	1 Load JPG	☒
26	23/04/18 14:37	General View	1 Load JPG	☒
27	23/04/18 14:37	General View	1 Load JPG	☒
28	23/04/18 14:37	General View	1 Load JPG	☒
29	23/04/18 14:37	General View	1 Load JPG	☒
30	23/04/18 14:37	General View	1 Load JPG	☒
31	23/04/18 14:37	General View	1 Load JPG	☒
32	23/04/18 14:37	General View	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	23/04/18 14:37	General View		☒
34	23/04/18 14:37	General View	Load JPG	☒
35	23/04/18 14:37	General View	Load JPG	☒
36	23/04/18 14:37	General View	Load JPG	☒
37	23/04/18 14:37	General View	Load JPG	☒
38	23/04/18 14:37	General View	Load JPG	☒
39	23/04/18 14:37	General View	Load JPG	☒
40	23/04/18 14:37	General View	Load JPG	☒
41	23/04/18 14:37	General View	Load JPG	☒
42	23/04/18 14:37	General View	Load JPG	☒
43	23/04/18 14:37	General View	Load JPG	☒
44	23/04/18 14:37	General View	Load JPG	☒
45	23/04/18 14:37	General View	Load JPG	☒
46	23/04/18 14:37	General View	Load JPG	☒
47	23/04/18 14:37	General View	Load JPG	☒
48	23/04/18 14:37	General View	Load JPG	☒
49	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
50	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
51	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
52	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
53	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
54	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
55	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
56	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
57	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
58	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
59	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
60	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
61	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
62	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
63	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
64	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
65	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
66	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
67	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
68	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
69	23/04/18 14:37	BEFORE PAINT	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/01/18 08:51	SLK5913H E FILE REPORT From: SC - Reg. No: SJM6475L, Claimant: MS HE JIAJING	Load PDF	
2	25/01/18 08:54	PRI Request	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001530/SQBQ2

Date: 27/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28868481QMX

Claimant Vehicle No: SLK5913H

Insured Vehicle No: SJM6475L

Date of Loss: 20/01/2018

Nature of Claim: TP

Claim No: 547074

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK5913H

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB4265213

Reg. Date: 20/01/2017 (Man. Year: 2016)

Chassis No: GP71045114

Colour: Silver

Odometer: 110623 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Giti 6 mm

Rear Left Side: Giti 6 mm

Front Right Side: Giti 6 mm

Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,329.76	4,299.36	1,030.40	19.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,750.00	1,250.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,329.76	6,049.36	2,280.40	27.38
+ GST 7.00/7.00% (S\$)	583.08	423.46	159.62	27.38
Nett Amount (S\$)	8,912.84	6,472.82	2,440.02	27.38

INSPECTION

Date of Assignment: 25/01/2018

Date Inspected: 26/01/2018 Inspected At:

World Auto Pte Ltd - Kranji (HQ)
No 1 Kranji Loop
Singapore 739535

Estimated Period of Repair: 6.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Apr 2018)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5913H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,450.00 FL	*1,200.00 FL
2	1		*TAILGATE LOCK ASSY	Jammed	260.00 FL	*200.00 FL
3	1		*TAILGATE HYBRID EMBLEM	Necessary	84.60 FL	*84.60 FL
4	1		*TAILGATE SHUTTLE EMBLEM	Necessary	88.60 FL	*88.60 FL
5	1		*REAR BUMPER	Punctured	1,200.00 FL	*1,200.00 FL
6	1		*REAR BUMPER REFLECTOR LENS -LH	Not Necessary	118.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR LENS GARNISH LH	Cut	128.00 FL	*128.00 FL
8	1		*REAR BUMPER SIDE RETAINER LH	Necessary	78.00 FL	*78.00 FL
9	1		*REAR BOOT WEATHER STRIP	Deformed	310.50 FL	*310.50 FL
10	1		*REAR END PANEL	Dented	950.00 FL	*660.00 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	260.00 FL	*260.00 FL
12	1		*TAIL LAMP PANEL LH	Dented	411.50 FL	*411.50 FL
13	1		*REAR BOOT COMPARTMENT BOX	Not Necessary	420.00 FL	*- FL
14	1		*REAR BOOT COMPARTMENT BOX BACK COVER	Deformed	158.00 FL	*158.00 FL
15	1		*SET REAR WINDSCREEN GLASS MOULDING	Necessary	195.00 FL	*195.00 FL
16	1		*SET TAILGATE INNER TRIM CLIP	Necessary	30.00 FS	*30.00 FS
17	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
18	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
19	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
20	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,552.20	5,294.20
- List Item Discount on L Items 20.00/20.00% (S\$)	1,222.44	994.84
Total Parts (S\$)	5,329.76	4,299.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
2	WIRINGS CHECK AND RECTIFY WHERE NECESSARY	New	120.00	30.00
3	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT ,CUT /WELD ,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	1,500.00	800.00
4	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,000.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >