

ASS. REC. BY:

REF:

05/FCI/8001537/Alfred

Special Instruction:

SUMMARY:

Rasul

ASSIGNMENT (Office)From (Person): CWS Ang Yin Min of FCI Date/Time: 24/03/018 440pm

Estimated Cost: _____ Bill to: _____

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHB 3799D Insured: SHA 9275Pat Workshop m/s Ding Auto Tel: 83039888of 31 Corporation RoadPolicy No: _____ Claim No: 018000734MF5H

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23012018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DSI' H.O.D. Endorsement: _____

Date/Time: 25/01/08 1011am Person Contacted: Alex Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 3799D - x
	SHA 9275P - NS / INC 15021959 / Hlgm2 DUA: 211215
30/1/18	Email preti revised to FCI
12/3/18	LS \$ 6450 confirmed by email (Red 10,281.17, 612)

432

Survey Department Check List (Case Handler)

Reference No.: CS | FCI 18001537 | Rlvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 12/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001537/R1vb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9275P	Veh. Inspected	SHB 3799D
Policy No.		Coverage (\$)	0.00
Claim No.	D18000734MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages on

--	--

5. General Information

Accident Date	23/01/2018	Inspection Date	25/01/2018
Survey held at	31 CORPORATION RD		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	23-01-2018	Our Ref No. D18000734MFSH
Accident Date	23-01-2018	Claim Type. Third Party
Insured Vehicle	SHA9275P	Third Party Vehicle. SHB3799D
Survey Location	BLK 10, #01-20 SIN MING INDUSTRIAL ESTATE SECTOR C	
Contact Person.	ALEX KHONG	
Contact No.	64521208/ 83039588	Fax No. 64520614
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	DING AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

25012018 @ 11am
Mr. vkhin
31 Corporation Rd

Job Sheet (/ClaimWS/Surveyor/JobSheet/234235)



PRI Documents



Close



PRI Header Details

Claim No	D18000734MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & DII
Workshop Name	DING AUTOMOTIVE PTE LTD (Contact Person : ALEX KHONG)	Survey Location & Contact Details	BLK 10, #01-20 SIN MING INDUSTRIAL ESTAT Mobile: 83039588 , Phone: 64521208 , Fax: EmailId: TAXISCS@STENGG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9275P	TP Vehicle No	SHB37
PRI Recieved Date	23-01-2018 09:36:09 PM	Surveyor Appointed Date	24-01-2018 04:39:48 PM	Surveyor Accept Date	25-01-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	25-01-2018	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 30 January 2018 12:38 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000734MFSH/1, SHB 3799D
Attachments: SHB 3799D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 3799D
Date of survey: 25/1/2018
Number of days: 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 25 January 2018 10:12 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000734MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 January, 2018 4:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000734MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000734MFSH
Our Ref: CS/FCI18001537/R1vb

Date : 30/1/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 3799D


We thank you for your instruction on 24/1/2018

Please be informed that we had conducted the inspection of the above mentioned
25/1/2018 at the premises of M/s DING AUTO PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$16,731.17
Revised Estimate Amount	: S\$8,078.46
"Check" Items Amount	: S\$114.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2839G

Vehicle Details

Vehicle No.: SHB3799D

Vehicle to be Exported: No

Intended De-registration Date: 12 Mar 2018

Vehicle Make: HYUNDAI

Vehicle Model: SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour: Yellow

Manufacturing Year: 2012

Engine No.: D4EA7295917

Chassis No.: KMHET41VMCA829699

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,348.00

Original Registration Date: 27 Sep 2012

First Registration Date: 27 Sep 2012

Transfer Count: 0

Actual ARF Paid: \$14,348.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Sep 2020

PARF Rebate Amount: \$10,043.00

Intended COE Rebate Details

COE Expiry Date: 26 Sep 2020

COE Category: A - Car (1600cc & below)

COE Period(Years):	8
PQP Paid:	\$51,531.00
COE Rebate Amount:	\$16,353.00
Total Rebate Amount:	\$26,396.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2018 11:15
Date Of Accident	23/01/2018 00:30
Exact Location Of Accident	ALONG JALAN BESAR TOWARDS KITCHENER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB3799D
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 CRDI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY


Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D-15072702MFSH
Cover Note Number	

Driver

Name of Driver	CHIN YEN HING , WILLY
NRIC No	S7804852B
Date Of Birth	23/01/1978
Occupation	OUTDOOR
Date Of Driving Pass	21/09/1999
Driving Experience	18 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93636033
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	APT BLK 139 JALAN BUKIT MERAH #03-1456 SINGAPORE 160139
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH STATEMENT .

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NOT SUITABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA9275P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHIN YEN HING WILLY
------	---------------------



Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHB3799D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode



Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 2

SKETCH PLAN

A: SHB 37990
B: SHA 9275P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 23/1/2018 at about 00:30 Along
Jalan Besar Towards Kitchen Rd. I was stopping
waiting pedestrian traffic light. Suddenly this party vehicle:
(SHA 9275P) hit onto my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

高GAO

Express Towing Services

You Call, We Tow - Fast, Secured, Reliable



Bik 27 Marine Crescent Vile #10-01 Singapore 440027 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: <http://www.gaoexpress towing.sg>

CASH SALE/WORK ORDER

寶號

Messrs:

Ding Automobile

車號

車型

Vehicle No: SHB3799D Model No: Senat9

時間(日/夜)

Time (day/night): 01.12

Contact No: 93636033

由

Location:

JIN BESAR X KETCHENER RD

到

To:

Corporation Rd

Cash \$:

其他

Others:

USD

經手人

Authorised By:

Tow Truck

Driver Name:

YM765U

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

No. 134678

Date:

23/1/18

☐ Jump Start/Changing of battery

☐ Tyre Replacement

☒ Accident/Breakdown

☐ Multi/Baseament

☐ With Load/Cargo Box

☐ King Dolly

☐ Transport Charge

☐ Low Body Kit

☐ Door Opening Service

☐ Crane Up/Winch Out

☐ Collect Doc/Key

☐ Repo

☐ Woodlands and Tuas Checkpoint



DING AUTOMOTIVE PTE LTD

BLK 10, #01-20 SIN MING INDUSTRIAL EST, SEC C SINGAPORE 575645

TEL: 6432 1208 FAX: 6432 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

23/01/2018 16:23

JOB-NO: 50110472

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 3

VEHICLE DETAILS

LICENSE NO: SHB3799D TRANS: AUTO
MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHET41VMCA829699
ENGINE: D4EA7295917

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,800.00	0.00	1,800.00		Y	1400
2 R&R REAR WINDSCREEN GLASS	1.00	120.00	0.00	120.00		Y	120
3 R&R REAR FUEL TANK ASSY	1.00	120.00	0.00	120.00		Y	X 117
4 R&R REAR SPARE TYRE BOARD/CARPET/TRIM	1.00	80.00	0.00	80.00		Y	60
5 R&R REAR SEATS & CARPETS TO ASSIST REPAIR	1.00	80.00	0.00	80.00		Y	X 117
6 ADJUST TAIL LAMP AIM & CHECK WIRING	1.00	80.00	0.00	80.00		Y	30
7 RUST PROOFING	1.00	80.00	0.00	80.00		Y	60
8 SUNDRIES	1.00	50.00	0.00	50.00		Y	20
9 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	200
10 RESPRAY REAR FENDER RH	1.00	250.00	0.00	250.00		Y	200
11 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
12 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	200
13 RESPRAY REAR SPRAY TYRE BOARD	1.00	250.00	0.00	250.00		Y	200
14 RESPRAY BOOTLID	1.00	250.00	0.00	250.00		Y	200
15 TOWING CHARGES	1.00	100.00	0.00	100.00		Y	40 ? receipt
16 MOUNT WORK BENCH	1.00	300.00	0.00	300.00		Y	X 117
TOTAL:		4,310.00	0.00	4,310.00			
<u>MATERIALS</u>							
1 REAR BUMPER DE	1.00	523.93	0.00	523.93	L	Y	DE
2 REAR BUMPER REINFORCEMENT CRA	1.00	462.30	0.00	462.30	L	Y	CRA
3 REAR BUMPER RETAINER LH nee	1.00	42.68	0.00	42.68	L	Y	nee
4 REAR BUMPER RETAINER RH nee	1.00	42.68	0.00	42.68	L	Y	nee
5 REAR BUMPER BRACKET LH nee	1.00	79.75	0.00	79.75	L	Y	nee
6 REAR BUMPER BRACKET RH nee	1.00	79.75	0.00	79.75	L	Y	nee
7 REAR BUMPER SPONGE CRA	1.00	113.52	0.00	113.52	L	Y	CRA
8 REAR BUMPER PROTECTOR LH DE	1.00	102.96	0.00	102.96	L	Y	DE
9 REAR BUMPER PROTECTOR RH X	1.00	102.96	0.00	102.96	L	Y	X 117
10 REAR BUMPER LWR EXT DE	1.00	40.70	0.00	40.70	L	Y	DE
11 REAR BUMPER LWR COVER LH cut	1.00	38.83	0.00	38.83	L	Y	cut
12 BOOTLID PA	1.00	1,139.00	0.00	1,139.00	L	Y	PA
13 BOOTLID EMBLEM-LOGO nee	1.00	21.45	0.00	21.45	L	Y	nee
14 BOOTLID EMBLEM-HYUNDAI nee	1.00	20.13	0.00	20.13	L	Y	nee
15 BOOTLID EMBLEM-SONATA nee	1.00	40.92	0.00	40.92	L	Y	nee
16 BOOTLID EMBLEM-CRDI nee	1.00	18.70	0.00	18.70	L	Y	nee

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 BOOTLID LAMP LH <i>CRA /</i>	1.00	203.50	0.00	203.50	L	Y	<i>/</i>
18 BOOTLID LAMP RH <i>CRA /</i>	1.00	203.50	0.00	203.50	L	Y	<i>/</i>
19 BOOTLID PLATE LAMP LH <i>X</i>	1.00	49.50	0.00	49.50	L	Y	<i>X</i>
20 BOOTLID PLATE LAMP RH <i>X</i>	1.00	49.50	0.00	49.50	L	Y	<i>X</i>
21 BOOTLID HINGE LH <i>X</i>	1.00	109.45	0.00	109.45	L	Y	<i>X</i>
22 BOOTLID HINGE RH <i>X</i>	1.00	109.45	0.00	109.45	L	Y	<i>X</i>
23 BOOTLID LOCK <i>PA /</i>	1.00	109.45	0.00	109.45	L	Y	<i>/</i>
24 BOOTLID LOCK CATCH <i>PA /</i>	1.00	108.90	0.00	108.90	L	Y	<i>/</i>
25 BOOTLID INSULATOR <i>PA /</i>	1.00	155.10	0.00	155.10	L	Y	<i>/</i>
26 BOOTLID RUBBER BEADING <i>PA /</i>	1.00	91.30	0.00	91.30	L	Y	<i>/</i>
27 BOOTLID DAMPER LH <i>X</i>	1.00	104.50	0.00	104.50	L	Y	<i>X</i>
28 BOOTLID DAMPER RH <i>X</i>	1.00	104.50	0.00	104.50	L	Y	<i>X</i>
29 BOOTLID KEY LOCK <i>PA /</i>	1.00	109.01	0.00	109.01	L	Y	<i>/</i>
30 BOOTLID CABLE <i>X</i>	1.00	109.02	0.00	109.02	L	Y	<i>X</i>
31 REAR END PANEL <i>PA /</i>	1.00	323.29	0.00	323.29	L	Y	<i>/</i>
32 REAR END PANEL TOP GARNISH <i>CRA /</i>	1.00	42.02	0.00	42.02	L	Y	<i>/</i>
33 TAIL LAMP LH <i>CRA /</i>	1.00	323.40	0.00	323.40	L	Y	<i>/</i>
34 TAIL LAMP RH <i>CRA /</i>	1.00	323.40	0.00	323.40	L	Y	<i>/</i>
35 TAIL LAMP INNER PANEL LH <i>R</i>	1.00	267.30	0.00	267.30	L	Y	<i>R</i>
36 TAIL LAMP INNER PANEL RH <i>R</i>	1.00	267.30	0.00	267.30	L	Y	<i>R</i>
37 SPARE TYRE PANEL <i>PA /</i>	1.00	812.90	0.00	812.90	L	Y	<i>/</i>
38 SPARE TYRE BOARD <i>X</i>	1.00	162.14	0.00	162.14	L	Y	<i>X</i>
39 SPARE TYRE SIDE PANEL LH <i>R</i>	1.00	179.30	0.00	179.30	L	Y	<i>R</i>
40 SPARE TYRE SIDE PANEL RH <i>R</i>	1.00	179.30	0.00	179.30	L	Y	<i>R</i>
41 SPARE TYRE TYRE LOCK <i>?</i>	1.00	18.00	0.00	18.00	L	Y	<i>X</i>
42 REAR FENDER LH <i>R</i>	1.00	1,598.30	0.00	1,598.30	L	Y	<i>R</i>
43 REAR FENDER RH <i>R</i>	1.00	1,598.30	0.00	1,598.30	L	Y	<i>R</i>
44 REAR WINDSCREEN MLDG <i>X</i>	1.00	49.28	0.00	49.28	L	Y	<i>X</i>
45 REAR BUMPER ADS STICKER <i>PA /</i>	1.00	180.00	0.00	180.00	S	Y	<i>100</i>
46 REAR BUMPER RUBBER PROTECTOR PAD <i>X</i>	1.00	150.00	0.00	150.00	S	Y	<i>X</i>
47 BOOTLID STICKER-CAB BOOKING 65521111 <i>PA /</i>	1.00	40.00	0.00	40.00	S	Y	<i>/</i>
48 BOOTLID STICKER-CITY CAB <i>PA /</i>	1.00	40.00	0.00	40.00	S	Y	<i>/</i>
49 BOOTLID ADS STICKER <i>X</i>	1.00	250.00	0.00	250.00	S	Y	<i>X</i>
50 SBOOTLID INSULATOR CLIP SET <i>PA /</i>	1.00	35.00	0.00	35.00	S	Y	<i>/</i>
51 REAR NUMBER PLATE <i>PA /</i>	1.00	35.00	0.00	35.00	S	Y	<i>/</i>
52 REAR END PANEL SEALANT <i>PA /</i>	1.00	50.00	0.00	50.00	S	Y	<i>/</i>
53 SPARE TYRE PANEL INSULATOR PAD <i>X</i>	1.00	280.00	0.00	280.00	S	Y	<i>X</i>
54 SPARE TYRE PANEL SEALANT <i>PA /</i>	1.00	50.00	0.00	50.00	S	Y	<i>/</i>
55 REAR FENDER SEALANT LH <i>X</i>	1.00	50.00	0.00	50.00	S	Y	<i>X</i>
56 REAR FENDER ADS STICKER LH <i>PA /</i>	1.00	250.00	0.00	250.00	S	Y	<i>150</i>
57 REAR FENDER SEALANT RH <i>X</i>	1.00	50.00	0.00	50.00	S	Y	<i>X</i>
58 REAR FENDER ADS STICKER RH <i>PA /</i>	1.00	250.00	0.00	250.00	S	Y	<i>150</i>
59 REAR WINDSCREEN GLASS INNER SEAL <i>PA /</i>	1.00	30.00	0.00	30.00	S	Y	<i>/</i>
60 REAR WINDSCREEN GLASS SEALANT <i>PA /</i>	1.00	50.00	0.00	50.00	S	Y	<i>/</i>
TOTAL:		12,421.17	0.00	12,421.17			
TOTAL PARTS & LABOUR :		16,731.17	0.00	16,731.17			

EXCESS/LOADING:SS 0.00

No. Of Day: *12 days*RE-SURVEY: BEFORE *AFTER* PAINTING
PART-BY-PART OR *LUMP SUM: SS*DATE OF SURVEY: *24 / 01 / 18 @ 1400*SURVEYED BY: *RASUL (LKK)*CONTACT NO: *90010068* FAX NO:email: *rasul@lkkauto.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ref:00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 12 March 2018 4:37 PM
To: 'Accounts Ding Auto'
Cc: Rasul (LKKAUTO); SUR; Kenneth Ding; DAMtaxi
Subject: RE: FW: SHB3799D-Finalize Amount & After Repair Photo.

Dear Michelle,

Noted with thanks.

Final invoice and all supporting documents sent to First Capital Ins Ltd. OIC AUNG YIN MIN (REF: D18000734MFSH)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accounts Ding Auto [mailto:accounts@dingauto.sg]
Sent: Monday, 12 March 2018 4:08 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Kenneth Ding <kenneth.ding@dingauto.sg>; DAMtaxi <TAXISCS@stengg.com>
Subject: Re: FW: SHB3799D-Finalize Amount & After Repair Photo.

Dear Veron,

We confirm the finalize amount.

Thank you so much.

Yours Sincerely,
Fang XinYi Michelle
Office Contact : 92394128
Ding Automotive Pte Ltd

On Mon, Mar 12, 2018 at 11:25 AM, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Michelle,

Kindly confirmed Lump Sum \$6450.

No of days: 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, [Ubi Avenue 1, #02-25](#) | S(408933)

From: Accounts Ding Auto [<mailto:accounts@dingauto.sg>]

Sent: Monday, 12 March 2018 9:50 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Kenneth Ding <kenneth.ding@dingauto.sg>; DAMtaxi <TAXISCS@stengg.com>

Subject: Re: FW: SHB3799D-Finalize Amount & After Repair Photo.

Morning all,

Please advice the finalize amount for this case as we still have not receive any update from you till today.

Kindly check and update us as soon as possible.

Thank you so much.

Yours Sincerely,

Fang XinYi Michelle

Office Contact : 92394128

Ding Automotive Pte Ltd

On Tue, Feb 27, 2018 at 9:26 AM, Accounts Ding Auto <accounts@dingauto.sg> wrote:

Morning all,

Please advice the finalize amount for this case as we still have not receive any update from you till today.

Kindly check and update us as soon as possible.

Thank you so much.

Yours Sincerely,

Fang XinYi Michelle

Office Contact : 92394128

Ding Automotive Pte Ltd

On Fri, Feb 23, 2018 at 4:27 PM, Accounts Ding Auto <accounts@dingauto.sg> wrote:

Dear all,

Please advice the finalize amount for this case as we still have not receive any update from you till today.

Kindly check and update us as soon as possible.

Thank you so much.

Yours Sincerely,

Fang XinYi Michelle

HP Contact : 87483145

Office Contact : 92394128

Ding Auto Pte Ltd

Ding Automotive Pte Ltd

On Mon, Feb 5, 2018 at 9:10 AM, Asher Sng (LKKAUTO) <AsherSng@lkkauto.com> wrote:

Hi Veron / Rasul,

FYA.

CS/FCI18001537/R1vb

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: taxiscs@stengg.com [<mailto:taxiscs@stengg.com>]

Sent: Monday, 5 February 2018 8:54 AM

To: Rasul (LKKAUTO) <Rasul@lkkauto.com>

Cc: ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG

Subject: SHB3799D-Finalize Amount & After Repair Photo.

Hi rasul ,

Please see below for the finalize according to our conversion to finalize for SHB3799D

Finalize Amount

Total Repair - 12 Days

Labour - \$2930

Special Netts - \$730

Parts - \$5573.07

Parts after 20% discount =\$4458.45

Total L+S+P =\$8118.45 -20% LUMP SUM

Final Amount = \$6494.76

Please help to close this case ASAP

Thanks

Best Regards

Ding Automotive Pte Ltd

Alex Khong

Hp :65508768

ST Engineering. Strength in action

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Dps Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001537/R1vbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-03-2018



Code : FCI2

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SHA 9275P	Veh. Inspected	SHB 3799D
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18000734MFSH	Excess (\$)	0.00
Assign From	AUNG YIN MIN	Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA 2.0	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KMHET41VMCA829699	Colour	YELLOW
Odometer	107049	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	TRIANGLE	5 mm
L/H Front Tyre	215/60 R16	TRIANGLE	5 mm
R/H Rear Tyre	215/60 R16	TRIANGLE	5 mm
L/H Rear Tyre	215/60 R16	TRIANGLE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/01/2018	Inspection Date	25/01/2018
Survey held at	31 CORPORATION RD		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3799D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	523.93	523.93
1	REAR BUMPER REINFORCEMENT	CRACKED	462.30	462.30
1	REAR BUMPER RETAINER LH	NECESSARY	42.68	42.68
1	REAR BUMPER RETAINER RH	NECESSARY	42.68	42.68
1	REAR BUMPER BRACKET LH	NECESSARY	79.75	79.75
1	REAR BUMPER BRACKET RH	NECESSARY	79.75	79.75
1	REAR BUMPER SPONGE	CRACKED	113.52	113.52
1	REAR BUMPER PROTECTOR LH	DEFORMED	102.96	102.96
1	REAR BUMPER PROTECTOR RH	SERVICEABLE	102.96	-
1	REAR BUMPER LWR EXT	DEFORMED	40.70	40.70
1	REAR BUMPER LWR COVER LH	CUT	38.83	38.83
1	BOOTLID	BENT	1,139.00	1,139.00
1	BOOTLID EMBLEM - LOGO	NECESSARY	21.45	21.45
1	BOOTLID EMBLEM - HYUNDAI	NECESSARY	20.13	20.13
1	BOOTLID EMBLEM - SONATA	NECESSARY	40.92	40.92
1	BOOTLID EMBLEM - CRDI	NECESSARY	18.70	18.70
1	BOOTLID LAMP LH	CRACKED	203.50	203.50
1	BOOTLID LAMP RH	CRACKED	203.50	203.50
1	BOOTLID PLATE LAMP LH	SERVICEABLE	49.50	-
1	BOOTLID PLATE LAMP RH	SERVICEABLE	49.50	-
1	BOOTLID HINGE LH	SERVICEABLE	109.45	-
1	BOOTLID HINGE RH	SERVICEABLE	109.45	-
1	BOOTLID LOCK	BENT	109.45	109.45
1	BOOTLID LOCK CATCH	BENT	108.90	108.90
1	BOOTLID INSULATOR	TORN	155.10	155.10
1	BOOTLID RUBBER BEADING	NECESSARY	91.30	91.30
1	BOOTLID DAMPER LH	SERVICEABLE	104.50	-
1	BOOTLID DAMPER RH	SERVICEABLE	104.50	-
1	BOOTLID KEY LOCK	BENT	109.01	109.01
1	BOOTLID CABLE	SERVICEABLE	109.02	-
1	REAR END PANEL	BENT	323.29	323.29

Report Ref No. CS/FCI18001537/R1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL TOP GARNISH	CRACKED	42.02	42.02
1	TAIL LAMP LH	CRACKED	323.40	323.40
1	TAIL LAMP RH	CRACKED	323.40	323.40
1	TAIL LAMP INNER PANEL LH	TO REPAIR SEE LABOUR	267.30	-
1	TAIL LAMP INNER PANEL RH	TO REPAIR SEE LABOUR	267.30	-
1	SPARE TYRE PANEL	BUCKLED	812.90	812.90
1	SPARE TYRE BOARD	SERVICEABLE	162.14	-
1	SPARE TYRE SIDE PANEL LH	TO REPAIR SEE LABOUR	179.30	-
1	SPARE TYRE SIDE PANEL RH	TO REPAIR SEE LABOUR	179.30	-
1	SPARE TYRE LOCK	SERVICEABLE	18.00	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,598.30	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,598.30	-
1	REAR WINDSCREEN MLDG	NOT NECESSARY	49.28	-
	LESS 20% DISCOUNT		-	-1,114.61
			10,631.17	4,458.46
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	REAR BUMPER ADS STICKER (SN)	NECESSARY	180.00	100.00
1	REAR BUMPER RUBBER PROTECTOR PAD (SN)	SERVICEABLE	150.00	-
1	BOOTLID STICKER - CAB BOOKING 65521111 (SN)	NECESSARY	40.00	40.00
1	BOOTLID STICKER - CITY CAB (SN)	NECESSARY	40.00	40.00
1	BOOTLID ADS STICKER (SN)	NOT NECESSARY	250.00	-
1	SET BOOTLID INSULATOR CLIP (SN)	NECESSARY	35.00	35.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	35.00	35.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SPARE TYRE PANEL INSULATOR PAD (SN)	NOT NECESSARY	280.00	-
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FENDER SEALANT LH (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER ADS STICKER LH (SN)	NECESSARY	250.00	150.00

Report Ref No. CS/FCI18001537/R1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER SEALANT RH (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER ADS STICKER RH (SN)	NECESSARY	250.00	150.00
1	REAR WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	30.00	30.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	50.00	50.00
			1,840.00	750.00
	LABOUR			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF TAIL LAMP INNER PANEL LH, TAIL LAMP INNER PANEL RH, SPARE TYRE SIDE PANEL LH, SPARE TYRE SIDE PANEL RH, REAR FENDER LH AND REAR FENDER RH.		1,800.00	1,400.00
	R&R REAR WINDSCREEN GLASS.		120.00	120.00
	R&R REAR FUEL TANK ASSY.	NOT NECESSARY	120.00	-
	R&R REAR SPARE TYRE BOARD/CARPET/TRIM.		80.00	60.00
	R&R REAR SEATS & CARPETS TO ASSIST REPAIR.	NOT NECESSARY	80.00	-
	ADJUST TAIL LAMP AIM & CHECK WIRING.		80.00	30.00
	RUST PROOFING.		80.00	60.00
	RESPRAY REAR FENDER LH.		250.00	200.00
	RESPRAY REAR FENDER RH.		250.00	200.00
	RESPRAY REAR BUMPER.		250.00	200.00
	RESPRAY REAR END PANEL.		250.00	200.00
	RESPRAY REAR SPRAY TYRE BOARD.		250.00	200.00
	RESPRAY BOOTLID.		250.00	200.00
	TOWING CHARGES.		100.00	40.00
	MOUNT WORK BENCH.	NOT NECESSARY	300.00	-
			4,260.00	2,910.00
GRAND TOTAL			16,731.17	8,118.46

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,450.00
---	--	--	-----------------

Report Ref No. CS/FCI18001537/R1vbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.