

ASS. REC. BY:

REF: CS / ATG 18001540 / Kgbn2 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office) ✓

From (Person): Normanese

of

ATGDate/Time: 25/01/2018 2:04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 6243G

Insured:

SGE 9797R

at Workshop m/s

Trust Autoworks

Tel:

9108 2728

of

Blk 5035 AMK Incl Park 2 # 01-345

Policy No:

2109412129

Claim No:

111028405756

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/01/2018

(Client's Record)

26/01/2018CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement:

Date/Time: 25/01/2018 2:33pm

Person Contacted:

AnthonyVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLJ 6243G - x</u>
	<u>SGE 9797R - x</u>
<u>20/12</u>	<u>11 Hrs @ 49000 Confirm (Red @ 3587.30, 42%)</u>

ALG

26/01/2018

SLJ 6243G

12 16

0

SLJ 6243G

Trust Autoworks

BLK 5035, AMK Ind. Park 2 # 01-315


Bmw A1 320i

1998

M. P. White

44111

WBA 8A16080N4 39847



225/50R17

SS SUN BANDVA G- PS L24 M-C OHTSLER SWI  
TOYOTA YOKO

Item	7	7	7
PS	7	7	7
LS	7	7	7
CS	24/1/18	24/1/18	26/1/18

29/1 File pass to Catherine, EM & GIA not ready

RECEIVED 22 FEB 2018

wp/kyr



Prep. Report

Final Report

Days Of Report

3

Resurvey No. of Ties

1

M&R-TP

490

250

20

270



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18001540/Kqb

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 25-01-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGE 9797R	Veh. Inspected	SLJ 6243G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	NOOR MARIESA	Assign Date	25/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	24/01/2018	Inspection Date	25/01/2018
Survey held at	BLK 5038 AMK IND PARK 2 #01-405		
Repairer	TRUST AUTOWORKS		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# Survey Department Check List (Case Handler)

Reference No.: 03/AIG/1800549/Kqb  
Policy Type: OD/TP/TP RES/TL/EVA

SLJ 67436

Case Handler

Typist

**Admin** ( Cath ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA/REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

**Surveyor** ( Kenneth ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

	Y-Date	N-Date	Y-Date	N-Date
C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

## (2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓		
--	---	--	--

## (3) Workshop Estimate/Assignment Form

N ALL Parts condition	✓		
C Market Value for OD cases			
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
C Days of repair	✓		
C Finalised Amount	✓		
C Re-inspection Cases to Finalize within 5 Days			

## (4) System - (Views/Merimen)

C Resurvey photo Uploaded	✓		
---------------------------	---	--	--

Check By:

Chris 27/7/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014

## Catherine Chong (LKK Auto)

---

**From:** Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>  
**Sent:** Thursday, 25 January, 2018 2:04 PM  
**To:** 'assignments@lkkauto.com'; 'admin-a@lkkauto.com'  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene  
**Subject:** aigencrypt - Pre repair inspection request - SLJ6243G VS SGE9797R (OI) DOA: 24/01/2018  
**Attachments:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGE97... (55.4 KB); 20180125105943937.pdf

Hi,

Please refer to the enclosed request from **Chia S Arul LLC**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.*

Thank you.

Best Regards,

Mariesa Abu Kassim

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

---

Our Ref : SLJ 6243G

Your Ref :

25 January 2018

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way #08-16  
Chartis Building  
Singapore 079120

**BY EMAIL**

Dear Sir,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : LYE CHEE BOON**  
**ACCIDENT INVOLVING SLJ 6243G & SGE 9797R ALONG CARPARK OF BLK**  
**683 HOUGANG AVE 8 ON 24/1/18**

1. We act for **Lye Chee Boon**, the owner of motor vehicle no. SLJ 6243G, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SGE 9797R for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Trust Autoworks at Blk 5035 #01-345 Ang Mo Kio Industrial Pk 2 Singapore 569538 and kindly arrange with Mr Anthony Cheong at T: 9108 2728.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to [kelly@chiaarul.com](mailto:kelly@chiaarul.com).

Yours faithfully,



**MR ARULCHELVAN S**

cc: Client (By email)

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/01/2018 09:56
Date Of Accident	24/01/2018 14:00
Exact Location Of Accident	BLK 683 HOUGANG AVE 8 (CARPARK)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ6243G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LYE CHEE BOON (LAI ZHIWEN)
NRIC No	S7131569Z
Email Address	WILLIAMLCB@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90088431
Alternative Phone No	OTHERS-90088431

### Vehicle Particulars

Manufacturer	BMW
Model	320I LED NAV

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1880177
Cover Note Number	

### Driver

Name of Driver	LYE CHEE BOON (LAI ZHIWEN)
NRIC No	S7131569Z
Date Of Birth	09/09/1971
Occupation	INDOOR
Date Of Driving Pass	21/04/1993
Driving Experience	24 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90088431
Fax Number	
Contact Number	OTHERS-90088431
Email Address	WILLIAMLCB@GMAIL.COM



Address	BLK 178 EDGEFIELD PLAINS #16-226
Postcode	820178
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : OVANN LYE GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG TO SEND THROUGH EMAIL
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGE9797R
Vehicle Make/Model/Colour	TOYOTA / ALTIS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN GECK HUAH
NRIC/Passport Number	S0092513F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature


Date & Time:

25/01/18  
10.00 Am

  
Driver's Signature

(If driver is not the policyholder)

Date & Time:

  
Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
Hp 91082728

Lye Chee Boon  
Blk 178 Edgefield Plains  
#16-225  
Singapore 820178

Vehicle No : SLJ 6243 G  
Make/Model : BMW 320 I  
Year : 2017

*Not Authorised*  
*1-B1*  
*Resny B4 paint*  
*2-3 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Front n/s headlamp assy
1 pc	Front bumper
1 pc	Front bumper reinforcement
1 pc	Front bumper sponge
1 pc	Front n/s bumper side retainer
2 pcs	Front n/s bumper sensor
1 pc	Front n/s fender innershield
1 pc	Front n/s fog lamp assy
1 pc	Front n/s fog lamp garnish
1 pc	Front n/s fog lamp garnish chrome finisher
1 pc	Front n/s radiator grille

<i>Ln</i>	\$3,092.00	<i>✓</i>
<i>Br Ind</i>	\$1,285.00	<i>✓</i>
<i>n</i>	\$685.00	<i>X</i>
	\$235.00	<i>7 ✓ CHA</i>
	\$95.00	<i>7 ✓ VMS</i>
<i>\$265.00</i>	\$530.00	<i>7 ✓ short</i>
<i>Ln</i>	\$255.00	<i>X</i>
	\$485.00	<i>7 ✓ mtg era</i>
<i>Ln</i>	\$275.00	<i>✓</i>
	\$205.00	<i>7 ✓ SCH</i>
<i>Ln</i>	\$305.00	<i>X</i>
	\$7,447.00	
Less 10 %	\$744.70	
	\$6,702.30	

## S Nett Item

15 pcs Rear bumper clip

*Ln* \$4.00 \$60.00 *✓*

## Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$700.00 *300*

To putty and spray paint

\$700.00 *320*

Check and reconnect wiring.

\$45.00 *20*

Remove/renew front bumper sensor and to reset same

\$280.00 *80*

Total

\$8,487.30

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kg

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
Hp 91082728

Lye Chee Boon  
Blk 178 Edgefield Plains  
#16-225  
Singapore 820178

Vehicle No : SLJ 6243 G  
Make/Model : BMW 320 I  
Year : 2017

Not Authorised  
HBT  
Resny B4 paint  
:- 3 days  
L1 Bny \$ 4900h

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Front n/s headlamp assy
1 pc	Front bumper
1 pc	Front bumper reinforcement
1 pc	Front bumper sponge
1 pc	Front n/s bumper side retainer
2 pcs	Front n/s bumper sensor
1 pc	Front n/s fender innershield
1 pc	Front n/s fog lamp assy
1 pc	Front n/s fog lamp garnish
1 pc	Front n/s fog lamp garnish chrome finisher
1 pc	Front n/s radiator grille

Br	Ln	\$3,092.00	✓
Br	Ln	\$1,285.00	✓
	n	\$685.00	X
	cm	\$235.00	✓
	n	\$95.00	✓
Shon	\$265.00	\$530.00	✓
	Ln	\$255.00	X
	mg cm	\$485.00	✓
	Ln	\$275.00	✓
	Ln	\$205.00	✓
	Ln	\$305.00	X
		\$7,447.00	
	Less 10 %	\$744.70	
		\$6,702.30	

## S Nett Item

15 pcs	Rear bumper clip
--------	------------------

Ln	\$4.00	\$60.00	✓
----	--------	---------	---

## Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$700.00	300h
----------	------

To putty and spray paint

\$700.00	320h
----------	------

Check and reconnect wiring.

\$45.00	20h
---------	-----

Remove/renew front bumper sensor and to reset same

\$280.00	80h
----------	-----

Total

\$8,487.30
------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18001540/KQBN2

Date: 23/02/2018

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100412129
Claimant Vehicle No :	SLJ6243G	Insured Vehicle No :	SGE9797R
Date of Loss:	24/01/2018	Nature of Claim:	TP
		Claim No:	1110284057SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLJ6243G	Engine No:	20119713B48B20A
Make & Model:	BMW 320i, 2.0 SEDAN LED NAV (A)	Chassis No:	WBA8A16080NU39847
Reg. Date:	20/12/2016 (Man. Year: 2016)	Odometer:	44111 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,762.30	5,403.30	1,359.00	20.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,725.00	720.00	1,005.00	58.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,487.30</b>	<b>6,123.30</b>	<b>2,364.00</b>	<b>27.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,487.30</b>	<b>4,900.00</b>	<b>3,587.30</b>	<b>42.27</b>

## INSPECTION

Date of Assignment:	25/01/2018	
Date Inspected:	26/01/2018	Inspected At:
		Trust Autoworks - Ang Mo Kio (HQ)
		Blk 5035, #01-345 Ang Mo Kio Industrial
		Pk 2
		Singapore 569538

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEADLAMP ASSY	Cut	3,092.00 FL	*3,092.00 FL
2	1		*FRONT BUMPER	Buckled/Dented	1,285.00 FL	*1,285.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	685.00 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Cracked	235.00 FL	*235.00 FL
5	1		*FRONT N/S BUMPER SIDE RETAINER	Distorted	95.00 FL	*95.00 FL
6	2		*FRONT N/S BUMPER SENSOR	Shorted (1 pc only)	530.00 FL	*265.00 FL
7	1		*FRONT N/S FENDER INNERSHIELD	Serviceable	255.00 FL	*- FL
8	1		*FRONT N/S FOG LAMP ASSY	Mtg Cracked	485.00 FL	*485.00 FL
9	1		*FRONT N/S FOG LAMP GARNISH	Cut	275.00 FL	*275.00 FL
10	1		*FRONT N/S FOG LAMP GARNISH CHROME FINISHER	Scratched	205.00 FL	*205.00 FL
11	1		*FRONT N/S RADIATOR GRILLE	Serviceable	305.00 FL	*- FL
12	15		*REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,507.00</b>	<b>5,997.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>744.70</b>	<b>593.70</b>
<b>Total Parts (\$\$)</b>	<b>6,762.30</b>	<b>5,403.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	700.00	300.00
2	TO PUTTY AND SPRAY PAINT	New	700.00	320.00
3	CHECK AND RECONNECT WIRING	New	45.00	20.00
4	REMOVE/RENEW FRONT BUMPER SENSOR AND TO RESET SAME	New	280.00	80.00
Gross Labour Cost (S\$)			<b>1,725.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >