



SLD3879Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 1/23/18

Vehicle Reg. No. : SLD3879Z
Vehicle Reg. Date: 15-Jun-2016
Make / Model : COROLLA AXIO 1.5G CVT
Engine No. : 2NR8500587
Chassis No. : NRE1610009698

COST OF CLAIMS

Parts Cost / List Items : \$ 10,199.60
Plus/Less 25% \$ 2,549.90
Total Cost / List : \$ 7,649.70
Special Nett Items : \$ 540.00
Total Parts Amount : \$ 8,189.70
Total Labour Amount : \$ 3,350.00
Gross Total : \$ 11,539.70
GST % : 7% \$ 807.78
Nett Amount : \$ 12,347.48

Surveyor Name and Company :

RASUL (LKK)

Date of survey : 25/01/18 @ 1620

Part by Part / Lump Sum : 6 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : rasul@lkkauto.com

Fax No : _____

HP No : 90010068

This claim is handled by : Edmond

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD3879Z**
 Vehicle Reg. Date: **6/15/16**
 Make / Model : **COROLLA AXIO 1.5G CVT ABS D/AIRBAG 2W**
 Engine No. : **2NR8500587**
 Chassis No. : **NRE1610009698**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear bumper	DE ✓	\$ 1,486.00		
2	1	Rear bumper reflector LH	✓	\$ 185.00		
3	1	Rear bumper retainer LH	neu ✓	\$ 172.00		
4	1set	Rear bumper clip - set	neu ✓	\$ 64.00		
5	1	Taillamp LH	SCA ✓	\$ 1,200.00		
6	1	Taillamp panel LH	R	\$ 1,024.00		
7	1set	Taillamp clip - set	neu ✓	\$ 30.00		
8	1	Taillamp lower bracket LH	✓	\$ 330.00		
9	1	Rear end panel	R	\$ 663.00		
10	1	Rear end panel top garnish	✓	\$ 241.00		
11	1set	Rear end panel top garnish clip	neu ✓	\$ 40.00		
12	1	Rear impact bracket LH	✓	\$ 348.00		
13	1	Rear fender LH	R	\$ 835.00		
14	1	Rear fender side board LH	DE ✓	\$ 344.00		
15	1set	Rear fender side board clip	neu ✓	\$ 50.00		
16	1	Rear fender inner shield LH	X	\$ 90.00		
17	1set	Rear fender inner shield clips	X	\$ 40.00		
18	1	Rear fender air duct LH	X	\$ 79.00		
19	1	Rear boot	R	\$ 1,093.00		
20	1	Rear boot emblem - Logo	neu ✓	\$ 60.00		
21	1	Rear boot emblem - Corrolla	neu ✓	\$ 67.00		
22	1	Rear boot emblem - Axio	neu ✓	\$ 69.00		
23	1	Rear boot weatherstrip	X Repaired	\$ 212.00		
24	1	Rear boot insulator paste	X	\$ 298.60		
25	1set	Rear boot insulator clip - set	X	\$ 50.00		
26	2	Rear boot hinge	X	\$ 575.00		
27	1	Rear boot chrome garnish	X	\$ 312.40		
28	1set	Rear boot chrome garnish clip - set	X	\$ 30.00		
29	1	Rear boot weatherstrip	neu ✓	\$ 211.60		
30	1	Reverse sensor	DS ✓		\$ 300.00	200
31	1	Taillamp seal			\$ 80.00	X
32	1	Rear end panel sealant			\$ 80.00	X
33	1	Rear fender sealant			\$ 80.00	X
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1