



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR L PRAVIN KUMAR
83 FLORA DRIVE
#02-36 SINGAPORE 506887

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : GBA 9280 U (AXA)
OUR REF : TP 5862
VEHICLE NO : FBA 3559 G
MAKE/MODEL : YAMAHA SPARK
DATE OF ACCIDENT : 24.12.17

SURVEY BY

DATE : 23.01.18

- 1 SET FAIRING ASSY *s.de*
- 1 SET REAR BUMPER
- 1 PC TAILLAMP
- 1 PC REAR EXHAUST RIM
- 1 PC REAR FENDER
- 1 PC REAR RIM SHAFT
- 1 PC REAR RIM BEARING
- 1 PC SWING ARM
- 1 PC REAR KEY SET LOCK ASSY

SS	<i>one</i>	425.00	—
	<i>NS</i>	350.00	X
	<i>one</i>	135.00	—
	<i>11</i>	280.00	X
	<i>de</i>	120.00	—
		45.00	?
		38.00	?
		365.00	?
	<i>2</i>	65.00	X
SS		1,823.00	
LESS	10%	182.30	
SS		1,640.70	

- 1 PC REAR NO. PLATE
- 1 PC REAR BOX
- 1 PC REAR BOX BRACKET
- 1 PC REAR TYRE
- 1 PC SWING ARM BUSH

SS	<i>Sub</i>	18.00	<i>105.00</i>
	<i>1/c cut</i>	180.00	X " S/NETT
	<i>11</i>	100.00	X "
	<i>11</i>	120.00	X "
		55.00	?
SS		473.00	

TO CHECK WIRING FUNCTION

SS *11* 80.00 X

LABOUR CHARGES

380.00 *200*

SS 2,573.70

SIN DOLLARS: TWO THOUSAND FIVE HUNDRED SEVENTY-THREE AND CENTS SEVENTY ONLY

YOUR FAITHFULLY,

Not Authorized
here
2/5
3 day
30/1/18
to be signed

I KK Auto Consultants hence notify
CYS AUTOMOBILE SERVICES PTE LTD

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg