

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKA8887U (AXA)

Accident Date : 19-01-2018

Our Ref : SJQ3837A / CHAN

CHIN HUI CAR RENTAL

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. EST. SECTOR C

01-76

SINGAPORE 575642

Date : 24-01-2018

*Not Authorise
11 Pym & ?
Resurvey After Paim
3 days*

ESTIMATE COST OF REPAIR FOR TOYOTA ALTIS 1.6 (A) SJQ3837A

| | | | | |
|-------|-------------------------------------|--------------|-------------------|---|
| 1 PC | REAR BUMPER FASCIA | <i>Bu in</i> | \$459.80 | ✓ |
| 2 PCS | REAR BUMPER BRACKET @ \$82.80 | <i>R</i> | \$165.60 | X |
| 1 PC | REAR BUMPER REINFORCEMENT | | \$117.50 | ? |
| 2 PCS | REAR BUMPER SIDE RETAINER @ \$51.20 | <i>Sn</i> | \$102.40 | X |
| 1 PC | REAR END PANEL | <i>R</i> | \$552.30 | X |
| 1 PC | END PANEL TOP GARNISH | <i>Sn</i> | \$185.30 | X |
| | | | <u>\$1,582.90</u> | |
| | | | LESS 25% | |
| | | | <u>\$395.73</u> | |
| | | | <u>\$1,187.17</u> | |

\$1,187.17

1 SET REAR BUMPER REVERSE SENSOR

Shay \$300.00 SN *2005n*

TO APPLY UNDERSEALING

nn \$60.00 X

TO PUTTY AND SPRAY REPLACED PARTS

\$500.00 *Poc*

TO PANEL BEATING, CUT OUT DAMAGED PARTS, ADJUST, ALIGN & REFIX ABOVE PARTS

\$600.00 *300*

\$2,647.17

Singapore Dollars Two Thousand Six Hundred Forty Seven And Cents Seventeen Only

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: