

Industrial Vehicles.
20,000 Served. And Counting.

DATE : 25/1/2018
TO : CHINA TAIPING INSURANCE SINGAPORE PTE. LTD.
ATTN : MOTOR CLAIMS DEPT
OFFICE / MOBILE :
EMAIL ADDRESS :

FROM : GOLDBELL ENGINEERING PTE LTD (PANDAN)
ATTN : ANDY OOI
MOBILE/ EMAIL : 67730073
FAX NO. : 67730928

VEHICLE NO. : SGA5926H
MODEL NO. : MITSUBISHI AIRTREKT SR
CHASSIS NO. : JMYLYCU2W5U000611
ENGINE NO. : 4G63LM1267
REG. DATE : 22/11/2005

REF. NO. : GBP/SVC/SALES-
D.O.A. : 11/1/2018
POLICY NO. : MC012586
CLAIM TYPE : TP CLAIM-EQ INSURANCE

WORKSHOP : BLK K PANDAN LOOP IND EST #01-12 SINGAPORE 128230

S/N	PART NO.	DESCRIPTION	QUANTITY	LIST PRICE
1		TAIL LAMP LHS	1	\$ 590.00 <i>BR</i>
2		REAR BUMPER	1	\$ 680.00 <i>DE</i>
3		REAR BUMPER BRACKET LHS	1	\$ 11.00 <i>ne</i>
4		REAR BUMPER RETAINER LHS	1	\$ 27.00 <i>ne</i>
5		REAR BUMPER CLIPS	10	\$ 20.00 <i>ne</i>
6		REAR BUMPER REINFORCEMENT	1	\$ 130.00 <i>?</i>
7		REAR BUMPER REFLECTOR LHS	1	\$ 32.00 <i>X</i>
8		REAR FENDER LHS	1	\$ 1,060.00 <i>R</i>
9		REAR FENDER INNER SHIELD LH	1	\$ 22.00 <i>X</i>
10		REAR FENDER CLIPS	10	\$ 20.00 <i>X</i>
11		TAILGATE PANEL	1	\$ 1,060.00 <i>X</i>
12		TAILGATE INNER LOCK	1	\$ 256.00 <i>X</i>
13		TAILGATE INNER LOCK CATCH	1	\$ 81.00 <i>X</i>
14		REAR WINDSCREEN GLASS WITH MOULDING	1	\$ 823.00 <i>X</i>
15		REAR END PANEL	1	\$ 420.00 <i>R</i>

TOTAL : \$ 5,232.00
PART DISCOUNT 10% : \$ 523.20
PARTS TOTAL : \$ 4,708.80

SPECIAL-NETT ITEMS

1	REAR PARKING SENSOR	1	\$ 280.00 <i>X</i>
2	REAR BUMPER REVERSE SENSOR	1	\$ 350.00 <i>X</i>

SPECIAL-NETT TOTAL : \$ 630.00

PARTS TOTAL \$ 5,338.80

LABOUR CHARGES

1	TO REMOVE & REFIT DAMAGED PARTS ,CUT WELD ,PANEL BEAT ,STRAIGHTEN & REALIGN	1	\$ 1,400.00 <i>500</i>
2	TO REMOVE & REPLACE TAILGATE INNER COMPONENT	1	\$ 150.00 <i>X</i>
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	\$ 120.00 <i>X</i>
4	TO PUTTY ,CLEAN ,SPRAY PAINT & POLISH ,ETC ,AFFECTED AREAS	1	\$ 1,008.00 <i>700</i>

LABOUR TOTAL : \$ 2,670.00

GRAND TOTAL : \$ 8,008.80

Industrial Vehicles.
20,000 Served. And Counting.

PREPARED BY : ANDY OOI
DATE / TIME : 26/01/16 @ 0920
SURVEYOR : RASUL
MOBILE NO. : 90016068
OFFICE FAX NO. :
EMAIL ADDRESS : rasul@lkkauto.com
REPAIR TYPE : PART-BY-PART / LUMPSUM
RE-SURVEY : BEFORE PAINT / AFTER PAINT
NO. OF DAYS : 5 days
REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: