

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

|            |   |                    |
|------------|---|--------------------|
| Estimate   | : | Accident Repairs   |
| Workshop   | : | Ubi Road 1         |
| Contact No | : | 6366 2323          |
| Fax No     | : | 6841 1183          |
| Reference  | : | PA/TP/0094/2018/GW |
| Date       | : | 23-Jan-18          |

Vehicle NOT IN workshop. Kindly arrange for survey.

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

|                   |   |                                             |
|-------------------|---|---------------------------------------------|
| Owner's Name      | : | Ms. Aileen Laemonta                         |
| Address           | : | 72 Flora Road<br>#03-24<br>Singapore 506915 |
| Telephone         | : | HP +65 97494934                             |
| Type of Claim     | : | Third party Claims                          |
| Policy No.        | : | SD17V04575/VPC/R01/E00                      |
| Vehicle No        | : | <b>SKL 1368 P</b>                           |
| Model Code        | : | Audi Q5 2.0 TFSI QU                         |
| Model / Year      | : | Sep-13                                      |
| Engine No         | : | CNC 019081                                  |
| Chassis No        | : | WAUZZZ8R9EA009749                           |
| Mileage           | : |                                             |
| Date In           | : |                                             |
| Liability         | : | -                                           |
| Excess Cost       | : | -                                           |
| Estimated By      | : | Johnny Boo / Allan Wu                       |
| Accident Date     | : | 19-Jan-18                                   |
| Place of Accident | : | CTE (BUKIT TIMAH EXIT) TOWARDS KK HOSPITAL  |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

|            |   |                    |
|------------|---|--------------------|
| Estimate   | : | Accident Repairs   |
| Workshop   | : | Ubi Road 1         |
| Contact No | : | 6366 2323          |
| Fax No     | : | 6841 1183          |
| Reference  | : | PA/OD/0094/2018/GW |
| Date       | : | 23-Jan-18          |

Vehicle NOT IN workshop. Kindly arrange for survey.

## Liberty Insurance Pte Ltd

51 Club Street

#03-00 Liberty House

Singapore 069428

## Attn: Motor Claims Dept

Tel: 6328 0620 - Fax: 6224 1047

|                   |   |                                             |
|-------------------|---|---------------------------------------------|
| Owner's Name      | : | Ms. Aileen Laemonta                         |
| Address           | : | 72 Flora Road<br>#03-24<br>Singapore 506915 |
| Telephone         | : | HP +65 97494934                             |
| Type of Claim     | : | Own Damage Claims                           |
| Policy No.        | : | SD17V04575/VPC/R01/E00                      |
| Vehicle No        | : | <b>SKL 1368 P</b>                           |
| Model Code        | : | Audi Q5 2.0 TFSI QU                         |
| Model / Year      | : | Sep-13                                      |
| Engine No         | : | CNC 019081                                  |
| Chassis No        | : | WAUZZZ8R9EA009749                           |
| Mileage           | : |                                             |
| Date In           | : |                                             |
| Liability         | : | -                                           |
| Excess Cost       | : | -                                           |
| Estimated By      | : | Johnny Boo / Allan Wu                       |
| Accident Date     | : | 19-Jan-18                                   |
| Place of Accident | : | CTE (BUKIT TIMAH EXIT) TOWARDS KK HOSPITAL  |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKL 1368 P

| S/n                  | Nature of Jobs                                                                                                      |     | Estimated<br>Charges       | Surveyor's<br>Recommendation |
|----------------------|---------------------------------------------------------------------------------------------------------------------|-----|----------------------------|------------------------------|
| 1                    | To remove and transfer rear parking aid . Check function.                                                           | S/N | \$ 280.00                  | ✓                            |
| 2                    | To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed. |     | \$ <del>1,050.00</del> 600 |                              |
| 3                    | To respray rear bumper and lower spoiler.                                                                           |     | \$ <del>1,400.00</del> 900 |                              |
| 4                    | To carry out diagnostic check.                                                                                      | S/N | \$ 192.00                  | ✓                            |
| TOTAL LABOUR CHARGES |                                                                                                                     | :   | <u>\$ 2,922.00</u>         |                              |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKL 1368 P

| S/N                  | Parts Description                | Damaged Parts & Prices |             |
|----------------------|----------------------------------|------------------------|-------------|
|                      |                                  | S/Nett                 | Remark      |
| 1                    | REAR BUMPER <i>deland</i>        | \$ 1,430.00            | ✓           |
| 2                    | REAR BUMPER SPOILER <i>Repis</i> | \$ 749.00              | X           |
| 3                    | REAR BUMPER CARRIER <i>Norm</i>  | \$ 571.00              | X           |
| 4                    | REAR BUMPER SENSOR <i>Norm</i>   | 2 \$ 421.00            | X           |
| 5                    | SUNDRIES                         | \$ 200.00              | ?           |
| TOTAL SPARE PARTS    |                                  | :                      | \$ 3,371.00 |
| TOTAL LABOUR CHARGES |                                  |                        | \$ 2,922.00 |
| GRAND TOTAL          |                                  |                        | \$ 6,293.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Admin Ly  
Surveyed Date : 31/01/18  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 Days.

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant