



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/MSG18001558/Atb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 25-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 1791E	Veh. Inspected	SH 4880H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	25/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/01/2018	Inspection Date	25/01/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 26 January 2018 11:39 AM
To: Iryani Amin; Ong Chin Kiat
Cc: SUR; KKLau; Accounts (LKKAuto); Christopher Chionh
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - HUA MENG SPRAY PAINTING WORKSHOP (TP VEHICLE: GBB 1101B, INSURED VEHICLE: GY 3814J, DOA: 30-05-2017)
Attachments: sh 4880h gia.pdf

Dear Iryani/Chin Kiat,

Please be informed that we had inspected the vehicle **SH 4880H** at M/s: **HUA MENG SPRAY PAINTING WORKSHOP, 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883.**

Enclosed herewith a copy of TP's GIA report.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 16:38
Date Of Accident	20/01/2018 17:00
Exact Location Of Accident	JUNC JALAN BESAR & DESKER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH4880H
Insured/Policyholder	
Name Of Registered Owner	LOW BOON TIN
NRIC No	S2081094G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97478752
Alternative Phone No	OFFICE-97478752
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D-170087932MSH
Cover Note Number	
Driver	
Name of Driver	KONG LONG HIAN
NRIC No	S0119061Z
Date Of Birth	27/12/1954
Occupation	OUTDOOR
Date Of Driving Pass	23/11/2010
Driving Experience	7 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84152367
Fax Number	
Contact Number	OFFICE-84152367
Email Address	NOEMAIL

Address	BLK 180 BUKIT BATOK WEST AVENUE 8 #07-197
Postcode	651194
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR1791E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	82339281
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

Accident Sketch Plan

IMPORTANT NOTICE

1. This report is for use by the insurers and the General Insurance Association of Singapore (GIA).
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and the copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along in lane 1 of Jalan Besar on 20.01.2018 @ 11:00hrs. I was stationary at lane 1 for pick up passenger. When I start to move, suddenly I heard a bang sound and felt an impact from my left. Vehicle B from lane 2 suddenly turn right and collided onto left side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Person's Signature
Name:
NRIC/FIN No

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0074/2018/JT 23-Jan-18 CHANG 1 of 1 SJQ 700 E Audi TTC 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	SIGNAL HORN - LH/RH	\$ 318.00	
2	AUDI ALUMINIUM NOTICE STICKER	\$ 17.00	
3	BONNET EDGE PROTECTION - LH/RH	\$ 54.00	
TOTAL PARTS :		\$ 389.00	
GRAND TOTAL :		\$ 389.00	

Adrian
26/01/18

For Premium Automobiles Pte Ltd



Authorised Signature

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NZE167065470

LOW BOON TIN
1 KAKI BUKIT AVE 6
#01-61
S 417883

TP MS16.
Denise.

Date :26.01.2018
Vehicle no :SH 4880 H
Make/Model :TOYOTA AXIO
Accident date :20.01.2018

No	Description	Qty	Amount (\$\$)
List Items			
1	Front bumper <i>deformed.</i>	1	\$ 477.2 ✓
2	Front bumper side holder @ \$57.10 <i>LH 2nd</i>	2	\$ 114.2 <i>57.10</i>
3	Front bumper LH fog lamp garnish <i>ok</i>	1	\$ 78.8 ✓
4	Front bumper centre lower grille <i>not new</i>	1	\$ 267.9 X
5	Front bumper sponge <i>crushed</i>	1	\$ 95.3 ✓
6	Front bumper reinforcement <i>not new</i>	1	\$ 319.7 X
7	Front bumper lower cover <i>torn</i>	1	\$ 147.5 ✓
8	Front bumper inner lower cover	1	\$
9	Front bumper clips(1set) <i>new</i>	1	\$ 50.30
10	Front LH fender <i>dented</i>	1	\$ 790.4 ✓
11	Front LH fender inner shield <i>torn</i>	1	\$ 176.9 ✓
12	Front LH fender inner shield lower garnish <i>torn</i>	1	\$ 79.9 ✓
13	Front LH fender inner shield clips(1set) <i>new</i>	1	\$ 50.30
14	Front LH door <i>Repair</i>	1	\$ 1012.6 X
15	Front LH door top hinge	1	\$ 94.4 +
16	Front LH door lower hinge	1	\$ 94.4 +
17	Front LH door glass outer moulding	1	\$ 134.3 X
18	Front LH door frame black sticker @(1set) <i>new</i>	1	\$ 65.8 X
19	Front LH head lamp <i>ok</i>	1	\$ 736.8 ✓
20	Front support panel <i>Repair</i>	1	\$ 957.4 X
			\$ 5743.5
Less 25% Disc			\$ 1435.88
Total			\$ 4307.62

Labour Cost

- 1 Remove & reinstall air con fill in gas
- 2 Remove & reinstall door glass
- 3 Remove ,replace & repair consistent to the accident
- 4 Respray painting
- 5 Tuff kote

\$ 150 X
\$ 100 X
\$ 1400 <i>500</i>
\$ 1200 <i>700</i>
\$ 100 X 30
\$ 2950

Total

Grand Total

\$ 7257.2

62

LKK Auto Corp. hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total. 3254.92
h/s: 2.6K
OH pays

3K

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18001558/ATBN2

Date: 29/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27710689DMA
Claimant Vehicle No :	SH4880H	Insured Vehicle No :	SJR1791E
Date of Loss:	20/01/2018	Nature of Claim:	TP
		Claim No:	547688

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH4880H	Engine No:	1NZE456701
Make & Model:	TOYOTA COROLLA, 1.5 X AXIO (A)	Chassis No:	NZE1617065470
Reg. Date:	26/06/2014 (Man. Year: 2013)	Odometer:	511219 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,307.62	2,024.92	2,282.70	52.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,230.00	1,720.00	58.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,257.62	3,254.92	4,002.70	55.15
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	7,257.62	2,600.00	4,657.62	64.18

INSPECTION

Date of Assignment:	26/01/2018	
Date Inspected:	25/01/2018 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2018)
Parts:	143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH4880H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	477.20 FL	*477.20 FL
2	1	*FRONT BUMPER SIDE HOLDER	N/s Damaged	114.20 FL	*57.10 FL
3	1	*FRONT BUMPER LH FOG LAMP GARNISH	Cut	78.80 FL	*78.80 FL
4	1	*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	267.90 FL	*- FL
5	1	*FRONT BUMPER SPONGE	Cracked	95.30 FL	*95.30 FL
6	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	319.70 FL	*- FL
7	1	*FRONT BUMPER LOWER COVER }	Torn	147.50 FL	*147.50 FL
8	1	*FRONT BUMPER INNER LOWER COVER }		0.00 FL	*- FL
9	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
10	1	*FRONT LH FENDER	Dented	790.40 FL	*790.40 FL
11	1	*FRONT LH FENDER INNER SHIELD	Torn	176.90 FL	*176.90 FL
12	1	*FRONT LH FENDER INNER SHIELD LOWER GARNISH	Torn	79.90 FL	*79.90 FL
13	1	*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FL	*30.00 FL
14	1	*FRONT LH DOOR	Repair	1,012.60 FL	*- FL
15	1	*FRONT LH DOOR TOP HINGE	Not Necessary	94.40 FL	*- FL
16	1	*FRONT LH DOOR LOWER HINGE	Not Necessary	94.40 FL	*- FL
17	1	*FRONT LH DOOR GLASS OUTER MOULDING	Not Necessary	134.30 FL	*- FL
18	1	*SET FRONT LH DOOR FRAME BLACK STICKER	Not Necessary	65.80 FL	*- FL
19	1	*FRONT LH HEAD LAMP	Cut	736.80 FL	*736.80 FL
20	1	*FRONT SUPPORT PANEL	Repair	957.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,743.50	2,699.90
- List Item Discount on L Items 25.00/25.00% (S\$)	1,435.88	674.98
Total Parts (S\$)	4,307.62	2,024.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL AIR CON FILL IN GAS	New	150.00	-
2	REMOVE & REINSTALL DOOR GLASS	New	100.00	-
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,400.00	500.00
4	RESPRAY PAINTING	New	1,200.00	700.00
5	TUFF KOTE	New	100.00	30.00
Gross Labour Cost (S\$)			2,950.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >