

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0104/2018/JT
Date : 25-Jan-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ng Siew Gek
Address : Blk 203 Toa Payoh North
#04-1103
Singapore 310203
Telephone : HP +65 9009 4548
Type of Claim : Own Damage Claims
Policy No. : 2100265041-06000
Vehicle No : **SKB 7159 P**
Model Code : Audi A4 1.8 TFSI Mu
Model / Year : Jun-11
Engine No : CDH 131420
Chassis No : WAUZZZ8K2BA152069
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jan-18
Place of Accident : Lor 1 Toa Payoh turning into Tpa Payoh North

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 7159 P.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damages.	S/N \$ 280.00	✓
2	To remove and transfer rear lid convenience lock system and wire harness for tail lights.	S/N \$ 280.00	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse & relay tryas, electrical and audio equipment.	S/N \$ 480.00	?
4	To dismantle rear bumper and boot lid. Cut out and weld rear outer, inner and lower rear cross panel Renew rear bumper and rear lid. Re-organize rear crash management compoenents. Reinstall all parts removed.	\$ 3,600.00	1250 .
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,200.00	1650 .
6	To remove and renew centre and rear exhaust silencer.	S/N \$ 480.00	?
7	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>7,512.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 7159 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Replaced</i>	\$ 1,621.00	✓
2	REAR REINFORCEMENT BEAM ?	\$ 563.00	?
3	REAR REINFORCEMENT HOLDER - LHS/RHS <i>new</i>	\$ 382.00	✗
4	REAR SPOILER <i>Replaced</i>	\$ 333.00	✓
5	REAR BUMPER GUIDE - LHS <i>new</i>	\$ 37.00	✗
6	REAR BUMPER INNER GUIDE - LHS <i>new</i>	\$ 20.00	✗
7	REAR SPOILER TRIM ?	\$ 222.00	?
8	REAR PARKING AID ?	TBC	?
9	PARKING AID WIRING SET <i>new</i>	\$ 458.00	✗
10	REAR LID <i>Dented</i>	\$ 1,923.00	✓
11	REAR LID HINGE - LHS/RHS <i>new</i>	\$ 496.00	✗
12	REAR WEATHERSTRIP <i>new</i>	\$ 176.00	✗
13	PACKING ADHESIVE ?	\$ 29.00	✓
14	AUDI EMBLEM <i>new</i>	\$ 108.00	✓
15	"A4" EMBLEM	\$ 83.00	✓
16	"1.8T" EMBLEM	\$ 83.00	✓
17	INNER LED TAIL LIGHT - LHS <i>2 new</i>	2 \$ 885.00	✗
18	OUTER LED TAIL LIGHT - LHS	2 \$ 735.00	✗
19	REAR CROSS PANEL ?	\$ 275.00	?
20	REAR INNER CROSS PANEL ?	2 \$ 468.00	?
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,897.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 7159 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	REAR LOWER CROSS PANEL ?	\$ 765.00 ?	
22	VENT TRIM ?	\$ 63.00 ?	
23	REAR SILENCER	\$ 990.00 ?	
24	REAR SILENCER BRACKET - <i>2ml d</i>	\$ 50.00 ✓	
25	DUAL CLIP ?	\$ 47.00 ?	
26	CENTRE SILENCER <i>new</i>	\$ 1,016.00 ✕	
27	STONE CHIP ?	S/N \$ 180.00 ?	
28	CAVITY WAX ?	S/N \$ 140.00 ?	
29	ACRYLIC SEALER ?	S/N \$ 180.00 ?	
30	REAR NUMBER PLATE <i>new</i>	S/N \$ 25.00 ✕	
31	SUNDRIES ?	\$ 400.00 ?	
TOTAL SPARE PARTS CHARGES		: \$ 12,753.00	
TOTAL LABOUR CHARGES		\$ 7,512.00	
GRAND TOTAL		<u>\$ 20,265.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 25/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant