

REF:

CC3 / ALG18001561 / Agbn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2160460426Claims No. 483958280356Sum Insured: _____ Excess: 300 29/1/18

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 130K.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10/8/18 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFG3773A. Yr Regn: 2016 AprilType: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan. c.c. 1395Colour: Black. A.O. Insured / Std / NI / NASp. Reading: 56020 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF49GA039392Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16.R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental.

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 25/01/18Survey held at Premium.Des. of Damages (FR) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD 416.

SFG 3773A - X

26/1/18 @ 10.54am revert to Victor via Messenger.

29/1/18 @ 2.31pm Victor informed CA via Messenger.

29/1/18 @ 3.12pm informed Jeffrey CA & Ex: \$300 by email.

23/3/18 @ 2.13pm confirmed with Mr Bor final pg & 24827.40, 10 days by email.

(Ref 815568.60, 29/1/18)

RECEIVED 29 MAR 2018

Date/Time File Pass to?

☐

Preli. Report

29/3 4pm

☐

Final Report

Date/Time File Return to?

2)

Days Of Repair: 10Resurvey No. of Trip: 1

Survey Fee:

Transportation:

3-PS \$1

Photos:

Times:

TOTAL

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Invs \$

☐

Weekend \$

Report Format: REP-0D

Lump Sum / I.B.I: (\$

24827.40

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18001561/Aqb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 25-01-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SFG 3773A
Policy No. 2100460426	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	25/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 22/01/2018	Inspection Date 25/01/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 23 March 2018 2:13 PM
To: 'Boo seng yak'; SUR; Carrine Leong; Nora Khai
Subject: RE: FINAL REVISION SFG3773A - OD AIG - SURVEYED 25 JAN 18

Dear Mr Boo,

Confirm final fig \$24,827.40 before excess \$300.00 & GST and 10 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [<mailto:boojohnny@gmail.com>]

Sent: Monday, 19 March 2018 3:16 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION SFG3773A - OD AIG - SURVEYED 25 JAN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$24,827.40 @ 10 days of repairs with lock carrier replacement and additional parts.

Your early closure is appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 29 January 2018 3:12 PM
To: Claims Dept; SUR
Subject: RE: OD CLAIM FOR SFG 3773 A

Dear Jeffrey,

As instructed by our client, please proceed to repair the insured vehicle **SFG 3773A (excess \$300/-)**.

Kindly arrange our surveyor to take re-survey photo for condenser, check items and supplementary if have.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Friday, 26 January 2018 8:29 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SFG 3773 A

Dear all,

Kindly assist in the approval for this case.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		[] Merimen Administrator
1	22 Jan 2018 19:57	Clim Veh Model Changed	Reg No: SFG3773A. Policy No: 2100460426-01000. Acct Date: 2018/01/22. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118011054		[I] Merimen Administrator
2	22 Jan 2018 19:57	Clim Created			[] CATHERINE CHONG KAI LING
3	25 Jan 2018 17:36	Clim Registration Modified	Settl.Type:3->0. Claim Type:SC->OD.		[] CATHERINE CHONG KAI LING
4	25 Jan 2018 17:36	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[A] CATHERINE CHONG KAI LING
5	25 Jan 2018 17:36	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] CATHERINE CHONG KAI LING
6	25 Jan 2018 17:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/05		[A] CATHERINE CHONG KAI LING
7	25 Jan 2018 17:36	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.		[A] CATHERINE CHONG KAI LING
8	25 Jan 2018 17:36	Clim Registration Modified	Rep:1137->200611.		[A] CATHERINE CHONG KAI LING
9	25 Jan 2018 17:36	Clim Veh Model Changed	(204567) AUDI A4 1.4 T (A).		[A] CATHERINE CHONG KAI LING
10	25 Jan 2018 17:36	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] SHIAU CHAN
11	26 Jan 2018 10:44	Adj Rpt Initiated			[A] SHIAU CHAN
12	26 Jan 2018 10:44	Clim Details Notified			[A] SHIAU CHAN
13	26 Jan 2018 10:53	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/05		[A] SHIAU CHAN
14	26 Jan 2018 10:53	Adj Mandate Request	Cur.Req:31716.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[I] Dally Amri, Mimi Zarina
15	26 Jan 2018 15:23	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 300.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.		[A] Merimen Administrator
16	26 Jan 2018 15:23	Label Added	(20226):Coverage Confirmed.		[I] Koh, Victor-CK
17	29 Jan 2018 14:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/05. Mandate Remarks: Re-inspect and upload damage photos of Condenser. Re-inspection to be done for damage check and supplementary items / labour.		[I] Koh, Victor-CK
18	29 Jan 2018 14:31	Adj Mandate Set	Approved:26428.00:Re-inspect and upload damage photos of Condenser. Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.		

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1706199	26/01/2018 10:44	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFG3773A		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No. 199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 26 Jan 2018

Preliminary AdviceVehicle No : SFG3773A
Make : AUDI A4
Assignment Date : 25/01/2018
Date of Inspection : 25/01/2018
Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)
55 UBI ROAD 1
SINGAPORE 408699Accident Date : 22/01/2018
Policy No. : 2100460426-01000
Excess : S\$0.00
Est. Duration of Repair : 7.00**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,964.00
Revised Amount	:S\$	26,428.00
Check Items (Estimated)	:S\$	5,288.00
Total	:S\$	31,716.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	58,770.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,230.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6339D
Vehicle Details	
Vehicle No.:	SFG3773A
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	CVN004998
Chassis No.:	WAUZZZF49GA039392
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,076.00
Original Registration Date:	12 Apr 2016
First Registration Date:	12 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$26,907.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2026
PARF Rebate Amount:	\$20,180.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,000.00
COE Rebate Amount:	\$38,590.00
Total Rebate Amount:	\$58,770.00

The information contained herein is correct as at 26 Jan 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S1506339D**
 Name: **TAN KIM HENG**
 Birth Date: **25 Mar 1961**
 Issue Date: **20 Sep 2003**

000850324K

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1506339D


 Name: **TAN KIM HENG**
 Race: **CHINESE**
 Date of birth: **25-03-1961**
 Country/Place of birth: **SINGAPORE**
 Sex: **M**

5181560

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms
 PASS DATE: **29 Sep 1983**

NP 428A

Licence No: S1506339D

5181560


 DRIVING No: **S1506339D**


 Date of issue: **12-06-2013**

Address:
APT BLK 496C TAMPINES STREET 43
#08-255
SINGAPORE 526496



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100460426-01000

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SFG3773A

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

TAN KIM HENG

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

12 Apr 2017

4) DATE OF EXPIRY OF INSURANCE

11 Apr 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN United Overseas Bank Limited

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 13 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPQCC

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0101/2018/CCS
Date	:	24-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tan Kim Heng
Address	:	Blk 496C Tampines Street 43 #08-255 Singapore 526496
Telephone	:	(HP) 98428719
Type of Claim	:	Own Damage Claims
Policy No.	:	2100460426-01000
Vehicle No	:	SFG 3773 A
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	Apr-16
Engine No	:	CVN 004998
Chassis No	:	WAUZZZF49GA039392
Mileage	:	
Date In	:	22-Jan-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Jan-18
Place of Accident	:	PIE towards Tuas before Clementi Rd exit lane 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFG 3773 A.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,100.00	✓
3	To dismantle front bumper, both front fenders, bonnet and headlights. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,400.00	2750. ✓
4	To respray front bumper, both front fenders, bonnet and hinges.	\$ 3,300.00	1600 1100 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Disturbed</i>	\$ 1,849.00	✓ 1479.20
2	FRONT BUMPER SECURING STRIP <i>new</i>	\$ 60.00	✗
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	\$ 171.00	✓ 136.90
4	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	\$ 180.00	✗
5	RADIATOR GRILLE <i>new</i>	\$ 972.00	✓ 777.70
6	FRONT BUMPER GRILLE - LH/RH <i>new</i>	2 \$ 236.00	✗
7	FRONT REINFORCEMENT BEAM <i>set</i>	\$ 702.00	✓ 561.60
8	FRONT BUMPER SUPPORT - LH/RH <i>new</i>	2 \$ 24.00	? 38.74 ✓
9	FRONT BUMPER INNER FOAM <i>new</i>	\$ 107.00	✓ 85.70
10	FRONT BUMPER TOP COVER <i>new</i>	\$ 109.00	✓ 87.70
11	SIGN ' CAUTION ' STICKER <i>3 new</i>	\$ 12.00	✓ 9.28
12	STICKER FOR AIR CONDITIONER	\$ 7.00	✓ 4.88
13	BONNET RELEASE LEVER <i>new</i>	\$ 12.00	✗
14	BONNET BOWDEN CABLE <i>new</i>	\$ 50.00	✗
15	FRONT LOCK CARRIER BRACKET <i>new</i>	\$ 118.00	✓ 94
16	FRONT FENDER - LH/RH <i>new</i>	2 \$ 1,330.00	✗
17	FRONT FENDER CLOSING ELEMENT - LH/RH <i>new</i>	2 \$ 88.00	✗
18	FRONT FENDER BRACKET - LH/RH <i>3 new</i>	2 \$ 62.00	✗
19	FRONT FENDER RIVET SET	\$ 35.00	✗
20	LED HEADLIGHT - LH/RH <i>new</i>	2 \$ 13,946.00	✓ 1156.80
SUB-TOTAL SPARE PARTS CHARGES		\$ 20,070.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	HEADLIGHT WASH CYLINDER - LH/RH <i>acc in</i>	2 \$ 368.00	+
22	WASH CYLINDER BRACKET - LH/RH <i>2 acc in new</i>	2 \$ 11.00	+
23	WASH CYLINDER CORRUGATED PIPE <i>2 acc in replaced.</i>	\$ 79.00	62.56 ✓
24	BONNET <i>Dented</i>	\$ 2,163.00	1750.40
25	BONNET HINGE - LH/RH <i>acc in</i>	2 \$ 532.00	+
26	BONNET IMPACT PROTECTION - LH/RH <i>2 acc in</i>	2 \$ 48.00	37.76 ✓
27	BONNET IMPACT PROTECTION - CENTER	\$ 24.00	18.88 ✓
28	FRONT FENDER TOP TRIM - LH/RH OUTER <i>2 acc in</i>	2 \$ 40.00	+
29	FRONT FENDER TOP TRIM - LH/RH INNER	2 \$ 54.00	+
30	BONNET LOCK <i>Not New</i>	2 \$ 376.00	2.8
31	BONNET LOCK STRIKER - LH/RH <i>Not New</i>	2 \$ 88.00	2.8
32	BONNET LOCK BOWDEN CABLE <i>acc in</i>	\$ 50.00	+
33	FRONT LOCK CARRIER <i>2 acc in</i>	\$ 891.00	712.80 ✓
34	RADIATOR SUPPORT <i>acc in</i>	2 \$ 66.00	2.8
35	FRT LOCK CARRIER AIR GUIDE - LH/RH <i>2 acc in</i>	2 \$ 46.00	36.80 ✓
36	FRT LOCK CARRIER AIR GUIDE - LH/RH OUTER <i>2 acc in</i>	2 \$ 20.00	15.36 ✓
37	FRT LOCK CARRIER AIR GUIDE - UPPER <i>2 acc in</i>	\$ 14.00	2.8
38	A/C CONDENSER <i>Dented</i>	\$ 540.00	432 ✓
39	A/C CONDENSER PRESSURE SENSOR <i>acc in</i>	\$ 165.00	+
40	A/C CONDENSER PRESSURE VALVE <i>acc in</i>	\$ 46.00	+
SUB-TOTAL SPARE PARTS CHARGES		\$ 5,621.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	RADIATOR <i>tested</i>	\$ 585.00	? 468 ✓
42	RADIATOR RUBBER BUSH SET <i>Ne m</i>	\$ 38.00	? 8
43	ADDITIONAL RADIATOR - OUTER <i>tested.</i>	\$ 455.00	? 364 ✓
44	COOLANT <i>Ne</i>	\$ 133.00	✓ 106.24
45	RADIATOR FAN RING <i>Ne New</i>	\$ 230.00	? 8
46	RADIATOR FAN WITH CONTROL UNIT <i>Ne New</i>	\$ 2,055.00	? 8
47	FRONT NUMBER PLATE <i>Best</i>	S/N \$ 25.00	✓
48	SUNDRIES <i>Ne</i>	\$ 400.00	? 40.08 ✓
TOTAL SPARE PARTS CHARGES		:	\$ 29,612.00
TOTAL LABOUR CHARGES			\$ 10,352.00
GRAND TOTAL			\$ 39,964.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

40323.36

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan
Surveyed Date : 25/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0101/2018/CCS 5-Feb-18 CHANG 1 of 1 SFG 3773 A Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT REINFORCEMENT BEAM BRACKET - LH/RH	\$ 390.00	PA - 312
2	FRONT REINFORCEMENT BEAM BOLT SET	\$ 42.00	me 33.12
TOTAL PARTS :		\$ 432.00	
GRAND TOTAL :		\$ 432.00	

For Premium Automobiles Pte Ltd

Rachel
06/02/18
P1220


Authorized Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 1,849.00	✓
2	FRONT BUMPER SECURING STRIP <i>new</i>	\$ 60.00	✗
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	\$ 171.00	✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	\$ 180.00	✗
5	RADIATOR GRILLE <i>new</i>	\$ 972.00	✓
6	FRONT BUMPER GRILLE - LH/RH <i>new</i>	2 \$ 236.00	✗
7	FRONT REINFORCEMENT BEAM <i>new</i>	\$ 702.00	✓
8	FRONT BUMPER SUPPORT - LH/RH <i>?</i>	2 \$ 24.00	✗
9	FRONT BUMPER INNER FOAM <i>new</i>	\$ 107.00	✓
10	FRONT BUMPER TOP COVER <i>new</i>	\$ 109.00	✓
11	SIGN ' CAUTION ' STICKER <i>new</i>	\$ 12.00	✓
12	STICKER FOR AIR CONDITIONER	\$ 7.00	✓
13	BONNET RELEASE LEVER <i>new</i>	\$ 12.00	✗
14	BONNET BOWDEN CABLE <i>new</i>	\$ 50.00	✗
15	FRONT LOCK CARRIER BRACKET <i>new</i>	\$ 118.00	✓
16	FRONT FENDER - LH/RH <i>new</i>	2 \$ 1,330.00	✗
17	FRONT FENDER CLOSING ELEMENT - LH/RH <i>new</i>	2 \$ 88.00	✗
18	FRONT FENDER BRACKET - LH/RH <i>new</i>	2 \$ 62.00	✗
19	FRONT FENDER RIVET SET	\$ 35.00	✗
20	LED HEADLIGHT - LH/RH <i>new</i>	2 \$ 13,946.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 20,070.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remark
21	HEADLIGHT WASH CYLINDER - LH/RH <i>acc in</i>	2	\$	368.00	+
22	WASH CYLINDER BRACKET - LH/RH <i>green</i>	2	\$	11.00	+
23	WASH CYLINDER CORRUGATED PIPE		\$	79.00	+ na ✓
24	BONNET <i>Dented</i>		\$	2,163.00	—
25	BONNET HINGE - LH/RH <i>acc in</i>	2	\$	532.00	+
26	BONNET IMPACT PROTECTION - LH/RH <i>green</i>	2	\$	48.00	✓
27	BONNET IMPACT PROTECTION - CENTER		\$	24.00	✓
28	FRONT FENDER TOP TRIM - LH/RH OUTER <i>green</i>	2	\$	40.00	+
29	FRONT FENDER TOP TRIM - LH/RH INNER	2	\$	54.00	+
30	BONNET LOCK ?	2	\$	376.00	?
31	BONNET LOCK STRIKER - LH/RH ?	2	\$	88.00	?
32	BONNET LOCK BOWDEN CABLE <i>acc in</i>		\$	50.00	+
33	FRONT LOCK CARRIER ?		\$	891.00	? CPA ✓
34	RADIATOR SUPPORT ?	2	\$	66.00	?
35	FRT LOCK CARRIER AIR GUIDE - LH/RH ?	2	\$	46.00	? CPA ✓
36	FRT LOCK CARRIER AIR GUIDE - LH/RH OUTER ?	2	\$	20.00	? CPA ✓
37	FRT LOCK CARRIER AIR GUIDE - UPPER ?		\$	14.00	?
38	A/C CONDENSER <i>Dented</i>		\$	540.00	✓
39	A/C CONDENSER PRESSURE SENSOR <i>acc in</i>		\$	165.00	+
40	A/C CONDENSER PRESSURE VALVE <i>acc in</i>		\$	46.00	+
SUB-TOTAL SPARE PARTS CHARGES			:	<u>\$ 5,621.00</u>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	RADIATOR ?	\$ 585.00	? R ✓
42	RADIATOR RUBBER BUSH SET ?	\$ 38.00	?
43	ADDITIONAL RADIATOR - OUTER ?	\$ 455.00	? R ✓
44	COOLANT <i>mu</i>	\$ 133.00	✓
45	RADIATOR FAN RING ?	\$ 230.00	?
46	RADIATOR FAN WITH CONTROL UNIT ?	\$ 2,055.00	?
47	FRONT NUMBER PLATE <i>Bent</i>	S/N \$ 25.00	✓ 25.00
48	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		\$ 29,612.00	
TOTAL LABOUR CHARGES		\$ 10,352.00	
GRAND TOTAL		\$ 39,964.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0101/2018/CCS
Date : 24-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian you recommended 7 days

We took 10 days with check item
replaced. Jb - 19 Mar 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Kim Heng
Address : Blk 496C Tampines Street 43
#08-255
Singapore 526496
Telephone : (HP) 98428719
Type of Claim : Own Damage Claims
Policy No. : 2100460426-01000
Vehicle No : **SFG 3773 A**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Apr-16
Engine No : CVN 004998
Chassis No : WAUZZZF49GA039392
Mileage :
Date In : 22-Jan-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Jan-18
Place of Accident : PIE towards Tuas before Clementi Rd exit lane 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFG 3773 A.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N	\$ 1,100.00	\$ 1,100.00
3	To dismantle front bumper, both front fenders, bonnet and headlights. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.		\$ 5,400.00	\$ 2,750.00
4	To respray front bumper, both front fenders, bonnet and hinges.		\$ 3,300.00	\$ 1,600.00
5	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,352.00	\$ 6,002.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER SECURING STRIP	\$ 60.00	
3	FRONT BUMPER GRILLE - CENTER	\$ 171.00	\$ 136.80
4	FRONT BUMPER CLOSING ELEMENT - LOWER	\$ 180.00	
5	RADIATOR GRILLE	\$ 972.00	\$ 777.20
6	FRONT BUMPER GRILLE - LH/RH	2 \$ 236.00	
7	FRONT REINFORCEMENT BEAM	\$ 702.00	\$ 561.60
8	FRONT BUMPER SUPPORT - LH/RH	2 \$ 24.00	\$ 38.24
9	FRONT BUMPER INNER FOAM	\$ 107.00	\$ 85.20
10	FRONT BUMPER TOP COVER	\$ 109.00	\$ 87.20
11	SIGN ' CAUTION ' STICKER	\$ 12.00	\$ 9.28
12	STICKER FOR AIR CONDITIONER	\$ 7.00	\$ 4.88
13	BONNET RELEASE LEVER	\$ 12.00	
14	BONNET BOWDEN CABLE	\$ 50.00	
15	FRONT LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
16	FRONT FENDER - LH/RH	2 \$ 1,330.00	
17	FRONT FENDER CLOSING ELEMENT - LH/RH	2 \$ 88.00	
18	FRONT FENDER BRACKET - LH/RH	2 \$ 62.00	
19	FRONT FENDER RIVET SET	\$ 35.00	
20	LED HEADLIGHT - LH/RH	2 \$ 13,946.00	\$ 11,156.80
SUB-TOTAL SPARE PARTS CHARGES		\$ 20,070.00	\$ 14,430.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 3773 A.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	14,430.40
21	HEADLIGHT WASH CYLINDER - LH/RH	2 \$	368.00	
22	WASH CYLINDER BRACKET - LH/RH	2 \$	11.00	
23	WASH CYLINDER CORRUGATED PIPE	\$	79.00	\$ 62.56
24	BONNET	\$	2,163.00	\$ 1,730.40
25	BONNET HINGE - LH/RH	2 \$	532.00	
26	BONNET IMPACT PROTECTION - LH/RH	2 \$	48.00	\$ 37.76
27	BONNET IMPACT PROTECTION - CENTER	\$	24.00	\$ 18.88
28	FRONT FENDER TOP TRIM - LH/RH OUTER	2 \$	40.00	
29	FRONT FENDER TOP TRIM - LH/RH INNER	2 \$	54.00	
30	BONNET LOCK	2 \$	376.00	
31	BONNET LOCK STRIKER - LH/RH	2 \$	88.00	
32	BONNET LOCK BOWDEN CABLE	\$	50.00	
33	FRONT LOCK CARRIER	\$	891.00	\$ 712.80
34	RADIATOR SUPPORT	2 \$	66.00	
35	FRT LOCK CARRIER AIR GUIDE - LH/RH	2 \$	46.00	\$ 36.80
36	FRT LOCK CARRIER AIR GUIDE - LH/RH OUTER	2 \$	20.00	\$ 15.36
37	FRT LOCK CARRIER AIR GUIDE - UPPER	\$	14.00	
38	A/C CONDENSER	\$	540.00	\$ 432.00
39	A/C CONDENSER PRESSURE SENSOR	\$	165.00	
40	A/C CONDENSER PRESSURE VALVE	\$	46.00	
	SUB-TOTAL SPARE PARTS CHARGES		\$ 5,621.00	\$ 17,476.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SFG 3773 A.

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

All charges are not inclusive of GST.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0101/2018/CCS 5-Feb-18 CHANG 1 of 1 SFG 3773 A Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT REINFORCEMENT BEAM BRACKET - LH/RH <i>Sent</i>	\$ 390.00	\$ 312.00
2	FRONT REINFORCEMENT BEAM BOLT SET <i>Sent</i>	\$ 42.00	\$ 33.12
TOTAL PARTS :		\$ 432.00	\$ 345.12
GRAND TOTAL :		\$ 432.00	

For Premium Automobiles Pte Ltd

Adrian Ling
Sent

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFG 3773 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0101/2018/MAS

29 March 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SFG 3773 A, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SFG 3773 A**, claimant, **Mr. Tan Kim Heng**, please find the related document per attached.

1. A copy of the Original invoice no. 85012294 – S\$26,244.32
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SFG 3773 A

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 1183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jan 2018 10:44		25 Jan 2018 17:36 Edit Adj Rpt	S\$24,827.40 Edit Estimates	S\$24,827.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN KIM HENG, ID: S1506339D, Tel: +6598428719, Email: NOEMAIL								
Vehicle Reg. No.:	SFG3773A	Date of Loss:	22/01/2018 08:00 - :59						
Claim Type:	OD / 4839589803SG	Policy/Cover Note No.:	2100460426 (Comprehensive) Coverage: 12/04/2017 - 11/04/2018						
		Excess:	S\$300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/02/2018]								
Driver/Custodian:	TAN KIM HENG (56 / Male), NRIC: S1506339D, Tel: +6598428719								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (29/01/2018): Alert - Adj Mandate Approved (S\$26428.00) - SFG3773A - Claim Handler: Dally Amri... - AIG_SG (26/01/2018): SFG3773A / OD / 22/01/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFG3773A (4839589803SG)
OD
Jan 22 2018 8:00AM
[TAN KIM HENG]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Video						1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	22/01/18 19:51	Video - Accident [Linked Accident Report Documents]		Load MP4			
Assessment Reports						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	26/01/18 10:53	Adjuster Immediate Advice		Load HTM			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	26/01/18 10:48	General View		Load JPG	☒		
2	26/01/18 10:48	Chassis Number		Load JPG	☒		
3	26/01/18 10:48	General View		Load JPG	☒		
4	26/01/18 10:48	General View		Load JPG	☒		
5	26/01/18 10:48	General View		Load JPG	☒		
6	26/01/18 10:48	General View		Load JPG	☒		
7	26/01/18 10:48	General View		Load JPG	☒		
8	26/01/18 10:48	General View		Load JPG	☒		
9	26/01/18 10:48	General View		Load JPG	☒		
10	26/01/18 10:48	General View		Load JPG	☒		
11	26/01/18 10:48	General View		Load JPG	☒		
12	26/01/18 10:48	General View		Load JPG	☒		
13	26/01/18 10:48	General View		Load JPG	☒		
14	26/01/18 10:48	General View		Load JPG	☒		
15	26/01/18 10:48	General View		Load JPG	☒		
16	26/01/18 10:48	General View		Load JPG	☒		
17	26/01/18 10:48	General View		Load JPG	☒		
18	26/01/18 10:48	General View		Load JPG	☒		
19	26/01/18 10:48	General View		Load JPG	☒		
20	26/01/18 10:48	General View		Load JPG	☒		
21	26/01/18 10:48	General View		Load JPG	☒		
22	26/01/18 10:48	General View		Load JPG	☒		
23	26/01/18 10:48	General View		Load JPG	☒		
24	26/01/18 10:48	General View		Load JPG	☒		
25	26/01/18 10:48	General View		Load JPG	☒		
26	26/01/18 10:48	General View		Load JPG	☒		
27	26/01/18 10:48	General View		Load JPG	☒		
28	26/01/18 10:48	General View		Load JPG	☒		
29	26/01/18 10:48	General View		Load JPG	☒		
30	26/01/18 10:48	General View		Load JPG	☒		
31	26/01/18 10:48	General View		Load JPG	☒		
32	26/01/18 10:48	General View		Load JPG	☒		
33	26/01/18 10:48	General View		Load JPG	☒		

34	26/01/18 10:48	General View	1	Load JPG	☒
35	26/01/18 10:48	General View	1	Load JPG	☒
36	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
37	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
38	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
39	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
40	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
41	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
42	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
43	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
44	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
45	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
46	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
47	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
48	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
49	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
50	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
51	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
52	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
53	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
54	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
55	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
56	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
57	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
58	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
59	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
60	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
61	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
62	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒
63	19/03/18 18:16	Reinspection Photo	1	Load JPG	☒

Documentation

1 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/01/18 10:48	Singapore Accident Statement	1 Load PDF	
2	26/01/18 10:48	Certificate of Insurance	1 Load PDF	
3	26/01/18 10:48	Drivers Driving License	1 Load PDF	
4	26/01/18 10:48	WORKSHOP ESTIMATE	1 Load PDF	
5	02/04/18 16:48	WORKSHOP INVOICE	1 Load PDF	
6	02/04/18 16:48	DISCHARGE VOUCHER	1 Load PDF	
7	02/04/18 16:49	Supplementary	1 Load PDF	

Linked Accident Report Documents

View Use Viewer

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/18 19:51	Video - Accident	1 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/18 19:57	Accident Statement	1 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/18 19:54	Accident Photo	1 Load JPG	☒
2	22/01/18 19:54	Accident Photo	1 Load JPG	☒

3	22/01/18 19:54	Accident Photo		Load JPG	☒
4	22/01/18 19:54	Accident Photo		Load JPG	☒
5	22/01/18 19:54	Accident Photo		Load JPG	☒
6	22/01/18 19:54	Accident Photo		Load JPG	☒
7	22/01/18 19:54	Accident Photo		Load JPG	☒
8	22/01/18 19:54	Accident Photo		Load JPG	☒
9	22/01/18 19:54	Accident Photo		Load JPG	☒
10	22/01/18 19:54	Accident Photo		Load JPG	☒
Documentation			1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/01/18 19:55	Sketch Plan		Load JPG	☒
2	22/01/18 19:55	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001561/AQBN2

Date: 02/04/2018

REFERENCE

Insured/Claimant: TAN KIM HENG Policy No: 2100460426
Date of Loss: 22/01/2018 Nature of Claim: OD Claim No: 4839589803SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFG3773A
Make & Model: AUDI A4, 1.4 T (A) Engine No: CVN004998
Reg. Date: 12/04/2016 (Man. Year: 2016) Chassis No: WAUZZZF49GA039392
Colour: Black Odometer: 56020 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$130,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	29,971.36	18,825.40	11,145.96	37.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,352.00	6,002.00	4,350.00	42.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,323.36	24,827.40	15,495.96	38.43
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	40,023.36	24,527.40	15,495.96	38.72
+ GST 7.00/7.00% (S\$)	2,801.64	1,716.92	1,084.72	38.72
Nett Amount (S\$)	42,825.00	26,244.32	16,580.68	38.72

INSPECTION

Date of Assignment: 25/01/2018

Date Inspected: 25/01/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,849.00 FS	*1,479.20 FS
2	1	*FRONT BUMPER SECURING STRIP	Not Necessary	60.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE-CENTER	Cracked	171.00 FS	*136.80 FS
4	1	*FRONT BUMPER CLOSING ELEMENT-LOWER	Not Necessary	180.00 FS	*- FS
5	1	*RADIATOR GRILLE	Cracked	972.00 FS	*777.20 FS
6	2	*FRONT BUMPER GRILLE-LH/RH	Not Necessary	236.00 FS	*- FS
7	1	*FRONT REINFORCEMENT BEAM	Bent	702.00 FS	*561.60 FS
8	2	*FRONT BUMPER SUPPORT-LH/RH	Damaged	38.24 FS	*38.24 FS
9	1	*FRONT BUMPER INNER FOAM	Cracked	107.00 FS	*85.20 FS
10	1	*FRONT BUMPER TOP COVER	Deformed	109.00 FS	*87.20 FS
11	1	*SIGN CAUTION STICKER	Necessary	12.00 FS	*9.28 FS
12	1	*STICKER FOR AIR CONDITIONER	Necessary	7.00 FS	*4.88 FS
13	1	*BONNET RELEASE LEVER	Not Necessary	12.00 FS	*- FS
14	1	*BONNET BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
15	1	*FROTN LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
16	2	*FRONT FENDER-LH/RH	Not Necessary	1,330.00 FS	*- FS
17	2	*FRONT FENDER CLOSING ELEMENT-LH/RH	Not Necessary	88.00 FS	*- FS
18	2	*FRONT FENDER BRACKET-LH/RH	Not Necessary	62.00 FS	*- FS
19	1	*FRONT FENDER RIVET SET	Not Necessary	35.00 FS	*- FS
20	2	*LED HEADLIGHT-LH/RH	Cracked	13,946.00 FS	*11,156.80 FS
21	2	*HEADLIGHT WASH CYLINDER-LH/RH	Not Necessary	368.00 FS	*- FS
22	2	*WASH CYLINDER BRACKET-LH/RH	Not Necessary	11.00 FS	*- FS
23	1	*WASH CYLINDER CORRUGATED PIPE	Deformed	79.00 FS	*62.56 FS
24	1	*BONNET	Dented	2,163.00 FS	*1,730.40 FS
25	2	*BONNET HINGE-LH/RH	Not Necessary	532.00 FS	*- FS
26	2	*BONNET IMPACT PROTECTION-LH/RH	Necessary	48.00 FS	*37.76 FS
27	1	*BONNET IMPACT PROTECTION-CENTER	Necessary	24.00 FS	*18.88 FS
28	2	*FRONT FENDER TOP TRIM-LH/RH OUTER	Not Necessary	40.00 FS	*- FS
29	2	*FRONT FENDER TOP TRIM-LH/RH INNER	Not Necessary	54.00 FS	*- FS
30	2	*BONNET LOCK	Not Necessary	376.00 FS	*- FS
31	2	*BONNET LOCK STRIKER-LH/RH	Not Necessary	88.00 FS	*- FS
32	1	*BONNET LOCK BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
33	1	*FRONT LOCK CARRIER	Cracked	891.00 FS	*712.80 FS
34	2	*RADIATOR SUPPORT	Not Necessary	66.00 FS	*- FS
35	2	*FRT LOCK CARRIER AIR GUIDE-LH/RH	Damaged	46.00 FS	*36.80 FS
36	2	*FRT LOCK CARRIER AIR GUIDE-LH/RH OUTER	Damaged	20.00 FS	*15.36 FS
37	1	*FRT LOCK CARRIER AIR GUIDE-UPPER	Not Necessary	14.00 FS	*- FS
38	1	*A/C CONDENSER	Dented	540.00 FS	*432.00 FS
39	1	*A/C CONDENSER PRESSURE SENSOR	Not Necessary	165.00 FS	*- FS
40	1	*A/C CONDENSER PRESSURE VALVE	Not Necessary	46.00 FS	*- FS
41	1	*RADIATOR	Dented	585.00 FS	*468.00 FS
42	1	*RADIATOR RUBBER BUSH SET	Not Necessary	38.00 FS	*- FS
43	1	*ADDITIONAL RADIATOR-OUTER	Dented	455.00 FS	*364.00 FS
44	1	*COOLANT	Necessary	133.00 FS	*106.24 FS
45	1	*RADIATOR FAN RING	Not Necessary	230.00 FS	*- FS
46	1	*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	2,055.00 FS	*- FS
47	1	*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
48	1	*SUNDRIES	Necessary	400.00 FS	*40.08 FS
49	2	*FRONT REINFORCEMENT BEAM BRACKET-LH/RH	Bent	312.00 FS	*312.00 FS
50	1	*FRONT REINFORCEMENT BEAM BOLT SET	Bent	33.12 FS	*33.12 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 29,971.36 18,825.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER,RADIATOR,CHARGED AIR COOLER,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,100.00	1,100.00
3	TO DISMANTLE FRONT BUMPER,BOTH FRONT FENDERS,BONNET AND HEADLIGHTS.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RENEW DAMAGED PANELS.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,400.00	2,750.00
4	TO RESPRAY FRONT BUMPER,BOTH FRONT FENDERS,BONNET AND HINGES	New	3,300.00	1,600.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			10,352.00	6,002.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >