



# 樹發汽車修理廠 SHU FATT AUTO WORKS

9-115

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo  
13<sup>th</sup> January 2018  
TP

## SKP 5144 X NISSAN SYLPHY

		S\$	
Spare Parts	1 Rear bumper.	667.00	Nett <del>Rx</del>
	2 Rear bumper side retainers. @\$38.60	77.20	Nett x
	1 Rt rear bumper reflector.	58.00	Nett x
	1 Set rear bumper clips.	52.80	Snet x
		855.00	
Less 10% on Nett		80.22	
		774.78	
Labour	To knock rear support panel, rear inner panel, rear lower panel, rear side panel, renew rear bumper, retainers, reflector and assembly.	400.00	200
	To respray damaged parts.	400.00	200
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.	80.00	x
	To reseal joints, reinsulate, anti rust panels and assembly.	50.00	x
		1704.78	

Falken 205/55R16  
MNTBBAB17Z0020134  
71525

Tanpin 97495749  
-wp-

24/1/18 @ 1130

2 days

Resurvey after repair

sur @ lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: