

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	1,060.00	0.00
Total Labour 530	1,060.00	0.00 530

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	600.00	0.00
Total Spray Painting & Panel Beating	600.00	0.00 560.

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
88-25320-6008		6010299	SIGNAL LAMP LED	1	1,274.10	10.00	1,146.69	Replace	Replace	No <i>Xnn</i>
88-25225-6039		6010298	STOP LAMP LED	2	1,141.70	10.00	2,055.06	Replace	Replace	No <i>cm</i>
F01001-CW273		6010062	REAR TAIL LAMP COVER RH	1	974.70	10.00	877.23	Replace	Replace	No <i>cm</i>
A01001-CW564		6009992	RH SIDE PANEL R11	1	1,782.50	10.00	1,604.25	Repair	Replace	No <i>Ry</i>
TOTAL MATERIALS							4,078.98	5,683.23		
TOTAL MATERIALS(Discounted)							4,078.98	5,683.23		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									