



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



INDIA INTERNATIONAL INSURANCE P/L		NAME :	MS JIANG HONGXIA MICHELLE	WIP :	16264
64 CECIL STREET		ADDRESS :	781 UPPER CHANGI ROAD EAST	EXCESS :	
#04-#05 IOB BUILDING			#04-17	DATE:	25-Jan-18
SINGAPORE 049711			SINGAPORE 486069		
ATTN. :	MOTOR CLAIMS	TEL :	91058308		
FAX :					
VEH NO :	SLP5512E	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWYS920403E09521	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI COOPER F60	DATE REG.:	9-Jun-17	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER ✓ cut	1	M51.12.7.389.377		\$ 2,123.69
2	REAR BUMPER SPOILER ✓ PWR	1	M51.12.7.391.199		\$ 298.63
3	REAR BUMPER LOWER GARNISH ✓ cut	1	M51.12.7.411.083		\$ 232.00
4	REAR BUMPER CLAMP ✓	1	M51.12.7.482.914		\$ 23.25
5	REAR BUMPER BLIND RIVET ✓ - NRC -	2	B51.24.8.226.003		\$ 9.76
6	REAR BUMPER GROMMET ✓	4	B51.12.7.461.407		\$ 15.24
7	REAR BUMPER FASTENER ✓	4	M07.14.9.807.127		\$ 4.52
8	ULTRASONIC SENSOR GASKET ✓	4	B66.20.9.283.203		\$ 25.24
9	ULTRASONIC SENSOR ✓ DMG	2	B66.20.9.274.427		\$ 621.76
TOTAL PARTS					\$ 3,354.09
					\$ -
TOTAL PARTS COST					\$ 3,354.09

Labour Description

1	TO REPLACE REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,000.00 840
2	TO RESPRAY REAR BUMPER.			\$ 1,000.00 800
3	TO TRANSFER THE REVERSE SENSORS.			\$ 500.00 420
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00 180
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 350.00 280
6	SUNDRIES.		NETT	\$ 100.00 50

TOTAL LABOUR	\$ -	\$ 3,200.00
TOTAL PARTS	\$ -	\$ 3,354.09
TOTAL	\$ -	\$ 6,554.09
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -

GRAND TOTAL	\$	-	\$	-
-------------	----	---	----	---

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sebastian
30/1/18.

- Part by part repair
- Photo Before Paint.

90036121

sebastianyeang@lkkauto.com.

3-4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: