

INS. CASE OWNER:

Shundari

CC 6/III1800

1572, P1 ua39

LKK:

IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT

8/1/18

Date / Time:

28/1/18

Registered in Merimen:

28/1/18

Pre-assign / CCU / FTE

SH 9233T



Insured Vehicle No.

Name of Insured

LPR

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

1/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

NON KAM THONG

Driver Tel No.:

(V/L: YES / NO)

SH 6332L

SH 9233T

SLT 8002U



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

21/1/18
11HSLT 8002U - X
SH 9233T - C14/11/17 24561 / WPA3, V08-10/1/18
- C03/11/17 6483 (1/1/18) 02, V08-10/1/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Ol:

After call ltr to Ol:

NA

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to Ol:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3-1-19

Confirm with:

ASHLEY

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

Repair Cost:

GST

SS

1,870.38

Loss of Rental (LOR):

SS

481.50

(3

days)

150

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

2,351.88

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,351.88

Name 1:

HUA HONG PRIVATE LIMITED

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III18001572/R1ua3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 25-01-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9233T	Veh. Inspected	SLT 8002U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	25/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/01/2018	Inspection Date	05/02/2018	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



HUA HONG PRIVATE LIMITED

250 Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

888.02

860.00

1748.02

3 days

Estimate Repair List

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HHTPClaims18-07

Acknowledged by Repairer

Signature:

Date:

29 January 2018

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SLT 8002 U, SH 9233 T & SHD 6332 L ON 01/01/2018 ALONG PIE (EXITING STEVENS RD) AT ABOUT 1220 HOURS

Insured : SNG CHEE LEONG
Vehicle Registration No : SLT 8002 U
Vehicle Make : NISSAN
Vehicle Model : X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Vehicle Chassis No : JN1JANT32Z0001200
Policy No : MT700424832
Date of Accident : 1/1/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 650.80
2	10	Rear Bumper Clip	\$ 5.20	\$ 52.00
3	2	Rear Bumper Retainer (LH/RH)	\$ 45.00	\$ 90.00
4	1	Rear Bumper Lower Grille		\$ 135.00
5	1	Rear Reinforcement		\$ 565.80
6	2	Rear Bumper Reflector (LH/RH)	\$ 75.00	\$ 150.00
				\$ 1,843.60
				Less 28% 30%
				\$ (410.90)
				\$ 1,232.70
7	1	Reverse Sensor (1 set)	NETT	\$ 400.00
				\$ 800.00
				\$ 20.00
				\$ 80.00
				\$ 700.00
				\$ 3,212.70
				\$ 224.89
				\$ 3,437.59

To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear end panel and all area affected by accident.

To perform wire checking.

To dismantie & refit rear bumper sensor.

To spray rear bumper, rear reinforcement and rear panel.

Authorised by Claims Dept.

Mrs Tan @ 9639 9195



HUA HONG PRIVATE LIMITED

25D Sungei Kadul Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

29 January 2018

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HHTPClaims18-07

Acknowledged by Repairer

Signature:

Date:

ACCIDENT INVOLVING SLT 8002 U, SH 9233 T & SHD 6332 L ON 01/01/2018 ALONG PIE
(EXITING STEVENS RD) AT ABOUT 1220 HOURS

Insured : SNG CHEE LEONG
Vehicle Registration No : SLT 8002 U
Vehicle Make : NISSAN
Vehicle Model : X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Vehicle Chassis No : JN1JANT32Z0001200
Policy No : MT/00424832
Date of Accident : 1/1/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 650.80 <i>PE</i>
2	10	Rear Bumper Clip	\$ 5.20	\$ 52.00 <i>see</i>
3	2	Rear Bumper Retainer (LH/RH)	\$ 45.00	\$ 90.00 <i>X</i>
4	1	Rear Bumper Lower Grille		\$ 135.00 <i>?</i>
5	1	Rear Reinforcement		\$ 565.80 <i>?</i>
6	2	Rear Bumper Reflector (LH/RH)	\$ 75.00	\$ 150.00 <i>X</i>
				\$ 1,643.60
				Less 25% \$ (410.90)
				\$ 1,232.70
7	1	Reverse Sensor (1 set)	NETT	\$ 400.00 <i>200?</i>
To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear end panel and all area affected by accident.				\$ 800.00 <i>200</i>
To perform wire checking.				\$ 20.00 <i>HP 90010068</i>
To dismantle & refit rear bumper sensor.				\$ 60.00 <i>40 2 days</i>
To spray rear bumper, rear reinforcement and rear panel.				\$ 700.00 <i>200 P/P</i>
				\$ 3,212.70
				\$ 224.89
				\$ 3,437.59

Authorised by Claims Dept
Mrs Tan @ 9639 9195

Print Received Message

This mail is associated with :

***SLT8002U (MCT18010008)
[SH9233T]**

TP
SNG CHEE LEONG
Jan 1 2018 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hua Hong Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 07/05/2019 10:06 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2351.88) - SLT8002U - Claim Handler: Sundari Nagarajan

Approved:2351.88:Agree to do direct settlement. Please seek mandate through merimen

2018/2/5

AUTHORIZATION TO ACT

I, SNG CHEE LEONG ("the third party claimant")
of 31K 550 CHOA CHU KANG STREET 52 #06-65 (GROEP) (address),
owner of SLT 8002 M (vehicle no.) hereby authorize
HMA HONG PRIVATE LIMITED
("the workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
vehicle no. SLT 8002 M that was damaged pursuant to the
accident which occurred on 01/01/2018 (date) along PIE
(EXITING STEVENS ROAD) (location)
involving vehicle no/s SH 933T, SHD 6332 L
("the accident").

I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 05 day of Feb (month) 20 18 (year)


Signed by "the third party claimant"



Signed by "the workshop"
(with chop)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18010008
Claimant Ref: SLT 8002U

We/I, HUA HONG PRIVATE LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 1,870.38 (repair cost), S\$ 481.50 (loss of ~~rental~~/rental), S\$ - (search fee), vehicle no. SLT 8002U that was damaged pursuant to the accident which occurred on 01.01.2018 (date) at PIE (location) involving vehicle no. SH 9233T (insured vehicle). This is pursuant to the inspection conducted on 05/02/2018 (date) at "the workshop".

We/I confirm that we/I am/am authorized by the owner SNG CHEE LEONG ("the third party claimant") of vehicle no. SLT 8002U to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLT 8002U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,351.89 to HUA HONG PRIVATE LIMITED

Dated this 6 day of June 20 19

CLAIMANT:

Signature:


Signed by "the workshop" (with chop)

Name:

Hua Hong Pte Ltd

NRIC:

200900308M

Address:

25B Sungei Kadut St 1
5729332

Nationality:

Occupation:

WITNESS:

Signature:



MRB

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

Nationality:

Occupation:



HUA HONG PRIVATE LIMITED

250 Sungei Kadut Street | Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

31/1/18
18/2/18
15/4/18

TAX INVOICE

26 December 2018

HHTPClaims18-07F

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SLT 8002 U, SH 9233 T & SHD 6332 L ON 01/01/2018 ALONG PIE (EXITING STEVENS RD) AT ABOUT 1220 HOURS

Insured : SNG CHEE LEONG
Vehicle Registration No : SLT 8002 U
Vehicle Make : NISSAN
Vehicle Model : X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Vehicle Chassis No : JN1JANT32Z0001200
Policy No : MT/00424832
Date of Accident : 01/01/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 650.80
2	10	Rear Bumper Clip	\$ 5.20	\$ 52.00
3	1	Rear Reinforcement		\$ 565.80
				\$ 1,268.60
				Less 30%
				\$ (380.58)
				\$ 888.02
4	1	Reverse Sensor (1 set)	Nett	\$ 200.00
To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear end panel and all area affected by accident.				\$ 300.00
To perform wire checking.				\$ 20.00
To dismantle & refit rear bumper sensor.				\$ 40.00
To spray rear bumper, rear reinforcement and rear panel.				\$ 300.00
				\$ 1,748.02
				7% GST
				\$ 122.36
				\$ 1,870.38
Loss of rental @ 3 days (receipt attached)				\$ 481.50
Total				\$ 2,351.88



Authorised by-Claims Dept
Mrs Tan @ 9639 9195



HUA HONG PRIVATE LIMITED


250 SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

VEHICLE RENTAL AGREEMENT

Date: 05.02.2018

V.R.A No.: 2018020006

Vehicle Rental Agreement made between HUA HONG PRIVATE LIMITED (THE OWNER) and THE HIRER/DRIVER, under the terms and conditions as set forth.

HIRER'S DETAILS					
NAME OF HIRER	SNG CHEE LEONG	NRIC No.	S 7146830 E	Gender	MALE
ADDRESS (AS STATED IN NRIC)	BLOCK 550 CHOA CHU KANG STREET 52 #06-65, S680550				
EMAIL ADDRESS			CONTACT NUMBER		
DRIVING LICENCE No.	S 7146830 E	DATE OF BIRTH	20.12.1971		
DRIVING EXPRIENCE	24 YEARS	NATIONALITY	SINGAPOREAN	PLACE OF ISSUE	SINGAPORE
VEHICLE DETAILS					
MAKE / MODEL	BMW 318i		VEHICLE REG No.	SKP 9859 R	
LEFT SIDE 			LEGEND: O - DENT X - SCRATCH C - CHIP R - RUST	PETROL 	
RIGHT SIDE 					
DATE OUT	5/2/2018	TIME OUT	1130 HRS	HIRER'S SIGNATURE	
DATE IN	8/2/2018	TIME IN	1100 HRS	HIRER'S SIGNATURE	
RENTAL DETAILS					
SECURITY DEPOSIT	S\$ NA		INSURANCE EXCESS	Please View Terms & Conditions Clause 27.	
RENTAL CHARGES	S\$ 150 /- @ PER DAY		NUMBER OF DAY(S) / WEEK(S)	3 days	
TOTAL	S\$ 450 /-	GST	S\$ 31.50	GRAND TOTAL	S\$ 481.50
REMARK(S)					


AUTHORISED SIGNATURE


HIRER'S NAME, NRIC & SIGN

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jan 2018 Edit Reg		05 Feb 2018 00:00 Edit Adj Rpt	S\$1,748.02 Edit Estimates	S\$1,748.02 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	SNG CHEE LEONG , ID: 57146830E								
Vehicle Reg. No.:	SLT8002U	Date of Loss:	01/01/2018 12:00 - :59 [25 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18010008	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH9233T	Policy No. (Claimant):	MT/00424832						
		Excess:							
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 05/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (07/05/2019): Alert - Adj Mandate Approved (S\$2351.88) - SLT8002U - Claim Handler: Sundari Nag... - III_SG (26/01/2018): Alert - Adj Mandate Approved (S\$0.00) - SLT8002U - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT8002U (MCT18010008)
[SH9233T]
TP
SNG CHEE LEONG
Jan 1 2018 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hua Hong Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	07/05/19 09:42	General View		Load JPG	☒						
2	07/05/19 09:42	General View		Load JPG	☒						
3	07/05/19 09:42	General View		Load JPG	☒						
4	07/05/19 09:42	General View		Load JPG	☒						
5	07/05/19 09:42	General View		Load JPG	☒						
6	07/05/19 09:42	General View		Load JPG	☒						
7	07/05/19 09:42	General View		Load JPG	☒						
8	07/05/19 09:42	General View		Load JPG	☒						
9	07/05/19 09:42	General View		Load JPG	☒						
10	07/05/19 09:42	General View		Load JPG	☒						
11	07/05/19 09:42	General View		Load JPG	☒						
12	07/05/19 09:42	General View		Load JPG	☒						
13	07/05/19 09:42	General View		Load JPG	☒						
14	07/05/19 09:42	General View		Load JPG	☒						
15	07/05/19 09:42	General View		Load JPG	☒						
16	07/05/19 09:42	General View		Load JPG	☒						
17	07/05/19 09:42	General View		Load JPG	☒						
18	07/05/19 09:42	General View		Load JPG	☒						
19	07/05/19 09:42	General View		Load JPG	☒						
20	07/05/19 09:42	General View		Load JPG	☒						
21	07/05/19 09:42	General View		Load JPG	☒						
22	07/05/19 09:42	General View		Load JPG	☒						
23	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
24	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
25	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
26	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
27	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
28	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
29	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
30	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
31	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
32	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
33	07/05/19 09:43	Reinspection Photo		Load JPG	☒						
Documentation									1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	25/01/18 19:05	TP GIA REPORT		Load PDF							
2	07/02/18 13:36	TP ESTIMATE - MARKED		Load PDF							

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	07/05/19 09:44	RENTAL INVOICE	 Load PDF	
4	04/07/19 12:31	WORKSHOP INVOICE & LOD	 Load PDF	
5	04/07/19 12:31	AUTHORISATION TO ACT FORM	 Load PDF	
6	04/07/19 12:31	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/01/18 08:38	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer. Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18001572/R1JA3Q2

Date: 04/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : SLT8002U **Insured Vehicle No :** SH9233T
 Date of Loss: 01/01/2018 Nature of Claim: TP Claim No: MCT18010008

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT8002U**
 Make & Model: NISSAN X-TRAIL, 2.0 CVT (A) Engine No: MR20785264B
 Reg. Date: 26/11/2015 (Man. Year: 2015) Chassis No: JN1JANT32Z0001200
 Colour: Grey Odometer: 35523 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R20 Rear Tyre Size: 255/45 R20
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,632.70	1,088.02	544.68	33.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	660.00	920.00	58.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,212.70	1,748.02	1,464.68	45.59
+ GST 7.00/7.00% (S\$)	224.89	122.36	102.53	45.59
Nett Amount (S\$)	3,437.59	1,870.38	1,567.21	45.59
+ Car Rental (3.0 x S\$150.00/day + 7.00% GST) (S\$)		481.50		
	Nett Liability (S\$)	2,351.88		

INSPECTION

Date of Assignment: 05/02/2018
 Date Inspected: 05/02/2018 Inspected At: Hua Hong Pte Ltd (Sungei Kadut)
 25D Sungei Kadut Street 1
 Singapore 729332
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 May 2019)	
Parts:	N/A	NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8002U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	650.80 FL	*650.80 FL
2	10		*REAR BUMPER CLIP	Necessary	52.00 FL	*52.00 FL
3	2		*REAR BUMPER RETAINER (LH/RH)	Not Necessary	90.00 FL	*- FL
4	1		*REAR BUMPER LOWER GRILLE	Not Necessary	135.00 FL	*- FL
5	1		*REAR REINFORCEMENT	Bent	565.80 FL	*565.80 FL
6	2		*REAR BUMPER REFLECTOR (LH/RH)	Not Necessary	150.00 FL	*- FL
7	1		*SET REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
					Sub Total (\$\$)	2,043.60 1,468.60
					- List Item Discount on L Items 25.00/30.00% (\$\$)	410.90 380.58
					Total Parts (\$\$)	1,632.70 1,088.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & CHARGE REAR BUMPER ,REAR REINFORCEMENT ,KNOCKING & PULL STRAIGHT REAR END PANEL AND ALL AREA AFFECTED BY ACCIDENT	New	800.00	300.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO DISMANTLE & REFIT REAR BUMPER SENSOR	New	60.00	40.00
4	TO SPRAY REAR BUMPER ,REAR REINFORCEMENT AND REAR PANEL	New	700.00	300.00
Gross Labour Cost (S\$)			1,580.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >