

20/03/2002

ASS. REC. BY:

REF:

CS/CTI18001590/Utd307

Special Instruction:

Surveyor:
Meunier

Marcus

ASSIGNMENT (Office)

From (Person):

Sharon Han

of

CTI

Date/Time:

26/1/18 @ 1:31pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD5861D

Insured:

GV1359K

at Workshop m/s

Liu's Brother

Tel:

67411730

of

Blk 1, Kaki Blk Ave 6 #01-01 Autobay

Policy No:

DMCVSN0152571716

Claim No:

SNM18D00443C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/01/2018

CA / REV / REP. / REV 24 HRS

Imp

H.O.D. Endorsement:

Date/Time:

2:25pm @ 26/1/18

Person Contacted:

Susan

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

(08/11/13) wef

ASS. REC. BY: *Marius*

REF:

C71/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *6BD5861D*at Workshop m/s *11u's Bm*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *6BD5861D*Yr Regn: *1/15*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CM*Make: *Fiat Doblo*c.c. *1598*Colour: *white*

A/C: Insured / Std / NI / NA

Sp. Reading: *76581*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *2FA26300006192634*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *195/60R16*

R: _____

BS / DUN / EXNOVA / *GV* / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *22/1/18*D.O.I. *26/1/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/1/18 Confirmed L/S & H250 with Susan.
(Red: 7276-90 : 63%)

Date/Time, File Pass to? _____



Preli. Report

1/31/18 Typist

Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: *4*

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS. \$ _____

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: *TP*Lump Sum / I.B.I. (\$) *4250*

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	26 Jan 2018		26 Jan 2018 13:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HENG BOON SENG CONSTRUCTION PTE LTD, Co. Reg. No.: 198500593R		
Main Claimant:	STVE PTE LTD, Co. Reg. No.: 198703585C		
Vehicle Reg. No.:	GBD5861D	Date of Loss:	22/01/2018 17:00 - :59
Claim Type:	TP / SNM18D00443C02	Policy/Cover Note No.:	DMCVSN0152571716 (Third Party Only)
Vehicle Reg. No. (Insured):	GV1359K	Policy No. (Claimant):	D-17087422MFCV
		Excess:	S\$0.00
Repairer:	Lius Brother Auto Workshop (HQ) Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, 417883 Kaki Bukit - Tel: 67411730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/02/2018]		
Driver/Custodian (Insured):	HENG SEOW YONG (65 / Male), NRIC: S0870110E, Tel: +6596158784		
Adj. Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CT118001590/Utd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 26-01-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GV 1359K	Veh. Inspected	GBD 5861D	
Policy No.	DMCVSN0152571716	Coverage (\$)	0.00	
Claim No.	SNM18D00443C02	Excess (\$)	0.00	
Assign From	MERIMEN (SHARON HAN)	Assign Date	26/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/01/2018	Inspection Date		
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-012826

Date of Request: 24/01/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 24/01/2018
Enquiry By Susan Low Siew Yian
TP Vehicle No. GV1359K
Accident Date 22/01/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GV1359K	China Taiping Insurance (Singapore) Pte. Ltd.	07/12/2017-06/12/2018	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2018 14:52
Date Of Accident	22/01/2018 17:20
Exact Location Of Accident	ALG SLIP RD OF JLN BUKIT MERAH TURNING LEFT TO CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD5861D
Insured/Policyholder	
Name Of Registered Owner	STVE PTE LTD
Co Reg No	198703585C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90493086

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087422MFCV
Cover Note Number	N.A.

Driver

Name of Driver	CHUA LEE KEONG
NRIC No	S7537311B
Date Of Birth	03/12/1975
Occupation	OUTDOOR
Date Of Driving Pass	28/11/1998
Driving Experience	19 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90493086
Fax Number	
Contact Number	
Email Address	CHUA.ANDYLEEKEONG@SGP.FUJIXEROX.COM


[illegible]

x Andy

23/1/84

VERIFIED BY AJAX MARK
REPORTING OFFICER
Mustafa Karami

Driver's Signature (Must be in ink) / Date & Time

[illegible]

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3585C

Vehicle Details

Vehicle No.: GBD5861D

Vehicle to be Exported: No

Intended De-registration Date: 24 Jan 2018

Vehicle Make: FIAT

Vehicle Model: DOBLO CARGO SX JTD 1.6MJ PANEL

Primary Colour: White

Manufacturing Year: 2014

Engine No.: 198A30007175033

Chassis No.: ZFA26300006192634

Maximum Power Output: -

Open Market Value: \$19,172.00

Original Registration Date: 19 Jan 2015

First Registration Date: 19 Jan 2015

Transfer Count: 0

Actual ARF Paid: \$959.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:Company

Owner ID:3585C

Vehicle Details

Vehicle No.:GBD5861D

Vehicle to be Exported:No

Intended De-registration Date:26 Jan 2018

Vehicle Make:FIAT

Vehicle Model:DOBLO CARGO SX JTD
1.6MJ PANEL

Primary Colour:White

Manufacturing Year:2014

Engine No.:198A30007175033

Chassis No.:ZFA26300006192634

Maximum Power Output:-

Open Market Value:\$19,172.00

Original Registration Date:19 Jan 2015

First Registration Date:19 Jan 2015

Transfer Count:0

Actual ARF Paid:\$959.00

Intended PARF Rebate Details

PARF Eligibility:No

PARF Eligibility Expiry Date:-

PARF Rebate Amount:\$0.00

Intended COE Rebate Details

COE Expiry Date:18 Jan 2025

COE Category:C - Goods Vehicle & Bus

COE Period(Years):10

PQP Paid:\$39,409.00

COE Rebate Amount:\$27,501.00

Total Rebate Amount:\$27,501.00

The information contained herein is correct as at 26 Jan 2018

OK

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 4 #01-01, Kaki Bukit, Singapore 417883

ROB No: 532917301 Tel: 6741-1730 Fax: 6744-5746 Email: lhb@lhb.com.sg

Invoice/Ref No: GBD5861D180122

Estimate

Customer			
Name:	China Taiping Insurance (Singapore) Pte Ltd	Date:	24-01-18
Address:	Motor Claims Department	Vehicle No:	GBD5861D
	3 Anson Road #16-00	Model/Make:	Fiat Doblo Cargo
	Springleaf Tower		SX JTD 1.6MJ Panel
	Singapore 079909		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>20/2e 651.62</i>	\$ 745.00	
2	Bumper Clips 1 set <i>rec 45.00</i>	\$ 65.00	
3	Bumper Reinforcement <i>320.92</i>	\$ 475.30	
4	Bumper Reflector 02 pcs (@ \$98.60) <i>117</i>	\$ 197.20	X
5	Bumper Reverse Sensor <i>one</i>	\$ 220.00	SN 200.5.~
6	"Corporate Advertisement" Sticker <i>rec</i>	\$ 400.00	SN 280.5.~
7	Rear Rh Tailgate <i>Body 1,858.33</i>	\$ 1,825.90	
8	Tailgate Weatherstrip <i>turn</i>	\$ 237.00	
9	Tailgate Lock <i>100% 168.20</i>	\$ 192.90	
10	Tailgate "Doblo" Emblem <i>rec 65.20</i>	\$ 118.20	
11	Tailgate "Maxi" Emblem <i>rec 52.58</i>	\$ 98.00	
12	Tailgate "6 Pax" Sticker <i>rec</i>	\$ 15.00	SN 105.~
13	Rear Lh Tailgate <i>2 10%</i>	\$ 2,156.30	X
14	Tailgate Weatherstrip <i>11</i>	\$ 279.00	X
15	Tailgate "IOS" Emblem <i>rec</i>	\$ 97.50	
16	Tailgate "Multijet" Emblem <i>rec 65.20</i>	\$ 119.60	
17	Tailgate "70 KM/H" Sticker <i>rec</i>	\$ 15.00	SN 105.~
	To check all wiring & electrical component for proper function	\$ 180.00	30
	Remove and refix rear Rh & Lh tailgate components & wiper mechanism	\$ 160.00	60
	Remove and refix 2 Tailgate windscreen glass	\$ 240.00	100
	Remove and refix rear reverse sensor	\$ 100.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	600
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,600.00	800
	To apply Rust Proofing, reseal tuff coating treatment on accident area	\$ 120.00	50


Total Parts & Labour of estimate for damaged vehicle

\$ 11,526.90

Total amount in Part By Part / Lump Sum basis for repaired vehicle

\$

SPLS:



P-3511.54
10%
3160.39

M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S.N-500
labour-1690
5350.39
4280.31

Not Affected
when
L/S \$ 4250
4 day
take photo after repair

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

RUBI No. 532917930 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: lusbros@ymail.com

Invoice/Ref No: GBD5861D180122

Estimate**Customer**

Name: **China Taiping Insurance (Singapore) Pte Ltd**
Address: **Motor Claims Department**
3 Anson Road #16-00
Springleaf Tower Singapore 079909

Date: **24-01-18**
Vehicle No: **GBD5861D**
Model/Make: **Fiat Doblo Cargo**
SX JTD 1.6MJ Panel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>20/02</i>	\$ 745.00	
2	Bumper Clips 1 set <i>neu</i>	\$ 65.00	
3	Bumper Reinforcement	\$ 475.30	
4	Bumper Reflector 02 pcs (@ S\$98.60) <i>11</i>	\$ 197.20	X
5	Bumper Reverse Sensor <i>one</i>	\$ 220.00	SN 2005.~
6	"Corporate Advertisement" Sticker <i>neu</i>	\$ 400.00	SN 2805.~
7	Rear Rh Tailgate <i>Body</i>	\$ 1,895.90	
8	Tailgate Weatherstrip <i>turn</i>	\$ 237.00	
9	Tailgate Lock <i>upper 100000 TWI</i>	\$ 192.90	
10	Tailgate "Doblo" Emblem	\$ 118.20	
11	Tailgate "Maxi" Emblem <i>neu</i>	\$ 98.00	
12	Tailgate "6 Pax" Sticker <i>neu</i>	\$ 15.00	SN 105.~
13	Rear Lh Tailgate <i>neu</i>	\$ 2,156.30	
14	Tailgate Weatherstrip <i>11</i>	\$ 279.00	X
15	Tailgate "IOS" Emblem <i>neu</i>	\$ 97.50	
16	Tailgate "Multijet" Emblem <i>neu</i>	\$ 119.60	
17	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 15.00	SN 105.~
	To check all wiring & electrical component for proper function	\$ 180.00	30
	Remove and refix rear Rh & Lh tailgate components & wiper mechanism	\$ 160.00	60
	Remove and refix 2 Tailgate windscreen glass	\$ 240.00	100
	Remove and refix rear reverse sensor	\$ 100.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	600
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,600.00	800
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 120.00	50

Total Parts & Labour of estimate for damaged vehicle

\$ 11,526.90

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jan 2018		26 Jan 2018 13:31 Edit Adj Rpt	S\$4,250.00 Edit Estimates	S\$4,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	HENG BOON SENG CONSTRUCTION PTE LTD, Co. Reg. No.: 198500593R		
Main Claimant:	STVE PTE LTD, Co. Reg. No.: 198703585C		
Vehicle Reg. No.:	GBD5861D	Date of Loss:	22/01/2018 17:00 - :59
Claim Type:	TP / SNM18D00443C02	Policy/Cover Note No.:	DMCVSN0152571716 (Third Party Only)
Vehicle Reg. No. (Insured):	GV1359K	Policy No. (Claimant):	D-17087422MFCV
		Excess:	S\$0.00
Repairer:	Lius Brother Auto Workshop (HQ) Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, 417883 Kaki Bukit - Tel: 67411730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/02/2018]		
Driver/Custodian (Insured):	HENG SEOW YONG (65 / Male), NRIC: S0870110E, Tel: +6596158784		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBD5861D (SNM18D00443C02)**
[GV1359K]
TP
STVE PTE LTD
Jan 22 2018 5:00PM
[HENG BOON SENG CONSTRUCTION PTE LTD]
Lius Brother Auto Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	☒	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	23/01/18 15:25	Accident Statement	1	Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
5	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
8	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
9	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
10	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
11	23/01/18 15:21	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
12	23/01/18 15:21	Driving License [Linked Accident Report Documents]	1	Load JPG	☒
13	23/01/18 15:21	Driving License [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/01/18 15:02	General View	1	Load JPG	☒
2	31/01/18 15:02	General View	1	Load JPG	☒
3	31/01/18 15:02	General View	1	Load JPG	☒
4	31/01/18 15:02	General View	1	Load JPG	☒
5	31/01/18 15:02	General View	1	Load JPG	☒
6	31/01/18 15:02	General View	1	Load JPG	☒
7	31/01/18 15:02	General View	1	Load JPG	☒
8	31/01/18 15:02	General View	1	Load JPG	☒
9	31/01/18 15:02	General View	1	Load JPG	☒
10	31/01/18 15:02	General View	1	Load JPG	☒
11	31/01/18 15:02	General View	1	Load JPG	☒
12	31/01/18 15:02	General View	1	Load JPG	☒
13	31/01/18 15:02	General View	1	Load JPG	☒

14	31/01/18 15:02	General View	1	Load JPG	☒
15	31/01/18 15:02	General View	1	Load JPG	☒
16	31/01/18 15:02	General View	1	Load JPG	☒
17	31/01/18 15:02	General View	1	Load JPG	☒
18	31/01/18 15:02	General View	1	Load JPG	☒
19	31/01/18 15:02	General View	1	Load JPG	☒
20	31/01/18 15:02	General View	1	Load JPG	☒
21	31/01/18 15:02	General View	1	Load JPG	☒
22	31/01/18 15:02	General View	1	Load JPG	☒
23	31/01/18 15:02	General View	1	Load JPG	☒
24	31/01/18 15:02	General View	1	Load JPG	☒
25	31/01/18 15:02	General View	1	Load JPG	☒
26	31/01/18 15:02	General View	1	Load JPG	☒
27	31/01/18 15:02	General View	1	Load JPG	☒
28	31/01/18 15:02	General View	1	Load JPG	☒
29	31/01/18 15:02	General View	1	Load JPG	☒
30	31/01/18 15:02	General View	1	Load JPG	☒
31	31/01/18 15:02	General View	1	Load JPG	☒
32	31/01/18 15:02	General View	1	Load JPG	☒
33	31/01/18 15:02	General View	1	Load JPG	☒
34	31/01/18 15:02	General View	1	Load JPG	☒
35	31/01/18 15:02	General View	1	Load JPG	☒
36	31/01/18 15:02	General View	1	Load JPG	☒
37	31/01/18 15:02	General View	1	Load JPG	☒
38	31/01/18 15:02	General View	1	Load JPG	☒
39	31/01/18 15:02	General View	1	Load JPG	☒
40	31/01/18 15:02	General View	1	Load JPG	☒
41	31/01/18 15:02	General View	1	Load JPG	☒
42	31/01/18 15:02	General View	1	Load JPG	☒
43	31/01/18 15:02	General View	1	Load JPG	☒
44	31/01/18 15:02	General View	1	Load JPG	☒
45	31/01/18 15:02	General View	1	Load JPG	☒
46	31/01/18 15:02	General View	1	Load JPG	☒
47	31/01/18 15:02	General View	1	Load JPG	☒
48	31/01/18 15:02	General View	1	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/01/18 13:31	PRS	1 Load PDF	
2	26/01/18 13:31	OI GIA REPORT	1 Load PDF	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	23/01/18 15:21	Sketch Plan [Linked Accident Report Documents]	1 Load JPG	☒
2	23/01/18 15:21	Sketch Plan #2 [Linked Accident Report Documents]	1 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	23/01/18 15:25	Accident Statement	1 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	23/01/18 15:21	Accident Photo	 Load JPG	☒
2	23/01/18 15:21	Accident Photo	 Load JPG	☒
3	23/01/18 15:21	Accident Photo	 Load JPG	☒
4	23/01/18 15:21	Accident Photo	 Load JPG	☒
5	23/01/18 15:21	Accident Photo	 Load JPG	☒
6	23/01/18 15:21	Accident Photo	 Load JPG	☒
7	23/01/18 15:21	Accident Photo	 Load JPG	☒
8	23/01/18 15:21	Accident Photo	 Load JPG	☒
9	23/01/18 15:21	Accident Photo	 Load JPG	☒
10	23/01/18 15:21	Accident Photo	 Load JPG	☒
11	23/01/18 15:21	Accident Photo	 Load JPG	☒
12	23/01/18 15:21	Driving License	 Load JPG	☒
13	23/01/18 15:21	Driving License	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	23/01/18 15:21	Sketch Plan	 Load JPG	☒
2	23/01/18 15:21	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18001639/UTD3E2

Date: 05/02/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN0152571716
Claimant Vehicle No :	GBD5861D	Insured Vehicle No :	GV1359K
Date of Loss:	22/01/2018	Nature of Claim:	TP
		Claim No:	SNM18D00443C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD5861D		
Make & Model:	FIAT DOBLO, 1.3 D SX Cargo (M)	Engine No:	198A30007175033
Reg. Date:	19/01/2015 (Man. Year: 2014)	Chassis No:	ZFA26300006192634
Colour:	White	Odometer:	76581 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,326.90	3,660.39	3,666.51	50.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,690.00	2,510.00	59.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,526.90	5,350.39	6,176.51	53.58
Approved Total (Overridden) (\$\$)		4,250.00		
Nett Amount (\$\$)	11,526.90	4,250.00	7,276.90	63.13

INSPECTION

Date of Assignment:	26/01/2018	
Date Inspected:	26/01/2018 Inspected At:	Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Feb 2018)
Parts: N/A FIAT DOBLO 1.3 D SX Cargo (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBD5861D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	745.00 F	*601.62 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*45.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	475.30 F	*320.92 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	197.20 F	*- FL
5	1		*REAR BUMPER REVERSE SENSOR	Cracked	220.00 FS	*200.00 FS
6	1		*REAR CORPORATE ADVERTISEMENT STICKER	Necessary	400.00 FS	*280.00 FS
7	1		*REAR RH TAILGATE	Badly Dented	1,895.90 F	*1,858.33 FL
8	1		*REAR RH TAILGATE WEATHERSTRIP	Torn	237.00 F	*237.00 FL
9	1		*REAR RH TAILGATE DOBLO EMBLEM	Necessary	118.20 F	*65.20 FL
10	1		*REAR RH TAILGATE MAXI EMBLEM	Necessary	98.00 F	*52.58 FL
11	1		*REAR RH TAILGATE 6 PAX STICKER	Necessary	15.00 FS	*10.00 FS
12	1		*REAR LH TAILGATE	Repair	2,156.30 F	*- FL
13	1		*REAR LH TAILGATE WEATHERSTRIP	Not Necessary	279.00 F	*- FL
14	1		*REAR LH TAILGATE IOS EMBLEM	Necessary	97.50 F	*97.50 FL
15	1		*REAR LH TAILGATE MULTIJET EMBLEM	Necessary	119.60 F	*65.20 FL
16	1		*REAR LH TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
17	1		*REAR RH TAILGATE LOCK LOWER	Twisted	192.90 F	*168.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,326.90	4,011.55
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	351.16
Total Parts (\$\$)	7,326.90	3,660.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	180.00	30.00
2	REMOVE AND REFIX REAR RH & LH TAILGATE COMPONENTS & WIPER MECHANISM	New	160.00	60.00
3	REMOVE AND REFIX 2 TAILGATE WINDSCREEN GLASS	New	240.00	100.00
4	REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	50.00
5	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,800.00	600.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,600.00	800.00
7	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	120.00	50.00
Gross Labour Cost (S\$)			4,200.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >