

## SMRT Accident Vehicle Repair Estimates

AIG

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5179E  
 Ref. No : TAX/01/18/2148  
 Reg. Date : 13/04/2012  
 Vehicle Type : TAXI  
 Make : CHEVROLET EPICA 2.0 VCDI  
 Model : EPICA-2.0  
 Name of Driver : TAN QUEE PENG  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 24/01/2018 11:35:00 PM  
 Accident Reported Date / Time : 25/01/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094287  
 Special Instruction to ARC, if any :  
 SLP340S - AIG - LKK  
 Prepared Date : 25/01/2018 01:27:43 PM



Sebastian.  
 25/1/18.  
 - Lump Sum Repair.  
 - Question mark Item Photo  
 - Photo After Paint.  
 90036121  
 sebastianyeang@lkkauto.com.

**LKK Auto Consultants** hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB126297

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 2,714.07	2,714.07
Other Charges	: 460.00	0.00
<b>TOTAL</b>	<b>: 4,966.07</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 4,950.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	<del>0.00</del> 2 days
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 25/01/2018 02:52:43 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/01/2018 02:52:43 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 1/25/2018 2:53:46 PM

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	676.00	<del>0.00</del> 300
<b>Total Labour</b>	<b>676.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	<del>0.00</del> 200
TO RESPRAY FRONT FENDER RH	378.00	<del>0.00</del> 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY RIM	180.00	0.00 X
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	<del>0.00</del> 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	<del>0.00</del> 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	<del>0.00</del> 20
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>460.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93744489	FRONT	6504592	BUMPER FRT ASSY	1	1,238.00	10.00	1,114.20	Replace	Replace R	No
96633984	FRONT		BRACKET FRT BUMPER SIDE RH	1	9.00	10.00	8.10	Replace	Replace ?	No
96437322	FRONT	6504616	BEZEL FOG LAMP RH ( COVER )	1	26.00	10.00	23.40	Replace	Replace ?	No
96644858	FRONT	6504614	LAMP HEAD RH	1	841.00	10.00	756.90	Replace	Replace ✓ SCR	No
96636328	RIGHT	6504581	PANEL FRT FENDER RH	1	606.00	10.00	545.40	Replace	Replace R	No
	COMMO N	6504666	TYRE RIM	1	328.99	0.00	328.99	Replace	Replace X	No
96634054	FRONT	6504593	BEAM FRT BUMPER IMPACT	1	465.00	10.00	418.50	Replace	Replace ?	No
96634053	FRONT	6504681	ABSORBER ENGY FRT BUMPER	1	219.00	10.00	197.10	Replace	Replace ?	No
<b>TOTAL MATERIALS</b>								<b>3,392.59</b>	<b>3,392.59</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>2,714.07</b>	<b>2,714.07</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									