

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
S068811

ATTN: Motor Claim Department
Your Ref No: OD 0118-6337
Claim Type: Own Damage
Accident Date: 25/01/2018

Estimate No: EST1503228
Date: 25 Jan 2018
Policy No: GA0633777/1
Veh Reg No: SJD7618H
Make/Model: HONDA ODYSSEY 2.4 A
Chassis No: JHMRB18508C203194
Engine No: K24A65003183
Reg. Date: 01/04/2008

Estimate Repair Cost to Vehicle No :SJD7618H

Description	U/Price	Quantity	Price S\$	Amount S\$
Special Net				
1 FRONT NUMBER PLATE WITH CASING <i>Bed</i>	35.00	1 SET	35.00	35.00 <i>35</i>
Spare Parts				
2 FRONT BUMPER <i>Dehnd</i>	370.00	1 PC	370.00	
3 FRONT BUMPER CLIPS <i>n</i>	1.00	10 PC	10.00	
4 FRONT BUMPER SIDE HOLDER - L.H. RH <i>n</i>	12.00	2 PC	24.00	
5 FRONT BUMPER SPOILER <i>Spic</i>	140.00	1 PC	140.00	
6 FRONT REINFORCEMENT <i>Bed</i>	160.00	1 PC	160.00	
7 FRONT GRILLE <i>crulnd</i>	140.00	1 PC	140.00	
8 FRONT GRILLE "HONDA" EMBLEM <i>n</i>	18.00	1 PC	18.00	
9 FRONT GRILLE CHROME GARNISH <i>est n</i>	215.00	1 PC	215.00	
10 FRONT GRILLE CLIPS <i>Adn n</i>	1.00	1 PC	1.00	
			1,381.00	1,381.00 <i>704</i>
Labour				
11 TO REMOVE, REALIGN, REPAIR FRONT BONNET, FRONT SUPPORT PANEL, CUT/WELD, KNOCK OUT DENTS & REPLACE ACCIDENT PARTS	450.00	1 JOB	450.00 <i>300</i>	
12 TO RESPRAY PAINT ON ACCIDENT PORTIONS	500.00	1 JOB	500.00 <i>400</i>	
13 TO REMOVE, REFIX FRONT BUMPER SENSOR	40.00	1 JOB	40.00	
			990.00	990.00 <i>740</i>
Total			S\$ 2,406.00	
Add GST @ 7%				168.42
Total Amount Payable				S\$ 2,574.42

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FIVE HUNDRED SEVENTY FOUR AND CENTS FORTY TWO ONLY

Adrian
P/P 30/01/18
03 Day
B4 Point
Resurveyed
Adrian
R.S. 31/01/18

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

PARTS 704.00
SN 35.00
LAB 740.00
1479.00