



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SMB49X

Ref. No

BUS/01/18/1033

Reg. Date

24/01/2018

Vehicle Type

BUS -12M

Make

MBOC500 (MERCEDES)

Model

MERCEDES MBOC500

Name of Driver

Raja Muhammad Khaled Bin

Raja Basir

Type of Accident

SIDE SWIPE

Date / Time of Accident

19/01/2018 12:45:00 PM

Accident Reported Date / Time :

22/01/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

MSIG

Vehicle is Towed Back?

No

Towed Back Date/Time

19/01/2018

Replacement Vehicle issued?

No


Accident Repair Job Card No :

Special Instruction to ARC, if any :

smb49x - right view mirror broken yn7665r(tp) insured with MSIG

Prepared Date

24/01/2018 11:24:03 AM



Sebastian
25/1/18.
- Lup Sur Repair.
- Photo After Paint
90036121
Sebastianyeong @lkkanto.com.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No :

Mileage

Quotation from ARC

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Adjusted by Surveyor, if applicable

01/01/2000

Total Labout Charges

265.00

Total Spray Painting Charges

132.50

Total Material Charges

0.00

0.00

837.00

837.00

Other Charges

200.00

200.00

TOTAL

1,302.00

1,169.50

Lum Sum Total No. of Repair Days 1,300.00

1,150.00

1.00

0.50 /

Prepared / Adjusted By

Sunny Tan Ah Leong

Arc / Surveyor Sing Off Date

: 01/01/1900 12:00:00 AM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 24/01/2018 12:59:11 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

BUS/01/18/1033

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	265.00	132.50
Total Labour	265.00	132.50

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	200.00	200.00
Total Other Costs	200.00	200.00

BUS/01/18/1033 Page:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
314/143- 690			VIEW MIRROR RH (NEW)	1	1,162.50	10.00	1,046.25	Replace	Replace	No DMG
TOTAL MATERIALS					1,046.25 1,046.25					
TOTAL MATERIALS(Discounted)						837.00	837.00			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

BUS/01/18/1033