

TE

cc 4, AXA 1800 1608, H uas

INSURANCE

WUP

DOI:

ASSIGNMENT

24-01-18

Date / Time:

26/01/18

Registered in Merimen:

24/1/18

Pre-assign / CCU / FTE

SHCS185 G



Insured Vehicle No.:

Name of Insured:

TRANS. CHASSERICE P/L

Insured Tel No.:

HP:

Excess Sec II :SS

5,000.00

D.O.A.:

24/01/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

GUY YEO CHYE

Driver Tel No.:

97369053 (V/L: YES / NO)

Claim No.:

C0468519

Policy No.:

P1680220

Make / Model:

Renault Latitude

Place of Accident:

DUNSTON ROAD

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBF 1933 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

MH7



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

30/1/18

GBF 1933 X : SHCS185 G - X

OI rear-ended to TP.

RECEIVED 1 + MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

THIN By Email

After call ltr to OI:

6/5

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

DIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

8/5/18

Confirm with

Sakyi

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

3800.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

500.00 (\$100 x 5 days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

4307.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4307.45

Name 1:

NEW MOCK TECK MOTOR PTE LTD

Payee 2: (Strive 1/2/3)

S\$

Name 2:

Payee 3: (Strive 4/5/6)

S\$

Name 3:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	Q/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBF1933X Yr Regn: 2016 July  
 Type: M.Car / M.Cycle / Bus / Van / Corv / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Dyac. cc 2982  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 117338 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTFAT35YSOK 20 66/6  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modl: NI / S/Rim / STD A/Rim or  
 Tyre Size: F: 195R15C Westlake  
 R: 155R12C Maxtrex

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front Rear  
 R/Bal. 06 mm R/Bal. 26 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 29/01/18  
 Survey held at NHT

Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TPAXA

L/S - \$ 3800+ (Red: \$ 7733.95/67%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RE \$

) Photos

) Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/AXA18001608/ua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-01-2018	
		Code : AXA2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
	Insured Veh. SHC 5185G	Veh. Inspected	GBF 1933X
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	26/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
	R/H Front Tyre		mm
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
	Accident Date 24/01/2018	Inspection Date	
	Survey held at NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

M-TECH AIRCON & SECURITY ENGINEERING PTE LTD

24/01/2018

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP AXA

JTFAT35Y50K 206616

Thin Thin.

Accident date: 24/01/2018

Estimated repair cost for vehicle no: GBF1933X TOYOTA DYNA 150 M 3.0 '16

S/n	Qty	Items	U/price	Amount
1	1	Rear Tailgate <i>Dented</i>		\$1,714.40 <i>1415.10</i>
2	2	Rear Tailgate Top Side Handle <i>Not Nec</i>	\$187.30	\$374.60 <i>x</i>
3	2	Rear Tailgate Lower Side Lock <i>2nd</i>	\$171.40	\$342.80 <i>x</i>
4	2	Rear Tailgate Lower Side Hinge <i>1st</i>	\$181.70	\$363.40 <i>x</i>
5	1	Rear Tailgate Lower Member <i>Dented</i>		\$750.00 <i>485</i>
6	2	Rear Tail Lamp <i>1st</i>	\$327.50	<del>\$655.00</del> <i>570.60</i>
7	2	Rear Tail Lamp Panel <i>Not nec</i>	\$374.45	\$748.90 <i>x</i>
8	1	Rear Number Plate <i>Bent</i>		\$50.00 <i>30 (SW)</i>
9	1	Rear Number Plate Lamp <i>Not nec</i>		\$131.35 <i>x</i>
10	1	Rear Number Plate Panel <i>Bent</i>		\$127.30 <i>✓</i>
11	1	Rear Spare Tyre Lock <i>Damaged</i>		\$283.00 <i>✓</i>
12	1	Rear Exhaust <i>Bent</i>		<del>\$980.10</del> <i>691.80</i>
13	1	Rear Centre Exhaust <i>Not Nec</i>		\$678.10 <i>x</i>
				<i>3572.80</i>
				<i>2679.60</i>
				<i>SA 10</i>
Subtotal :-				\$7,198.95

S/n	Qty	Items / Special Nett	U/price	Amount
14	1	Rear Tailgate Toyota Sticker <i>2nd</i>		\$80.00 <i>✓</i>
15	1	Rear Tailgate Dyna Sticker <i>1st</i>		\$40.00 <i>✓</i>
16	1	Rear Tailgate 70km/h Sticker <i>2nd</i>		<del>\$30.00</del> <i>15</i>
17	1	Rear Tailgate 13pax Sticker <i>1st</i>		<del>\$30.00</del> <i>15</i>
18	1	Rear Tailgate Aluminium Cover <i>Not Nec</i>		\$450.00 <i>x</i>
19	30	Rear Tailgate Aluminium Cover Rivet <i>Nec</i>	\$1.50	\$45.00 <i>✓</i>
20	1	Rear Step Panel <i>Bent</i>		<del>\$150.00</del> <i>100</i>
21	1	Rear Reverse Sensor <i>Damaged</i>		<del>\$380.00</del> <i>200</i>
				<i>475</i>
Subtotal :-				\$1,205.00

### Labour charges

To remove & refit reverse sensor	\$100.00 <del>50</del>
To remove & refit rear & centre exhaust	\$380.00 <del>00</del>
To check wiring	\$100.00 <del>30</del>
Tuff kote	\$150.00 <del>50</del>
Panel beating	\$1,400.00 <del>700</del>
Spray painting	\$1,000.00 <del>600</del>

Subtotal :- \$3,130.00

Total:- \$11,533.95

total 4734.60  
h/s: 38K  
05 days

38K

05 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4048W

### Vehicle Details

Vehicle No.:	GBF1933X
Vehicle to be Exported:	No
Intended De-registration Date:	24 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2626015
Chassis No.:	JTFAT35Y50K206616
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	26 Jul 2016
First Registration Date:	26 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	25 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$39,882.00
COE Rebate Amount:	\$33,910.00
<b>Total Rebate Amount:</b>	<b>\$33,910.00</b>

The information contained herein is correct as at 24 Jan 2018

OK

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. GBF1933X and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 29 day of 01 20 18.

Signature : Tan  
Name : MTECH ANTON & SECURITY ENGINEERING PTE LTD  
ID No. : 199304048W  
Address : \_\_\_\_\_  
Witness Signature : [Signature]  
Witness Name : Chew Yee Ynn  
Witness ID : SPP266184  
Witness Address : 1 Kaki Bukit Avenue 6 #01-43  
Singapore 417883



**Print Received Message**

This mail is associated with :

**\*GBF1933X (C0468519)**  
**[SHC5185G]**

TP

M-TECH AIR-CON & SECURITY ENGINEERING PTE LTD

Jan 24 2018 12:00AM

[TRANS-CAB SERVICES PTE LTD]

New Hock Teck Motor Pte Ltd

**From:** AXA Insurance Pte Ltd (HQ) (AXA\_SG), sent on 21/04/2018 13:47 PM.  
**To:** LKK\_HQ  
**Subject:** Alert - Adj Mandate Approved (S\$4307.45) - GBF1933X - Claim Handler: Ernest Tay

Approved: 4307.45.

## NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1803-0052/ GBF1933X  
Your Ref : SHC5185G  
Date : 21<sup>st</sup> March 2018

1 Kaki Bukit Avenue 6  
Blk C #01-43 Autobay@KB  
Singapore 417883

AXA Insurance Singapore Pte Ltd  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811

Dear Sirs,

**RE: ACCIDENT INVOLVING GBF1933X & SHC5185G AT DUNEARN ROAD ON 24.01.2018,  
08:45HR**

We are instructed by **M-TECH AIRCON & SECURITY ENGINEERING PTE LTD** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **GBF1933X** was damaged by vehicle **SHC5185G** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 3,800.00
2) Loss of Use for 05 days	\$ 750.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 4,557.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum \$4,557.45 made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,

NEW HOCK TECK MOTOR PTE LTD



## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Tuesday, 6 March 2018 1:54 PM  
**To:** claims@transcab.com.sg  
**Cc:** CS A Team; 'carrisaalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'  
**Subject:** ACCIDENT INVOLVING SHC 5185G AND GBF 1933X ALONG DUNEARN ROAD ON 24/01/2018

06 MARCH 2017

Transcab Taxi  
Singapore

Dear Sir/Mdm,

OUR REF : CC4/AXA18001608/Aua3  
YOUR REF : SHC 5185G

### **ACCIDENT INVOLVING SHC 5185G AND GBF 1933X ALONG DUNEARN ROAD ON 24/01/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **New Hock Teck Motor Pte Ltd** acting on behalf of the owner of GBF 1933X against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

We also wish to advise that there is an excess of S\$5,000.00 attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- (1) Any settlement equal to or above the excess, you shall be liable to make the payment of S\$5,000.00; or
- (2) Any settlement below the excess, you shall be liable for the amount settled.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) within 7 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to [cst@axa.com.sg](mailto:cst@axa.com.sg) or deliver it by hand to AXA's Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com). Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

THIN THIN HLAING  
LKK Auto Consultants Pte Ltd  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

This is a computer generated letter and no signature is required.

Cc Motor Claims Department  
AXA Insurance Pte Ltd

# LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd  
Kaki Bukit Avenue 6  
Blk 1 #01-43  
Singapore 417883

Dear Sir,

Accident on 24/01/18, 0845  
Involving Vehicles GBF1933X, SHC 5185G  
Along Duneam Rd

I/We, the registered owner/driver of vehicle registration no: GBF1933X  
have involved in the above accident.

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, -, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,



Owner's Signature  
(Company's stamp if applicable)

Name: M-TECH AIR-CON & SECURITY ENGINEERING P/L  
NRIC No.: 199304048W  
Date: 29-01-18



redefining / insurance

CLAIM REF : C0468519  
INSURED : TRANS-CAB SERVICES PTE LTD

# DISCHARGE VOUCHER

We/I [M-TECH AIR-CON & SECURITY ENGINEERING PTE LTD. 199304048W] hereby agree to accept the sum of dollars Four Thousand Three Hundred Seven and Cents Forty Five Only (S\$4,307.45) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SHC 5185G as a result of an accident along DUNEARN ROAD on 24/01/2018 of which we/I were/was the driver/owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. GBF 1933X.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SHC 5185G in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SHC 5185G.

Dated this 08 day of 06 2018

Claimant's Signature : \_\_\_\_\_

NRIC no./ Company Stamp : 199304048W

Occupation/ Business : \_\_\_\_\_

Address : \_\_\_\_\_

Telephone No. : 6567 3090

Witness's Name : 新 福 德 車 廠

Witness's Signature : \_\_\_\_\_

Witness's NRIC No. : \_\_\_\_\_

**NEW HOCK TECK MOTOR PTE LTD**  
1 Kaki Bukit Ave 6, Blk C #01-43  
Autobay@Kaki Bukit Singapore 417883  
Tel: 6747 9241 Fax: 6744 7276  
Email: admin@nhtmotor.com  
UEN: 201718370K

*Suly Chong*



新福德車廠私人有限公司

**NEW HOCK TECK MOTOR PTE. LTD.**

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

## TAX INVOICE

**AXA Insurance Singapore Pte Ltd**

8 Shenton Way,

#B1-01,

Singapore 068811

Client: M TECH AIRCON & SECURITY  
ENGINEERING PTE LTD

Invoice No : NPL1803-0052

Date : 21-Mar-18

Date of Accident : 24-Jan-18

Vehicle No. : GBF1933X

Model Type : Toyota Dyna

Descriptions		Amount
Lump Sum Repair Cost		3,800.00
Total		3,800.00

SIN DOLLARS: THREE THOUSAND AND EIGHT HUNDRED ONLY





Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 24 Jan 2018 / 15:36:37

Receipt Date/Time : 24 Jan 2018 / 15:36:37

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-180124-001328

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHC5185G As at 24 Jan 2018/08:45:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SHC5185G Enquiry Fee 20180124153552134762	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180124153557557	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[Print Receipt](#) [OK](#) [Save as PDF](#)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2018		26 Jan 2018 09:47 <a href="#">Edit Adj Rpt</a>	<b>S\$3,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by Insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	M-TECH AIR-CON & SECURITY ENGINEERING PTE LTD, Co. Reg. No.: 199304048W		
Vehicle Reg. No.:	GBF1933X	Date of Loss:	24/01/2018 00:00 - :59 [17 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0468519	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC5185G	Policy No. (Claimant):	SD17V07783/VCV/R00
		Excess:	S\$5,000.00
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Bldg C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Ernest Tay - 6880 4835]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/02/2018]		
Driver/Custodian (Insured):	GDH YEO CHYE (64 / Male), NRIC: S0199569C, Tel: +6597369053		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AXA\_SG (21/04/2018): Alert - Adj Mandate Approved (S\$4307.45) - GBF1933X - Claim Handler: Ernest Tay
- AXA\_SG (11/04/2018): Re: Fw: <MANDATE> Your ref : C0468519 ; Our ref : CC4/AXA18001608/Aua3 [AC...

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBF1933X (C0468519)

[SHC5185G]

TP

M-TECH AIR-CON & SECURITY ENGINEERING PTE LTD

Jan 24 2018 12:00AM

[TRANS-CAB SERVICES PTE LTD]

New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Letters/Correspondences							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AXA Insurance Pte Ltd (HQ)					Thumbnail		Print	
1	26/01/18 09:46	TP SELECT LKK					Load PDF			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown					Edit			
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	07/03/18 13:38	Adjuster Immediate Advice					Load HTM			
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
2	07/03/18 11:37	Chassis Number					Load JPG		<input checked="" type="checkbox"/>	
3	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
4	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
5	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
6	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
7	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
8	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
9	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
10	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
11	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
12	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
13	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
14	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
15	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
16	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
17	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
18	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
19	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
20	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
21	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
22	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
23	07/03/18 11:37	General View					Load JPG		<input checked="" type="checkbox"/>	
24	07/03/18 11:37	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
25	07/03/18 11:37	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
26	07/03/18 11:37	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
27	07/03/18 11:37	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
28	07/03/18 11:37	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
29	07/03/18 11:37	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
30	07/03/18 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	07/03/18 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	07/03/18 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	07/03/18 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	10/05/18 11:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	10/05/18 11:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	10/05/18 11:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	25/01/18 08:49	GIA GBF1933X TP_ABS	 Load PDF	
2	25/01/18 08:49	GIA SHC5185G INSD_ABS	 Load PDF	
3	25/01/18 08:49	EMAIL_ABS	 Load PDF	
4	25/01/18 08:57	WORKSHOP	 Load PDF	
5	25/01/18 12:28	NEW EMAIL_ABS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 13:31	MARK ESTIMATE	 Load PDF	
2	29/03/18 14:09	LTA SEARCH	 Load PDF	
3	16/05/18 13:19	WORKSHOP INVOICE	 Load PDF	
4	16/05/18 13:19	AUTHORISATION TO ACT FORM	 Load PDF	
5	16/05/18 13:19	DISCHARGE VOUCHER	 Load PDF	
6	16/05/18 13:19	LOD	 Load PDF	
7	16/05/18 13:19	LETTER TO OI	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC5185G (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D (M)
	GBF1933X (TP veh)		
Date of Accident:	24/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,533.95
Final Repair Cost	:	\$	3,800.00
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,307.45

5.00 days at \$100.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	:	\$ 4,307.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

16 May  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18001608/AUA3Q2

Date: 16/05/2018

## REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No: P1680520

Claimant Vehicle No: GBF1933X

Insured Vehicle No: SHC5185G

Date of Loss: 24/01/2018

Nature of Claim: TP

Claim No: C0468519

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBF1933X

Make &amp; Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2626015

Reg. Date: 26/07/2016 (Man. Year: 2016)

Chassis No: JTFAT35Y50K206616

Colour: Silver

Odometer: 117338 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C

Front Left Side: West Lake 6 mm

Rear Left Side: Maxtrex 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: Maxtrex 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,403.95	3,204.60	5,199.35	61.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,530.00	1,600.00	51.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,533.95</b>	<b>4,734.60</b>	<b>6,799.35</b>	<b>58.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,533.95</b>	<b>3,800.00</b>	<b>7,733.95</b>	<b>67.05</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,307.45</b>		

## INSPECTION

Date of Assignment: 26/01/2018

Date Inspected: 29/01/2018 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 14 May 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF1933X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (CONSISTENT)	Dented	1,714.40 F	*1,415.10 FL
2	2		*REAR TAILGATE TOP SIDE HANDLE (CONSISTENT)	Not Necessary	374.60 F	*- FL
3	2		*REAR TAILGATE LOWER SIDE LOCK (CONSISTENT)	Not Necessary	342.80 F	*- FL
4	2		*REAR TAILGATE LOWER SIDE HINGE (CONSISTENT)	Not Necessary	363.40 F	*- FL
5	1		*REAR TAILGATE LOWER MEMBER (CONSISTENT)	Dented	750.00 F	*485.00 FL
6	2		*REAR TAIL LAMP (CONSISTENT)	Cut	655.00 F	*570.60 FL
7	2		*REAR TAIL LAMP PANEL (CONSISTENT)	Not Necessary	748.90 F	*- FL
8	1		*REAR NUMBER PLATE (CONSISTENT)	Bent	50.00 FS	*30.00 FS
9	1		*REAR NUMBER PLATE LAMP (CONSISTENT)	Not Necessary	131.35 F	*- FL
10	1		*REAR NUMBER PLATE PANEL (CONSISTENT)	Bent	127.30 F	*127.30 FL
11	1		*REAR SPARE TYRE LOCK (CONSISTENT)	Damaged	283.00 F	*283.00 FL
12	1		*REAR EXHAUST (CONSISTENT)	Bent	980.10 F	*691.80 FL
13	1		*REAR CENTRE EXHAUST (CONSISTENT)	Not Necessary	678.10 F	*- FL
14	1		*REAR TAILGATE TOYOTA STICKER (CONSISTENT)	Necessary	80.00 FS	*80.00 FS
15	1		*REAR TAILGATE DYNA STICKER (CONSISTENT)	Necessary	40.00 FS	*40.00 FS
16	1		*REAR TAILGATE 70KM/H STICKER (CONSISTENT)	Necessary	30.00 FS	*15.00 FS
17	1		*REAR TAILGATE 13PAX STICKER (CONSISTENT)	Necessary	30.00 FS	*15.00 FS
18	1		*REAR TAILGATE ALUMINIUM COVER (CONSISTENT)	Not Necessary	450.00 FS	*- FS
19	1		*REAR TAILGATE ALUMINIUM COVER RIVET (CONSISTENT) (30 PCS)	Necessary	45.00 FS	*45.00 FS
20	1		*REAR STEP PANEL (CONSISTENT)	Bent	150.00 FS	*100.00 FS
21	1		*REAR REVERSE SENSOR (CONSISTENT)	Damaged	380.00 FS	*200.00 FS
					<b>Sub Total (\$\$)</b>	<b>8,403.95 4,097.80</b>
					<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00 893.20</b>
					<b>Total Parts (\$\$)</b>	<b>8,403.95 3,204.60</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	100.00
3	TO CHECK WIRING	New	100.00	30.00
4	TUFF KOTE	New	150.00	50.00
5	PANEL BEATING	New	1,400.00	700.00
6	SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (S\$)			3,130.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >