

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-81 Auto Bay @ Kaki Bukit Singapore 417887

ROB No. 532917993, Tel: 6741-1700 - 731, Fax: 6741-2746, Email: liubro@lynnail.com

Invoice/Ref No: YN3369Y171227

Estimate

Customer

Name: India International Insurance Pte Ltd
Address: Motor Claims Department
64 Cecil Street #04-00 & #05-00
IOB Building, Singapore 049711

Date: 25-01-18
Vehicle No: YN3369Y
Model/Make: Hino FD8JPKA

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Bumper <i>twintec</i>	\$ 300.00	X
2	Tail Lamp <i>one</i>	\$ 375.00	X
3	Tail Lamp Holder <i>an</i>	\$ 200.00	SN X
4	Electronics Box <i>an</i>	\$ 1,400.00	SN X
	To check all wiring & electrical component for proper function	\$ 100.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	- 200
	To putty & spray painting & including touch up paint on accident affected area	\$ 400.00	- 200

Total Parts & Labour of estimate for damaged vehicle

\$ 3,275.00

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$

SDLS:

not Authorized



M/s Liu's Brother Auto Engrg Wks

*P/P 757.50/2
2 day
Take photo after repair
26/1/18*

*1-375
102
337.50
757.50*

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: