

# LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417882

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liubro@ymail.com

Invoice/Ref No: YN3369Y171227

## Estimate

### Customer

Name: India International Insurance Pte Ltd

Address: Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building Singapore 049711

Date: 25-01-18

Vehicle No: YN3369Y

Model/Make: Hino FD8JPKA

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Bumper <i>twintlc</i>	\$ 300.00	X
2	Tail Lamp <i>CNE</i>	\$ 375.00	X
3	Tail Lamp Holder <i>u7</i>	\$ 200.00	SN X
4	Electronics Box <i>u7</i>	\$ 1,400.00	SN X
	To check all wiring & electrical component for proper function	\$ 100.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	- 200
	To putty & spray painting & including touch up paint on accident affected area	\$ 400.00	- 200

Total Parts & Labour of estimate for damaged vehicle

\$ 3,275.00

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$ -

SDLS:

*not Authorised*



M/s Liu's Brother Auto Engrg Wks

*2 hrs  
P/P 757.50/2  
2 day  
Take photo after repair  
26/1/18*

*P- 375  
102  
337.50  
757.50*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: