

ASS. REC. BY

REF: CS/FCI18001610/Kvd3n2

Special Instructions

CWS Kenneth
joanne yang

ASSIGNMENT (Office)

From (Person): joanne yang of FCI Date/Time: 26/1/18 @ 9:21am

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHD 98585 Insured: SHC 8407Y

at Workshop m/s Trans-Cab Tel: 6287 6666

of No. 2 Amk street 63

Policy No: Claim No: D18 000812 MFSH

Sum Insured: Excess:

Make of Veh: DOA 23/01/2018

(Client's Record)

CA / REV / REP: / REV 24 HRS

'up'

Date/Time: 9:25am @ 26/1/18

Person Contacted: Jiang Han

Vehicle IN/OUT

Date/Time	Action/Inspection	Remarks
	SHD 98585 - CC3/AXA16020838/Tieb3y2	D.O.A: 31/10/2016
	SHC 8407Y - X	

29/1/18 Email preli revised to FCI

FCI

26/01/18

SHD 98585

05 14

C

02 00 WS TR PERS 03 PERS 04 WS TR PERS

SHD 98585

Trans-Cab

No. 2 AMIC Street 63

Permit A Latitude
M. White 1 Per
494478

1995

VIFIABLISAUC 277323


C

C

C

C

Ling Lay 215/60R16
Wetlake



BS DUN BANGA G: PS LIA M: DHTS PR BLV
TOYO YOKO

BS

PS

PS

PS

Compass

BS DUN BANGA PS PS LIA M: DHTS PR BLV

NIS Rec

BS DUN BANGA

BS DUN BANGA

BS DUN BANGA

BS DUN BANGA

BS DUN BANGA

BS DUN BANGA

BS DUN BANGA

BS DUN BANGA

BS DUN BANGA

29/1 156 pass to Catherine
1/1m @ 1650

29/1/18 LS \$1850 (Red 21, 025.43, 929)

RECEIVED 29 JAN 2018



Pre-Report

Final Report

Days Of Report 2

Resurvey No. of Trs -

12x15=180

170+180

50

12

29/1- typist

CWS
1850/p

087
30/1/18

412



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001610/Kvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8407Y	Veh. Inspected	SHD 9858S
Policy No.		Coverage (\$)	0.00
Claim No.	D18000812MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	26/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/01/2018	Inspection Date	26/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000812MFSH
Our ref: CS/FCI18001610/Kvd3

Date : 29/1/2018

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 9858S


We thank for your instruction on 26/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/1/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$22,875.43
Revised Estimate Amount	: S\$1,850.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No.: CS/FCI/8001610/Kvd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

VERON

29/1/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	25-01-2018	Our Ref No. D18000812MFSH
Accident Date	23-01-2018	Claim Type. Third Party
Insured Vehicle	SHC8407Y	Third Party Vehicle. SHD9858S
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	JIONG HOW NG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234330)



PRI Documents



Close



PRI Header Details

Claim No	D18000812MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : JIONG HOW NG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: JIONGHOW.NG@TRANCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8407Y	TP Vehicle No	SHD9858S
PRI Recieved Date	25-01-2018 08:06:30 PM	Surveyor Appointed Date	26-01-2018 09:20:41 AM	Surveyor Accept Date	26-01-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-01-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 29 January 2018 4:38 PM
To: 'Claim Workflow System'
Cc: 'JOANNEYONG@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18000812MFSH/1, SHD 9858S (AMEND)
Attachments: SHD 9858S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 9858S
Date of survey: 26/1/2018
Number of days: 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 29 January 2018 12:08 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000812MFSH/1, SHD 9858S

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 9858S
Date of survey: 26/1/2018
Number of days: 2.5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 26 January 2018 11:46 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000812MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, 26 January 2018 9:21 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18000812MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD98585
Vehicle to be Exported:	Yes
Intended De-registration Date:	24 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C001009
Chassis No.:	VF1ABL15AUC277323
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	09 May 2014
First Registration Date:	09 May 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 May 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	08 May 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$60,414.00
COE Rebate Amount:	\$32,383.00
Total Rebate Amount:	\$41,756.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Jan 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9858S - FCIL**AAD1801-259***Not Authored
C/Sy B 1850/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 9858S - JHOW

VF1ABL15AUC277323

RENAULT

LATITUDE

23.01.2018

FCIL**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Br</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>nd / br</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	} X
4	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
5	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	
6	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	
9	1	ROCKER PANEL OUTER LH	\$	<i>N</i> 987.49	
10	1	FENDER PANEL REAR LH	\$	<i>N</i> 3,299.13	
11	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	
12	1	TAILLAMP LH	\$	<i>Sn</i> 552.55	
13	1	TAILLAMP PANEL LH	\$	<i>N</i> 986.70	
14	1	DOOR PANEL REAR LH	\$	<i>N</i> 2,844.66	
15	1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82	
16	1	DOOR HINGE UPPER LH	\$	<i>N</i> 274.50	
17	1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55	
18	1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96	
19	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49	
20	1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52	
21	1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89	
22	1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22	
23	1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60	
24	1	DOOR FINISHER REAR LH	\$	<i>Sn</i> 423.10	
25	1	DOOR WHEATHESTRIIP REAR LH	\$	<i>Sn</i> 410.66	
26	1	DOOR SEAL REAR LH	\$	<i>Sn</i> 162.02	
27	1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>Sn</i> 334.69	
28	1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82	

TOTAL	\$	14,397.14
10%	\$	1,439.71
	\$	12,957.43

Special Nett

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-259

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9858S - FCIL

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4	1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
5	1SET	BUMEP R RETAINER LH CLIP RR	\$	nn	20.00	X
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	—
8	1	TAILLAMP CLIP LH	\$	nn	5.00	} X
9	1SET	WHEELARCH CLIP RR LH	\$	nn	66.00	
10	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
11	1	WINDSCREEN MOULDING	\$	Sn	100.00	
12	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
13	1	CAP HUB LH RR	\$	Sn	35.00	
14	1	RIM LH RR	\$	Sn	385.00	
15	1	TYRE LH RR	\$	Sn	330.00	
16	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	} X
17	1	DOOR STICKER "Classic"	\$	nn	30.00	
18	1	DOOR STICKER "6555-3333"	\$	nn	80.00	

TOTAL	\$	2,208.00
TOTAL PARTS	\$	15,165.43

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	601
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	2001
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Towing Fees	\$	nn 120.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-259**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9858S - FCIL

To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X

TOTAL	\$	7,710.00
Over All Total	\$	22,875.43

(PARTS BY PARTS)**Repair Days***10 Days*
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001610/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8407Y	Veh. Inspected	SHD 9858S	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000812MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	26/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC277323	Colour	METALLIC WHITE / RED	
Odometer	494478	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	LING LONG	9 mm	
L/H Front Tyre	215/60 R16	LING LONG	9 mm	
R/H Rear Tyre	215/60 R16	WEST LAKE	8 mm	
L/H Rear Tyre	215/60 R16	WEST LAKE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/01/2018	Inspection Date	26/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9858S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	987.49	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-

Report Ref No. CS/FCI18001610/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
	LESS 10% DISCOUNT		-1,439.71	-187.73
			12,957.43	1,689.57
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RR LH (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	SERVICEABLE	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-
1	DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
			2,208.00	165.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI18001610/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER LH,FENDER PANEL REAR LH,TAILLAMP PANEL LH,DOOR PANEL REAR LH,DOOR HINGE UPPER LH AND DOOR HINGE LOWER LH.		2,800.00	200.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			7,710.00	480.00
	GRAND TOTAL		22,875.43	2,334.57
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CS/FCI18001610/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.