

REF: CS/MSG18001621 / Gvd3n2

ASS. REC BY: GB

ASSIGNMENT (Office)

Merimen

Elaine Ngu

MSIG

Date/Time: 25/01/2018 @ 4:25 pm

Estimated Cost:

OD (IP) WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 9325X

Insured: SKA 1537B

Tel: 9847 6209

at Workshop no:

Borneo Motors

of

17 Ubi Road 4, 408611

Claim No: 540407

Sum Insured:

Make of Veh:  
(Client's Record)

DGA 09/12/2017  
29/01/18 @ After 9:30am

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 8:44am @ 26/1/18

Person Contacted:

Sam

Vehicle IN/OUT

Date/Time

Action/Instruction

SLC 9325X - X

SKA 1537B - X

31/1/18 Send preli revised by merimen

19/3/18 Final fig \$ 10,712.75 (Recd 2669.80, 2018 confirmed by email)

Xbrl.

MSIG

29/01/18

SLC9325X

30 May 2016

0

SLC 9325X  
Borneo Motors  
17 Ubi Rd 4 408611

Toyota wish  
Beige  
26611

1798

JTDGG20W90J004214

AFTER 9:30am  
SAM 98476209

195/65 R15  
"



Remarks: The van has commenced its repair at the time of inspection

Days of Repair: 8 days  
Consistent? Yes or No  
Res: Yes or No

BB DUN EXNOVA  
TOYO YOKO  
6  
6  
29-01-18  
RPM  
W/S

RECEIVED 19 MAR 2018

Final Report

Days Of Repair: 8  
Res: 1

193 - typist

merimen  
p/p \$ 10,712.75

300
10
310

## Survey Department Check List (Case Handler)

Reference No. : CS/MSG/800/6>1/6rd3  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** \_\_\_\_\_ **):** Case handler to make sure all Information created by the assignment team are ACCURATE.

		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
<b>(1) Office Assign Form</b>					
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

**Surveyor (** \_\_\_\_\_ **):** Case handler to make sure the surveyor completed all required information.

		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
<b>(1) Assignment Form</b>					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

<b>(2) System - (Views/Merimen)</b>					
C	Damaged Vehicle Photographs Uploaded	✓			

<b>(3) Workshop Estimate/Assignment Form</b>					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

<b>(4) System - (Views/Merimen)</b>					
C	Resurvey photo Uploaded	✓			

Check By: VERON 19/3/18  
 Case Handler Date

\*C: Critical \*N: Non-Critical



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001621/Gvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 26-01-2018	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKA 1537B	Veh. Inspected	SLC 9325X
Policy No.	27041845SMP	Coverage (\$)	0.00
Claim No.	540407	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	26/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	09/12/2017	Inspection Date	
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017		25 Jan 2018 16:25 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>LIM SIAN KWANG ANDY, ID: S7824480A</b>		
Main Claimant:	<b>TAN JEE JIAR ANDREW JAIR, ID: S1165379J</b>		
Vehicle Reg. No.:	<b>SLC9325X</b>	Date of Loss:	09/12/2017 00:00 - :59
Claim Type:	<b>TP / 540407</b>	Policy/Cover Note No.:	27041845SMP Coverage: 24/01/2017 - 23/01/2018
Vehicle Reg. No. (Insured):	<b>SKA1537B</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4, 408611 Ubi - Tel: 6631 1868</b>		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]</b>		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/01/2018]</b>		
Adj Asg. Remarks:	Sam informed survey on 29/01/18, anytime after 10am		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 19 March 2018 11:10 AM  
**To:** 'Sam San Joi UBI'; SUR  
**Cc:** Guo Qiang (LKKAuto)  
**Subject:** RE: Guo Qiang: finalize SLC9325X

Dear Sam,

Confirmed finalize amount \$10,712.75 before GST

No of days: 8 days

**Final invoice and all supporting documents sent over to MSIG**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 13 March 2018 1:30 PM  
**To:** 'Sam San Joi UBI' <SanJoi.Sam@borneomotors.com.sg>; SUR <sur@lkkauto.com>  
**Cc:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>  
**Subject:** RE: Guo Qiang: finalize SLC9325X

Dear Sam,

Kindly forward us rear lower floor panel photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Sam San Joi UBI [mailto:SanJoi.Sam@borneomotors.com.sg]  
**Sent:** Tuesday, 13 March 2018 10:00 AM  
**To:** SUR <sur@lkkauto.com>  
**Subject:** Guo Qiang: finalize SLC9325X

## Hasrianah Binte Hassan

---

**From:** Woon Choo Kwok  
**Sent:** Tuesday, 12 December, 2017 9:00 AM  
**To:** Christina Wong; Hasrianah Binte Hassan  
**Cc:** Christopher Chionh; Foo Ai Ngho; Jason Sim  
**Subject:** FW: Direct Settlement(SM) - Accident Involving SLC9325X & SKA1537B DOA 09.12.2017  
**Attachments:** img-17121113713-0001.pdf; DSC07471.JPG; DSC07472.JPG; DSC07473.JPG; DSC07474.JPG; DSC07475.JPG; DSC07476.JPG; DSC07477.JPG; DSC07478.JPG

Dear CW & HAS,

FYA

Best Regards

**Kwok Woon Choo**  
Senior Administrative Officer, Claims Services  
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | [woonchoo\\_kwok@sg.msigg-asia.com](mailto:woonchoo_kwok@sg.msigg-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msigg.com.sg](http://msigg.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Agnes Lee  
**Sent:** Monday, December 11, 2017 5:32 PM  
**To:** Woon Choo Kwok <[WoonChoo\\_Kwok@sg.msigg-asia.com](mailto:WoonChoo_Kwok@sg.msigg-asia.com)>  
**Subject:** FW: Direct Settlement(SM) - Accident Involving SLC9325X & SKA1537B DOA 09.12.2017

**From:** Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]  
**Sent:** 11 December 2017 16:37  
**To:** Claims <[claims@sg.msigg-asia.com](mailto:claims@sg.msigg-asia.com)>  
**Subject:** Direct Settlement(SM) - Accident Involving SLC9325X & SKA1537B DOA 09.12.2017

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SKA1537B thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Sam Joi @ 9847 6209 / 6631 1687** is located at **17 Ubi Road 4** for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

*Warmest Regards,*

*SURAIDAH*

*TPR TEAM, CLAIMS DEPT*

*D: 6631 1887 | F: 6872 7260 | E: [suraidahb.saidi@inchcape.com.sg](mailto:suraidahb.saidi@inchcape.com.sg)*

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

[www.borneomotors.com.sg](http://www.borneomotors.com.sg) | [www.lexus.com.sg](http://www.lexus.com.sg) | [www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg) | [www.hino.com.sg](http://www.hino.com.sg)

---

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

<b>To:</b> MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Elaine Ngu Siau Mei	
<b>Date:</b> 31 Jan 2018	
<b>Preliminary Advice</b>	

<b>Insured Vehicle No :</b> SKA1537B	
<b>TP Vehicle No :</b> SLC9325X	<b>Accident Date :</b> 09/12/2017
<b>Make :</b> TOYOTA WISH	<b>Assignment Date :</b> 25/01/2018
<b>Date of Inspection :</b> 29/01/2018	<b>Est. Duration of Repair :</b> 8.00
<b>Inspection At :</b> BORNEO MOTORS (S) PTE LTD (UBI) 17 UBI ROAD 4 SINGAPORE 408611	

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,382.55
Revised Amount	:S\$	10,800.23
Check Items (Estimated)	:S\$	569.99
<b>Total</b>	<b>:S\$</b>	<b>11,370.22</b>

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5379J
Vehicle Details	
Vehicle No.:	SLC9325X
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Beige
Manufacturing Year:	2016
Engine No.:	2ZR1766877
Chassis No.:	JTDGG20W90J004214
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,953.00
Original Registration Date:	30 May 2016
First Registration Date:	30 May 2016
Transfer Count:	0
Actual ARF Paid:	\$19,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2026
PARF Rebate Amount:	\$14,964.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$42,480.00
<b>Total Rebate Amount:</b>	<b>\$57,444.00</b>

The information contained herein is correct as at 30 Jan 2018

OK

AXA INSURANCE PTE LTD  
8 Shenlon Way, #24-01  
AXA Tower, Singapore 068811  
Customer Service Centre #B1-01  
Tel:(65)63387288 Fax:(65)63382522  
Website:www.axa.com.sg  
GST Registration Number: 199903512M  
customer.service@axa.com.sg



## CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)	
CERTIFICATE NO. : VPA/P1931849	Account No. : 14888
Coverage : Comprehensive (SmartDrive Toyota Prestige)	
Sum Insured : Market Value At The Time Of Loss	
Name of Policy Holder : TAN JEE JIAR ANDREW JAIR	
Vehicle Registration No. : SLC9325X	
Period of Insurance : From 30/05/2017 To 29/05/2018 (Both Dates Inclusive)	
<b>PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*</b>	
(a) The Policyholder The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner	
(b) Any other person who is driving on the Policyholder's order or with his permission Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
<b>LIMITATIONS AS TO USE*</b>	
Use only for social, domestic and pleasure purposes and for the Policyholder's business The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.	
(01)	
<b>Basic Own Damage Excess : SGD 500.00</b>	
An Additional Excess is applicable as follows: S\$2,500.00 for Young or Inexperienced Driver. Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.	
(Please refer to your policy on the terms & conditions)* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.	

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Issued by - SGOAGPH on 18/05/2017

IMPORTANT :

  
Authorized Signature

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1165379J



Name



TAN JEE JIAR ANDREW JAIR

陳玉雅

Race

CHINESE

Date of Birth

Sex

05-11-1955

M

Country of Birth

SINGAPORE

S1165379J

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S1165379J

Name:

TAN JEE JIAR ANDREW JAIR

Birth Date: 05 Nov 1955

Issue Date: 26 May 2003



000511207K



2064905

NRIC No. S1165379J



Blood Group

Date of issue

O

26-05-1994

20 SARACA VIEW  
SINGAPORE 807296  
NRIC No: S1165379J

Date: 12-11-2005 No: 5315916

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

05 Jul 1977



License No: S1165379J

NP 428A

Ubl  
Sam

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/12/2017 09:22
Date Of Accident	09/12/2017 12:35
Exact Location Of Accident	TRAFFIC JUNCT@UPP SERANGOON RD(INFT OF B/22 HOUGAN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC9325X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN JEE JIAR ANDREW JAIR
NRIC No	S1165379J
Email Address	ANDREW.TANJJ@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98776011
Alternative Phone No	OFFICE-92276113
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1931849
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN JEE JIAR ANDREW JAIR
NRIC No	S1165379J
Date Of Birth	05/11/1955
Occupation	INDOOR
Date Of Driving Pass	05/07/1977
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98776011
Fax Number	
Contact Number	OFFICE-92276113
E-Mail Address	ANDREW.TANJJ@HOTMAIL.COM

Address 20 SARACA VIEW  
 Postcode 807296  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: VIDEO FOOTAGE WITH MCA  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKA1537B  
 Vehicle Make/Model/Colour BMW  
 Details Of Properties  
 Name of Driver ANDY LIM  
 NRIC/Passport Number S7824480A  
 Contact Number 92789980  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver) 1

**Details of Witness**

Name  
 Phone Number  
 Email Address

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 11/12/17  
Policyholder's Signature / Date & Time  
OS30

Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

### Sketch Plan



**Describe Circumstances of the Accident**

I was driving along Upper Serangoon Road. Nearing a traffic light, I slowed down as traffic light was about to turn RED. Suddenly, I felt a 'bang' coming from the rear of my vehicle (SLC 9325X).


Coming out from car, I noticed a BMW (SKA 1537B) was behind. I checked my vehicle's rear and saw the damaged rear.

I took photos of the affected cars' parts and the surrounding area, including vehicles.


Driver of BMW (SKA 1537B) was asked by me to move our vehicles to a nearby HDB car park so that we can exchange details and plan the next steps of actions, including reporting procedures.

**Declaration**

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time  
0830hr

\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

Co Reg No : 196700086Z  
 GST-Reg No : MR-8500000-9

**ESTIMATE**

 Online Service Booking :  
 www.toyotasingapore.com.sg  
 Toyota BodyCare Centre  
 17 Ubi Road 4  
 Singapore 409611  
 Tel no. : 6631 1188

 Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 069807 Attn: Motor Claims Dept		S1000004 / ICCUA1	
		Document No	
		Document Date	
		0	Mr Tan Jee Jiar Andrew Jiar 20 Saraca View  Singapore 807296 Mobile: 99776011
		11/12/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	PERNA	S6	30/05/2016	SLC9325X	19741	15669	7DS/SLC9325X/09121
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W90J004214	2ZR1766877		50	Sam San Jai	11/12/2017 10:00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SKA1537B ACC DATE:09/12/2017 DRIVE IN:11/12/2017 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ / 30.00
2	3	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR				✓ / 169.50
3	3	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT GARNIS H. CARPET AND TRIMMING TO ASSIST REPAIR				✓ / 339.00
4	3	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA				✓ / 339.00
5	3	BP-SUBLET REPLACE & INSTALL REAR WINDSCREEN GLASS				✓ / 436.00
6	3	BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLA R FILM				✓ / 480.00
7	3	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓ / 169.50
8	3	BP-SUBLET SEALANT - TAILGATE, REAR END PANEL				✓ / 169.00
9	3	BP-SUBLET REPLACE REAR BUMPER, REAR END PANEL, ETC				✓ / 3390.00
10	3	BP-SUBLET STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				✓ 2112 / 2780.00
11	1	T52159-68907 REAR BUMPER COVER, / re.	1.00	574.80	15.00	488.66 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
	<div style="border: 1px solid black; padding: 5px;"> <p><b>LKK Auto Consultants hence notify the Repairer of the following:</b></p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No legal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div>		Amount Due
			3566738

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLC9325X

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD


**Borneo Motors**



Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

**ESTIMATE**

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)  
 17 Ubi Road 4  
 Singapore 409611  
 Tel no.: 6631 1198

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail		
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004/ICCUA1	Mr Tan Jee Jiar Andrew Jair 20 Saraca View  Singapore 807296 Mobile: 98776011		
		Document No			0
		Document Date			11/12/2017

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HFXNP	S6	30/05/2016	SLC9325X	19741	15669	'7DS/SLC9325X/09121'
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W90J004214	2ZR1766877		60	Sam Sah Jai	11/12/2017 10:00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	2	T52576-68020 L/R SIDE BPR RETAINER, <i>rec</i>	1.00	44.40	15.00	37.74 ✓
13	3	T52156-68030 L/RR BUMPER SUPPORT, <i>X NN</i>	1.00	93.90	15.00	79.81 ✓
14	4	T52575-68020 R/R SIDE BPR RETAINER, <i>X rec</i>	1.00	44.40	15.00	37.74 ✓
15	5	T52155-68030 R/RR BUMPER SUPPORT, <i>X NN</i>	1.00	93.90	15.00	79.81 ✓
16	6	S52161-0K040 CLIPS - <i>rec</i>	10.00	3.90	15.00	33.10 ✓
17	7	T58307-68031 REAR LOWER FLR PANEL, <i>BT (photo)</i>	1.00	520.00	15.00	442.00 ✓
18	8	T52181-68010 ARM, RR BUMPER, <i>X</i>	2.00	52.10	15.00	88.56 ✓
19	9	T57655-68010 REAR FLOOR MEMBER 2, <i>X NN</i>	1.00	106.90	15.00	90.86 ✓
20	0	T57666-68010 L/R LWR BACK PANEL, <i>X NN</i>	1.00	56.90	15.00	48.36 ✓
21	1	T58035-68010 R/RR FLOOR EXTENSION, <i>X NN</i>	1.00	90.40	15.00	76.84 ✓
22	2	T67935-68020 BO PLATE BACK DOOR, <i>X DD</i>	1.00	288.70	15.00	245.39 ✓
23	3	T67005-68041 PANEL ASSY, BACK DOOR, <i>rec</i>	1.00	1428.40	15.00	1214.14 ✓
24	4	T67881-68030 WEATHERSTRIP, BACK, <i>rec</i>	1.00	325.80	15.00	276.93 ✓
25	5	T68105-68071 REAR BACK DOOR GLASS, <i>rec</i>	1.00	1009.20	15.00	857.82 ✓
26	6	T69350-28151 LOCK ASSY, BACK DOOR, <i>X NN</i>	1.00	399.60	13.00	339.66 ✓
27	7	T69430-28050 STRIKER ASSY, BACK, <i>X NN</i>	1.00	39.60	15.00	33.66 ✓
28	8	T90975-02086 FRONT BONNET EMBLEM, <i>X rec</i>	1.00	72.20	15.00	61.37 ✓
29	9	T75444-68010 PLATE, LUGGAGE COMPT (VALVE MATI) - <i>rec</i>	1.00	39.70	15.00	33.74 ✓
30	0	T75443-ELGAN ELEGANCE EMBLEM, <i>rec</i>	1.00	40.00	15.00	34.00 ✓
31	1	SP2061-12010 27 4TS SENSOR, <i>X NN</i>	1.00	151.60	15.00	128.86 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

**3566739**

TO SECURITY GUARD

**3566739**

DATE 11/12/2017  
 TIME 11:31

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLC9325X

CUSTOMER SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

Co Reg No : 196700086Z  
 GST-Reg No : MR-8500000-9

## ESTIMATE

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)  
 17 Ubi Road 4  
 Singapore 409611  
 Tel no. : 6531 1199

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No S1000004 / ICCUAI	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		Document No 0	Mr Tan Jee Jiar Andrew Jair 20 Saraca View	
		Document Date 11/12/2017	Singapore 807296 Mobile: 98776011	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP S6	ZGE20R	30/05/2016	SLC9325X	19741	15669	7DS/SLC9325X/09121
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W90J004214	22R1766877		60	Sam San Joi	11/12/2017 10.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	2	T89997-30070	1.00	160.60	15.00	136.51 ✓
33	3	T08826-08609	1.00	90.08	15.00	76.57 X
34	4	T08826-08682	1.00	173.44	15.00	147.42 X

*Handwritten notes:*  
 ? dm  
 - NOT REC.  
 Lmo Q'imp. - 82880282  
 8 Days.  
 29/1/18.  
 before paint photos.  
 31/1/18

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total	13,382.55
	Please acknowledge receipt of vehicle	Parts	5,089.55	GST 7.00% 936.78 Less 0.00 <b>Amount Due</b> 14,319.33
		Labour	30.00	
		Materials	8,263.00	
		Lubrication/Fluid	0.00	
		Others	0.00	

PLEASE TEAR ALONG PERFORATED LINE

3566740

TO SECURITY GUARD

3566740

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 11/12/2017  
 TIME 11:31

VEHICLE NO SLC9325X

CUSTOMER

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

# TAX INVOICE

Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
Attn: Motor Claims Dept

S1000004 /ICCUA1

39006254

08/03/2018

Mr Tan Jee Jiar Andrew Jair  
20 Saraca View

Singapore 807296

Mobile: 98776011

16 HPXNP S6      ZGE20R    30/05/2016    SLC9325X      26611      15669      '7DS/SLC9325X/09121'

JTDGG20W90J004214      22R1766877      60      Sam San Joi      11/12/2017 10.04    05/02/2018 19.32

QTY	DESCRIPTION	UNIT	PRICE	TOTAL
1	2 BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SKA1537B ACC DATE:09/12/2017 DRIVE IN:11/12/2017 DATE-IN:29/01/2018 DATE SURVEY:29/01/2018 NO OF REPAIR DAYS:8 DAYS BY:GUO QIANG(LKK)			30.00
2	S BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR	A45	169.50	
3	S BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT GARNIS	A45	339.00	
4	S BP-SUBLET H, CARPET AND TRIMMING TO ASSIST REPAIR		339.00	
4	S BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA	A45	436.00	
5	S BP-SUBLET REPLACE & INSTALL REAR WINDSCREEN GLASS	A45	480.00	
6	S BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLA	M30		
	R FILM		169.50	
7	S BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST	A45	160.00	
8	S BP-SUBLET SEALANT - TAILGATE, REAR END PANEL	A45	2712.00	
9	S BP-SUBLET REPLACE REAR BUMPER, REAR END PANEL, ETC	A45		
	STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS		2224.00	
10	S BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR	A45		
	EAS		1.00	
11	1 T52159-68907 COVER RR BUMPER		574.90	15.00
			488.66	

08/03/2018  
13:14

SLC9325X

# TAX INVOICE

Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
Attn: Motor Claims Dept

S1000004 / ICCUA1

39006254

08/03/2018

Mr Tan Jee Jiar Andrew Jair  
20 Saraca View

Singapore 807296

Mobile: 98776011

16 HPXNP S6      ZGE20R    30/05/2016    SLC9325X      26611      15669      '7DS/SLC9325X/09121'  
  
JTDGG20W90J004214      2ZR1766877      60      Sam San Joi      11/12/2017 10.04    05/02/2018 19.32

12	2	T52576-68020	RETAINER RR BUMPER	1.00	44.40	15.00	37.74
13	3	T52575-68020	RETAINER RR BUMPER	1.00	44.40	15.00	37.74
14	4	S52161-0K040	PIECE, RR BUMPER	10.00	3.90	15.00	33.10
15	5	T58307-68031	PANEL LAMP LOWER	1.00	520.00	15.00	442.00
16	6	T67005-68041	PANEL ASSY, BACK DOOR	1.00	1428.40	15.00	1214.14
17	7	T67881-68030	WEATHERSTRIP, BACK	1.00	325.80	15.00	276.93
18	8	T68105-68071	GLASS BACK DOOR	1.00	1009.20	15.00	857.82
19	9	T90975-02086	EMBLEM, SYMBOL	1.00	72.20	15.00	61.37
20	0	T75444-68010	PLATE, LUGGAGE COMPT	1.00	39.70	15.00	33.74
21	1	T75443-ELGAN	ELEGANCE EMBLEM	1.00	40.00	15.00	34.00
22	2	T89997-30070	ANTENNA, ELECTRICAL	1.00	160.60	15.00	136.51

			10,712.75
3,653.75	GST 7.00%		749.89
30.00			0.00
7,029.00			
0.00			
0.00			
			11,462.64

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

08/03/2018  
13:14

SLC9325X

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001621/GVD3N2

Date: 20/03/2018

#### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27041845SMP
Claimant Vehicle No :	SLC9325X	Insured Vehicle No :	SKA1537B
Date of Loss:	09/12/2017	Nature of Claim:	TP <span style="float: right;">Claim No: 540407</span>

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC9325X	Engine No:	2ZR1766877
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W90J004214
Reg. Date:	30/05/2016 (Man. Year: 2016)	Odometer:	26611 km
Colour:	Beige		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,119.55	3,683.75	1,435.80	28.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,263.00	7,029.00	1,234.00	14.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,382.55</b>	<b>10,712.75</b>	<b>2,669.80</b>	<b>19.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>936.78</b>	<b>749.89</b>	<b>186.89</b>	<b>19.95</b>
<b>Nett Amount (S\$)</b>	<b>14,319.33</b>	<b>11,462.64</b>	<b>2,856.69</b>	<b>19.95</b>

#### INSPECTION

Date of Assignment:	25/01/2018	Inspected At:	Borneo Motors (S) Pte Ltd (Ubi)
Date Inspected:	29/01/2018		17 Ubi Road 4
			Singapore 408611

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2018)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC9325X)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	488.66 FS	*488.66 FS
2	1		*L/R SIDE BPR RETAINER	Necessary	37.74 FS	*37.74 FS
3	1		*L/RR BUMPER SUPPORT	Not Necessary	79.81 FS	*- FS
4	1		*R/R SIDE BPR RETAINER	Necessary	37.74 FS	*37.74 FS
5	1		*R/RR BUMPER SUPPORT	Not Necessary	79.81 FS	*- FS
6	10		*CLIPS	Necessary	33.10 FS	*33.10 FS
7	1		*REAR LOWER FLR PANEL	Bent	442.00 FS	*442.00 FS
8	2		*ARM,RR BUMPER	Not Necessary	88.56 FS	*- FS
9	1		*REAR FLOOR MEMBER 2	Not Necessary	90.86 FS	*- FS
10	1		*L/R LWR BACK PANEL	Not Necessary	48.36 FS	*- FS
11	1		*R/RR FLOOR EXTENSION	Not Necessary	76.84 FS	*- FS
12	1		*PLATE BACK DOOR	Not Necessary	245.39 FS	*- FS
13	1		*PANEL ASSY, BACK DOOR	Dented	1,214.14 FS	*1,214.14 FS
14	1		*WEATHERSTRIP, BACK	Necessary	276.93 FS	*276.93 FS
15	1		*REAR BACK DOOR GLASS	Necessary	857.82 FS	*857.82 FS
16	1		*LOCK ASSY, BACK DOOR	Not Necessary	339.66 FS	*- FS
17	1		*STRIKER ASSY, BACK	Not Necessary	33.66 FS	*- FS
18	1		*FRONT BONNET EMBLEM	Necessary	61.37 FS	*61.37 FS
19	1		*PLATE, LUGGAGE COMPT (VALVE MATI	Necessary	33.74 FS	*33.74 FS
20	1		*ELEGANCE EMBLEM	Necessary	34.00 FS	*34.00 FS
21	1		*4T8 SENSOR	Not Necessary	128.86 FS	*- FS
22	1		*ELECTRICAL ANTENNA	Damaged	136.51 FS	*136.51 FS
23	1		*SUPER FAST URETHANE BLACK	Not Necessary	76.57 FS	*- FS
24	1		*SINGLE STEP PRIMER	Not Necessary	147.42 FS	*- FS
25	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
<b>Total Parts (\$\$)</b>					<b>5,119.55</b>	<b>3,683.75</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DRILL HOLE & INSTALL REAR REVERSE SENSOR	New	169.50	169.50
2	REMOVE & INSTALL REAR COMPARTMENT GARNISH,CARPET AND TRIMMING TO ASSIST REPAIR	New	339.00	339.00
3	REMOVE & INSTALL REAR REVERSE CAMERA	New	339.00	339.00
4	REPLACE & INSTALL REAR WINDSCREEN GLASS	New	436.00	436.00
5	SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM	New	480.00	480.00
6	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	169.50	169.50
7	SEALANT-TAILGATE,REAR END PANEL	New	160.00	160.00
8	REPLACE REAR BUMPER,REAR END PANEL,ETC.STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	New	3,390.00	2,712.00
9	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	New	2,780.00	2,224.00
<b>Gross Labour Cost (S\$)</b>			<b>8,263.00</b>	<b>7,029.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >