

10/52110

INS. CASE OWNER: ONG LIL LI | CC6/LPC18001624 / A#302 | LKK: IDAC:

Surveyor: ADRIAN DOI: 25/01/18 Date / Time: 25/01/18  
Registered in Merimen: \_\_\_\_\_

Pre-assign / CCU / FTE



Insured Vehicle No. : SLC 9940U Claim No. : 17/18/18/V005/020352  
Name of Insured : FOONG HUIJUN (FANG HUIJUN) Policy No. : Z17VP05014660  
Insured Tel No. : \_\_\_\_\_ HP: 9784 8785 Make / Model : AVOZ Q7-3.0 (A)  
Excess Sec II :SS \_\_\_\_\_ D.O.A. : 23/01/18 Place of Accident : UPPER BUKIT TIMAH ROAD TOWARDS  
Is driver the owner? (  YES / NO ) Nature of Accident : CHOA CHU KANG

If NO, Driver Name / Age : \_\_\_\_\_ OI GIA REPORT:  YES / NO ; TP GIA REPORT:  YES / NO  
Driver Tel No. : \_\_\_\_\_ (VA  YES / NO ) Insured Liability : % Final ? Yes / No

SLV 6410C



INSRs: WSP: MG Solution  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRs: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRs: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRs: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 19/02/18 Sent By: JIC

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_  
Repair Cost: 49 SS 4,000.00 (6 days) Reduction: 60 % Email  Call

FINAL SETTLEMENT Date/Time: 24/01/18 Confirm with: W WONG Email  Call   
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27  
Repair Cost: (w/g/d) SS 4,280.00 If NO or B 28, Ass. Lia: COI KORE-ENDED TP

Loss of Rental (LOR): SS \_\_\_\_\_ ( \_\_\_\_\_ days)  
Loss of Use (LOU): SS 120.00 x 60 x 7 days  
Loss of Income (LOI): SS \_\_\_\_\_ ( \_\_\_\_\_ x \_\_\_\_\_ days)  
LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]  
GIA/LTA Search SS 7.45  
Medical: SS \_\_\_\_\_  
Disbursement: SS \_\_\_\_\_ (e.g. Tow/ Independent)  
Legal Cost SS \_\_\_\_\_

Total: SS 4,707.45 Global Sum SS: \_\_\_\_\_  
1) Claim status: Normal/Reject/Private Settle  
2) Report Format: \_\_\_\_\_  
3) Survey fee: 450.00

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: SS 4,707.45 Name 1: MG SOLUTION PTE LTD  
Payee 2: (Strike if N.A.) SS \_\_\_\_\_ Name 2: \_\_\_\_\_  
Payee 3: (Strike if N.A.) SS \_\_\_\_\_ Name 3: \_\_\_\_\_

Surzulla

REF:

SLC 93400

### ASSIGNMENT

10/07/08  
2008 July

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLV6410C Yr Regn: 2008 July  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Jazz cc 1339  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 124381 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JHMGD185085215172  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: in order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: in order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/50R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or hankook  
 Front Rear  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 25/01/18  
 Survey held at MG Solution  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 6 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP: / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Date / Time	Action / Instruction
	TP Lon Pcc
	U/S \$4,000.00 (Rep: \$8,498.28 / 68%)
	MV: <del>11.51C</del>
	PV: 7.51C
	Net: 41C.

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_ Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  Site Insp (\$ \_\_\_\_\_)  S+RC LSI  
 Interview (\$ \_\_\_\_\_)  Prices  
 Tech. Invs (\$ \_\_\_\_\_)  Other  
 Weekend (\$ \_\_\_\_\_)  
 TOTAL \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC18001624/Ahs3

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 26-01-2018



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 9940U	Veh. Inspected	SLV 6410C
Policy No.	Z17VP05014660	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	23/01/2018	Inspection Date	25/01/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020352  
Our ref: CC6/LPC18001624/Ahs3

Date: 19.03.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLV 6410C**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25.01.2018 at the premises of M/s MG SOLUTION PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	12,498.28
Revised Estimate Amount	: S\$	4,000.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

ADRIAN LING  
Licensed Appraiser

## Vic (LKKAuto)

---

**From:** MG Solution <mg3solution@gmail.com>  
**Sent:** Tuesday, 14 August, 2018 10:33 AM  
**To:** Vic (LKKAuto)  
**Cc:** Asher Sng (LKKAuto); Admin A  
**Subject:** Re: 3rd Party Claim for Accident involving Vehicle SLV6410C & SLC9940U on 23/01/2018 LKK REF CC6/LPC18001624/Ahb3  
**Attachments:** image001.jpg; TI189203 for SLV6410C (SMG188096).pdf; DV for SLV6410C.pdf

Your Ref: **CC6/LPC18001624/Ahb3 (SLC9940U)**

Our Ref: **SLC6410C**

Dear Vic,

Please find attached **TAX INVOICE** and our duty signed **DV** by our client for your kind onward action. Original copy will sent to you by post.

Best Regards,

**Su Wong**

**MG SOLUTION PTE LTD**

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

On Tue, Jul 24, 2018 at 4:07 PM Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)> wrote:

Without Prejudice

Dear Sharon,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and confirm acceptance of your offer of **\$4,707.45** (all in) to settle your client's claim.

Kindly confirm let the owner chop and sign the attached DV and **forward to us the original signed copy together with the LOD and all supporting documents** for payment processing.

The above amount is to be made payable to MG SOLUTION PTE LTD.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.*

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAuto)

**Sent:** Monday, 23 July, 2018 3:59 PM

**To:** MG Solution

**Cc:** Asher Sng (LKKAuto); Admin A; Vic (LKKAuto)

**Subject:** RE: 3rd Party Claim for Accident involving Vehicle SLV6410C & SLC9940U on 23/01/2018 LKK REF CC6/LPC18001624/Ahb3

Without Prejudice

Dear Su Wong,

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1835N
Vehicle Details	
Vehicle No.:	SLV6410C
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A55000967
Chassis No.:	JHMGD18508S215172
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,896.00
Original Registration Date:	10 Jul 2008
First Registration Date:	10 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$13,896.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2018
PARF Rebate Amount:	\$6,948.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$11,009.00
COE Rebate Amount:	\$500.00
<b>Total Rebate Amount:</b>	<b>\$7,448.00</b>

The information contained herein is correct as at 25 Jan 2018



**Honda Jazz 1.3A**      **\$15,800**      N.A      23-Jun-2008      1,339 cc      -      Hatchback      Available

Cheapest In Market, 1 Owner Only, From Kah Motor, Very Well Maintained, Clean And Neat Interior.

Posted: 04-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.3A**      **\$10,800**      N.A      27-Jun-2008      1,339 cc      109,890 km      Hatchback      Available

Full Loan To Make Ur Dream Become Reality! In House Loan/Balloon Scheme Available With 100% Fast Approval Rate! Lowest Genuine Mileage! Road Tax Paid Till Jun 2018! Nice And Clean Interior! 100% Accid...

Le Motor Enterprise

Posted: 20-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.3A**      **\$11,800**      **\$8,760 /yr**      15-Aug-2008      1,339 cc      -      Hatchback      Available

Graded B by **STRA**

\$0 Down Payment! Free Insurance, Road Tax & Unlimited Warranty! Made And Assembled In Japan, Buy With A Peace Of Mind, Professional After Sales Service Assured, No Hassle When We Can Proceed With Imme...

Dickson Automobile

Posted: 22-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.3A**      **\$11,900**      **\$8,360 /yr**      29-Aug-2008      1,339 cc      180,816 km      Hatchback      Available

Owner Is Selling Due To Relocation. Perfect For New Drivers! Safe And Reliable, Brakes Changed Recently, Don't Miss This Offer! Ideal For COE Renewal. View To Believe! Call To Arrange For Appointment ...

Posted: 10-Dec-2017    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.3A**      **\$11,800**      **\$8,140 /yr**      01-Sep-2008      1,339 cc      -      Hatchback      Available

\$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Confidence! No Hidden Cost! Low Mileage! 100% Accident Free! In House Loan Or Bank Loan Avail...

88 Motor Trading

Posted: 25-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.3A (OPC)**      **\$12,800**      **\$12,740 /yr**      04-Sep-2008      1,339 cc      68,100 km      Hatchback      Available

Very Low Mileage, 1 Owner, Accident Free, Engine And Body Excellent Condition, Sheltered Carpark, Can Renew COE. Can Convert To Full Time Car. Good For Uber, Grab Too. (Please Message).

Posted: 20-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.3A**      **\$12,500**      **\$8,360 /yr**      26-Sep-2008      1,339 cc      -      Hatchback      Available

Consignment Unit, One Of The Cheapest In The Market. Good For Short Term Usage, Quick Sale, Major Accident Free. Low Maintenance. Selling As Its Original Condition. Kindly Call Our Friendly Sales Advi...

Posted: 25-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.5M L Skyroof (OPC)**      **\$15,800**      **\$6,490 /yr**      10-Nov-2008      1,497 cc      -      Hatchback      Available

Well Maintained, Limited Skyroof Unit! Very High Residual Value! Only 1 Owner! Very Low Mileage! Best Value For Money! Extended Warranty Available! Fuel Efficient Yet Gives You The Power You Desire, C...

Dickson Automobile

Posted: 03-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.3A L**      **\$16,800**      **\$9,830 /yr**      11-Nov-2008      1,339 cc      -      Hatchback      Available

1 Owner Only! Well Maintained! Extended Warranty Available! Looking For A Car With Excellent Fuel Economy And Yet Comes With Spacious Interior For Your Comfort, Check This Out. Buy It From Us With A P...

Dickson Automobile

Posted: 22-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



Compare

**Honda Jazz 1.3A L**      **\$15,999**      **\$8,730 /yr**      14-Nov-2008      1,339 cc      -      Hatchback      Available

1 Owner Sporty Blue In Two Tone Honda Jazz 1.3L! Most Popular Honda Hatchback For Your Family And Daily Usage. Very Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful Drive. 100% Accident ...

Posted: 18-Jan-2018    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



**Honda Jazz 1.5A Skyroof**      **\$17,688**      **\$8,620 /yr**      15-Nov-2008      1,497 cc      207,000 km      Hatchback      Available

Family Car. Kah Motor Maintained. Good For Short Term Driving Or Renewal For COE. Drive Away With No Repairs Needed. Ready To Let Go Immediately.

Posted: 24-Dec-2017    Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda

**Honda Jazz 1.5A Skyroof**      **\$17,000**      **\$7,690 /yr**      18-Nov-2008      1,497 cc      90,224 km      Hatchback      Available

Small Scratch On Rear Bumper, Easy Fix, Standard Jazz 1.5A, Paint Still Quite Nice, Genuine Low Mileage(90000 Km), No Mechanical Issue. Fuel Consumption Still Ok, City 13-14km/l, Highway 17-19km/l, Ho...

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

<b>TO</b>	: LONPAC INSURANCE	<b>DATE</b>	: 20/01/2017
<b>ATTENTION</b>	: MOTOR CLAIMS DEPT	<b>JOB TYPE</b>	: T/P CLAIM
<b>ESTIMATE REPORT</b>	:		
<b><u>VEHICLE DETAILS</u></b>			
<b>VEHICLE NO</b>	: SLV6410C	<i>Vic</i>	
<b>MODEL</b>	: HONDA JAZZ 1.4A	<i>JHMGD18508 S215172</i>	
<b>CHASSIS NO</b>	:		
<b><u>ACCIDENT DETAILS</u></b>	<b>DATE</b>	: 25-Jan-18	
	<b>TIME</b>	: 19:20HRS	
<b>THIRD PARTY REQUESTOR / CONTACT</b>	: JACK LI		

**CLAIM DETAIL : PARTS ( REAR )**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Distorted</i>	1	\$ 956.40	\$ <del>956.40</del> <i>849.90</i>
2	TAIL GATE LOGO <i>new</i>	1	\$ 74.50	\$ <del>74.50</del> <i>38.40</i>
3	TAIL GATE EMBLEM 'JAZZ' <i>new</i>	1	\$ 56.20	\$ <del>56.20</del> <i>35.40</i>
4	TAIL GATE DAMPER <i>new</i>	2	\$ 325.00	\$ 650.00 <i>+</i>
5	TAIL GATE STOPPER <i>new</i>	4	\$ 36.20	\$ 144.80 <i>+</i>
6	TAIL GATE INNER HANDLE <i>new</i>	1	\$ 103.50	\$ 103.50 <i>+</i>
7	TAIL GATE INNER LOCK <i>Distorted</i>	1	\$ 256.00	\$ <del>256.00</del> <i>109.40</i>
8	TAIL GATE CATCH <i>new</i>	1	\$ 68.50	\$ 68.50 <i>+</i>
9	TAIL GATE WEATHER STRIP <i>ht</i>	1	\$ 224.00	\$ 224.00 <i>-</i>
10	TAIL GATE INNER TRIM BOARD <i>could</i>	1	\$ 562.00	\$ <del>562.00</del> <i>181.20</i>
11	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 164.00	\$ 164.00 <i>-</i>
12	REAR BUMPER <i>could</i>	1	\$ 550.00	\$ <del>550.00</del> <i>176.10</i>
13	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 85.60	\$ 171.20 <i>+</i>
14	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.30	\$ <del>124.60</del> <i>50.8</i>
15	REAR BUMPER BEAM <i>new</i>	1	\$ 265.00	\$ 265.00 <i>+</i>
16	NUMBER PLATE GARNISH <i>could</i>	1	\$ 211.30	\$ 211.30 <i>-</i>
17	NUMBER PLATE LAMP(SET) <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
18	TAIL LAMP <i>could</i>	2	\$ 356.90	\$ <del>713.80</del> <i>487</i>

19	TAIL LAMP LOWER BRACKET <i>Men</i>	2	\$ 52.40	\$ 104.80	+
20	TAIL LAMP PANEL <i>Men</i>	2	\$ 153.00	\$ 306.00	+
21	REAR FENDER INNER TRIM <i>Delat Panel</i>	2	\$ 275.60	\$ 551.20	+
22	REAR FENDER AIR VENT <i>Men</i>	2	\$ 75.20	\$ 150.40	+
23	REAR END PANEL <i>Dented</i>	1	\$ 524.60	\$ <del>524.60</del>	296.60
24	REAR END PANEL TOP GARNISH <i>Delat</i>	1	\$ 163.50	\$ <del>163.50</del>	63.20
25	FLOOR PANEL <i>Rye</i>	1	\$ 824.00	\$ 824.00	+
26	REAR FLOOR PANEL TOP BOARD <i>Men</i>	1	\$ 235.80	\$ 235.80	+
27	REAR EXHAUST PIPE <i>Best</i>	1	\$ 654.50	\$ <del>654.50</del>	464.80
28	REAR EXHAUST MOUNTING <i>Men</i>	4	\$ 26.50	\$ 106.00	+

4200.50  
3360.40

TOTAL PRICE \$ 9,066.60  
LESS 20% \$ 1,813.32  
SUB TOTAL PRICE \$ 7,253.28

SPECIAL NETT ITEMS ( REAR )

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>n</i>	1	\$ 55.00	\$ 55.00	30
3	TAIL GATE SEALANT <i>Men</i>	1	\$ 80.00	\$ 80.00	+
4	TAIL GATE INNER TRIM CLIP (SET) <i>n</i>	2	\$ 30.00	\$ <del>60.00</del>	20
5	TAIL GATE WINDSCREEN SEALANT <i>n</i>	1	\$ 80.00	\$ <del>80.00</del>	30
6	TAIL GATE WINDSCREEN INNER SEAL <i>n</i>	1	\$ 60.00	\$ <del>60.00</del>	30
7	TAIL GATE WINDSCREEN SOLAR FILM <i>Men</i>	1	\$ 180.00	\$ 180.00	+
8	TAIL LAMP CLIP (SET) <i>Men</i>	2	\$ 30.00	\$ <del>60.00</del>	20
9	TAIL LAMP PANEL SEALANT <i>Men</i>	2	\$ 80.00	\$ 160.00	+
10	REAR FENDER INNER TRIM CLIPS (SET) <i>Ru</i>	2	\$ 30.00	\$ 60.00	+
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>n</i>	2	\$ 30.00	\$ <del>60.00</del>	10
12	REAR END PANEL INSULATION SEAL <i>n</i>	1	\$ 120.00	\$ 120.00	60
13	REAR FLOOR PANEL INSULATION SEAL <i>Men</i>	1	\$ 250.00	\$ 250.00	+
14	REVERSE SENSOR <i>Best</i>	1	\$ 220.00	\$ <del>220.00</del>	200

510

TOTAL \$ 1,495.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,400.00	900	
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00	800	
3	TUFF COAT	\$250.00	40	
4	WIRING CHECK	\$180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$150.00	60	

6	REMOVE AND REFIX TAILGATE WINDSCREEN	<del>\$150.00</del> 120.	
7	TO TRANSFER TAILGATE MECHANISM	<del>\$150.00</del> 80	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	<del>\$150.00</del> 40	
9	CONDUCT WATER LEAKAGE TEST	\$120.00 x	

TOTAL

\$3,750.00

2070

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 8,748.28  
 TOTAL LABOUR COST : \$ 3,750.00  
 TOTAL REPAIR COST : \$ 12,498.28

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King  
 H/S 25/01/18.  
 062p-

total 594040  
 H/S: AK  
 (Nett Value)

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## Shirley Hiew (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Friday, 26 January 2018 4:51 PM  
**To:** Shirley Hiew (LKK Auto); 'mt\_claim@lonpac.com'  
**Cc:** 'ericwoo@lonpac.com'; 'llong@lonpac.com'; GERALD POH WEE BIN; Vic (LKKAuto); Asher Sng (LKKAuto); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SLC9940U (OI : LPC - TBA) AND SLV6410C (TP : LKK REF - CC6/LPC18001624/Ahs3 ) on 23/01/2018  
**Attachments:** SLC9940U.PDF

Dear Shirley

Pls see our Insured's GIA report attached- our Insured has indicated a different TP vehicle no. Kindly verify with Insured before proceeding further.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

**Sent:** Friday, 26 January, 2018 4:32 PM

**To:** 'mt\_claim@lonpac.com'

**Cc:** 'ericwoo@lonpac.com'; 'llong@lonpac.com'; GERALD POH WEE BIN; Vic (LKKAuto); Asher Sng (LKKAuto); Admin A

**Subject:** Direct Settlement - Accident Involving SLC9940U (OI : LPC - TBA) AND SLV6410C (TP : LKK REF - CC6/LPC18001624/Ahs3 ) on 23/01/2018

### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case.

We have inspected TP vehicle SLV 6410C at M/s MG Solution Pte Ltd - Kaki Bukit.

Enclosed for your perusal is:

- TP's GIA report

We will revert preliminary advice in due course.

Meanwhile, Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Retain Registered Vehicle No. (Acknowledgement)**  
**Business Transaction Details**

Business Transaction Ref. No.: 20180108152942134871  
Business Transaction Date: 08 Jan 2018  
Business Transaction Time: 15:29:42

**Vehicle No. Details**

Retained Vehicle No.: SJG6304D  
Retained Vehicle No. Expiry Date: 21 Jan 2018  
Re-assigned Vehicle No.: SLV6410C  
Chassis No.: JHMGD185085215172  
Engine No.: L13A55000967  
Motor No.: -  
Vehicle Make: HONDA  
Vehicle Model: JAZZ 1.4A

**Message**

Vehicle No. retained successfully.

Please note that \$100.00 will be deducted from the motor dealer's GIRO account.

The number plates on the existing vehicle must be changed by 11 Jan 2018 to display the newly assigned vehicle registration number. Failure to comply with this requirement is an offence under the Road Traffic Act.

SJG6304D is not transferable and must be used to register a vehicle by 21 Jan 2018 or \$1,200.00 will be deducted from the motor dealer's GIRO account after the validity period.

OK

**MG SOLUTION PTE LTD**

23 Kaki Bukit Ave 4 (South Wing) #02-03B  
Vicom Inspection Centre, Singapore 415933  
Tel: 6243 1373 Fax: 6243 1376  
GST Reg. No. : 201427944N

**MOTOR CLAIM DISCHARGE**

INSURED: AWESOME RENTALS PTE LTD  
CAR/ LORRY/CYCLE: REG NO: SLV 6410S POLICY NO: .....  
ACCIDENT CLAIM NO: .....

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SLV 6410S .....from the repairers,  
Messrs MG SOLUTION PTE LTD .....

And that all repairs necessary as a result of an accident in which the said vehicle was Involved on or  
about the 23 day of 01 2018 have been completed to my / our satisfaction, and that  
I / we have no further claim on the above company in Respect thereof.

Date: ..... Signature: .....



Co's Stamp: ..... NRIC No: .....

25/1/2018 - PK1  
28/1/2018 - Sunday

vehicle In - 25/1/2018  
vehicle Out - 31/1/2018  
LOW - 7 days x \$60  
= \$420



# MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

## PROFORMA BILL

Bill To:

**LONPAC INSURANCE BHD**

NO.100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Bill No. : 188096

Date : 18-April-2018

Vehicle Number : *SLV 6410C*

ATTN : MOTOR CLAIMS DEPARTMENT

QTY	CLAIM	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,000.00
		BEFORE GST 4,000.00
		7% GST 280.00
		<b>TOTAL \$ 4,280.00</b>

**Tax Invoice will be issue upon amount finalised.**

*Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis with sole intention of resolving the matter amicably without parties resorting to legal proceeding. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.*



Co's stamp & Authorised Signature



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC18001624/Ahb3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 20-08-2018



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 9940U	Veh. Inspected	SLV 6410C
Policy No.	Z17VP05014660	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020352	Excess (\$)	0.00
Assign From		Assign Date	25/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMGD18508S215172	Colour	RED
Odometer	124381	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	HANKOOK	6 mm
L/H Front Tyre	195/50 R15	HANKOOK	6 mm
R/H Rear Tyre	195/50 R15	HANKOOK	6 mm
L/H Rear Tyre	195/50 R15	HANKOOK	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	23/01/2018	Inspection Date	25/01/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6410C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAIL GATE	DISTORTED	956.40	849.90
1	TAIL GATE LOGO	NECESSARY	74.50	38.40
1	TAIL GATE EMBLEM 'JAZZ'	NECESSARY	56.20	35.40
2	TAIL GATE DAMPER @\$325.00	NOT NECESSARY	650.00	-
4	TAIL GATE STOPPER @\$36.20	NOT NECESSARY	144.80	-
1	TAIL GATE INNER HANDLE	NOT NECESSARY	103.50	-
1	TAIL GATE INNER LOCK	DAMAGED	256.00	109.40
1	TAIL GATE CATCH	NOT NECESSARY	68.50	-
1	TAIL GATE WEATHER STRIP	CUT	224.00	224.00
1	TAIL GATE INNER TRIM BOARD	CRACKED	562.00	181.20
1	TAIL GATE WINDSCREEN MOULDING	NECESSARY	164.00	164.00
1	REAR BUMPER	DEFORMED	550.00	476.10
2	REAR BUMPER SIDE BRACKET @\$85.60	NOT NECESSARY	171.20	-
2	REAR BUMPER SIDE RETAINER @\$62.30	NECESSARY	124.60	48.00
1	REAR BUMPER BEAM	NOT NECESSARY	265.00	-
1	NUMBER PLATE GARNISH	CRACKED	211.30	211.30
1	SET NUMBER PLATE LAMP	NOT NECESSARY	150.00	-
2	TAIL LAMP @\$356.90	CRACKED	713.80	487.00
2	TAIL LAMP LOWER BRACKET @\$52.40	NOT NECESSARY	104.80	-
2	TAIL LAMP PANEL @\$153.00	NOT NECESSARY	306.00	-
2	REAR FENDER INNER TRIM @\$275.60	CRACKED	551.20	551.20
2	REAR FENDER AIR VENT @\$75.20	NOT NECESSARY	150.40	-
1	REAR END PANEL	DENTED	524.60	296.60
1	REAR END PANEL TOP GARNISH	DEFORMED	163.50	63.20
1	FLOOR PANEL	TO REPAIR SEE LABOUR	824.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	235.80	-
1	REAR EXHAUST PIPE	BENT	654.50	464.80
4	REAR EXHAUST MOUNTING @\$26.50	NOT NECESSARY	106.00	-
	LESS 20% DISCOUNT		-1,813.32	-840.10
			7,253.28	3,360.40

Report Ref No. CC6/LPC18001624/Ahb3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	55.00	30.00
1	TAIL GATE SEALANT (SN)	NOT NECESSARY	80.00	-
2	SET TAIL GATE INNER TRIM CLIP @\$30.00 (SN)	NECESSARY	60.00	20.00
1	TAIL GATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	30.00
1	TAIL GATE WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	30.00
1	TAIL GATE WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	180.00	-
2	SET TAIL LAMP CLIP @\$30.00 (SN)	NECESSARY	60.00	20.00
2	TAIL LAMP PANEL SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
2	SET REAR FENDER INNER TRIM CLIPS @\$30.00 (SN)	NECESSARY	60.00	60.00
2	SET REAR END PANEL TOP GARNISH CLIPS @\$30.00 (SN)	NECESSARY	60.00	10.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	120.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	250.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,495.00	510.00
<b>LABOUR</b>				
PANEL BEATING ,REMOVAL AND REPLACING PARTS .INCLUSIVE OF THE REPAIR OF FLOOR PANEL . TO SPRAY PAINT AFFECTED AREA.			1,400.00	900.00
TUFF COAT.			1,200.00	800.00
WIRING CHECK .			250.00	40.00
REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.			180.00	30.00
REMOVE AND REFIX TAILGATE WINDSCREEN.			150.00	60.00
TO TRANSFER TAILGATE MECHANISM.			150.00	120.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.			150.00	80.00
CONDUCT WATER LEAKAGE TEST.			150.00	40.00
			120.00	-
			3,750.00	2,070.00
<b>GRAND TOTAL</b>			<b>12,498.28</b>	<b>5,940.40</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,000.00</b>
---	--	--	-----------------

Report Ref No. CC6/LPC18001624/Ahb3n2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**