

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

# **SMRT Accident Vehicle Repair Estimates**

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB118P

Ref. No : TAX/01/18/2150

Reg. Date : 29/12/2016

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : SIM KWANG LONG

Type of Accident : SIDE SWIPE

Date / Time of Accident : 25/01/2018 02:08:00 PM

Accident Reported Date / Time: 25/01/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by :

Vehicle is Towed Back? : No

Towed Back Date/Time


Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024094291

Special Instruction to ARC, if any:

XE2577D - ERGO

Prepared Date : 25/01/2018 03:53:01 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U105768515 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates** 

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labout Charges : 676.00 0.00

Total Spray Painting Charges : 1,116.00 0.00

Total Material Charges : 3,483.41 3,483.41

 Other Charges
 : 460.00
 0.00

 TOTAL
 : 5,735.41
 0.00

 Lum Sum Total
 :
 0.00

 No. of Repair Days
 :
 5.00
 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 25/01/2018 04:50:54 PM 01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/01/2018 04:50:54 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date : Invoice Amount : Prepared Date :

#### **Section D - Details of Repair Estimates**

#### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR LH PORTION	676.00	0.00		
Total Labour	676.00	0.00		

## Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00
TO RESPRAY RIM	180.00	0.00
TO RESPRAY FRONT DOOR LH	378.00	0.00
TO RESPRAY VIEW MIRROR	180.00	0.00
Total Spray Painting & Panel Beating	1,116.00	0.00

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO REMOVE AND REFIX WING MIRROR	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	460.00	0.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
53802- 47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No
75374- 47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
42611 47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace	No
67002- 47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
87940- 47310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace	No
81740- 52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace	No
87945- 74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace	No
TOTAL MATERIALS							3,483.42	3,483.41		
	TOTAL MATERIALS(Discounted)							3,483.41	3,483.41	

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									