

REF: CS/EG118 001630/Uvd3 n2

REF: CS/EG118 001630/Uvd3 n2

ASSIGNMENT (ORIG)

From (Person): Yee Pei Li / EG1 Date: 25/1/18 @ 4:39pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD: ① WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: XD 7839X Branch: XD 8221X

at Workshop no: VFix Auto Tel: 6455 2957

of: 60 Kaki Bkt Ave 6

Policy No: \_\_\_\_\_ Claim No: DSMCR1800170

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Vch: \_\_\_\_\_ DOA: 24/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date Time: 8:54am @ 26/1/18 Person Conducted: Irene

Vehicle ID: ①

Date/Time	Action/Instruction (✓) Estimate	
	<u>XD 7839X - NA/INC17021890/r3</u>	<u>D.O.A: 15/11/2017</u>
	<u>XD 8221X - CS/MSG16022885/Gthm2</u>	<u>D.O.A: 26/11/2016</u>
<u>30/1/18</u>	<u>Email preli revised to Pei Li</u>	

EGI

29/1/18

XD 7839X

10/13

○

XD 7839X

Vfix AUTO

60 Kaki Bkt Ave 6

After 10 am



7-2  
3  
20

24-25 lwp

C

CA/

VOLVO FMX370

10/37

white

327074

YV2J1E1D9D4748123

315/80 R 22.5

315/80 R 22.5

Mirage

6

6/6 6/6

6

6/6 6/6

24/1/18

29/1/18

for

29/1/18 conf. int L/S & 4300 with michaele. (Red '6760.80, 617)

RECEIVED 30 JAN 2018



Print Report

Print Report

Days of Report 3

Results of Report -

30/1- typist

TP

LS \$4300/2

350

# **Survey Department Check List (Case Handler)**

Reference No.: CS/EGI 18001630/ Uvd3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are ACCURATE.

## **(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

## **(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

## **(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## **(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## **(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 20/1/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18001630/Uvd3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 26-01-2018



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 8221X	Veh. Inspected	XD 7839X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	26/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	24/01/2018	Inspection Date
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**Veron Chen (LKKAUTO)**

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 30 January 2018 9:31 AM  
**To:** Veron Chen (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018

Veron,

Claim no. is DSMCV1800170.

Rgds  
Pei Li

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Tuesday, 30 January, 2018 8:25 AM  
**To:** Survey Report (ERGO Insurance Pte. Ltd.)  
**Cc:** SUR  
**Subject:** RE: XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018

Dear Pei Li,

Enclosed preliminary revised of vehicle XD 7839X  
Date of survey: 29/1/2018  
Number of days:3 days

**Kindly provides us the claim number**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 26 January 2018 8:57 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,  
**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]**Sent:** Thursday, 25 January 2018 4:39 PM**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>**Subject:** OI : XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018

Dear Catherine,

Please assist to conduct these survey:-

S/N	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	XD 7839X	VFIX AUTO SERVICES PTE LTD @ 60 KAKI BUKIT AVE 6 ARK@KB	6455 2957	XD8221X/RH	ROHAINI	DOA : 24/01/2018 WP

**Note:** To survey on without prejudice basis. Please obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Tel.: 65 6829 9199 DID: 65 6829 9194

Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 30 January 2018 8:25 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018  
**Attachments:** PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle XD 7839X  
Date of survey: 29/1/2018  
Number of days:3 days

**Kindly provides us the claim number**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 26 January 2018 8:57 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments  
<assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Thursday, 25 January 2018 4:39 PM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018

Dear Catherine,

Please assist to conduct these survey:-

S/N	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	XD 7839X	VFIX AUTO SERVICES PTE LTD @ 60 KAKI BUKIT AVE 6 ARK@KB	6455 2957	XD8221X/RH	ROHAINI	DOA : 24/01/2018 WP

**Note: To survey on without prejudice basis. Please obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.**

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: PLEASE ADVISED  
Our Ref: CS/EG118001630/Uvd3

Date: 30/1/2018

The Motor Claims Department  
M/s: ERGO Insurance Pte Ltd

*Without Prejudice*

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. XD 7839X**


We thank you for your instruction on 25/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/1/2018 at the premises of M/s VFIX AUTO SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,060.80
Revised Estimate Amount	: S\$4,300.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

**Nivitha (LKK Auto)**

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Thursday, 25 January 2018 4:39 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : XD8221X / TP : XD7839X/LKK / DOA : 24/01/2018  
**Attachments:** XD8221X - SAS.pdf; XD7839X- SAS.pdf

Dear Catherine,

Please assist to conduct these survey:-

S/N	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	XD 7839X	VFIX AUTO SERVICES PTE LTD @ 60 KAKI BUKIT AVE 6 ARK@KB	6455 2957	XD8221X/RH	ROHAINI	DOA : 24/01/2018 WP

*Note: To survey on without prejudice basis. Please obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.*

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 8963W

## Vehicle Details

Vehicle No.: XD7839X

Vehicle to be Exported: No

Intended De-registration Date: 29 Jan 2018

Vehicle Make: VOLVO

Vehicle Model: FMX370 64R SLEEPER CAB

Primary Colour: White

Manufacturing Year: 2013

Engine No.: D11294672

Chassis No.: YV2J1E1D9DA748123

Maximum Power Output: -

Open Market Value: \$111,122.00

Original Registration Date: 02 Oct 2013

First Registration Date: 02 Oct 2013

Transfer Count: 1

Actual ARF Paid: \$5,557.00

## Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

## Intended COE Rebate Details

COE Expiry Date: 01 Oct 2023

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$71,001.00

COE Rebate Amount: \$40,272.00

**Total Rebate Amount: \$40,272.00**

The information contained herein is correct as at 29 Jan 2018

OK



ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

**Attention: Motor Claim Department**

**RE : VEHICLE NO : XD7839X VOLVO FMX**

Vfix Auto Service Pte Ltd  
60 Kaki Bukit Ave 6  
Ark@KB Singapore 417892  
Email: vfixauto@gmail.com  
Tel: 64489268 Fax: 64452368

**ESTIMATE**

DATE : 25/01/2018  
ACC DATE : 28/01/2018  
REF NO. : VFIX-TP20180407  
POLICY NO :

Not Attached  
2/5 4300  
3 day  
take photo. Attached  
29/1/18

DESCRIPTION	AMOUNT S\$
1 1 WIPER LINKAGE	11 883.60 α
2 1 WIPER GARNISH	11 741.00 α
3 1 FRONT BONNET	11 1,810.20 —
4 1 FRONT BONNET GRILLE	11 1,155.00 —
5 1 FRONT BONNET DAMPER	11 140.00 α
6 2 FRONT BONNET LOCK	142.00 11 284.00 α
7 2 FRONT BONNET CATCH	76.00 11 152.00 α
8 1 FRONT PANEL	11 1,145.00 α
9 2 CABIN SHOCK ABSORBER FRONT	350.00 0/57m 700.00 12 c
10 1 AIR CON CONDENSER	11 750.00 —
	7,760.80

10%

4806.2 4056.2  
4326.58 3650.58

**LABOUR & MISCELLANEOUS:**

	AMOUNT S\$
1 To remove damaged parts with all necessary components/ attachments apply hot-works where necessary replace new parts refit align into position with all necessary components attachments	600 1,400.00
2 To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	400 1,000.00
3 To remove,refit cabin interior components,garnishes,roof lining with all necessary attachments	11 X 300.00
4 To remove,replace air con condenser and recharge gas	100 150.00
5 To remove,replace front windscreen glass and water test	11 X 200.00
6 To remove,refit dashboard meter with all accessories components	11 X 250.00
	\$ 3,300.00
	5425.58

SINGAPORE DOLLARS : ELEVEN THOUSAND AND SIXTY AND CENTS  
EIGHTY ONLY

Vfix Auto Service Pte Ltd



Unif Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No equal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18001630/Uvd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 01-02-2018	
		Code : EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XD 8221X	Veh. Inspected	XD 7839X
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1800170	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	25/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	VOLVO FMX370 (A)	c.c	10837
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	YV2J1E1D9DA748123	Colour	WHITE
Odometer	327074	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	MIRAGE	6 mm
L/H Front Tyre	315/80 R22.5	MIRAGE	6 mm
R/H Rear Tyre	315/80 R22.5 (D/D)	MIRAGE	6/6 6/6 mm
L/H Rear Tyre	315/80 R22.5 (D/D)	MIRAGE	6/6 6/6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	24/01/2018	Inspection Date	29/01/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 7839X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	WIPER LINKAGE	NOT NECESSARY	883.60	-
1	WIPER GARNISH	CRACKED	741.00	741.00
1	FRONT BONNET	CRACKED	1,810.20	1,810.20
1	FRONT BONNET GRILLE	BROKEN	1,155.00	1,155.00
1	FRONT BONNET DAMPER	NOT NECESSARY	140.00	-
2	FRONT BONNET LOCK @\$142.00	NOT NECESSARY	284.00	-
2	FRONT BONNET CATCH @\$76.00	NOT NECESSARY	152.00	-
1	FRONT PANEL	TO REPAIR SEE LABOUR	1,145.00	-
2	CABIN SHOCK ABSORBER FRONT @\$350.00	O/S TWISTED	700.00	350.00
1	AIR CON CONDENSER	BENT / PUNCTURE	750.00	750.00
	LESS 10% DISCOUNT		-	-480.62
			7,760.80	4,325.58
<b>LABOUR</b>				
	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPLACE NEW PARTS REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS ATTACHMENTS.INCLUSIVE OF THE REPAIR OF FRONT PANEL.		1,400.00	600.00
	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		1,000.00	400.00
	TO REMOVE,REFIT CABIN INTERIOR COMPONENTS,GARNISHES,ROOF LINING WITH ALL NECESSARY ATTACHMENTS.	NOT NECESSARY	300.00	-
	TO REMOVE,REPLACE AIR CON CONDENSER AND RECHARGE GAS.		150.00	100.00
	TO REMOVE,REPLACE FRONT WINDSCREEN GLASS AND WATER TEST.	NOT NECESSARY	200.00	-
	TO REMOVE,REFIT DASHBOARD METER WITH ALL ACCESSORIES COMPONENTS.	NOT NECESSARY	250.00	-
			3,300.00	1,100.00
<b>GRAND TOTAL</b>			<b>11,060.80</b>	<b>5,425.58</b>

Report Ref No. CS/EGI18001630/Uvd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,300.00
---	--	--	----------

Report Ref No. CS/EGI18001630/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.