

22/05/2018

ASS: REC. BY:

REF: CS/QBE18001645/Avd302

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Joyce Foo

of QBE

Date/Time: 25/11/18 @ 2:19pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GR4128L

Insured: YP1094S

at Workshop m/s T & C Automotive

Tel: 9007 5148

of 1 Kaki Bkt Ave 6 #01-68

Policy No:

Claim No: V0012333

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/01/2018

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time: 10:11am @ 26/11/18

Person Contacted:

Ah chui

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	YP1094S-X
	GR4128L-X
31/8/18	@ 11:11am Ah chui will check
5/10/18	Adrian confirmed LS \$ 2600 (Red 5302.72, 67b)

SYMBOL

REF:

ASSIGNMENT

GR4128L

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: ~~Y210945~~
 Yr Regn: 2000, Jan.
 Type: M.Car / M.Cycle / Bus / Van (Lorry) Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Dyna. c.c 2779.
 Colour: white. A/C: Insured / Std / NI / NA
 Sp Reading: 161550 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: LY2110015826
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Tyre Size: F: 185R14C Maxmiles
 R: 155R12C Yoko
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 26/01/18
 Survey held at Tard C.
 Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP QBE

RECEIVED 09 OCT 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

Date/Time, File Return to?
 2) 9/10 - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	300
Transportation:	
Photos:	
Others:	
TOTAL:	300

Report Format : TP
 Lump Sum / I.B.I: (\$ 2600/2)

Survey Department Check List (Case Handler)

Reference No.: CS | QBE 18001645 | Avcl3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **):** Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (_____ **):** Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 9/10/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE18001645/Avd3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 26-01-2018	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 1094S	Veh. Inspected	GR 4128L
Policy No.		Coverage (\$)	0.00
Claim No.	V0012333	Excess (\$)	0.00
Assign From	JOYCE FOO	Assign Date	26/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/01/2018	Inspection Date	26/01/2018
Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Thursday, 25 January, 2018 2:19 PM
To: assignments@lkkauto.com
Subject: FW: Pre repair inspection Your ref: YP 1094S DOA 19.01.2018 Our ref: SRSTP.8092.18

Our Ref. V0012333

Hi


Please assist to arrange WP survey. Our insured has yet to report the accident.

Kindly acknowledge receipt.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Ong & Shan LLC [mailto:ongshanllc@gmail.com]
Sent: Thursday, 25 January, 2018 2:10 PM
To: Joyce Foo <joyce.foo@qbe.com>
Subject: Re: Pre repair inspection Your ref: YP 1094S DOA 19.01.2018 Our ref: SRSTP.8092.18

Dear Joyce,

Our client confirmed appointed of **M/s LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Name of workshop : M/s T & C Automotive

Address : 1 Kaki Bukit Ave 6 #01-68
Singapore 417883

Contact person : Mr. Ah Chai

Telephone no : 9-007-5148

Fax no : 6-741-5197

If you fail to conduct the pre-repair inspection within the next two(2) working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

For Surveyor

Please initial here after completion of pre-repair inspection. Thank you.

Name:

Signature:

Date & Time of Pre-repair inspection: /

Warmest Regards,

CM Chen
M/s Ong & Shan LLC
Block 184 Toa Payoh Central
#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261

Email: ongshanllc@gmail.com

On Thu, Jan 25, 2018 at 1:46 PM, Joyce Foo <joyce.foo@qbe.com> wrote:

Our ref : VC011114

Dear Mr Chen

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Priority Services
Quantum Risk Management (S) Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com

Visit us on the web at www.qbe.com.sg



From: Ong & Shan LLC [mailto:ongshanllc@gmail.com]

Sent: Thursday, 25 January, 2018 1:42 PM

To: Joyce Foo <joyce.foo@qbe.com>

Subject: Pre repair inspection Your ref: YP 10945 DOA 19.01.2018 Our ref: SRSTP.8092.18

Dear Joyce,

We refer to the above matter.

Kindly find attached of our letter for your necessary action.

Warmest Regards,

CM Chen

M/s Ong & Shan LLC

Block 184 Toa Payoh Central

#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261

Email: ongshanllc@gmail.com

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2018 17:47
Date Of Accident	19/01/2018 09:20
Exact Location Of Accident	JLN BUROH TOWARDS ROUNDABOUT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GR4128L
Insured/Policyholder	
Name Of Registered Owner	RADICAL AUTO PTE. LTD.
Co Reg No	201501717H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68995020

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5073695776-02
Cover Note Number	

Driver

Name of Driver	MARKANDAN MARIMUTHU
Passport No/FIN	F7888546R
Date Of Birth	29/07/1975
Occupation	OUTDOOR
Date Of Driving Pass	25/08/2014
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83745094
Fax Number	(LOCAL) +65-65620630
Contact Number	OFFICE-68995020
EMail Address	NOEMAIL

Address	NO.1 BUKIT BATOK CRESCENT #09-24 WCEGA PLAZA
Postcode	658064
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED. VEH B REVERSED ANG HIT MY VEH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP1094S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN CHAR POH
NRIC/Passport Number	S0601364C
Contact Number	98333165
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary at the traffic light. I honned when I saw veh B reversing but veh B still hit my veh front. When traffic light turned green, veh B drove off and I followed him back to his company at chin Bee Ave. I informed him what happened and he said he wanted to do private settlement. Later on veh B driver told me to file a report and claim against his veh insurance.

Refer police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

M. Maimun
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: 19-1-17
 NRIC/FIN No:

Annex D

Jurong West NPC
700 Corporation Road
Singapore 649818
Tel: 62689999
Fax: 62672438



Traffic Police Department
Charge Office
10 Ubi Avenue 3
Singapore 408865
Tel: 65470000

Traffic Police
Annex D

NOTICE OF REPORTING

Informant Name : MARKANDAN MARIMUTHU
Identity/Fin Card No : F7888546R
Sex / Age / Race : Male/41yrs/Indian
Address : C/O GBAD SERVICES PTE LTD
Occupation : CONSTRUCTION
Telephone No : 83745094

This is to confirm that the above informant has reported to the Police a non-injury traffic accident which occurred along Jln Buroh towards Roundabout on 19/1/2018 at 0918hrs involving the following vehicles:

V1: GR4128L
V2: YP1094S

On 19/1/2018 at about 0918hrs, my vehicle, V1 was stationary along Jln Buroh towards roundabout at the red traffic light. I then horned when I saw V2 reversing. Due to the reversing, the rear of V2 hit my front. The traffic light then turned green and V2 drove off. I then followed V2 back to his company at Chin Bee Ave and informed the driver, a Chinese, male subject about what happened. He then wanted to settle privately and told me to file a report to claim insurance.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Common Statement Pg. 1

Issuing Officer	:	SGT T1140072
Date / Time	:	19/1/2018@1215HRS
Station Diary No	:	61
Police Post	:	Jurong West NPC

Signature of Informant	:	<i>M. Maimun</i>
Signature of Issuing Officer	:	<i>[Signature]</i> JURONG WEST NPC 700 Corporation Road Singapore 630700 Tel: 6733 2222 Fax: 6733 2222

ESTIMATE

T & C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6, #01-49, SINGAPORE 417883

Date : 26/01/2018

TP QBE

Vehicle no.: GR4128L

Veron

Chassis no.: LY211R-TLMGS

Descriptions	Qty	Unit Price	Amount
Spare Parts			
Front windscreen <i>cracked.</i>	1	\$1,271.73	\$1,271.73 ✓
Front windscreen weatherstrip <i>New</i>	1	\$303.50	\$303.50 ✓
Front wiper garnish inner panel <i>Repair</i>	1	repair	repair X
Front wiper garnish <i>New</i>	1	\$278.80	\$278.80 ✓
Front wiper garnish RH <i>New</i>	1	\$188.00	\$188.00 ✓
Front wiper blade <i>New</i>	2	\$81.20	\$162.40 X
Front wiper arm <i>Dynad RH</i>	2	\$114.40	\$228.80 11440
Front wiper motor <i>New</i>	1	\$729.40	\$729.40 X
Front wiper link <i>New</i>	2	\$351.70	\$703.40 X
Front panel <i>Repair</i>	1	repair	repair X
Front corner panel RH <i>Repair</i>	1	\$188.00	\$188.00 X
Front corner panel LH <i>Repair</i>	1	\$188.00	\$188.00 X
Front panel "Toyota" logo <i>New</i>	1	\$68.50	\$68.50 ✓
Front panel "Dyna" emblem <i>New</i>	1	\$58.50	\$58.50 ✓
Front bumper <i>New</i>	1	\$430.00	\$430.00 X
Front grille <i>cracked</i>	1	\$336.00	\$336.00 ✓
Front grille clip <i>New</i>	8	\$5.00	\$40.00 ✓
Headlamp RH <i>New</i>	1	\$106.40	\$106.40 X
Headlamp LH <i>New</i>	1	\$106.40	\$106.40 X
Front signal lamp RH <i>cracked.</i>	1	\$152.90	\$152.90 ✓
Front signal lamp LH <i>cracked.</i>	1	\$152.90	\$152.90 X
Front beam light RH <i>New</i>	1	\$98.60	\$98.60 ✓
Front beam light LH <i>New</i>	1	\$98.60	\$98.60 X
Front side panel RH <i>Repair</i>	1	\$204.00	\$204.00 X
Front side panel LH <i>Repair</i>	1	\$204.00	\$204.00 X
Side mirror LH <i>New</i>	1	\$238.20	\$238.20 ✓
			\$6,537.03
		Less 25%	\$1,634.26
		Sub Total 1	\$4,902.77

Special Nett

Round mirror LH <i>New</i>	1	\$80.00	\$80.00 X
Front number plate <i>New</i>	1	\$40.00	\$40.00 ✓
ERP sticker <i>New</i>	1	\$15.00	\$15.00 ✓
ERP bracket <i>New</i>	1	\$35.00	\$35.00 ✓
		Sub-Total 2	\$170.00

Labour

- Panel beating and straighten affected parts/area.
- Putty and spray painting affected parts/area.
- Remove and refit front windscreen glass.
- Rewiring
- Anti-rust undercoating

LKK Auto Centre

I hereby certify the work done on the above vehicle is in accordance with the terms and conditions of the LKK Auto Centre warranty.

- This warranty is given on a "no-fault" basis
- No legal responsibility is assumed
- Supplementary claims must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

950

\$1,200.00 ⁵⁰⁰

\$1,200.00 ³⁰⁰

\$150.00 ¹²⁰

\$90.00 ³⁰

\$90.00 X

total 3287.89 ✓

7802.77

2/5: 20K 05/1/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE18001645/Avd3e2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 01-11-2018	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 1094S	Veh. Inspected	GR 4128L
Policy No.		Coverage (\$)	0.00
Claim No.	V0012333	Excess (\$)	0.00
Assign From	JOYCE FOO	Assign Date	25/01/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2779
Engine No.	HIDDEN	Year of Reg.	2000
Chassis No.	LY2110019826	Colour	WHITE
Odometer	161550	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14C	MAXMILER	6 mm
L/H Front Tyre	185 R14C	MAXMILER	6 mm
R/H Rear Tyre	155 R12C	YOKOHAMA	6 mm
L/H Rear Tyre	155 R12C	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/01/2018	Inspection Date	26/01/2018
Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GR 4128L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN	CRACKED	1,271.73	1,271.73
1	FRONT WINDSCREEN WEATHERSTRIP	NECESSARY	303.50	303.50
1	FRONT WIPER GARNISH INNER PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT WIPER GARNISH	DEFORMED	278.80	278.80
1	FRONT WIPER GARNISH RH	CUT	188.00	188.00
2	FRONT WIPER BLADE @\$81.20	NOT NECESSARY	162.40	-
2	FRONT WIPER ARM @\$114.40	O/S DAMAGED	228.80	114.40
1	FRONT WIPER MOTOR	NOT NECESSARY	729.40	-
2	FRONT WIPER LINK @\$351.70	NOT NECESSARY	703.40	-
1	FRONT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT CORNER PANEL RH	TO REPAIR SEE LABOUR	188.00	-
1	FRONT CORNER PANEL LH	TO REPAIR SEE LABOUR	188.00	-
1	FRONT PANEL "TOYOTA" LOGO	NECESSARY	68.50	68.50
1	FRONT PANEL "DYNA" EMBLEM	NECESSARY	58.50	58.50
1	FRONT BUMPER	NOT NECESSARY	430.00	-
1	FRONT GRILLE	CRACKED	336.00	336.00
8	FRONT GRILLE CLIP @\$5.00	NECESSARY	40.00	40.00
1	HEADLAMP RH	NOT NECESSARY	106.40	-
1	HEADLAMP LH	NOT NECESSARY	106.40	-
1	FRONT SIGNAL LAMP RH	CRACKED	152.90	152.90
1	FRONT SIGNAL LAMP LH	NOT NECESSARY	152.90	-
1	FRONT BEAM LIGHT RH	NOT NECESSARY	98.60	-
1	FRONT BEAM LIGHT LH	NOT NECESSARY	98.60	-
1	FRONT SIDE PANEL RH	TO REPAIR SEE LABOUR	204.00	-
1	FRONT SIDE PANEL LH	TO REPAIR SEE LABOUR	204.00	-
1	SIDE MIRROR LH	BENT	238.20	238.20

Report Ref No. CS/QBE18001645/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-1,634.26	-762.63
			4,902.77	2,287.90
	SPECIAL NETT ITEMS			
1	ROUND MIRROR LH (SN)	NOT NECESSARY	80.00	-
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	40.00	-
1	ERP STICKER (SN)	NECESSARY	15.00	15.00
1	ERP BRACKET (SN)	NECESSARY	35.00	35.00
			170.00	50.00
	LABOUR			
	PANEL BEATING AND STRAIGHTEN AFFECTED PARTS / AREA. INCLUSIVE OF THE REPAIR OF FRONT WIPER GARNISH INNER PANEL, FRONT PANEL, FRONT CORNER PANEL RH, FRONT CORNER PANEL LH, FRONT SIDE PANEL RH AND FRONT SIDE PANEL LH.		1,200.00	500.00
	PUTTY AND SPRAY PAINTING AFFECTED PARTS / AREA.		1,200.00	300.00
	REMOVE AND REFIT FRONT WINDSCREEN GLASS.		150.00	120.00
	REWIRING.		90.00	30.00
	ANTI-RUST UNDERCOATING.	NOT NECESSARY	90.00	-
			2,730.00	950.00
	GRAND TOTAL		7,802.77	3,287.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/QBE18001645/Avd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.