

ASS. REC. BY

REF: CS/FCI18061646/4qbn2

Special Instructions

Surveyor

Marcus

ASSIGNMENT (Office)

CWS

From (Person)

Serene Ler

of

FCI

Date/Time 29/11/18 @ 3.20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN166P

Insured:

SHD 3889S

at Workshop m/s

Focus Auto

Tel:

68869097

of

No. 1 Kaki Bkt Ave 6 Autobay #02-50

Policy No:

p-18088936mk3H

Claim No:

D18060854MFSH

Sum Insured

Excess:

Make of Veh:

D.O.A 25/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

3.29pm 29/11/18

Person Contacted:

Ms-Sin

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 166P *

SHD 3889S *

31/1/18 @ 3.05pm revised to Serene by email.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 166

at Workshop m/s focus

of

Insured: SHD 38895

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: 2 Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN166P Yr Regn: 4, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: mazda 3 C.C. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 17466 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM63N24A8H0127109

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/1/18 D.O.I. 29/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/1/18 2/5 # 7800 confirmed with MR Wong
(Red 4274.16, 35%)

RECEIVED 31 FEB 2018

Date/Time, File Pass to? ☐ : Preli. Report13/1/18 tyris ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

2x15: 30

170 + 30

50

50

117

417

Report Format : TP

Lump Sum / I.B.I. (\$) 7800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001696/Uqb		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-01-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3889S	Veh. Inspected	SLN 166P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/01/2018	Inspection Date	29/01/2018	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Policy Type: OD / (TP) / TP RES / TL / EVA

Typist

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	26-01-2018	Our Ref No. D18000854MFSH
Accident Date	25-01-2018	Claim Type. Third Party
Insured Vehicle	SHD3889S	Third Party Vehicle. SLN166P
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50	
Contact Person.	MS SIN	
Contact No.	68869097/ 0	Fax No. 64819095
Survey Type	WITHOUT PREJUDICE: LIABILITY CLEAR / QUANTUM TO BE AGREED (NO EST. PROVIDED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FOCUS AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234408)



PRI Documents



Close



PRI Header Details

Claim No	D18000854MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & FOCUS AL
Workshop Name	FOCUS AUTO PTE LTD (Contact Person : MS SIN)	Survey Location & Contact Details	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50 Mobile: 0 , Phone: 68869097 , Fax: 64819095 EmailId: FOCUS.AUTOPTELTD@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILIRY CLEAR / QUANTUM TO PROVIDED)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3889S	TP Vehicle No	SLN166P
PRI Recieved Date	26-01-2018 09:01:12 PM	Surveyor Appointed Date	29-01-2018 03:19:31 PM	Surveyor Accept Date	29-01-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-01-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 31 January 2018 3:05 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000854MFSH/1
Attachments: CSFCI18001696Uqb.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLN 166P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 29 January 2018 3:31 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000854MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 29 January 2018 3:20 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000854MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000854MFSH

Date: 31 January 2018

Our Ref: CS/FCI18001696/Uqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 166P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/01/2018 at the premises of M/s FOCUS AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,074.16</u>
Revised Estimate Amount	: S\$ <u>9,772.96</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2756A

Vehicle Details

Vehicle No.: SLN166P
Vehicle to be Exported: No
Intended De-registration Date: 29 Jan 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: P520411023
Chassis No.: JM6BN24A8H0127109
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$19,463.00
Original Registration Date: 20 Apr 2017
First Registration Date: 20 Apr 2017
Transfer Count: 0
Actual ARF Paid: \$14,463.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Apr 2027
PARF Rebate Amount: \$10,847.00

Intended COE Rebate Details

COE Expiry Date: 19 Apr 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$52,000.00
COE Rebate Amount: \$47,969.00
Total Rebate Amount: \$58,816.00

The information contained herein is correct as at 29 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2756A

Vehicle Details

Vehicle No.: SLN166P

Vehicle to be Exported: No

Intended De-registration Date: 26 Jan 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 5-DOOR
HATCHBACK 1.5L SP.6EAT

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: P520411023

Chassis No.: JM6BN24A8H0127109

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$19,463.00

Original Registration Date: 20 Apr 2017

First Registration Date: 20 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$14,463.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Apr 2027

PARF Rebate Amount: \$10,847.00

Intended COE Rebate Details

COE Expiry Date: 19 Apr 2027

COE Category: A - Car up to 1600cc & 97kW
(130bhp)

COE Period(Years): 10

QP Paid: \$52,000.00

COE Rebate Amount: \$48,011.00

Total Rebate Amount: \$58,858.00

The information contained herein is correct as at 26 Jan 2018

OK

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S: FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
TEL: 6507 3848
ATTN: Motor Claim Department
Your Ref No: SLN166P
Claim Type: Third Party
Accident Date: 25/01/2018
TP Veh Reg No: SHD3889S

FAX: 6507 3849

Estimate No: EST0000576
Date: 27 Jan 2018
Policy No: 2100507548-00000
Veh Reg No: SLN166P
Make/Model: MAZDA 3
Chassis No: JM6BN24A8H0127109
Engine No: P520411023
Reg. Date: 20/04/2017

not Authorized
2/5#7800/-
6 day.
29/1/18
John photo after repair

Estimate Repair Cost to Vehicle No :SLN166P

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
MAZDA 3 1.5				
List Price				
1 Rear Boot	Body 20 1,269.0000	1 PC	1,269.00	✓
2 Rear Boot Lock	7w1 271.0000	1 PC	271.00	✓
3 Rear Boot Lock Catch	11 56.0000	1 PC	56.00	✗
4 Rear Boot Top Hinge	11 36.0000	2 PC	72.00	✗
5 Rear Boot Damper	11 121.0000	2 PC	242.00	✗
6 Rear Boot Rubber	1w1 130.0000	1 PC	130.00	✓
7 Rear Boot Emblem (Mazda 3)	ru 54.0000	1 PC	54.00	✓
8 Rear Boot Emblem (SKYACTIVE)	ru 64.0000	1 PC	64.00	✓
9 Rear Boot Centre Logo	ru 75.0000	1 PC	75.00	✓
10 Rear Boot Centre Garnish	cne 427.0000	1 PC	427.00	✓
11 Rear Boot Reflector Lamp	cne 444.0000	2 PC	888.00	✓
12 Rear Tail Lamp	cne 926.0000	2 PC	1,852.00	✓
13 Rear Tail Lamp Clipse	11 15.0000	2 PC	30.00	✗
14 Rear Boot Inner Cover Board	de/cne 358.0000	1 PC	358.00	✓
15 Rear Spare Tyre Cover Board	7w1 308.0000	1 PC	308.00	✓
16 Rear Tool Sponge Tray	7w1 227.0000	1 PC	227.00	✓
17 Rear End Panel	Body 20 625.0000	1 PC	625.00	✓
18 Rear End Panel Top Garnish	7w1 196.0000	1 PC	196.00	✓
19 Rear Bumper	D13 950.0000	1 PC	950.00	✓
20 Rear Bumper Reinforcement	D13 538.0000	1 PC	538.00	✓
21 Rear Bumper Side Retainer	3w1 36.0000	2 PC	72.00	✓
22 Rear Bumper Sensor	shld 173.0000	2 PC	346.00	✓
23 Rear Bumper Top Clipse	ru 15.0000	3 PCS	45.00	✓
24 Rear Bumper Towing Cover RH	7w1 20.0000	1 PC	20.00	✓
25 Rear Bumper Lower Garnish <i>lower retainer</i>	CM 135.0000	1 PC	135.00	✓
26 Rear Bumper Lower Side Cover LH	AF 30.0000	1 PC	30.00	✗
27 Rear Bumper Reflector	o/s/cne 49.0000	2 PC	98.00	1 PC
28 Rear Exhaust Silencer	ru 1,024.0000	1 PC	1,024.00	✗
29 Rear Exhaust Rubber Mounting	11 34.0000	2 PCS	68.00	✓
30 Rear Exhaust Top Heat Cover	ru 143.0000	1 PC	143.00	✗
31 Rear Windscreen Lower Rubber Seal	ru 56.0000	1 PC	56.00	✓

8955
9216.2
7372.96

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
TEL: 6507 3848 FAX: 6507 3849
ATTN: Motor Claim Department
Your Ref No: SLN166P
Claim Type: Third Party
Accident Date: 25/01/2018
TP Veh Reg No: SHD3889S

Estimate No: EST0000576
Date: 27 Jan 2018
Policy No: 2100507548-00000
Veh Reg No: SLN166P
Make/Model: MAZDA 3
Chassis No: JM6BN24A8H0127109
Engine No: P520411023
Reg. Date: 20/04/2017

Estimate Repair Cost to Vehicle No :SLN166P

PAGE:2/2

Description	U/Price	Quantity	List Price SS	Amount SS
			10,669.00	
		Less 20%	2,133.80	8,535.20
Special Net				
32 Rear Windscreen <i>Gum Sealant</i>	<i>all</i> 80.0000	1 PC	80.00	<i>405.~</i> 80.00
Labour				
33 Towing Fees	50.0000	1 PC	50.00	<i>α</i>
34 Panel Beating	1,600.0000	1 PC	1,600.00	<i>980</i>
35 Check Wiring	60.0000	1 PC	60.00	<i>30</i>
36 Rust Proofing	60.0000	1 PC	60.00	<i>50</i>
37 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	<i>60</i>
38 To Remove & Replace Exhaust	80.0000	1 PC	80.00	<i>120</i>
39 To Remove & Refit Rear Windscreen	160.0000	1 PC	160.00	<i>980</i>
40 To Spray Painting	1,000.0000	1 PC	1,000.00	<i>80</i>
41 To Remove & Refit Rear Garnish & Upholstery	160.0000	1 PC	160.00	
			3,250.00	3,250.00
		Total		SS 11,865.20

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND EIGHT HUNDRED SIXTY FIVE AND CENTS TWENTY ONLY

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE

12074.16

Link Auto Consultants hereby notify the Repairer of the following:

- To resurvey before spray painting
- To dispose damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alterations/modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S :

FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
TEL: 6507 3848
ATTN: Motor Claim Department
Your Ref No: SLN166P
Claim Type: Third Party
Accident Date: 25-01-2018
TP Veh Reg No: SHD3889S

FAX: 6507 3849

Estimate No: EST0000576
Date: 27 Jan 2018
Policy No: 2100507548-00000
Veh Reg No: SLN166P
Make/Model: MAZDA 3
Chassis No: JM6BN24A8H0127109
Engine No: P520411023
Reg. Date: 20-04-2017

Estimate Repair Cost to Vehicle No :SLN166P

PAGE:1/1

Item No	Description	U/Price	Quantity	List Price SS	Amount SS
MAZDA 3 1.5 SUPPLEMENTRY ITEM					
List Price					
32	RSSENSOR	Rear Smart Sensor	1 PC	210.20	
33	RBLGL	Rear Bumper Lower Garnish	6 PC	51.00	
				261.20	
				Less 20%	52.24
					208.96
				Total	SS 208.96

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SEVENTY FOUR AND CENTS SIXTEEN ONLY

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001696/Uqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3889S	Veh. Inspected	SLN 166P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000854MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	29/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN24A8H0127109	Colour	BLACK	
Odometer	17466	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	6 mm	
L/H Front Tyre	205/60 R16	TOYO	6 mm	
R/H Rear Tyre	205/60 R16	TOYO	6 mm	
L/H Rear Tyre	205/60 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/01/2018	Inspection Date	29/01/2018	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 166P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BADLY DENTED	1,269.00	1,269.00
1	REAR BOOT LOCK	TWISTED	271.00	271.00
1	REAR BOOT LOCK CATCH	NOT NECESSARY	56.00	-
2	REAR BOOT TOP HINGE @\$36.00	NOT NECESSARY	72.00	-
2	REAR BOOT DAMPER @\$121.00	NOT NECESSARY	242.00	-
1	REAR BOOT RUBBER	TWISTED	130.00	130.00
1	REAR BOOT EMBLEM (MAZDA 3)	NECESSARY	54.00	54.00
1	REAR BOOT EMBLEM (SKYACTIVE)	NECESSARY	64.00	64.00
1	REAR BOOT CENTRE LOGO	NECESSARY	75.00	75.00
1	REAR BOOT CENTRE GARNISH	CRACKED	427.00	427.00
2	REAR BOOT REFLECTOR LAMP @\$444.00	CRACKED	888.00	888.00
2	REAR TAIL LAMP @\$926.00	CRACKED	1,852.00	1,852.00
2	REAR TAIL LAMP CLIPSE @\$15.00	NOT NECESSARY	30.00	-
1	REAR BOOT INNER COVER BOARD	DEFORMED / CRACKED	358.00	358.00
1	REAR SPARE TYRE COVER BOARD	TORN	308.00	308.00
1	REAR TOOL SPONGE TRAY	TORN	227.00	227.00
1	REAR END PANEL	BADLY DENTED	625.00	625.00
1	REAR END PANEL TOP GARNISH	TWISTED	196.00	196.00
1	REAR BUMPER	DISTORTED	950.00	950.00
1	REAR BUMPER REINFORCEMENT	DISTORTED	538.00	538.00
2	REAR BUMPER SIDE RETAINER @\$36.00	BENT	72.00	72.00
2	REAR BUMPER SENSOR @\$173.00	SHORTED	346.00	346.00
3	REAR BUMPER TOP CLIPSE @\$15.00	NECESSARY	45.00	45.00
1	REAR BUMPER TOWING COVER RH	TORN	20.00	20.00
1	REAR BUMPER LOWER INNER RETAINER	CRACKED	135.00	135.00
1	REAR BUMPER LOWER SIDE COVER LH	NOT FITTED	30.00	-
2	REAR BUMPER REFLECTOR @\$49.00	O/S CRACKED	98.00	49.00
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	1,024.00	-
2	REAR EXHAUST RUBBER MOUNTING @\$34.00	NOT NECESSARY	68.00	-

Report Ref No. CS/FCI18001696/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST TOP HEAT COVER	TO REPAIR SEE LABOUR	143.00	-
1	REAR WINDSCREEN LOWER RUBBER SEAL	NECESSARY	56.00	56.00
1	REAR SMART SENSOR (ADDITIONAL)	SHORTED	210.20	210.20
6	REAR BUMPER LOWER GARNISH RIVET @\$8.50 (ADDITIONAL)	NECESSARY	51.00	51.00
	LESS 20% DISCOUNT		-2,186.04	-1,843.24
			8,744.16	7,372.96
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
			80.00	40.00
	<u>LABOUR</u>			
	TOWING FEES.	NOT NECESSARY	50.00	-
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER AND REAR EXHAUST TOP HEAT COVER.		1,600.00	980.00
	CHECK WIRING.		60.00	30.00
	RUST PROOFING.		60.00	60.00
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	50.00
	TO REMOVE & REPLACE EXHAUST.		80.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN.		160.00	120.00
	TO SPRAY PAINTING.		1,000.00	980.00
	TO REMOVE & REFIT REAR GARNISH & UPHOLSTERY.		160.00	80.00
			3,250.00	2,360.00
	GRAND TOTAL		12,074.16	9,772.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,800.00

Report Ref No. CS/FC118001696/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.